


SZS CONSULTING GROUP

DRAFT ADA TRANSITION PLAN UPDATE
NEIGHBORHOOD AREA 1 NORTHWEST
SEPTEMBER 20, 2011



CITY OF CITRUS HEIGHTS

The Northwest Neighborhood Association

The Northwest Neighborhood Association Area is primarily a residential area with one commercial/retail center and one elementary school. The area borders are Interstate 80, Roseville Road, Whyte Avenue, and Tupelo Drive.

Conditions

Most of the sidewalks in this area are pre-1992 construction, which were identified with common issues such as non-compliant cross slopes, clear width issues, abrupt changes of level, and poor surface conditions. Many pre-1992 curb ramps were identified with multiple barriers to access. A new residential area adjacent to Roseville Road area was identified with post-1992 construction with more compliant sidewalks and some compliance issues identified at the curb ramps regarding detectable warnings (12" grooves and truncated domes). The main arterial roadway in this area is Antelope Blvd which appeared to be of post-1992 construction, in which minor compliance issues were identified in the curb ramps.



Built elements found within the public rights-of-way in the Northwest Neighborhood Area were “depressed curbs” which are not actual curb cuts but depressed areas in the concrete at intersection corners that it is assumed were intended to assist with travel over the existing vertical or rolled curb. Also, a number of locations were identified with “elbows” that were altered into curb ramps. These locations are in residential areas, in which 90 degree turns in the sidewalk were actually altered into curb ramps without a crossing through the roadway that the curb ramp would be intended to enable.

It is assumed that an error was made in the design or construction process that led to this issue, as the sidewalk at such locations is not required to have a curb cut or ramp, as it is not a safe location to encourage crossing due to the lack of line of sight for on-coming cars and due to the fact that this area constitutes the longest route of travel through the roadway at a crossing within the residential areas. A curb ramp at such a location actually makes pedestrian travel more difficult.

Statistics

An intersection inventory was compiled as part of the field assessment process. In the Northwest Neighborhood Association Area, 47 intersections were found to have no barriers to access and a total of 1281 barriers were identified. The compliant intersections are identified as follows:

#	Location	Notes
1	Brimstone Dr and Branchwater Wy - Corners B,C	Two - way intersection. Corners B,C compliant
2	Mimosa Ct and Buttonwood Wy - Corners A,D	Two - way intersection. Corners A,D compliant
3	Outlook Dr and Woodyard Wy - Corners A,B	Two - way intersection. Corners A,B compliant
4	Buttonwood Wy and Treelark Wy - Corners B,C	Two - way intersection. Corners B,C compliant
5	Lichen Dr and Mountainside Dr - Corners B,C,D	Three - way intersection. Corners B,C,D compliant
6	Mountainside Dr and Ferncreek Ct - Corners A,B	Two - way intersection corners A,B compliant
7	Lichen Dr and Treeleaf Wy - Corners B,C	Two - way intersection. Corners B,C compliant
8	Catamaran Dr and Catboat Cir and Schooner Wy - Corners A,B,C,D	Four - way intersection. Corners A,B,C,D compliant
9	Villaview Dr and Castleberry Cir - Corners A,B	Two - way intersection. Corners A,B compliant
10	Butternut Dr and Oakmyrtle Wy - Corner A,D	Two - way intersection. Corners A,D compliant
11	Parkvale Wy and Sierravale Wy - Corners B,C	Two - way intersection. Corners B,C compliant
12	Summerplace Dr and Stonehand Ave - Corners A,D	Two - way intersection. Corners A,D compliant
13	Summerplace Dr and Mesaview Dr - Corners A,D	Two - way intersection. Corners A,D compliant
14	Cornerstone Wy and Carmelwood Dr - Corners A,B,C,D	Four - way intersection. Corners A,B,C,D compliant
15	Stonehead Ave and Saybrook Dr - Corners A,B,C,D	Four - way intersection. Corners A,B,C,D compliant
16	Butternut Dr and Basswood Wy - Corners A,D	Two - way intersection. Corners A,D compliant
17	Viscount Wy and Zenith Dr - Corners A,B,C,D	Four - way intersection corners A,B,C,D compliant
18	Cloverleaf Wy and Treeleaf Wy - Corners B,C,D	Three - way intersection corners B,C,D compliant
19	Butternut Dr and Radford St - Corners A,B	Two - way intersection. Corners A,B compliant
20	Parkvale Wy and Schooner Wy - Corners A,B	Two - way intersection corners A,B compliant
21	Bitter Bush Wy and Zenith Dr - Corners A,D	Two - way intersection. Corners A,D compliant
22	Ravencrest Wy and Briartree Wy - Corners C,D	Two - way intersection. Corners C,D compliant
23	Villaview Dr and Butternut Dr - Corners A,B,C,D	Four - way intersection. Corners A,B,C,D compliant
24	Villaview Dr and Twining Wy - Corners B,C,D	Three - way intersection. Corners B,C,D compliant
25	Villaview Dr and Yardley Wy - Corners B,C,D	Three - way intersection. Corners B,C,D compliant
26	Zenith Dr and Sorrell Ct - Corners A,D	Two - way intersection. Corners A,D compliant
27	Villaview Dr and Castleberry Cir - Corners A,B,C,D	Four - way intersection. Corners A,B,C,D compliant
28	Zenith Dr and Brimstone Dr - Corners A,C,D	Three - way intersection. Corners A,C,D compliant
29	Ratten Wy and Briartree Wy - Corners A,B	Two - way intersection. Corners A,B compliant
30	Twining Wy and Radford St - Corners A,D	Two - way intersection. Corners A,D compliant
31	Treebine Ave and Leaoak Ct - Corners A,B	Two - way intersection. Corners A,B compliant
32	Stonehand Wy and Ashmont St - Corners A,B	Two - way intersection. Corners A,B compliant
33	Treebine Ave and Basswood Wy - Corners A,B,C	Three - way intersection. Corners A,B,C compliant

34	Butternut Dr and Woodyard Wy - Corners C,D	Two - way intersection. Corners C,D compliant
35	Cornerstone Wy and Bitter Bush Wy - Corners B,C	Two - way intersection. Corners B,C compliant
36	Lichen Dr and Stonecrop Ct - Corners A,D	Two - way intersection. Corners A,D compliant
37	Treebine Ave and Buttonwood Wy - Corners A,D	Two - way intersection. Corners A,D compliant
38	Basswood Wy and Buttonwood Wy - Corners B,C,D	Three - way intersection. Corners B,C,D compliant
39	Oakmyrtle Wy and Buttonwood Wy - Corners B,C	Two - way intersection. Corners B,C compliant
40	Lichen Dr and Treebine Ave - Corners B,C	Two - way intersection. Corners B,C compliant
41	Briartree Wy and Summerplace Dr - Corners A,B,C	Three - way intersection corners A,B,C compliant
42	Carmelwood Dr and Cornerstone Wy - Corners A,B,C,D	Four - way intersection. Corners A,B,C,D compliant
43	Twining Wy and Mannerly Wy - Corners A,B,C	Three - way intersection. Corners A,B,C compliant
44	Cornerstone Wy and Grey Oak Ct - Corners B,C	Two - way intersection. Corners B,C compliant
45	Mesaview Dr and Brockwood Wy - Corners A,B,C,D	Four - way intersection corners A,B,C,D compliant
46	Briartree Wy and Cornerstone Wy - Corners C,D	Two - way intersection. Corners C,D compliant
47	Tupelo Dr and Sierravale Wy - Corners A,B,C	Three - way intersection. Corners A,B,C compliant

Barrier severity ratings were calculated for the 5 ratings assigned as follows:

<i>Severity 1 (Necessary to Remove)</i>	<i>959 or 74% of total barriers</i>
<i>Severity 2 (Recommended to Remove)</i>	<i>248 or 20% of total barriers</i>
<i>Severity 3 (Hindrance to Access)</i>	<i>41 or 4% of total barriers</i>
<i>Severity 4 (Low Severity Barrier)</i>	<i>21 or 1% of total barriers</i>
<i>Severity 5 (Technically Infeasible to Remove)</i>	<i>12 or 1% of total barriers</i>

Barrier Removal Priority Assignment

The draft barrier removal priorities were assigned to the pedestrian facilities using the criteria described below:

Priority 1 - Primary arterial roadways where the majority of bus routes are located
Antelope Road

Priority 2 – Major collectors where remaining bus routes are located or where commercial centers, schools, parks, churches, state or local agency facilities exist
Butternut Drive
Lichen Drive

Priority 3 - Pedestrian routes leading from points of arrival at bus routes to schools, parks or other public accommodations
Outlook Drive
Zenith Drive

Priority 4 – Remaining residential areas

Cost Estimates

The total cost for barrier removal within this draft ADA Transition Plan update was calculated as follows:

Cost Estimate Total: \$26,212,575.00

Barrier removal takes place through annual phases that are determined according to the barrier priority assigned and existing budgetary constraints. Draft barrier removal priorities have the following costs associated with each priority assigned:

Cost Estimate - Priority 1: \$114,875.00

Cost Estimate - Priority 2: \$2,173,475.00

Cost Estimate - Priority 3: \$1,510,700.00

Cost Estimate - Priority 4: \$22,413,525.00

Further input is required to complete the ADA Transition Plan. Each Neighborhood Area (NA) must be reviewed by designated Citrus Heights City staff to determine whether overall priorities shall be set per NA or overall throughout the city. Other constraints were taken into consideration while compiling the cost estimates.

1. Currently all barriers are assigned a priority for removal. Some areas may not be used as pedestrian facilities, may be unimproved and could remain so until a request for accommodations is received by the City.
 - a. Assistance in prioritizing areas that lack sidewalk is required. Some segments are lengthy and may not be planned for improvements in the long or short term.
2. Cost estimates have been manually reviewed and corrected
 - a. In instances where more than one barrier exists at a curb ramp, cost estimates for curb ramp barriers are often manually changed to ensure that cost estimates do not exceed \$2,500. In these instances, the cost estimate for the first barrier (i.e. 24A, of 24B, 24C and 25D) is listed with a cost estimate of \$2,500 and the remaining barriers are listed with a cost of \$0. This may occur even when the first barrier listed is not ordinarily estimated as high as \$2,500.
 - b. Driveways with multiple slopes were assigned a severity 1 rating, rather than a rating that corresponded to the slope of only one of the measurements taken.
 - c. Bus stop benches with multiple barriers were only assigned one cost estimate for one accessible bench.

The following barrier data sheets must be reviewed in draft form to provide input for the final report.

Field Date: 9/28/2010 Report Date: 9/28/2010 Barrier #: 1

Location: Roseville Rd and Whyte Ave - Corner B

X Coordinate: -121.30975

Y Coordinate: 38.72181

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 10.4% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 2

Location: Roseville Rd and Whyte Ave - Corner C

X Coordinate: -121.30993

Y Coordinate: 38.72168

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 13.7% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: 9/28/2010 Report Date: 9/28/2010 Barrier #: 3

Location: Whyte Ave - North

X Coordinate: -121.30975

Y Coordinate: 38.72181

Barrier Area: Sidewalks

Barrier Type: Cross Slope - New Construction

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 84 Quantity: LF

Description: Cross slope exceeds 2.0% in new construction

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$10,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/28/2010 Report Date: 9/28/2010 Barrier #: 4

Location: Whyte Ave and Imran Woods Cir - Corner A

X Coordinate: -121.30956

Y Coordinate: 38.72167

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 10.6% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: 9/28/2010 Report Date: 9/28/2010 Barrier #: 5

Location: Whyte Ave and Imran Woods Cir - Corner B

X Coordinate: -121.30942

Y Coordinate: 38.72155

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 12.3% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 6

Location: Whyte Ave and Imran Woods Cir - Corner C

X Coordinate: -121.30956

Y Coordinate: 38.72141

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 11.3% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 7

Location: Whyte Ave and Imran Woods Cir - Corner D

X Coordinate: -121.30969

Y Coordinate: 38.72150

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 10.3% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: 9/28/2010 Report Date: 9/28/2010 Barrier #: 8

Location: Imran Woods Cir - West

X Coordinate: -121.30956

Y Coordinate: 38.72167

Barrier Area: Sidewalks

Barrier Type: Cross Slope - New Construction

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 352 Quantity: LF

Description: Cross slope exceeds 2.0% in new construction

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$44,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 9/28/2010 Report Date: 9/28/2010 Barrier #: 9

Location: Iman Woods Cir - West

X Coordinate: -121.30866

Y Coordinate: 38.72243

Barrier Area: Sidewalks

Barrier Type: Cross Slope - New Construction

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 126 Quantity: LF

Description: Cross slope exceeds 2.0% in new construction

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$15,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/28/2010 Report Date: 9/28/2010 Barrier #: 10

Location: Iman Woods Cir - North


X Coordinate: -121.30813

Y Coordinate: 38.72248

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 289 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$36,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/28/2010 Report Date: 9/28/2010 Barrier #: 11

Location: Julie Lynn Ct - North

X Coordinate: -121.30705

Y Coordinate: 38.72245

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (2.1% to 3.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 12 Quantity: LF

Description: Cross slope exceeds 2.0% (2.1% to 3.0%)

As Built Desc: 3.0% cross slope

Solution: Low severity barrier - no remediation recommended

Bar. Severity: 4 Low Severity

Cost Estimate: \$0.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 9/28/2010 Report Date: 9/28/2010 Barrier #: 12

Location: Julie Lynn Ct - South

X Coordinate: -121.30680

Y Coordinate: 38.72230

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 10 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance

Cost Estimate: \$1,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	9/28/2010	Report Date:	9/28/2010	Barrier #:	13A
Location:	Julie Lynn Ct and Imran Woods Cir - Corner C				
X Coordinate:	-121.30697				
Y Coordinate:	38.72230				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (4.1% to 4.9%)		
As Built Desc:	4.2% at 12" grooves		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	2 Recommended	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners C,D		

Field Date:	9/28/2010	Report Date:	9/28/2010	Barrier #:	13B
Location:	Julie Lynn Ct and Imran Woods Cir - Corner C				
X Coordinate:	-121.30697				
Y Coordinate:	38.72230				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH
Description:	No truncated domes provided at curb ramp		
As Built Desc:	No detectable warnings at curb ramp		
Solution:	Provide compliant truncated domes		
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners C,D		

Field Date:	9/28/2010	Report Date:	9/28/2010	Barrier #:	13C
Location:	Julie Lynn Ct and Imran Woods Cir - Corner C				
X Coordinate:	-121.30697				
Y Coordinate:	38.72230				
Barrier Area:	Curb Ramps				
Barrier Type:	Gutter Slope - Existing (8.3% or more)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.2				



As Built Meas:	1	Quantity:	SF
Description:	Gutter slope exceeds 5.0% (8.3% or more)		
As Built Desc:	8.3% gutter slope		
Solution:	Demolish existing and construct new gutter		
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners C,D		

Field Date:	9/28/2010	Report Date:	9/28/2010	Barrier #:	13D
Location:	Julie Lynn Ct and Imran Woods Cir - Corner C				
X Coordinate:	-121.30697				
Y Coordinate:	38.72230				
Barrier Area:	Curb Ramps				
Barrier Type:	Lip - Gutter to Asphalt Transition				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 303.3				



As Built Meas:	1	Quantity:	EACH
Description:	Transition at transition into asphalt not flush and free of any lip		
As Built Desc:	1" lip at asphalt transition into roadway		
Solution:	Remove lip to create flush transition		
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners C,D		

Field Date: 9/28/2010 Report Date: 9/28/2010 Barrier #: 14

Location: Julie Lynn Ct and Imran Woods Cir - Corner D

X Coordinate: -121.30716

Y Coordinate: 38.72231

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D

Field Date: 9/28/2010 Report Date: 9/28/2010 Barrier #: 15

Location: Imran Woods Cir - South


X Coordinate: -121.30716

Y Coordinate: 38.72227

Barrier Area: Sidewalks

Barrier Type: Cross Slope - New Construction

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 871 Quantity: LF

Description: Cross slope exceeds 2.0% in new construction

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$108,875.00 Status:


Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	9/28/2010	Report Date:	9/28/2010	Barrier #:	16A
Location:	Irman Woods Cir - East				
X Coordinate:	-121.30856				
Y Coordinate:	38.72239				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				
As Built Meas:	375	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	6.1% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$46,875.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					



Notes:

Field Date:	9/28/2010	Report Date:	9/28/2010	Barrier #:	16B
Location:	Irman Woods Cir - East				
X Coordinate:	-121.30865				
Y Coordinate:	38.72224				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				
As Built Meas:	4	Quantity:	LF		
Description:	Change in level greater than 1/2"				
As Built Desc:	1" lip in sidewalk surface				
Solution:	Grind or repair sidewalk to remove trip hazard				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					



Notes:

Field Date: 9/28/2010 Report Date: 9/28/2010 Barrier #: 17

Location: Whyte Ave - North


X Coordinate: -121.30903

Y Coordinate: 38.72144

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 324 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$40,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 9/28/2010 Report Date: 9/28/2010 Barrier #: 18

Location: Whyte Ave and Regli Woods Ct - Corner A

X Coordinate: -121.30826

Y Coordinate: 38.72148

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 11.1% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: 9/28/2010 Report Date: 9/28/2010 Barrier #: 19

Location: Whyte Ave and Regli Woods Ct - Corner B

X Coordinate: -121.30814

Y Coordinate: 38.72147

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 12.1% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: 9/28/2010 Report Date: 9/28/2010 Barrier #: 20

Location: Regli Woods Ct - West

X Coordinate: -121.30827

Y Coordinate: 38.72150

Barrier Area: Sidewalks

Barrier Type: Cross Slope - New Construction

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 148 Quantity: LF

Description: Cross slope exceeds 2.0% in new construction

As Built Desc: 6.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$18,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 9/28/2010 Report Date: 9/28/2010 Barrier #: 21

Location: Regli Woods Ct - West

X Coordinate: -121.30824

Y Coordinate: 38.72189

Barrier Area: Sidewalks

Barrier Type: Cross Slope - New Construction

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 128 Quantity: LF

Description: Cross slope exceeds 2.0% in new construction

As Built Desc: 6.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$16,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/28/2010 Report Date: 9/28/2010 Barrier #: 22

Location: Regli Woods Ct - East

X Coordinate: -121.30815

Y Coordinate: 38.72167

Barrier Area: Sidewalks

Barrier Type: Cross Slope - New Construction

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 124 Quantity: LF

Description: Cross slope exceeds 2.0% in new construction

As Built Desc: 5.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$15,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/28/2010 Report Date: 9/28/2010 Barrier #: 23

Location: Whyte Ave - North

X Coordinate: -121.30814

Y Coordinate: 38.72147

Barrier Area: Sidewalks

Barrier Type: Cross Slope - New Construction

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 260 Quantity: LF

Description: Cross slope exceeds 2.0% in new construction

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$32,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 24

Location: Whyte Ave and Imran Woods Cir - Corner A

X Coordinate: -121.30715

Y Coordinate: 38.72147

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 11.2% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 25

Location: Whyte Ave and Imran Woods Cir - Corner B

X Coordinate: -121.30707

Y Coordinate: 38.72145

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided at blended transition

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$1,400.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 26A

Location: Imran Woods Cir - West


X Coordinate: -121.30715

Y Coordinate: 38.72147

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 287 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$35,875.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 26B

Location: Imran Woods Cir - West

X Coordinate: -121.30717

Y Coordinate: 38.72193

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 26C

Location: Imran Woods Cir - West

X Coordinate: -121.30715

Y Coordinate: 38.72201

Barrier Area: Sidewalks

Barrier Type: Protruding Hazard

Code Ref: CBC 1133B.8.6.1 and ADA/ABA 307.2



As Built Meas: 1 Quantity: JOB

Description: Protruding object in route of travel between 27" and 80" high

As Built Desc: 24" protruding hazard at tree branches

Solution: Remove object or provide detectable warning

Bar. Severity: 1 Necessary Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 27

Location: Imran Woods Cir - East


X Coordinate: -121.30704

Y Coordinate: 38.72212

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 107 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$13,375.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 28A

Location: Imran Woods Cir - East

X Coordinate: -121.30704

Y Coordinate: 38.72185

Barrier Area: Sidewalks

Barrier Type: No Sidewalk - No Barricade

Code Ref: MUTCD Section 6D.01



As Built Meas: 1 Quantity: JOB

Description: No barricade provided where sidewalk ends in hazardous location

As Built Desc: No barricade or other warning provided for the visually impaired at end of sidewalk

Solution: Provide barricade with cane detectable warning at end of sidewalk

Bar. Severity: 1 Necessary

Cost Estimate: \$1,350.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:


Notes:

Field Date:	9/29/2010	Report Date:	9/29/2010	Barrier #:	28B
Location:	Imran Woods Cir - East				
X Coordinate:	-121.30706				
Y Coordinate:	38.72181				
Barrier Area:	Sidewalks				
Barrier Type:	No sidewalk				
Code Ref:	CBC 1127B.1 and ADA/ABA 206.2.1				



As Built Meas:	149	Quantity:	LF
Description:	No pedestrian route provided		
As Built Desc:	No sidewalk provided		
Solution:	Construct new firm and stable pedestrian route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$14,900.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	9/29/2010	Report Date:	9/29/2010	Barrier #:	29
Location:	Whyte Ave - North				
X Coordinate:	-121.30703				
Y Coordinate:	38.72139				
Barrier Area:	Sidewalks				
Barrier Type:	No sidewalk				
Code Ref:	CBC 1127B.1 and ADA/ABA 206.2.1				



As Built Meas:	249	Quantity:	LF
Description:	No pedestrian route provided		
As Built Desc:	No sidewalk provided		
Solution:	Construct new firm and stable pedestrian route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$24,900.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 30

Location: Whyte Ave and 2nd Ave - Corner A

X Coordinate: -121.30609

Y Coordinate: 38.72137

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided at blended transition

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$1,400.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 31

Location: Whyte Ave and 2nd Ave - Corner B

X Coordinate: -121.30598

Y Coordinate: 38.72141

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided at blended transition

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$1,400.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 32

Location: Whyte Ave - North


X Coordinate: -121.30596

Y Coordinate: 38.72139

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 201 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$20,100.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 33

Location: Whyte Ave and Lichen Dr - Corner A

X Coordinate: -121.30522

Y Coordinate: 38.72143

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 10.8% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date:	9/29/2010	Report Date:	9/29/2010	Barrier #:	34
Location:	Whyte Ave and Lichen Dr - Corner B				
X Coordinate:	-121.30503				
Y Coordinate:	38.72146				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	11.2% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	35
Location:	Whyte Ave and Lichen Dr - Corner C				
X Coordinate:	-121.30496				
Y Coordinate:	38.72129				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.6% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 36

Location: Whyte Ave and Lichen Dr - Corner D

X Coordinate: -121.30521

Y Coordinate: 38.72131

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 16.1% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 37

Location: Lichen Dr - West

X Coordinate: -121.30517

Y Coordinate: 38.72145

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 457 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$57,125.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	9/29/2010	Report Date:	9/29/2010	Barrier #:	38A
Location:	Whyte Ave - North				
X Coordinate:	-121.30502				
Y Coordinate:	38.72144				
Barrier Area:	Sidewalks				
Barrier Type:	No Sidewalk - No Barricade				
Code Ref:	MUTCD Section 6D.01				



As Built Meas:	1	Quantity:	JOB
Description:	No barricade provided where sidewalk ends in hazardous location		
As Built Desc:	No barricade or other warning provided for the visually impaired at end of sidewalk		
Solution:	Provide barricade with cane detectable warning at end of sidewalk		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,350.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	9/29/2010	Report Date:	9/29/2010	Barrier #:	38B
Location:	Whyte Ave - North				
X Coordinate:	-121.30502				
Y Coordinate:	38.72144				
Barrier Area:	Sidewalks				
Barrier Type:	No sidewalk				
Code Ref:	CBC 1127B.1 and ADA/ABA 206.2.1				



As Built Meas:	8	Quantity:	LF
Description:	No pedestrian route provided		
As Built Desc:	No sidewalk provided		
Solution:	Construct new firm and stable pedestrian route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$800.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 39

Location: Whyte Ave - North

X Coordinate: -121.30502

Y Coordinate: 38.72144

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 1597 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$159,700.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 40

Location: Whyte Ave and Vernon St - Corner A

X Coordinate: -121.29972

Y Coordinate: 38.72206

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided at blended transition

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date:	9/29/2010	Report Date:	9/29/2010	Barrier #:	41
Location:	Whyte Ave and Vernon St - Corner B				
X Coordinate:	-121.29957				
Y Coordinate:	38.72211				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	42
Location:	Whyte Ave and Vernon St - Corner C				
X Coordinate:	-121.29964				
Y Coordinate:	38.72190				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.9% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 43

Location: Whyte Ave and Vernon St - Corner D

X Coordinate: -121.29975

Y Coordinate: 38.72197

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided at blended transition

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 44

Location: Whyte Ave - North


X Coordinate: -121.29947

Y Coordinate: 38.72212

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 187 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$23,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	9/29/2010	Report Date:	9/29/2010	Barrier #:	45
Location:	Whyte Ave and Glenbrook Ave - Corner A				
X Coordinate:	-121.29886				
Y Coordinate:	38.72213				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date:	9/29/2010	Report Date:	9/29/2010	Barrier #:	46
Location:	Whyte Ave and Blue Springs Wy - Corner C				
X Coordinate:	-121.29889				
Y Coordinate:	38.72194				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	12.4% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners C,D		

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 47

Location: Whyte Ave and Blue Springs Wy - Corner D

X Coordinate: -121.29909

Y Coordinate: 38.72195

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 10.2% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 48

Location: Blue Springs Wy - East


X Coordinate: -121.29895

Y Coordinate: 38.72188

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 439 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$54,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:


Notes:

Field Date:	9/29/2010	Report Date:	9/29/2010	Barrier #:	49
Location:	Blue Springs Wy - East				
X Coordinate:	-121.29891				
Y Coordinate:	38.72075				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	151	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.8% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$18,875.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	9/29/2010	Report Date:	9/29/2010	Barrier #:	50
Location:	Blue Springs Wy - South				
X Coordinate:	-121.29913				
Y Coordinate:	38.72051				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	261	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.3% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$32,625.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 51

Location: Blue Springs Wy - South


X Coordinate: -121.30032

Y Coordinate: 38.72047

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 154 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$19,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 52A

Location: Blue Springs Wy - South


X Coordinate: -121.30098

Y Coordinate: 38.72058

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 145 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$18,125.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 52B

Location: Blue Springs Wy - South

X Coordinate: -121.30111

Y Coordinate: 38.72060

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 4 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary

Cost Estimate: \$500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 53

Location: Blue Springs Wy and Mountainside Dr - Corner B

X Coordinate: -121.30004

Y Coordinate: 38.72060

Barrier Area: Curb Ramps

Barrier Type: Water Accumulation - Existing

Code Ref: CBC 1133B.5.8 and ADA/ABA 405.10



As Built Meas: 1 Quantity: EACH

Description: Water does not drain off of curb ramp

As Built Desc: Standing water - New Construction

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D. Corners A,C,D compliant

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 54

Location: Blue Springs Wy and Whiteplains Ct - Corner C

X Coordinate: -121.30140

Y Coordinate: 38.72058

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 12.1% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 55

Location: Blue Springs Wy and Whiteplains Ct - Corner D

X Coordinate: -121.30155

Y Coordinate: 38.72062

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 11.6% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:


Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D

Field Date:	9/29/2010	Report Date:	9/29/2010	Barrier #:	56
Location:	Whiteplains Ct - East				
X Coordinate:	-121.30142				
Y Coordinate:	38.72056				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	150	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	7.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$18,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	9/29/2010	Report Date:	9/29/2010	Barrier #:	57
Location:	Whiteplains Ct - West				
X Coordinate:	-121.30153				
Y Coordinate:	38.72022				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	166	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$20,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 58

Location: Blue Springs Wy - South

X Coordinate: -121.30158

Y Coordinate: 38.72062

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 236 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$29,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 59

Location: Blue Springs Wy and Lost Cavern Ct - Corner C

X Coordinate: -121.30244

Y Coordinate: 38.72060

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 12.1% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 60

Location: Blue Springs Wy and Lost Cavern Ct - Corner D

X Coordinate: -121.30264

Y Coordinate: 38.72055

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 11.3% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 61

Location: Lost Cavern Ct - East


X Coordinate: -121.30248

Y Coordinate: 38.72055

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 227 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$28,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 62

Location: Lost Cavern Ct - West

X Coordinate: -121.30264

Y Coordinate: 38.72053

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 216 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$27,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 63

Location: Blue Springs Wy - South


X Coordinate: -121.30269

Y Coordinate: 38.72063

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 475 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$59,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 64

Location: Blue Springs Wy and Lost Mine Ct - Corner C

X Coordinate: -121.30435

Y Coordinate: 38.72054

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 13.1% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 65

Location: Blue Springs Wy and Lost Mine Ct - Corner D

X Coordinate: -121.30448

Y Coordinate: 38.72061

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 11.8% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 66

Location: Lost Mine Ct - East

X Coordinate: -121.30435

Y Coordinate: 38.72056

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 222 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$27,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 67

Location: Lost Mine Ct - West


X Coordinate: -121.30448

Y Coordinate: 38.72026

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 230 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$28,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 68

Location: Blue Springs Wy - South

X Coordinate: -121.30455

Y Coordinate: 38.72061

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 172 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$21,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 69

Location: Lichen Dr and Blue Springs Wy - Corner B

X Coordinate: -121.30507

Y Coordinate: 38.72077

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 9.2% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: 9/29/2010 Report Date: 9/29/2010 Barrier #: 70

Location: Lichen Dr and Blue Springs Wy - Corner C

X Coordinate: -121.30508

Y Coordinate: 38.72062

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 13.1% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 71

Location: Lichen Dr - East

X Coordinate: -121.30516

Y Coordinate: 38.72062

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 407 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$50,875.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 72

Location: Mountainside Dr - North

X Coordinate: -121.30517

Y Coordinate: 38.71950

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 438 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$54,750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:



Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 73

Location: Ferncreek Ct - West

X Coordinate: -121.30357

Y Coordinate: 38.71950

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 207 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$25,875.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:



Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 74

Location: Ferncreek Ct - East

X Coordinate: -121.30347

Y Coordinate: 38.71955

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 208 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$26,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 75

Location: Mountainside Dr - North

X Coordinate: -121.30338

Y Coordinate: 38.71946

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 187 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$23,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 76

Location: Mountainside Dr - North

X Coordinate: -121.30266

Y Coordinate: 38.71949

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 271 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$33,875.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 77

Location: Mountainside Dr - North

X Coordinate: -121.30171

Y Coordinate: 38.71952

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 152 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$19,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 78

Location: Canevalley Cir and Mountainside Dr - Corner A

X Coordinate: -121.30118

Y Coordinate: 38.71967

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - New Construction

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (>5.0%)

As Built Desc: 5.2% at 12" grooves - New Construction

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection corners A,C,D

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 79A

Location: Canevalley Cir and Mountainside Dr - Corner C

X Coordinate: -121.30439

Y Coordinate: 38.71933

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - New Construction

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (>5.0%)

As Built Desc: 7.1% at 12" grooves - New Construction

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection corners A,C,D

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	79B
Location:	Canevalley Cir and Mountainside Dr - Corner C				
X Coordinate:	-121.30439				
Y Coordinate:	38.71933				
Barrier Area:	Curb Ramps				
Barrier Type:	Perpendicular Ramp Landing - New Construction				
Code Ref:	CBC 1127B.5.4 and ADA/ABA 406.4				



As Built Meas:	1	Quantity:	EACH
Description:	Curb ramp landing or pan not level (>5.0% or more)		
As Built Desc:	5.1% landing slope		
Solution:	Demolish existing and construct new transition		
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Three - way intersection corners A,C,D		

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	80
Location:	Canevalley Cir and Mountainside Dr - Corner D				
X Coordinate:	-121.30117				
Y Coordinate:	38.71952				
Barrier Area:	Curb Ramps				
Barrier Type:	Parallel Ramp Landing - New Construction				
Code Ref:	CBC 1127B.5.4 and ADA/ABA 406.4				



As Built Meas:	1	Quantity:	EACH
Description:	Curb ramp landing or pan not level(4.1% to 4.9%)		
As Built Desc:	4.3% landing slope		
Solution:	Demolish existing and construct new transition		
Bar. Severity:	1 Necessary	Cost Estimate:	\$250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Three - way intersection corners A,C,D		

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	81
Location:	Mountainside Dr - North				
X Coordinate:	-121.30116				
Y Coordinate:	38.71968				
Barrier Area:	Sidewalks				
Barrier Type:	Running Slope (New Construction)				
Code Ref:	CBC 1133B.7.3 and ADA/ABA 403.3				



As Built Meas:	4	Quantity:	LF
Description:	Running slope exceeds 5.0%		
As Built Desc:	7.7% running slope		
Solution:	No remediation where sidewalk sloped as roadway		
Bar. Severity:	5 Technically Infeasible	Cost Estimate:	\$0.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	82
Location:	Mountainside Dr - North				
X Coordinate:	-121.30114				
Y Coordinate:	38.71967				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	159	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.9% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$19,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 83

Location: Mountainside Dr - North

X Coordinate: -121.30063

Y Coordinate: 38.71986

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 253 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$31,625.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 84

Location: Mountainside Dr - West

X Coordinate: -121.30024

Y Coordinate: 38.72072

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 213 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$26,625.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 85

Location: Whyte Ave and Mountainside Dr - Corner C

X Coordinate: -121.30034

Y Coordinate: 38.72131

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - New Construction

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (4.1% to 4.9%)

As Built Desc: 4.6% at 12" grooves - New Construction

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D. Corner D compliant

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 86A

Location: Whyte Ave - South

X Coordinate: -121.30060

Y Coordinate: 38.72132

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 283 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$35,375.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	86B
Location:	Whyte Ave - South				
X Coordinate:	-121.30059				
Y Coordinate:	38.72133				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing (36" to 43")				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	1	Quantity:	LF
Description:	Pedestrian route is not min. 48" wide (36" to 43")		
As Built Desc:	36" clear width due to foliage		
Solution:	Trim foliage to provide min. 48" clear width		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	87A
Location:	Whyte Ave - South				
X Coordinate:	-121.30161				
Y Coordinate:	38.72131				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	255	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$31,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	87B
Location:	Whyte Ave - South				
X Coordinate:	-121.30216				
Y Coordinate:	38.72129				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	4	Quantity:	LF
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)		
As Built Desc:	Cracked concrete		
Solution:	Repair surface to make firm and stable		
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	88
Location:	Whyte Ave - South				
X Coordinate:	-121.30243				
Y Coordinate:	38.72129				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	325	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$40,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 89A

Location: Whyte Ave - South

X Coordinate: -121.30363

Y Coordinate: 38.72128

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 382 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$47,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 89B

Location: Whyte Ave - South

X Coordinate: -121.30450

Y Coordinate: 38.72128

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 90A

Location: Lichen Dr - East

X Coordinate: -121.30497

Y Coordinate: 38.72121

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 182 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$22,750.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 90B

Location: Lichen Dr - East

X Coordinate: -121.30498

Y Coordinate: 38.72105

Barrier Area: Sidewalks

Barrier Type: Protruding Hazard

Code Ref: CBC 1133B.8.6.1 and ADA/ABA 307.2



As Built Meas: 1 Quantity: JOB

Description: Protruding object in route of travel between 27" and 80" high

As Built Desc: 26" protruding hazard at tree branches

Solution: Remove object or provide detectable warning

Bar. Severity: 1 Necessary Cost Estimate: \$1,400.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	90C
Location:	Lichen Dr - East				
X Coordinate:	-121.30499				
Y Coordinate:	38.72101				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip in sidewalk surface		
Solution:	Grind or repair to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	90D
Location:	Lichen Dr - East				
X Coordinate:	-121.30501				
Y Coordinate:	38.72102				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ($\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	1	Quantity:	LF
Description:	Pedestrian route is not min. 48" wide ($\leq 31"$ or less)		
As Built Desc:	28" clear width due to foliage		
Solution:	Trim foliage to provide min. 48" clear width		
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 91

Location: Blue Springs Wy - North

X Coordinate: -121.30491

Y Coordinate: 38.72071

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 391 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$48,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 92A

Location: Blue Springs Wy - North

X Coordinate: -121.30237

Y Coordinate: 38.72069

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 397 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$49,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 92B

Location: Blue Springs Wy - North

X Coordinate: -121.30355

Y Coordinate: 38.72069

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 4 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 93

Location: Blue Springs Wy - North

X Coordinate: -121.30321

Y Coordinate: 38.72068

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 579 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$72,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	94
Location:	Blue Springs Wy - North				
X Coordinate:	-121.30034				
Y Coordinate:	38.72053				
Barrier Area:	Sidewalks				
Barrier Type:	Running Slope (Existing)				
Code Ref:	CBC 1133B.7.3 and ADA/ABA 403.3				



As Built Meas:	4	Quantity:	LF
Description:	Running slope exceeds 5.0%		
As Built Desc:	6.9% running slope		
Solution:	No remediation where sidewalk sloped as roadway		
Bar. Severity:	5 Technically Infeasible	Cost Estimate:	\$0.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	95A
Location:	Mountainside Dr - East				
X Coordinate:	-121.30011				
Y Coordinate:	38.72067				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	247	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$30,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	95B
Location:	Mountainside Dr - East				
X Coordinate:	-121.30026				
Y Coordinate:	38.72101				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - New Construction				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	1	Quantity:	LF
Description:	Pedestrian route is not min. 48" wide		
As Built Desc:	0" clear width due to foilage growth		
Solution:	Trim foliage to provide min. 48" clear width		
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	96
Location:	Mountainside Dr - East				
X Coordinate:	-121.30036				
Y Coordinate:	38.72126				
Barrier Area:	Sidewalks				
Barrier Type:	Running Slope (New Construction)				
Code Ref:	CBC 1133B.7.3 and ADA/ABA 403.3				



As Built Meas:	4	Quantity:	LF
Description:	Running slope exceeds 5.0% where roadway slope does not		
As Built Desc:	8.4% running slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 97A

Location: Whyte Ave - South

X Coordinate: -121.30026

Y Coordinate: 38.72136

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 261 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$32,625.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 97B

Location: Whyte Ave - South

X Coordinate: -121.29994

Y Coordinate: 38.72154

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: Report Date: Barrier #:

Location:

X Coordinate:

Y Coordinate:

Barrier Area:

Barrier Type:

Code Ref:



As Built Meas: Quantity:

Description:

As Built Desc:

Solution:

Bar. Severity:

Cost Estimate:

Status:

Implementation Priority:

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: Report Date: Barrier #:

Location:

X Coordinate:

Y Coordinate:

Barrier Area:

Barrier Type:

Code Ref:



As Built Meas: Quantity:

Description:

As Built Desc:

Solution:

Bar. Severity:

Cost Estimate:

Status:

Implementation Priority:

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	98C
Location:	Whyte Ave - South				
X Coordinate:	-121.29948				
Y Coordinate:	38.72199				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - New Construction				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	4	Quantity:	LF
Description:	Pedestrian route is not min. 48" wide		
As Built Desc:	24" clear width due to pole and foliage		
Solution:	Make alterations to provide min.. 32" clear width		
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	99
Location:	Blue Springs Wy - West				
X Coordinate:	-121.29900				
Y Coordinate:	38.72194				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	198	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$24,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 100

Location: St. Albans Ct and Blue Springs Wy - Corner D

X Coordinate: -121.29909

Y Coordinate: 38.72118

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 10.6% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D. Corner A compliant

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 101

Location: St. Albans Ct -South

X Coordinate: -121.29934

Y Coordinate: 38.72132

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 102

Location: St. Albans Ct - South

X Coordinate: -121.29937

Y Coordinate: 38.72123

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 111 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$13,875.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 103

Location: Blue Springs Wy - West

X Coordinate: -121.29901

Y Coordinate: 38.72104

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 195 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$24,375.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	104
Location:	Blue Springs Wy - North				
X Coordinate:	-121.29918				
Y Coordinate:	38.72060				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	269	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$33,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	105
Location:	Mountainside Dr - East				
X Coordinate:	-121.30010				
Y Coordinate:	38.72042				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	191	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$23,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 106

Location: Mountainside Dr and Brushcreek Ct - Corner C

X Coordinate: -121.30029

Y Coordinate: 38.71988

Barrier Area: Curb Ramps

Barrier Type: Perpendicular Ramp Landing - New Construction

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level (>5.0% or more)

As Built Desc: 6.3% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary Cost Estimate: \$250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D. Corner D compliant

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 107

Location: Brushcreek Ct - East

X Coordinate: -121.30032

Y Coordinate: 38.71986

Barrier Area: Sidewalks

Barrier Type: Running Slope (New Construction)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 7 Quantity: LF

Description: Running slope exceeds 5.0% where roadway slope does not

As Built Desc: 6.4% running slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 108A

Location: Brushcreek Ct - East

X Coordinate: -121.30032

Y Coordinate: 38.71985

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 229 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$28,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 108B

Location: Brushcreek Ct - East

X Coordinate: -121.30020

Y Coordinate: 38.71974

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1

As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 12" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary Cost Estimate: \$125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 109

Location: Brushcreek Ct - East

X Coordinate: -121.30005

Y Coordinate: 38.71925

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 250 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$31,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 110

Location: Brushcreek Ct - West

X Coordinate: -121.30025

Y Coordinate: 38.71867

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 463 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$57,875.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 111

Location: Mountainside Dr - South

X Coordinate: -121.30054

Y Coordinate: 38.71975

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 149 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$18,625.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 112

Location: Canevalley Cir - East

X Coordinate: -121.30099

Y Coordinate: 38.71921

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 434 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$54,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 113A

Location: Canevalley Cir - South

X Coordinate: -121.30122

Y Coordinate: 38.71861

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 176 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 4.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$22,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 113B

Location: Canevalley Cir - South

X Coordinate: -121.30161

Y Coordinate: 38.71866

Barrier Area: Sidewalks

Barrier Type: Clear Width - New Construction

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide

As Built Desc: 18" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary Cost Estimate: \$125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 114

Location: Canevalley Cir - South

X Coordinate: -121.30200

Y Coordinate: 38.71863

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 262 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$32,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 115

Location: Canevalley Cir - South

X Coordinate: -121.30289

Y Coordinate: 38.71866

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 462 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$57,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 116

Location: Canevalley Cir - West

X Coordinate: -121.30455

Y Coordinate: 38.71865

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 227 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$28,375.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 117

Location: Mountainside Dr - South

X Coordinate: -121.30430

Y Coordinate: 38.71933

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 898 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$112,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	118
Location:	Canevalley Cir - West				
X Coordinate:	-121.30115				
Y Coordinate:	38.71948				
Barrier Area:	Sidewalks				
Barrier Type:	Running Slope (New Construction)				
Code Ref:	CBC 1133B.7.3 and ADA/ABA 403.3				



As Built Meas:	4	Quantity:	LF
Description:	Running slope exceeds 5.0% where roadway slope does not		
As Built Desc:	7.1% running slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	119
Location:	Canevalley Cir - West				
X Coordinate:	-121.30111				
Y Coordinate:	38.71946				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	264	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.9% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$33,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: Report Date: Barrier #:

Location:

X Coordinate:

Y Coordinate:

Barrier Area:

Barrier Type:

Code Ref:



As Built Meas: Quantity:

Description:

As Built Desc:

Solution:

Bar. Severity: Cost Estimate: Status:

Implementation Priority: Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: Report Date: Barrier #:

Location:

X Coordinate:

Y Coordinate:

Barrier Area:

Barrier Type:

Code Ref:



As Built Meas: Quantity:

Description:

As Built Desc:

Solution:

Bar. Severity: Cost Estimate: Status:

Implementation Priority: Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	122A
Location:	Canevalley Cir - North				
X Coordinate:	-121.30268				
Y Coordinate:	38.71873				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				
As Built Meas:	495	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.1% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$61,875.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					



Notes:

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	122B
Location:	Canevalley Cir - North				
X Coordinate:	-121.30290				
Y Coordinate:	38.71874				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				
As Built Meas:	4	Quantity:	LF		
Description:	Change in level greater than 1/2"				
As Built Desc:	1" lip in sidewalk surface				
Solution:	Grind or repair to remove trip hazard				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					



Notes:

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	123
Location:	Canevalley Cir - North				
X Coordinate:	-121.30437				
Y Coordinate:	38.71875				
Barrier Area:	Sidewalks				
Barrier Type:	Elbow in Sidewalk - Cross Slope (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	4	Quantity:	LF
Description:	Cross slope at elbow exceeds 2.0% (5.0% or more)		
As Built Desc:	12.1% cross slope		
Solution:	Demolish existing and construct new sidewalk without curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	124
Location:	Canevalley Cir - East				
X Coordinate:	-121.30442				
Y Coordinate:	38.71881				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	179	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$22,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	125
Location:	Canevalley Cir - East				
X Coordinate:	-121.30442				
Y Coordinate:	38.71922				
Barrier Area:	Sidewalks				
Barrier Type:	Running Slope (New Construction)				
Code Ref:	CBC 1133B.7.3 and ADA/ABA 403.3				



As Built Meas:	4	Quantity:	LF
Description:	Running slope exceeds 5.0% where roadway slope does not		
As Built Desc:	7.9% running slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	126
Location:	Mountainside Dr - South				
X Coordinate:	-121.30465				
Y Coordinate:	38.71932				
Barrier Area:	Sidewalks				
Barrier Type:	Running Slope (New Construction)				
Code Ref:	CBC 1133B.7.3 and ADA/ABA 403.3				



As Built Meas:	4	Quantity:	LF
Description:	Running slope exceeds 5.0% where roadway slope does not		
As Built Desc:	8.0% running slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 127

Location: Mountainside Dr - South

X Coordinate: -121.30470

Y Coordinate: 38.71939

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 160 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$20,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 9/30/2010 Report Date: 9/30/2010 Barrier #: 128A

Location: Lichen Dr - East

X Coordinate: -121.30527

Y Coordinate: 38.71923

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 409 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$51,125.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date:	9/30/2010	Report Date:	9/30/2010	Barrier #:	128B
Location:	Lichen Dr - East				
X Coordinate:	-121.30530				
Y Coordinate:	38.71835				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - New Construction				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	18	Quantity:	LF
Description:	Pedestrian route is not min. 48" wide		
As Built Desc:	24" clear width due to pole and guide wire		
Solution:	Make alterations to provide min.. 32" clear width		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,250.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	10/1/2010	Report Date:	10/1/2010	Barrier #:	129
Location:	Lichen Dr and Cloverleaf Wy - Corner C				
X Coordinate:	-121.30526				
Y Coordinate:	38.71795				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.8% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	Three - way intersection corners A,B,C. Corners A,B compliant
--------	---

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 130

Location: Cloverleaf Wy - North


X Coordinate: -121.30491

Y Coordinate: 38.71805

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 512 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$64,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 131

Location: Cloverleaf Wy - East

X Coordinate: -121.30274

Y Coordinate: 38.71777

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 93 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance

Cost Estimate: \$11,625.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 132

Location: Cloverleaf Wy - East

X Coordinate: -121.30286

Y Coordinate: 38.71614

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 610 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$76,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 133

Location: Cloverleaf Wy - South

X Coordinate: -121.30367

Y Coordinate: 38.71612

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 51 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$6,375.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 134A

Location: Cloverleaf Wy - South

X Coordinate: -121.30402

Y Coordinate: 38.71607

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 121 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$15,125.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 134B

Location: Cloverleaf Wy - South

X Coordinate: -121.30407

Y Coordinate: 38.71603

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair to remove trip hazard

Bar. Severity: 1 Necessary

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 135

Location: Cloverleaf Wy - South

X Coordinate: -121.30408

Y Coordinate: 38.71603

Barrier Area: Sidewalks

Barrier Type: Driveway - New Construction

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 35 Quantity: LF

Description: Driveway cross/running slope exceeds 2.0%

As Built Desc: 5.7% cross slope, 10.2% running slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 1 Necessary

Cost Estimate: \$4,375.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 136

Location: Treeleaf Wy - East

X Coordinate: -121.30432

Y Coordinate: 38.71569

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 83 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$10,375.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 137A

Location: Treeleaf Wy - South

X Coordinate: -121.30406

Y Coordinate: 38.71528

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 90 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$11,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 137B

Location: Treeleaf Wy - South

X Coordinate: -121.30441

Y Coordinate: 38.71517

Barrier Area: Sidewalks

Barrier Type: Elbow in Sidewalk - Cross Slope (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 8 Quantity: LF

Description: Cross slope at elbow exceeds 2.0% (5.0% or more)

As Built Desc: 10.3% cross slope

Solution: Demolish existing and construct new sidewalk without curb ramp

Bar. Severity: 1 Necessary

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 138

Location: Treeleaf Wy - South

X Coordinate: -121.30449

Y Coordinate: 38.71513

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 95 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$11,875.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 139

Location: Butternut Dr and Treeleaf Wy - Corner A

X Coordinate: -121.30507

Y Coordinate: 38.71503

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Three - way intersection corners A,B,C. Corners B,C compliant

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 140

Location: Butternut Dr - East

X Coordinate: -121.30461

Y Coordinate: 38.71447

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 201 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$25,125.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 141

Location: Butternut Dr - East

X Coordinate: -121.30444

Y Coordinate: 38.71384

Barrier Area: Sidewalks

Barrier Type: Continuous Surface

Code Ref: CBC 1133B.7.1 and ADA/ABA 402.2



As Built Meas: 42 Quantity: LF

Description: Sidewalks lack a continuous common surface

As Built Desc: No continuous sidewalk provided

Solution: Provide new sidewalk that is continuous

Bar. Severity: 1 Necessary Cost Estimate: \$5,250.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	10/1/2010	Report Date:	10/1/2010	Barrier #:	142A
Location:	Butternut Dr - East				
X Coordinate:	-121.30446				
Y Coordinate:	38.71374				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	320	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$40,000.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/1/2010	Report Date:	10/1/2010	Barrier #:	142B
Location:	Butternut Dr - East				
X Coordinate:	-121.30447				
Y Coordinate:	38.71374				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	4	Quantity:	LF
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)		
As Built Desc:	Cracked concrete		
Solution:	Repair surface to make firm and stable		
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 143

Location: Butternut Dr and Trefoil Ct - Corner B

X Coordinate: -121.30454

Y Coordinate: 38.71312

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 144

Location: Butternut Dr and Trefoil Ct - Corner C

X Coordinate: -121.30460

Y Coordinate: 38.71301

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 145A

Location: Butternut Dr - East

X Coordinate: -121.30480

Y Coordinate: 38.71268

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 1054 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$131,750.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 145B

Location: Butternut Dr - East

X Coordinate: -121.30482

Y Coordinate: 38.71265

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair to remove trip hazard

Bar. Severity: 1 Necessary

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 145C

Location: Butternut Dr - East

X Coordinate: -121.30551

Y Coordinate: 38.71177

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 4 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 145D

Location: Butternut Dr - East

X Coordinate: -121.30673

Y Coordinate: 38.71063

Barrier Area: Sidewalks

Barrier Type: Running Slope (New Construction)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 4 Quantity: LF

Description: Running slope exceeds 5.0% where roadway slope does not

As Built Desc: 8.2% running slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 145E

Location: Butternut Dr - East

X Coordinate: -121.30674

Y Coordinate: 38.71063

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - Tree Heaves

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip due to tree heaves

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 145F

Location: Butternut Dr - East

X Coordinate: -121.30696

Y Coordinate: 38.71041

Barrier Area: Sidewalks

Barrier Type: No Sidewalk - Transition to Shoulder

Code Ref: CBC 1121B.2 and ADA/ABA 206.2.1



As Built Meas: 1 Quantity: JOB

Description: Sidewalk ends and no ramp to pedestrian shoulder is provided

As Built Desc: No ramp to shoulder to enable pedestrian travel onto existing shoulder

Solution: Provide transition ramp to paved shoulder where no opposite sidewalk exists

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	10/1/2010	Report Date:	10/1/2010	Barrier #:	145G
Location:	Butternut Dr - East				
X Coordinate:	-121.30696				
Y Coordinate:	38.71041				
Barrier Area:	Sidewalks				
Barrier Type:	No Sidewalk - No Barricade				
Code Ref:	MUTCD Section 6D.01				



As Built Meas:	1	Quantity:	JOB
Description:	No barricade provided where sidewalk ends in hazardous location		
As Built Desc:	No barricade or other warning provided for the visually impaired at end of sidewalk		
Solution:	Provide barricade with cane detectable warning at end of sidewalk		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,350.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/1/2010	Report Date:	10/1/2010	Barrier #:	145H
Location:	Butternut Dr - East				
X Coordinate:	-121.30696				
Y Coordinate:	38.71041				
Barrier Area:	Sidewalks				
Barrier Type:	Shoulder Cross Slope - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	1056	Quantity:	LF
Description:	Cross slope exceeds 2.0% (2.1% to 3.0%)		
As Built Desc:	2.9% cross slope		
Solution:	Low severity barrier - no remediation recommended		
Bar. Severity:	4 Low Severity	Cost Estimate:	\$0.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/1/2010	Report Date:	10/1/2010	Barrier #:	146
Location:	Lichen Dr and Lichen Dr - Corner A				
X Coordinate:	-121.30711				
Y Coordinate:	38.71056				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Three - way intersection corners A,B,D		

Field Date:	10/1/2010	Report Date:	10/1/2010	Barrier #:	147
Location:	Lichen Dr and Lichen Dr - Corner B				
X Coordinate:	-121.30702				
Y Coordinate:	38.71043				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Three - way intersection corners A,B,D		

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	148
Location:	Lichen Dr and Lichen Dr - Corner D				
X Coordinate:	-121.30721				
Y Coordinate:	38.71041				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Three - way intersection corners A,B,D		

Field Date:	10/1/2010	Report Date:	10/1/2010	Barrier #:	149
Location:	Butternut Dr - West				
X Coordinate:	-121.30707				
Y Coordinate:	38.71057				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	266	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$33,250.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/1/2010	Report Date:	10/1/2010	Barrier #:	150
Location:	Butternut Dr and Treelark Wy - Corner A				
X Coordinate:	-121.30645				
Y Coordinate:	38.71114				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date:	10/1/2010	Report Date:	10/1/2010	Barrier #:	151
Location:	Butternut Dr and Treelark Wy - Corner B				
X Coordinate:	-121.30630				
Y Coordinate:	38.71129				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 152

Location: Butternut Dr - West

X Coordinate: -121.30629

Y Coordinate: 38.71128

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 663 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$82,875.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 153

Location: Butternut Dr - West

X Coordinate: -121.30485

Y Coordinate: 38.71298

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 772 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$96,500.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 154

Location: Butternut Dr - West

X Coordinate: -121.30507

Y Coordinate: 38.71508

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 300 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$37,500.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 155

Location: Butternut Dr -West

X Coordinate: -121.30582

Y Coordinate: 38.71588

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 190 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$23,750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	156
Location:	Butternut Dr and Lichen Dr - Corner A (A-B)				
X Coordinate:	-121.30645				
Y Coordinate:	38.71632				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	157
Location:	Butternut Dr and Lichen Dr - Corner A (A-A)				
X Coordinate:	-121.30645				
Y Coordinate:	38.71640				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 158

Location: Butternut Dr and Lichen Dr - Corner B

X Coordinate: -121.30625

Y Coordinate: 38.71653

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 159

Location: Butternut Dr and Lichen Dr - Corner C

X Coordinate: -121.30614

Y Coordinate: 38.71638

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 160

Location: Butternut Dr and Lichen Dr - Corner D

X Coordinate: -121.30629

Y Coordinate: 38.71628

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 161

Location: Lichen Dr -South

X Coordinate: -121.30606

Y Coordinate: 38.71648

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 163 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$20,375.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 162A

Location: Lichen Dr -East

X Coordinate: -121.30536

Y Coordinate: 38.71711

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 300 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$37,500.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 162B

Location: Lichen Dr -East

X Coordinate: -121.30530

Y Coordinate: 38.71725

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair to remove trip hazard

Bar. Severity: 1 Necessary

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 163A

Location: Cloverleaf Wy - South

X Coordinate: -121.30523

Y Coordinate: 38.71795

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 175 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$21,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 163B

Location: Cloverleaf Wy - South

X Coordinate: -121.30486

Y Coordinate: 38.71797

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	10/1/2010	Report Date:	10/1/2010	Barrier #:	164A
Location:	Cloverleaf Wy and Bramble Tree Wy - Corner C				
X Coordinate:	-121.30442				
Y Coordinate:	38.71793				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (>5.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (>5.0%)		
As Built Desc:	7.1% at 12" grooves		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners C,D		

Field Date:	10/1/2010	Report Date:	10/1/2010	Barrier #:	164B
Location:	Cloverleaf Wy and Bramble Tree Wy - Corner C				
X Coordinate:	-121.30442				
Y Coordinate:	38.71793				
Barrier Area:	Curb Ramps				
Barrier Type:	Parallel Ramp Landing - New Construction				
Code Ref:	CBC 1127B.5.9 and ADA/ABA 406.4				



As Built Meas:	1	Quantity:	EACH
Description:	Curb ramp pan is not level (2.0% in all directions)		
As Built Desc:	5.6% landing slope		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners C,D		

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 165A

Location: Cloverleaf Wy and Bramble Tree Wy - Corner D

X Coordinate: -121.30457

Y Coordinate: 38.71794

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 165B

Location: Cloverleaf Wy and Bramble Tree Wy - Corner D

X Coordinate: -121.30457

Y Coordinate: 38.71794

Barrier Area: Curb Ramps

Barrier Type: Transition into Roadway - Existing (8.3% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 16 Quantity: SF

Description: Transition from gutter into roadway slope exceeds 5.0% (8.3% or more)

As Built Desc: 16.3% transition into roadway at ramp landing

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary

Cost Estimate: \$0.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D

Field Date:	10/1/2010	Report Date:	10/1/2010	Barrier #:	166A
Location:	Cloverleaf Wy - South				
X Coordinate:	-121.30435				
Y Coordinate:	38.71795				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	163	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$20,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/1/2010	Report Date:	10/1/2010	Barrier #:	166B
Location:	Cloverleaf Wy - South				
X Coordinate:	-121.30401				
Y Coordinate:	38.71798				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip in sidewalk surface		
Solution:	Grind or repair to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 167A

Location: Cloverleaf Wy and Willow Tree Wy - Corner C

X Coordinate: -121.30358

Y Coordinate: 38.71794

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - New Construction

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (4.1% to 4.9%)

As Built Desc: 4.9% at 12" grooves - New Construction

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 167B

Location: Cloverleaf Wy and Willow Tree Wy - Corner C

X Coordinate: -121.30358

Y Coordinate: 38.71794

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes (New Const)

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp - New Construction

Solution: Provide compliant truncated domes

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 168

Location: Cloverleaf Wy and Willow Tree Wy - Corner D

X Coordinate: -121.30374

Y Coordinate: 38.71795

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes (New Const)

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp - New Construction

Solution: Provide compliant truncated domes

Bar. Severity: 1 Necessary Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 169

Location: Cloverleaf Wy - South

X Coordinate: -121.30331

Y Coordinate: 38.71797

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 82 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$10,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 170

Location: Cloverleaf Wy - West

X Coordinate: -121.30289

Y Coordinate: 38.71796

Barrier Area: Sidewalks

Barrier Type: Running Slope (New Construction)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 16 Quantity: LF

Description: Running slope exceeds 5.0% where roadway slope does not

As Built Desc: 9.0% running slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$2,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 171

Location: Cloverleaf Wy - North

X Coordinate: -121.30293

Y Coordinate: 38.71625

Barrier Area: Sidewalks

Barrier Type: Elbow in Sidewalk - Cross Slope (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 8 Quantity: LF

Description: Cross slope at elbow exceeds 2.0% (5.0% or more)

As Built Desc: 9.3% cross slope

Solution: Demolish existing and construct new sidewalk without curb ramp

Bar. Severity: 1 Necessary

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 172

Location: Cloverleaf Wy and Willow Tree Wy - Corner A

X Coordinate: -121.30375

Y Coordinate: 38.71624

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes (New Const)

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp - New Construction

Solution: Provide compliant truncated domes

Bar. Severity: 1 Necessary Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 173

Location: Cloverleaf Wy and Willow Tree Wy - Corner B

X Coordinate: -121.30354

Y Coordinate: 38.71624

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes (New Const)

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp - New Construction

Solution: Provide compliant truncated domes

Bar. Severity: 1 Necessary Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 174A

Location: Bramble Tree Wy and Willow Tree Wy - Corner A

X Coordinate: -121.30371

Y Coordinate: 38.71694

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - New Construction

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (>5.0%)

As Built Desc: 5.4% at 12" grooves - New Construction

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 174B

Location: Bramble Tree Wy and Willow Tree Wy - Corner A

X Coordinate: -121.30371

Y Coordinate: 38.71694

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes (New Const)Detecta

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp - New Construction

Solution: Provide compliant truncated domes

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 175

Location: Bramble Tree Wy and Willow Tree Wy - Corner D

X Coordinate: -121.30373

Y Coordinate: 38.71678

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes (New Const)

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp - New Construction

Solution: Provide compliant truncated domes

Bar. Severity: 1 Necessary Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 176

Location: Bramble Tree Wy - North

X Coordinate: -121.30375

Y Coordinate: 38.71688

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 16 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$2,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 177

Location: Bremble Tree Wy - North

X Coordinate: -121.30441

Y Coordinate: 38.71691

Barrier Area: Sidewalks

Barrier Type: Elbow in Sidewalk - Cross Slope (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 6 Quantity: LF

Description: Cross slope at elbow exceeds 2.0% (5.0% or more)

As Built Desc: 9.6% cross slope

Solution: Demolish existing and construct new sidewalk without curb ramp

Bar. Severity: 1 Necessary

Cost Estimate: \$750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 178

Location: Treeleaf Wy - North

X Coordinate: -121.30426

Y Coordinate: 38.71536

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 38 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$4,750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 179

Location: Butternut Dr - North

X Coordinate: -121.30494

Y Coordinate: 38.71516

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 8 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 180

Location: Butternut Dr - North

X Coordinate: -121.30526

Y Coordinate: 38.71555

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 24" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary

Cost Estimate: \$125.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	10/1/2010	Report Date:	10/1/2010	Barrier #:	181
Location:	Butternut Dr - North				
X Coordinate:	-121.30542				
Y Coordinate:	38.71574				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				
As Built Meas:	34	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	7.2% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,250.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					



Field Date:	10/1/2010	Report Date:	10/1/2010	Barrier #:	182
Location:	Butternut Dr - North				
X Coordinate:	-121.30562				
Y Coordinate:	38.71590				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				
As Built Meas:	217	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.2% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$27,125.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					



Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 183A

Location: Lichen Dr - East

X Coordinate: -121.30636

Y Coordinate: 38.71625

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 1147 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$143,375.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 183B

Location: Lichen Dr - East

X Coordinate: -121.30676

Y Coordinate: 38.71600

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 8 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete due to tree heaves

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 184

Location: Treebine Ave - North

X Coordinate: -121.30799

Y Coordinate: 38.71367

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 147 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$18,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 185

Location: Leaoak Ct - West

X Coordinate: -121.30744

Y Coordinate: 38.71370

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 200 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$25,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	10/1/2010	Report Date:	10/1/2010	Barrier #:	186
Location:	Leaoak Ct - East				
X Coordinate:	-121.30740				
Y Coordinate:	38.71417				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	210	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	13.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$26,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/1/2010	Report Date:	10/1/2010	Barrier #:	187
Location:	Treebine Ave - North				
X Coordinate:	-121.30724				
Y Coordinate:	38.71371				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	219	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	7.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$27,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 188

Location: Basswood Wy -West

X Coordinate: -121.30644

Y Coordinate: 38.71370

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 510 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$63,750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:



Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 189

Location: Basswood Wy -North

X Coordinate: -121.30707

Y Coordinate: 38.71503

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 254 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$31,750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:



Field Date:	10/1/2010	Report Date:	10/1/2010	Barrier #:	190
Location:	Basswood Wy -North				
X Coordinate:	-121.30633				
Y Coordinate:	38.71550				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				
As Built Meas:	177	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	6.0% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$22,125.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					



Field Date:	10/1/2010	Report Date:	10/1/2010	Barrier #:	191
Location:	Basswood Wy -South				
X Coordinate:	-121.30586				
Y Coordinate:	38.71569				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				
As Built Meas:	160	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	8.3% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$20,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					



Field Date:	10/1/2010	Report Date:	10/1/2010	Barrier #:	192
Location:	Basswood Wy -South				
X Coordinate:	-121.30640				
Y Coordinate:	38.71532				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	195	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$24,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/1/2010	Report Date:	10/1/2010	Barrier #:	193
Location:	Basswood Wy -East				
X Coordinate:	-121.30689				
Y Coordinate:	38.71495				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	483	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$60,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 194

Location: Treebine Ave - North

X Coordinate: -121.30620

Y Coordinate: 38.71368

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 168 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$21,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 195

Location: Buttonwood Way - West

X Coordinate: -121.30555

Y Coordinate: 38.71375

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 620 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$77,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: Report Date: Barrier #:

Location:

X Coordinate:

Y Coordinate:

Barrier Area:

Barrier Type:

Code Ref:



As Built Meas: Quantity:

Description:

As Built Desc:

Solution:

Bar. Severity: Cost Estimate: Status:

Implementation Priority: Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: Report Date: Barrier #:

Location:

X Coordinate:

Y Coordinate:

Barrier Area:

Barrier Type:

Code Ref:



As Built Meas: Quantity:

Description:

As Built Desc:

Solution:

Bar. Severity: Cost Estimate: Status:

Implementation Priority: Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/1/2010 Report Date: 10/1/2010 Barrier #: 197

Location: Oakmyrtle Wy - North

X Coordinate: -121.30553

Y Coordinate: 38.71312

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 188 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$23,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 198

Location: Treebine Ave - South

X Coordinate: -121.30817

Y Coordinate: 38.71356

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 329 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route


Bar. Severity: 1 Necessary Cost Estimate: \$41,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 199

Location: Treebine Ave - South

X Coordinate: -121.30644

Y Coordinate: 38.71356

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 166 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$20,750.00

Status:

Implementation Priority: 4


Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:



Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 200

Location: Treebine Ave - South

X Coordinate: -121.30623

Y Coordinate: 38.71356

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 158 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$19,750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: GPS 230



Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 201

Location: Buttonwood Way - West


X Coordinate: -121.30559

Y Coordinate: 38.71346

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 360 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$45,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 202

Location: Mimosa Ct - North


X Coordinate: -121.30612

Y Coordinate: 38.71259

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 224 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$28,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	203
Location:	Mimosa Ct - South				
X Coordinate:	-121.30623				
Y Coordinate:	38.71252				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	189	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$23,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	204A
Location:	Buttonwood Way - West				
X Coordinate:	-121.30618				
Y Coordinate:	38.71245				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	341	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$42,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	204B
Location:	Buttonwood Way - West				
X Coordinate:	-121.30626				
Y Coordinate:	38.71237				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip in sidewalk surface		
Solution:	Grind or repair to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	205A
Location:	Treelark Wy - East				
X Coordinate:	-121.30701				
Y Coordinate:	38.71171				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	494	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.8% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$61,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	205B
Location:	Treelark Wy - East				
X Coordinate:	-121.30740				
Y Coordinate:	38.71292				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ($\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	1	Quantity:	LF
Description:	Pedestrian route is not min. 48" wide ($\leq 31"$ or less)		
As Built Desc:	24" clear width due to foliage		
Solution:	Trim foliage to provide min. 48" clear width		
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	206
Location:	Treelark Wy - North				
X Coordinate:	-121.30743				
Y Coordinate:	38.71297				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	246	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$30,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 207

Location: Treelark Wy and Lichen Dr - Corner B

X Coordinate: -121.30828

Y Coordinate: 38.71297

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 208

Location: Treelark Wy and Lichen Dr - Corner C

X Coordinate: -121.30830

Y Coordinate: 38.71283

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C GPS 242

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 209

Location: Lichen Dr - East


X Coordinate: -121.30827

Y Coordinate: 38.71298

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 209 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$26,125.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 210

Location: Lichen Dr - North


X Coordinate: -121.30713

Y Coordinate: 38.71060

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 923 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$115,375.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 211

Location: Treelark Wy - South

X Coordinate: -121.30825

Y Coordinate: 38.71284

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 160 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.0% cross slope

Solution: Demolish existing and construct new route


Bar. Severity: 1 Necessary Cost Estimate: \$20,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 212

Location: Treelark Wy- West

X Coordinate: -121.30752

Y Coordinate: 38.71281

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 171 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$21,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 213

Location: Treelark Wy - North

X Coordinate: -121.30637

Y Coordinate: 38.71128

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 201 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$25,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 214A

Location: Buttonwood Way - East

X Coordinate: -121.30689

Y Coordinate: 38.71166

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 159 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$19,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	214B
Location:	Buttonwood Way - East				
X Coordinate:	-121.30586				
Y Coordinate:	38.71264				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	8	Quantity:	LF
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)		
As Built Desc:	Broken concrete		
Solution:	Repair surface to make firm and stable		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	215A
Location:	Oakmyrtle Wy - South				
X Coordinate:	-121.30560				
Y Coordinate:	38.71299				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing (32" to 35")				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	1	Quantity:	LF
Description:	Pedestrian route is not min. 48" wide (32" to 35")		
As Built Desc:	32" clear width due to foliage		
Solution:	Trim foliage to provide min. 48" clear width		
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 215B

Location: Oakmyrtle Wy - South

X Coordinate: -121.30558

Y Coordinate: 38.71299

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 193 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.4% cross slope

Solution: Demolish existing and construct new route


Bar. Severity: 1 Necessary Cost Estimate: \$24,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 216

Location: Whyte Ave - South

X Coordinate: -121.30991

Y Coordinate: 38.72165

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 76 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.5% cross slope

Solution: Demolish existing and construct new route


Bar. Severity: 1 Necessary Cost Estimate: \$9,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 217A

Location: Pronghorn Ct - West


X Coordinate: -121.30970

Y Coordinate: 38.72150

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 429 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$53,625.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 217B

Location: Pronghorn Ct - West

X Coordinate: -121.31057

Y Coordinate: 38.72069

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 10 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary

Cost Estimate: \$1,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	218
Location:	Pronghorn Ct - East				
X Coordinate:	-121.31051				
Y Coordinate:	38.72057				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	197	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$24,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	219
Location:	Pronghorn Ct and Ibex Woods Ct - Corner B				
X Coordinate:	-121.31003				
Y Coordinate:	38.72093				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	12.4% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			


Notes:	Two - way intersection corners B,C
--------	------------------------------------

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	220
Location:	Pronghorn Ct and Ibex Woods Ct - Corner C				
X Coordinate:	-121.31014				
Y Coordinate:	38.72091				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	10.8% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	221A
Location:	Ibex Woods Ct - South				
X Coordinate:	-121.31010				
Y Coordinate:	38.72091				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	277	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$34,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 221B

Location: Ibex Woods Ct - South

X Coordinate: -121.30956

Y Coordinate: 38.72059

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 222

Location: Ibex Woods Ct - North

X Coordinate: -121.30927

Y Coordinate: 38.72063

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 294 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$36,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 223

Location: Pronghorn Ct - East

X Coordinate: -121.30999

Y Coordinate: 38.72100

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 187 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$23,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 224A

Location: Whyte Ave - South

X Coordinate: -121.30951

Y Coordinate: 38.72142

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 1050 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$131,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 224B

Location: Whyte Ave - South

X Coordinate: -121.30949

Y Coordinate: 38.72144

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3

As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard


Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 225A

Location: Whyte Ave - South

X Coordinate: -121.30592

Y Coordinate: 38.72122

Barrier Area: Sidewalks

Barrier Type: Running Slope (New Construction)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3

As Built Meas: 192 Quantity: LF

Description: Running slope exceeds 5.0% where roadway slope does not

As Built Desc: 6.9% running slope

Solution: Demolish existing and construct new route


Bar. Severity: 1 Necessary Cost Estimate: \$24,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 225B

Location: Whyte Ave - South

X Coordinate: -121.30594

Y Coordinate: 38.72129

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 192 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$24,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 226A

Location: Lichen Dr - West

X Coordinate: -121.30520

Y Coordinate: 38.72128

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 475 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$59,375.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 226B

Location: Lichen Dr - West

X Coordinate: -121.30521

Y Coordinate: 38.72083

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing (32" to 35")

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide (32" to 35")

As Built Desc: 32" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 2 Recommended

Cost Estimate: \$125.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 227

Location: Lichen Dr and Villaview Dr - Corner A

X Coordinate: -121.30549

Y Coordinate: 38.72002

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 15.2% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:


Notes: Two - way intersection corners A,D

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	228
Location:	Lichen Dr and Villaview Dr - Corner D				
X Coordinate:	-121.30547				
Y Coordinate:	38.71980				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	15.0% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,D		

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	229
Location:	Villaview Dr - North				
X Coordinate:	-121.30556				
Y Coordinate:	38.72000				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	177	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$22,125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 230

Location: Villaview Dr - North


X Coordinate: -121.30640

Y Coordinate: 38.72000

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 563 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$70,375.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 231

Location: Castleberry Cir - East


X Coordinate: -121.30836

Y Coordinate: 38.71999

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 188 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$23,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 232A

Location: Castleberry Cir - North


X Coordinate: -121.30829

Y Coordinate: 38.72054

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 550 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$68,750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 232B

Location: Castleberry Cir - North

X Coordinate: -121.30759

Y Coordinate: 38.72058

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair to remove trip hazard

Bar. Severity: 1 Necessary

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 233

Location: Castleberry Cir - West


X Coordinate: -121.30627

Y Coordinate: 38.72051

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 188 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$23,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 234

Location: Castleberry Cir - East


X Coordinate: -121.30626

Y Coordinate: 38.72007

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 252 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$31,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 235

Location: Castleberry Cir - South

X Coordinate: -121.30625

Y Coordinate: 38.72076

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 644 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.8% cross slope

Solution: Demolish existing and construct new route


Bar. Severity: 1 Necessary Cost Estimate: \$80,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 236

Location: Castleberry Cir - West

X Coordinate: -121.30852

Y Coordinate: 38.72065

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 215 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$26,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 237A

Location: Villaview Dr - North

X Coordinate: -121.30865

Y Coordinate: 38.71999

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 483 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$60,375.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 237B

Location: Villaview Dr - North

X Coordinate: -121.30890

Y Coordinate: 38.71998

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 20 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 238A

Location: Villaview Dr - North


X Coordinate: -121.31020

Y Coordinate: 38.71998

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 350 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$43,750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 238B

Location: Villaview Dr - North

X Coordinate: -121.31067

Y Coordinate: 38.71993

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 28" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary

Cost Estimate: \$125.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 239

Location: Villaview Dr - West


X Coordinate: -121.31141

Y Coordinate: 38.71981

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 600 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$75,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 240

Location: Villaview Dr - West


X Coordinate: -121.31286

Y Coordinate: 38.71851

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 181 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$22,625.00 Status:


Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	241
Location:	Butternut Dr - North				
X Coordinate:	-121.31342				
Y Coordinate:	38.71812				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	100	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$12,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	242
Location:	Butternut Dr - North				
X Coordinate:	-121.31319				
Y Coordinate:	38.71794				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing (32" to 35")				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	1	Quantity:	LF
Description:	Pedestrian route is not min. 48" wide (32" to 35")		
As Built Desc:	35" clear width due to foliage		
Solution:	Trim foliage to provide min. 48" clear width		
Bar. Severity:	2 Recommended	Cost Estimate:	\$125.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	243
Location:	Butternut Dr - North				
X Coordinate:	-121.31168				
Y Coordinate:	38.71720				
Barrier Area:	Sidewalks				
Barrier Type:	Protruding Hazard				
Code Ref:	CBC 1133B.8.6.1 and ADA/ABA 307.2				



As Built Meas:	1	Quantity:	JOB
Description:	Protruding object in route of travel between 27" and 80" high		
As Built Desc:	48" protruding hazard at mailbox		
Solution:	Remove object or provide detectable warning		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,400.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	244
Location:	Butternut Dr - North				
X Coordinate:	-121.31152				
Y Coordinate:	38.71718				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	586	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$73,250.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 245

Location: Butternut Dr - North

X Coordinate: -121.30918

Y Coordinate: 38.71742

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 205 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$25,625.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 246

Location: Butternut Dr and Mistletoe Wy - Corner A

X Coordinate: -121.30848

Y Coordinate: 38.71744

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 247

Location: Butternut Dr and Mistletoe Wy - Corner B

X Coordinate: -121.30838

Y Coordinate: 38.71744

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 248A

Location: Butternut Dr - North

X Coordinate: -121.30829

Y Coordinate: 38.71743

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 660 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$82,500.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	248B
Location:	Butternut Dr - North				
X Coordinate:	-121.30812				
Y Coordinate:	38.71743				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip in sidewalk surface		
Solution:	Grind or repair to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	249
Location:	Lichen Dr - West				
X Coordinate:	-121.30623				
Y Coordinate:	38.71654				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	117	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$14,625.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 250

Location: Lichen Dr - West

X Coordinate: -121.30580

Y Coordinate: 38.71686

Barrier Area: Sidewalks

Barrier Type: Driveway - New Construction

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 43 Quantity: LF

Description: Driveway cross/running slope exceeds 2.0%

As Built Desc: 10.4% cross slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 1 Necessary

Cost Estimate: \$5,375.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 251

Location: Lichen Dr - West

X Coordinate: -121.30569

Y Coordinate: 38.71691

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 287 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance

Cost Estimate: \$35,875.00

Status:

Implementation Priority: 2

Facility Function:


Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	252
Location:	Lichen Dr - West				
X Coordinate:	-121.30547				
Y Coordinate:	38.71775				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	29	Quantity:	LF
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	10.0% cross slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	4 Low Severity	Cost Estimate:	\$3,625.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	253
Location:	Lichen Dr - West				
X Coordinate:	-121.30548				
Y Coordinate:	38.71786				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	69	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$8,625.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 254

Location: Lichen Dr - West

X Coordinate: -121.30546

Y Coordinate: 38.71825

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 50 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$6,250.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:



Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 255

Location: Lichen Dr - West

X Coordinate: -121.30547

Y Coordinate: 38.71825

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 29 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 8.0% cross slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 4 Low Severity

Cost Estimate: \$3,625.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:


Implementation Date:

Official Responsible:

Notes:



Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	256
Location:	Lichen Dr - West				
X Coordinate:	-121.30545				
Y Coordinate:	38.71871				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	29	Quantity:	LF
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	7.1% cross slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	4 Low Severity	Cost Estimate:	\$3,625.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	257
Location:	Lichen Dr - West				
X Coordinate:	-121.30546				
Y Coordinate:	38.71889				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ($\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	1	Quantity:	LF
Description:	Pedestrian route is not min. 48" wide ($\leq 31"$ or less)		
As Built Desc:	28" clear width due to foliage		
Solution:	Trim foliage to provide min. 48" clear width		
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 258

Location: Lichen Dr - West


X Coordinate: -121.30549

Y Coordinate: 38.71924

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 201 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$25,125.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 259

Location: Villaview Dr - South

X Coordinate: -121.30548

Y Coordinate: 38.71984

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 168 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$21,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 260

Location: Villaview Dr - South


X Coordinate: -121.30765

Y Coordinate: 38.71989

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 54 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$6,750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/4/2010 Report Date: 10/4/2010 Barrier #: 261

Location: Villaview Dr - South

X Coordinate: -121.30826

Y Coordinate: 38.71988

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 8 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 4

Facility Function:


Implementation Phase:

Implementation Date:

Official Responsible:


Notes:

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	262
Location:	Villaview Dr - South				
X Coordinate:	-121.30892				
Y Coordinate:	38.71986				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	364	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$45,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	263
Location:	Villaview Dr - South				
X Coordinate:	-121.31053				
Y Coordinate:	38.71984				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	774	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	7.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$96,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	264A
Location:	Villaview Dr - South				
X Coordinate:	-121.31274				
Y Coordinate:	38.71839				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	179	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.3% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$22,375.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	10/4/2010	Report Date:	10/4/2010	Barrier #:	264B
Location:	Villaview Dr - South				
X Coordinate:	-121.31317				
Y Coordinate:	38.71808				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ($\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	1	Quantity:	LF	
Description:	Pedestrian route is not min. 48" wide ($\leq 31"$ or less)			
As Built Desc:	28" clear width due to foliage			
Solution:	Trim foliage to provide min. 48" clear width			
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 265

Location: Twining Wy - North

X Coordinate: -121.31240

Y Coordinate: 38.71840

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 167 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route


Bar. Severity: 1 Necessary Cost Estimate: \$20,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 266

Location: Twining Wy and Yardley Wy - Corner A

X Coordinate: -121.31198

Y Coordinate: 38.71814

Barrier Area: Curb Ramps

Barrier Type: Lip - Gutter to Asphalt Transition

Code Ref: CBC 1127B.5.3 and ADA/ABA 303.3

As Built Meas: 1 Quantity: EACH

Description: Transition at transition into asphalt not flush and free of any lip

As Built Desc: 1" lip at asphalt transition into roadway

Solution: Remove lip to create flush transition

Bar. Severity: 1 Necessary Cost Estimate: \$250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B. Corner B compliant



Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 267

Location: Yardley Wy - West

X Coordinate: -121.31193

Y Coordinate: 38.71825

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 722 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$90,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 268

Location: Yardley Wy - East

X Coordinate: -121.31038

Y Coordinate: 38.71974

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 753 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$94,125.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 269

Location: Twinng Wy - North

X Coordinate: -121.31187

Y Coordinate: 38.71800

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 286 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$35,750.00

Status:

Implementation Priority: 4


Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:



Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 270A

Location: Mannerly Wy - West

X Coordinate: -121.31093

Y Coordinate: 38.71790

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 753 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$94,125.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:



Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 270B

Location: Mannerly Wy - West

X Coordinate: -121.30937

Y Coordinate: 38.71916

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing (32" to 35")

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide (32" to 35")

As Built Desc: 34" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 2 Recommended

Cost Estimate: \$125.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 271A

Location: Radford St and Mannerly Wy - Corner D

X Coordinate: -121.30936

Y Coordinate: 38.71909

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - New Construction

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (>5.0%)

As Built Desc: 5.5% at 12" grooves - New Construction

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Three - way intersection corners B,C,D. Corners B,C compliant

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 271B

Location: Radford St and Mannerly Wy - Corner D

X Coordinate: -121.30936

Y Coordinate: 38.71909

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - New Construction

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level (3.1% to 4.0%)

As Built Desc: 3.7% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary

Cost Estimate: \$0.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: New Construction

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 272

Location: Mannerly Wy - North

X Coordinate: -121.30907

Y Coordinate: 38.71923

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 159 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$19,875.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:


Notes:

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	273
Location:	Mistletoe Wy and Mannerly Wy - Corner D				
X Coordinate:	-121.30847				
Y Coordinate:	38.71914				
Barrier Area:	Curb Ramps				
Barrier Type:	Perpendicular Ramp Landing - New Construction				
Code Ref:	CBC 1127B.5.4 and ADA/ABA 406.4				



As Built Meas:	1	Quantity:	EACH
Description:	Curb ramp landing or pan not level (>5.0% or more)		
As Built Desc:	6.2% landing slope		
Solution:	Demolish existing and construct new transition		
Bar. Severity:	1 Necessary	Cost Estimate:	\$250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Three - way intersection corners A,C,D. Corners A,C compliant		

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	274
Location:	Mannerly Wy - North				
X Coordinate:	-121.30841				
Y Coordinate:	38.71921				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	586	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$73,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 275

Location: Mannerly Wy - West

X Coordinate: -121.30635

Y Coordinate: 38.71939

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 168 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$21,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 276

Location: Mannerly Wy - East

X Coordinate: -121.30625

Y Coordinate: 38.71970

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 141 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 4.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$17,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 277

Location: Mannerly Wy - South


X Coordinate: -121.30635

Y Coordinate: 38.71917

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 592 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$74,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 278A

Location: Mistletoe Wy - East


X Coordinate: -121.30831

Y Coordinate: 38.71888

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 469 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$58,625.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 278B

Location: Mistletoe Wy - East

X Coordinate: -121.30833

Y Coordinate: 38.71816

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 24" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary Cost Estimate: \$125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 279

Location: Mistletoe Wy - East

X Coordinate: -121.30831

Y Coordinate: 38.71761

Barrier Area: Sidewalks

Barrier Type: Driveway - New Construction

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 16 Quantity: LF

Description: Driveway cross/running slope exceeds 2.0%

As Built Desc: 8.8% cross slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 1 Necessary Cost Estimate: \$2,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 280

Location: Mistletoe Wy - West

X Coordinate: -121.30842

Y Coordinate: 38.71880

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 27 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$3,375.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 281

Location: Mannerly Wy - South

X Coordinate: -121.30856

Y Coordinate: 38.71911

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 455 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$56,875.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	282A
Location:	Radford St - East				
X Coordinate:	-121.30927				
Y Coordinate:	38.71888				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	482	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	9.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$60,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	282B
Location:	Radford St - East				
X Coordinate:	-121.30927				
Y Coordinate:	38.71867				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	283
Location:	Radford St - West				
X Coordinate:	-121.30941				
Y Coordinate:	38.71750				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	159	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.8% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$19,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	284
Location:	Radford St - West				
X Coordinate:	-121.30937				
Y Coordinate:	38.71823				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	247	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$30,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 285

Location: Mannerly Wy - South

X Coordinate: -121.31052

Y Coordinate: 38.71838

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 189 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$23,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 286

Location: Twining Wy - North

X Coordinate: -121.31056

Y Coordinate: 38.71786

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 321 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$40,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	287A
Location:	Twining Wy - South				
X Coordinate:	-121.30949				
Y Coordinate:	38.71798				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	183	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	7.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$22,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	287B
Location:	Twining Wy - South				
X Coordinate:	-121.30994				
Y Coordinate:	38.71795				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 288

Location: Twining Wy - South

X Coordinate: -121.31142

Y Coordinate: 38.71776

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 74 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$9,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 289

Location: Twining Wy - South

X Coordinate: -121.31235

Y Coordinate: 38.71820

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 107 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$13,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	290
Location:	Butternut Dr - South				
X Coordinate:	-121.31390				
Y Coordinate:	38.71825				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	16	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$2,000.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	291
Location:	Butternut Dr - South				
X Coordinate:	-121.31355				
Y Coordinate:	38.71798				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ($\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	1	Quantity:	LF
Description:	Pedestrian route is not min. 48" wide ($\leq 31"$ or less)		
As Built Desc:	24" clear width due to foliage		
Solution:	Trim foliage to provide min. 48" clear width		
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 292

Location: Butternut Dr - South

X Coordinate: -121.31321

Y Coordinate: 38.71777

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 146 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$18,250.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 293

Location: Butternut Dr - South

X Coordinate: -121.31229

Y Coordinate: 38.71722

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 328 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$41,000.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	294
Location:	Butternut Dr - South				
X Coordinate:	-121.31112				
Y Coordinate:	38.71698				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	182	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.8% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$22,750.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	295
Location:	Butternut Dr and Zenith Dr - Corner C				
X Coordinate:	-121.31025				
Y Coordinate:	38.71704				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH
Description:	No truncated domes provided at curb ramp		
As Built Desc:	No detectable warnings at curb ramp		
Solution:	Provide compliant truncated domes		
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	Two - way intersection corners C,D
--------	------------------------------------

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	296A
Location:	Butternut Dr and Zenith Dr - Corner D				
X Coordinate:	-121.31044				
Y Coordinate:	38.71700				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (>5.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH		
Description:	12" grooves at top of curb ramp are not level (>5.0%)				
As Built Desc:	7.0% at 12" grooves				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Two - way intersection corners C,D				

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	296B
Location:	Butternut Dr and Zenith Dr - Corner D				
X Coordinate:	-121.31044				
Y Coordinate:	38.71700				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Two - way intersection corners C,D				

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 296C

Location: Butternut Dr and Zenith Dr - Corner D

X Coordinate: -121.31044

Y Coordinate: 38.71700

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - New Construction

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0%

As Built Desc: 7.9% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary

Cost Estimate: \$0.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 297

Location: Butternut Dr - South

X Coordinate: -121.31017

Y Coordinate: 38.71712

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 737 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$92,125.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	298A
Location:	Butternut Dr - South				
X Coordinate:	-121.30725				
Y Coordinate:	38.71698				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	335	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	7.3% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$41,875.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	298B
Location:	Butternut Dr - South				
X Coordinate:	-121.30711				
Y Coordinate:	38.71687				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF		
Description:	Change in level greater than 1/2"				
As Built Desc:	1" lip in sidewalk surface				
Solution:	Grind or repair sidewalk to remove trip hazard				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	298C
Location:	Butternut Dr - South				
X Coordinate:	-121.30702				
Y Coordinate:	38.71682				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	299
Location:	Lichen Dr - West				
X Coordinate:	-121.30650				
Y Coordinate:	38.71631				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	132	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$16,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 300

Location: Lichen Dr and Tanoak Wy - Corner A

X Coordinate: -121.30700

Y Coordinate: 38.71602

Barrier Area: Curb Ramps

Barrier Type: Surface Condition

Code Ref: CBC 1127B.5 and ADA/ABA 403.2



As Built Meas: 3 Quantity: SF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$300.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D. Corner D compliant

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 301

Location: Lichen Dr - West

X Coordinate: -121.30711

Y Coordinate: 38.71592

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 193 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$24,125.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 302

Location: Stonecorp Ct - North

X Coordinate: -121.30771

Y Coordinate: 38.71562

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 188 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$23,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 303

Location: Stonecorp Ct - South

X Coordinate: -121.30849

Y Coordinate: 38.71593

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 144 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$18,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	304
Location:	Stonecorp Ct - South				
X Coordinate:	-121.30813				
Y Coordinate:	38.71576				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	129	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$16,125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	305
Location:	Lichen Dr - West				
X Coordinate:	-121.30789				
Y Coordinate:	38.71534				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	126	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$15,750.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 306A

Location: Lichen Dr and Outlook Dr - Corner A

X Coordinate: -121.30816

Y Coordinate: 38.71508

Barrier Area: Curb Ramps

Barrier Type: Lip - Bottom of Ramp at Flow Line

Code Ref: CBC 1127B.5.3 and ADA/ABA 303.3



As Built Meas: 1 Quantity: EACH

Description: Transition at ramp bottom (flow line) is not flush and free of any lip

As Built Desc: 1" lip at flow line

Solution: Remove lip to create flush transition

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 306B

Location: Lichen Dr and Outlook Dr - Corner A

X Coordinate: -121.30816

Y Coordinate: 38.71508

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 306C

Location: Lichen Dr and Outlook Dr - Corner A

X Coordinate: -121.30816

Y Coordinate: 38.71508

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - New Construction

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0%

As Built Desc: 10.8% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary

Cost Estimate: \$0.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 307A

Location: Outlook Dr and Lichen Dr - Corner D

X Coordinate: -121.30823

Y Coordinate: 38.71498

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 307B

Location: Outlook Dr and Lichen Dr - Corner D

X Coordinate: -121.30823

Y Coordinate: 38.71498

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (>5.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (>5.0%)

As Built Desc: 6.1% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary

Cost Estimate: \$0.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 308A

Location: Outlook Dr - North

X Coordinate: -121.30823

Y Coordinate: 38.71508

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 280 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$35,000.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	308B
Location:	Outlook Dr - North				
X Coordinate:	-121.30827				
Y Coordinate:	38.71510				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	N/A				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1/2" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	309
Location:	Outlook Dr and Tanoak Wy - Corner A				
X Coordinate:	-121.30942				
Y Coordinate:	38.71512				
Barrier Area:	Curb Ramps				
Barrier Type:	Gutter Slope - New Construction				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.2				



As Built Meas:	6	Quantity:	SF
Description:	Gutter slope exceeds 5.0%		
As Built Desc:	7.1% gutter slope		
Solution:	Demolish existing and construct new gutter		
Bar. Severity:	1 Necessary	Cost Estimate:	\$750.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B. Corner B compliant		

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 310A

Location: Outlook Dr - North

X Coordinate: -121.30947

Y Coordinate: 38.71510

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 550 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$68,750.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 310B

Location: Outlook Dr - North

X Coordinate: -121.30975

Y Coordinate: 38.71509

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 30" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary

Cost Estimate: \$125.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	311A
Location:	Outlook Dr and Zenith Dr - Corner A				
X Coordinate:	-121.31167				
Y Coordinate:	38.71509				
Barrier Area:	Curb Ramps				
Barrier Type:	Running Slope - Existing (9.5% or more)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.1				



As Built Meas:	1	Quantity:	EACH
Description:	Ramp run cross slope exceeds 2.0% (9.5% or more)		
As Built Desc:	11.5% running slope		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	311B
Location:	Outlook Dr and Zenith Dr - Corner A				
X Coordinate:	-121.31167				
Y Coordinate:	38.71509				
Barrier Area:	Curb Ramps				
Barrier Type:	Parallel Ramp Landing - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1127B.5.4 and ADA/ABA 406.4				



As Built Meas:	1	Quantity:	EACH
Description:	Curb ramp landing or pan not level(4.1% to 4.9%)		
As Built Desc:	4.1% landing slope		
Solution:	Demolish existing and construct new transition		
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 311C

Location: Outlook Dr and Zenith Dr - Corner A

X Coordinate: -121.31167

Y Coordinate: 38.71509

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$0.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 312A

Location: Outlook Dr and Zenith Dr - Corner B

X Coordinate: -121.31144

Y Coordinate: 38.71509

Barrier Area: Curb Ramps

Barrier Type: Running Slope - Existing (9.5% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.1



As Built Meas: 1 Quantity: EACH

Description: Ramp run cross slope exceeds 2.0% (9.5% or more)

As Built Desc: 12.0% running slope

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	312B
Location:	Outlook Dr and Zenith Dr - Corner B				
X Coordinate:	-121.31144				
Y Coordinate:	38.71509				
Barrier Area:	Curb Ramps				
Barrier Type:	Parallel Ramp Landing - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1127B.5.4 and ADA/ABA 406.4				



As Built Meas:	1	Quantity:	EACH
Description:	Curb ramp landing or pan not level(4.1% to 4.9%)		
As Built Desc:	4.7% landing slope		
Solution:	Demolish existing and construct new transition		
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	312C
Location:	Outlook Dr and Zenith Dr - Corner B				
X Coordinate:	-121.31144				
Y Coordinate:	38.71509				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH
Description:	No truncated domes provided at curb ramp		
As Built Desc:	No detectable warnings at curb ramp		
Solution:	Provide compliant truncated domes		
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 313A

Location: Outlook Dr and Zenith Dr - Corner C

X Coordinate: -121.31142

Y Coordinate: 38.71497

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 313B

Location: Outlook Dr and Zenith Dr - Corner C

X Coordinate: -121.31142

Y Coordinate: 38.71497

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (2.1% to 3.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (2.1% to 3.0%)

As Built Desc: 2.3% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 4 Low Severity

Cost Estimate: \$0.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 314

Location: Outlook Dr and Zenith Dr - Corner D

X Coordinate: -121.31165

Y Coordinate: 38.71500

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$1,400.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 315

Location: Outlook Dr - North

X Coordinate: -121.31168

Y Coordinate: 38.71506

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 282 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$35,250.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	316
Location:	Outlook Dr and Yardgate Wy - Corner B				
X Coordinate:	-121.31274				
Y Coordinate:	38.71514				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - New Construction				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (>5.0%)		
As Built Desc:	5.1% at 12" grooves - New Construction		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B. Corner A compliant		

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	317
Location:	Outlook Dr - North				
X Coordinate:	-121.31306				
Y Coordinate:	38.71509				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	474	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	7.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$59,250.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	318
Location:	Outlook Dr - North				
X Coordinate:	-121.31498				
Y Coordinate:	38.71504				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	242	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.0% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$30,250.00	Status:
Implementation Priority:	3	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	319A
Location:	Outlook Dr and Villaview Dr - Corner A				
X Coordinate:	-121.31594				
Y Coordinate:	38.71507				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH	
Description:	12" grooves at top of curb ramp are not level (3.1% to 4.0%)			
As Built Desc:	3.5% at 12" grooves			
Solution:	Demolish existing and construct new curb ramp			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	3	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Four - way intersection corners A,B,C,D			

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 319B

Location: Outlook Dr and Villaview Dr - Corner A

X Coordinate: -121.31594

Y Coordinate: 38.71507

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (8.3% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (8.3% or more)

As Built Desc: 12.8% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 319C

Location: Outlook Dr and Villaview Dr - Corner A

X Coordinate: -121.31594

Y Coordinate: 38.71507

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	320A
Location:	Outlook Dr and Villaview Dr - Corner B				
X Coordinate:	-121.31572				
Y Coordinate:	38.71507				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (4.1% to 4.9%)		
As Built Desc:	4.7% at 12" grooves		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	2 Recommended	Cost Estimate:	\$2,500.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	320B
Location:	Outlook Dr and Villaview Dr - Corner B				
X Coordinate:	-121.31572				
Y Coordinate:	38.71507				
Barrier Area:	Curb Ramps				
Barrier Type:	Gutter Slope - Existing (5.9% - 6.5%)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.2				



As Built Meas:	6	Quantity:	SF
Description:	Gutter slope exceeds 5.0% (5.9% - 6.5%)		
As Built Desc:	6.0% gutter slope		
Solution:	Demolish existing and construct new gutter		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 320C

Location: Outlook Dr and Villaview Dr - Corner B

X Coordinate: -121.31572

Y Coordinate: 38.71507

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 321A

Location: Outlook Dr and Villaview Dr - Corner C

X Coordinate: -121.31579

Y Coordinate: 38.71444

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (>5.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (>5.0%)

As Built Desc: 5.2% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 321B

Location: Outlook Dr and Villaview Dr - Corner C

X Coordinate: -121.31579

Y Coordinate: 38.71444

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 6.9% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended

Cost Estimate: \$0.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 321C

Location: Outlook Dr and Villaview Dr - Corner C

X Coordinate: -121.31579

Y Coordinate: 38.71444

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$0.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date:	10/7/2010	Report Date:	10/7/2010	Barrier #:	322A
Location:	Outlook Dr and Villaview Dr - Corner D				
X Coordinate:	-121.31592				
Y Coordinate:	38.71490				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (2.1% to 3.0%)		
As Built Desc:	2.8% at 12" grooves		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	4 Low Severity	Cost Estimate:	\$2,500.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	10/7/2010	Report Date:	10/7/2010	Barrier #:	322B
Location:	Outlook Dr and Villaview Dr - Corner D				
X Coordinate:	-121.31592				
Y Coordinate:	38.71490				
Barrier Area:	Curb Ramps				
Barrier Type:	Transition into Roadway - Existing (6.6% to 8.2%)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.2				



As Built Meas:	16	Quantity:	SF
Description:	Transition from gutter into roadway slope exceeds 5.0% (6.6% to 8.2%)		
As Built Desc:	7.4% transition into roadway at ramp landing		
Solution:	Demolish existing and construct new transition		
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	10/7/2010	Report Date:	10/7/2010	Barrier #:	322C
Location:	Outlook Dr and Villaview Dr - Corner D				
X Coordinate:	-121.31592				
Y Coordinate:	38.71490				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH
Description:	No truncated domes provided at curb ramp		
As Built Desc:	No detectable warnings at curb ramp		
Solution:	Provide compliant truncated domes		
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	10/5/2010	Report Date:	10/5/2010	Barrier #:	323
Location:	Outlook Dr - North				
X Coordinate:	-121.31601				
Y Coordinate:	38.71507				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	136	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$17,000.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 324A

Location: Outlook Dr and Adagio Wy - Corner A

X Coordinate: -121.31707

Y Coordinate: 38.71513

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.9% - 6.5%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.9% - 6.5%)

As Built Desc: 6.2% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 3 Hindrance Cost Estimate: \$750.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 324B

Location: Outlook Dr and Adagio Wy - Corner A

X Coordinate: -121.31707

Y Coordinate: 38.71513

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 325A

Location: Outlook Dr and Adagio Wy - Corner B

X Coordinate: -121.31690

Y Coordinate: 38.71510

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.8% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 325B

Location: Outlook Dr and Adagio Wy - Corner B

X Coordinate: -121.31690

Y Coordinate: 38.71510

Barrier Area: Curb Ramps

Barrier Type: Running Slope - Existing (9.5% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.1



As Built Meas: 1 Quantity: EACH

Description: Ramp run cross slope exceeds 2.0% (9.5% or more)

As Built Desc: 9.9% running slope

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 325C

Location: Outlook Dr and Adagio Wy - Corner B

X Coordinate: -121.31690

Y Coordinate: 38.71510

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$0.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: 10/5/2010 Report Date: 10/5/2010 Barrier #: 325D

Location: Outlook Dr and Adagio Wy - Corner B

X Coordinate: -121.31690

Y Coordinate: 38.71510

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (4.1% to 4.9%)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level(4.1% to 4.9%)

As Built Desc: 4.7% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 2 Recommended

Cost Estimate: \$0.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 326

Location: Villaview Dr - West


X Coordinate: -121.31542

Y Coordinate: 38.71608

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 626 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$78,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 327

Location: Villaview Dr - West

X Coordinate: -121.31471

Y Coordinate: 38.71677

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 328A

Location: Villaview Dr - West

X Coordinate: -121.31309

Y Coordinate: 38.71819

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 167 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$20,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 328B

Location: Villaview Dr - West

X Coordinate: -121.31084

Y Coordinate: 38.71989

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3

As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 329

Location: Villaview Dr - East

X Coordinate: -121.31130

Y Coordinate: 38.71966

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 105 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$13,125.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 330

Location: Villaview Dr - East


X Coordinate: -121.31542

Y Coordinate: 38.71580

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 429 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$53,625.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: Report Date: Barrier #:

Location:

X Coordinate:

Y Coordinate:

Barrier Area:

Barrier Type:

Code Ref:



As Built Meas: Quantity:

Description:

As Built Desc:

Solution:

Bar. Severity: Cost Estimate: Status:

Implementation Priority: Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: Report Date: Barrier #:

Location:

X Coordinate:

Y Coordinate:

Barrier Area:

Barrier Type:

Code Ref:



As Built Meas: Quantity:

Description:

As Built Desc:

Solution:

Bar. Severity: Cost Estimate: Status:

Implementation Priority: Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:


Notes:

Field Date:	10/7/2010	Report Date:	10/7/2010	Barrier #:	333
Location:	Woodyard Wy - East				
X Coordinate:	-121.31274				
Y Coordinate:	38.71719				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	12	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.9% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$1,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	10/7/2010	Report Date:	10/7/2010	Barrier #:	334A
Location:	Woodyard Wy - East				
X Coordinate:	-121.31406				
Y Coordinate:	38.71610				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	97	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.2% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$12,125.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	10/7/2010	Report Date:	10/7/2010	Barrier #:	334B
Location:	Woodyard Wy - East				
X Coordinate:	-121.31431				
Y Coordinate:	38.71590				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ($\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	1	Quantity:	LF
Description:	Pedestrian route is not min. 48" wide ($\leq 31"$ or less)		
As Built Desc:	28" clear width due to foliage		
Solution:	Trim foliage to provide min. 48" clear width		
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/7/2010	Report Date:	10/7/2010	Barrier #:	335
Location:	Woodyard Wy and Viscount Wy - Corner B				
X Coordinate:	-121.31431				
Y Coordinate:	38.71584				
Barrier Area:	Curb Ramps				
Barrier Type:	Clear Width				
Code Ref:	CBC 1127B.5.2				



As Built Meas:	1	Quantity:	EACH
Description:	Curb ramp not at least 48" wide		
As Built Desc:	31" clear width due to foliage		
Solution:	Trim foliage to provide min. 48" clear width		
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C. Corner C compliant		

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 336

Location: Viscount Wy - North

X Coordinate: -121.31428

Y Coordinate: 38.71581

Barrier Area: Sidewalks

Barrier Type: Running Slope (New Construction)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 4 Quantity: LF

Description: Running slope exceeds 5.0% where roadway slope does not

As Built Desc: 6.4% running slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 337A

Location: Viscount Wy - North


X Coordinate: -121.31428

Y Coordinate: 38.71585

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 840 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$105,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 337B

Location: Viscount Wy - North

X Coordinate: -121.31242

Y Coordinate: 38.71660

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 31" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary

Cost Estimate: \$125.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 338

Location: Viscount Wy and Yardgate Wy - Corner A

X Coordinate: -121.31190

Y Coordinate: 38.71645

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (2.1% to 3.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (2.1% to 3.0%)

As Built Desc: 2.8% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 4 Low Severity

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Three - way intersection corners A,C,D

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 339

Location: Viscount Wy and Yardgate Wy - Corner C

X Coordinate: -121.31168

Y Coordinate: 38.71639

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - New Construction

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (2.1% to 3.0%)

As Built Desc: 2.6% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection corners A,C,D

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 340

Location: Viscount Wy and Yardgate Wy - Corner D

X Coordinate: -121.31187

Y Coordinate: 38.71640

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - New Construction

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.2% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:


Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection corners A,C,D

Field Date:	10/7/2010	Report Date:	10/7/2010	Barrier #:	341A
Location:	Viscount Wy - North				
X Coordinate:	-121.31183				
Y Coordinate:	38.71648				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	338	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	8.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$42,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/7/2010	Report Date:	10/7/2010	Barrier #:	341B
Location:	Viscount Wy - North				
X Coordinate:	-121.31174				
Y Coordinate:	38.71646				
Barrier Area:	Sidewalks				
Barrier Type:	Protruding Hazard				
Code Ref:	CBC 1133B.8.6.1 and ADA/ABA 307.2				



As Built Meas:	1	Quantity:	JOB
Description:	Protruding object in route of travel between 27" and 80" high		
As Built Desc:	60" protruding hazard at tree branches		
Solution:	Remove object or provide detectable warning		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,400.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 341C

Location: Viscount Wy - North

X Coordinate: -121.31151

Y Coordinate: 38.71645

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 342A

Location: Zenith Dr - West

X Coordinate: -121.31059

Y Coordinate: 38.71625

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 290 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$36,250.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 342B

Location: Zenith Dr - West

X Coordinate: -121.31036

Y Coordinate: 38.71675

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 8 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 343

Location: Zenith Dr - East


X Coordinate: -121.31028

Y Coordinate: 38.71705

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 355 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$44,375.00 Status:


Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:


Official Responsible:

Notes:

Field Date:	10/7/2010	Report Date:	10/7/2010	Barrier #:	344
Location:	Starling Ct - North				
X Coordinate:	-121.31048				
Y Coordinate:	38.71608				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				
As Built Meas:	185	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	8.6% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$23,125.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					



Field Date:	10/7/2010	Report Date:	10/7/2010	Barrier #:	345
Location:	Starling Ct - South				
X Coordinate:	-121.31020				
Y Coordinate:	38.71570				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				
As Built Meas:	200	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.3% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$25,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					



Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 346A

Location: Zenith Dr - East


X Coordinate: -121.31071

Y Coordinate: 38.71598

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 406 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 8.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$50,750.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 346B

Location: Zenith Dr - East

X Coordinate: -121.31086

Y Coordinate: 38.71588

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 4 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary

Cost Estimate: \$500.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 347A

Location: Tanoak Wy - West


X Coordinate: -121.30936

Y Coordinate: 38.71519

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 556 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$69,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 347B

Location: Tanoak Wy - West

X Coordinate: -121.30936

Y Coordinate: 38.71523

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 348

Location: Tanoak Wy - North


X Coordinate: -121.30928

Y Coordinate: 38.71671

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 750 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$93,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 349A

Location: Tanoak Wy - South

X Coordinate: -121.30713

Y Coordinate: 38.71600

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 665 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$83,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	10/7/2010	Report Date:	10/7/2010	Barrier #:	349B
Location:	Tanoak Wy - South				
X Coordinate:	-121.30881				
Y Coordinate:	38.71660				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF	
Description:	Change in level greater than 1/2"			
As Built Desc:	1/2" lip in sidewalk surface			
Solution:	Grind or repair sidewalk to remove trip hazard			
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	10/7/2010	Report Date:	10/7/2010	Barrier #:	350
Location:	Tanoak Wy - East				
X Coordinate:	-121.30921				
Y Coordinate:	38.71644				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	456	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.2% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$57,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 351

Location: Zenith Dr - West

X Coordinate: -121.31161

Y Coordinate: 38.71529

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 454 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$56,750.00

Status:

Implementation Priority: 3


Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:



Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 352

Location: Viscount Wy - South

X Coordinate: -121.31082

Y Coordinate: 38.71619

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 248 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$31,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:



Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 353A

Location: Yardgate Wy - East


X Coordinate: -121.31170

Y Coordinate: 38.71637

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 522 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$65,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 353B

Location: Yardgate Wy - East


X Coordinate: -121.31265

Y Coordinate: 38.71528

Barrier Area: Sidewalks

Barrier Type: Protruding Hazard

Code Ref: CBC 1133B.8.6.1 and ADA/ABA 307.2



As Built Meas: 1 Quantity: JOB

Description: Protruding object in route of travel between 27" and 80" high

As Built Desc: 60" protruding hazard at tree branches

Solution: Remove object or provide detectable warning

Bar. Severity: 1 Necessary Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 354

Location: Yardgate Wy - West

X Coordinate: -121.31285

Y Coordinate: 38.71515

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 532 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$66,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 355

Location: Yardgate Wy - West

X Coordinate: -121.31185

Y Coordinate: 38.71635

Barrier Area: Sidewalks

Barrier Type: Running Slope (New Construction)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3

As Built Meas: 4 Quantity: LF

Description: Running slope exceeds 5.0% where roadway slope does not

As Built Desc: 6.9% running slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 4 Facility Function:


Implementation Phase: Implementation Date:

Official Responsible:

Notes:




Field Date:	10/7/2010	Report Date:	10/7/2010	Barrier #:	356
Location:	Viscount Wy - East				
X Coordinate:	-121.31192				
Y Coordinate:	38.71643				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	166	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.8% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$20,750.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	10/7/2010	Report Date:	10/7/2010	Barrier #:	357
Location:	Viscount Wy - South				
X Coordinate:	-121.31245				
Y Coordinate:	38.71657				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	672	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	6.1% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$84,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 358

Location: Woodyard Wy - East

X Coordinate: -121.31440

Y Coordinate: 38.71580

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 278 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$34,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 359

Location: Outlook Dr - South


X Coordinate: -121.31663

Y Coordinate: 38.71490

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 135 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$16,875.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 360

Location: Villaview Dr - West

X Coordinate: -121.31590

Y Coordinate: 38.71488

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 190 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.7% cross slope

Solution: Demolish existing and construct new route


Bar. Severity: 1 Necessary Cost Estimate: \$23,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 361A

Location: Outlook Dr - South

X Coordinate: -121.31576

Y Coordinate: 38.71497

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 1155 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 11.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$144,375.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date:	10/7/2010	Report Date:	10/7/2010	Barrier #:	361B
Location:	Outlook Dr - South				
X Coordinate:	-121.31193				
Y Coordinate:	38.71500				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1/2" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/7/2010	Report Date:	10/7/2010	Barrier #:	362
Location:	Zenith Dr - West				
X Coordinate:	-121.31162				
Y Coordinate:	38.71496				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	203	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$25,375.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/7/2010	Report Date:	10/7/2010	Barrier #:	363
Location:	Zenith Dr - East				
X Coordinate:	-121.31140				
Y Coordinate:	38.71439				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				
As Built Meas:	216	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	6.7% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$27,000.00	Status:	
Implementation Priority:	3	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					



Field Date:	10/7/2010	Report Date:	10/7/2010	Barrier #:	364A
Location:	Outlook Dr- South				
X Coordinate:	-121.31135				
Y Coordinate:	38.71500				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				
As Built Meas:	891	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	6.5% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$111,375.00	Status:	
Implementation Priority:	3	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					



Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 364B

Location: Outlook Dr- South

X Coordinate: -121.31042

Y Coordinate: 38.71501

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 28" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary

Cost Estimate: \$125.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 365A

Location: Lichen Dr - West


X Coordinate: -121.30826

Y Coordinate: 38.71499

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 1188 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$148,500.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 365B

Location: Lichen Dr - West

X Coordinate: -121.30843

Y Coordinate: 38.71342

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 365C

Location: Lichen Dr - West


X Coordinate: -121.30845

Y Coordinate: 38.71254

Barrier Area: Sidewalks

Barrier Type: Protruding Hazard

Code Ref: CBC 1133B.8.6.1 and ADA/ABA 307.2



As Built Meas: 1 Quantity: JOB

Description: Protruding object in route of travel between 27" and 80" high

As Built Desc: 27" protruding hazard at tree branches

Solution: Remove object or provide detectable warning

Bar. Severity: 1 Necessary

Cost Estimate: \$1,400.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 366

Location: Carmelwood Dr - North

X Coordinate: -121.31115

Y Coordinate: 38.71174

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 773 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$96,625.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 367

Location: Zenith Dr - East


X Coordinate: -121.31112

Y Coordinate: 38.71229

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 205 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$25,625.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	368
Location:	Zenith Dr and Briartree Wy - Corner B				
X Coordinate:	-121.31104				
Y Coordinate:	38.71240				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	13.9% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	10/7/2010	Report Date:	10/7/2010	Barrier #:	369
Location:	Zenith Dr and Briartree Wy - Corner C				
X Coordinate:	-121.31112				
Y Coordinate:	38.71229				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	11.4% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 370A

Location: Briartree Wy - South


X Coordinate: -121.31113

Y Coordinate: 38.71233

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 550 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$68,750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 370B

Location: Briartree Wy - South

X Coordinate: -121.31000

Y Coordinate: 38.71230

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 371

Location: Briartree Wy - East


X Coordinate: -121.30926

Y Coordinate: 38.71241

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 744 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$93,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 372A

Location: Briartree Wy - North


X Coordinate: -121.30937

Y Coordinate: 38.71438

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 591 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$73,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 372B

Location: Briartree Wy - North


X Coordinate: -121.30949

Y Coordinate: 38.71435

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 8 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/7/2010 Report Date: 10/7/2010 Barrier #: 373

Location: Briartree Wy and Zenith Dr - Corner B

X Coordinate: -121.31132

Y Coordinate: 38.71435

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 10.1% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D. Corners A,D compliant

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	374
Location:	Briartree Wy and Zenith Dr - Corner C				
X Coordinate:	-121.31134				
Y Coordinate:	38.71424				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	12.8% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D. Corners A,D compliant		

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	375
Location:	Briartree Wy - South				
X Coordinate:	-121.31115				
Y Coordinate:	38.71426				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	280	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$35,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 376A

Location: Briartree Wy - South

X Coordinate: -121.31013

Y Coordinate: 38.71425

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 203 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$25,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 376B

Location: Briartree Wy - South

X Coordinate: -121.30946

Y Coordinate: 38.71429

Barrier Area: Sidewalks

Barrier Type: Running Slope (Existing)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 20 Quantity: LF

Description: Running slope exceeds 5.0%

As Built Desc: 8.6% running slope

Solution: No remediation where sidewalk sloped as roadway

Bar. Severity: 5 Technically Infeasible Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 377

Location: Briartree Wy - South

X Coordinate: -121.30946

Y Coordinate: 38.71428

Barrier Area: Sidewalks

Barrier Type: Elbow in Sidewalk - Cross Slope (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 6 Quantity: LF

Description: Cross slope at elbow exceeds 2.0% (5.0% or more)

As Built Desc: 15.8% cross slope

Solution: Demolish existing and construct new sidewalk without curb ramp

Bar. Severity: 1 Necessary

Cost Estimate: \$750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 378

Location: Briartree Wy - West

X Coordinate: -121.30931

Y Coordinate: 38.71407

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 134 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$16,750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 379

Location: Briartree Wy and Ratten Wy - Corner D

X Coordinate: -121.30941

Y Coordinate: 38.71354

Barrier Area: Curb Ramps

Barrier Type: Water Accumulation - New Construction

Code Ref: CBC 1133B.5.8 and ADA/ABA 405.10



As Built Meas: 1 Quantity: EACH

Description: Water does not drain off of curb ramp

As Built Desc: Standing water - New Construction

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D. Corner A compliant

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 380A

Location: Ratten Wy - North

X Coordinate: -121.30937

Y Coordinate: 38.71363

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 150 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$18,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 380B

Location: Ratten Wy - North

X Coordinate: -121.31013

Y Coordinate: 38.71365

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 4 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 381

Location: Ratten Wy - West

X Coordinate: -121.31022

Y Coordinate: 38.71346

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 383 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$47,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 382

Location: Ratten Wy - East

X Coordinate: -121.31015

Y Coordinate: 38.71260

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 333 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$41,625.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 383

Location: Ratten Wy - South

X Coordinate: -121.30996

Y Coordinate: 38.71356

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 142 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$17,750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	384
Location:	Briartree Wy - West				
X Coordinate:	-121.30939				
Y Coordinate:	38.71356				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				




As Built Meas:	383	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$47,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	385
Location:	Briartree Wy - West				
X Coordinate:	-121.30936				
Y Coordinate:	38.71240				
Barrier Area:	Sidewalks				
Barrier Type:	Elbow in Sidewalk - Cross Slope (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	8	Quantity:	LF
Description:	Cross slope at elbow exceeds 2.0% (5.0% or more)		
As Built Desc:	12.0% cross slope		
Solution:	Demolish existing and construct new sidewalk without curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	386A
Location:	Briartree Wy - North				
X Coordinate:	-121.30936				
Y Coordinate:	38.71240				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	166	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	6.3% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$20,750.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	386B
Location:	Briartree Wy - North				
X Coordinate:	-121.30965				
Y Coordinate:	38.71234				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	4	Quantity:	LF	
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)			
As Built Desc:	Cracked concrete			
Solution:	Repair surface to make firm and stable			
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 387A

Location: Briartree Wy - North

X Coordinate: -121.30969

Y Coordinate: 38.71234

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 220 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$27,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 387B

Location: Briartree Wy - North

X Coordinate: -121.31033

Y Coordinate: 38.71234

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing (36" to 43")

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide (36" to 43")

As Built Desc: 36" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 3 Hindrance Cost Estimate: \$125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 388A

Location: Zenith Dr - East

X Coordinate: -121.31113

Y Coordinate: 38.71238

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 622 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$77,750.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 388B

Location: Zenith Dr - East

X Coordinate: -121.31118

Y Coordinate: 38.71386

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 24" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary

Cost Estimate: \$125.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 389

Location: Briartree Wy - South

X Coordinate: -121.31319

Y Coordinate: 38.71419

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 177 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$22,125.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 390

Location: Briartree Wy - South

X Coordinate: -121.31319

Y Coordinate: 38.71419

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 182 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$22,750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	391
Location:	Briartree Wy - South				
X Coordinate:	-121.31319				
Y Coordinate:	38.71419				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	186	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.5% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$23,250.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	392
Location:	Briartree Wy - South				
X Coordinate:	-121.31412				
Y Coordinate:	38.71418				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	220	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.3% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$27,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 393A

Location: Summerplace Dr - East

X Coordinate: -121.31468

Y Coordinate: 38.71362

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 582 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$72,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: GPS 025

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 393B

Location: Summerplace Dr - East

X Coordinate: -121.31432

Y Coordinate: 38.71279

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 12 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$1,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: GPS 026

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 394

Location: Summerplace Dr and Ravencrest Wy - Corner B

X Coordinate: -121.31397

Y Coordinate: 38.71207

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Exsiting Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 9.9% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 395

Location: Summerplace Dr and Ravencrest Wy - Corner C

X Coordinate: -121.31374

Y Coordinate: 38.71200

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Exsiting Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 11.9% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 396A

Location: Ravenscrest Wy - North

X Coordinate: -121.31388

Y Coordinate: 38.71209

Barrier Area: Sidewalks

Barrier Type: Running Slope (Existing)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 14 Quantity: LF

Description: Running slope exceeds 5.0%

As Built Desc: 9.2% running slope

Solution: No remediation where sidewalk sloped as roadway

Bar. Severity: 5 Technically Infeasible Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 396B

Location: Ravenscrest Wy - North

X Coordinate: -121.31388

Y Coordinate: 38.71209

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 198 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$24,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 397

Location: Ravenscrest Wy - West

X Coordinate: -121.31327

Y Coordinate: 38.71228

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 712 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$89,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 398

Location: Ravenscrest Wy - East

X Coordinate: -121.31393

Y Coordinate: 38.71417

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 730 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$91,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 399

Location: Ravenscrest Wy - South

X Coordinate: -121.31326

Y Coordinate: 38.71212

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 187 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$23,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 400

Location: Summerplace Dr - East

X Coordinate: -121.31374

Y Coordinate: 38.71200

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 186 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$23,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 401

Location: Carmelwood Dr - North

X Coordinate: -121.31336

Y Coordinate: 38.71148

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 306 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$38,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 402

Location: Cornerstone Wy - West

X Coordinate: -121.31230

Y Coordinate: 38.71173

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 950 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$118,750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 403A

Location: Cornerstone Wy - East

X Coordinate: -121.31226

Y Coordinate: 38.71173

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 266 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$33,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 403B

Location: Cornerstone Wy - East

X Coordinate: -121.31280

Y Coordinate: 38.71368

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 404

Location: Bitter Bush Wy - North

X Coordinate: -121.31265

Y Coordinate: 38.71342

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 383 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$47,875.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 405

Location: Bitter Bush Wy - South

X Coordinate: -121.31150

Y Coordinate: 38.71357

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 324 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$40,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 406

Location: Cornerstone Wy - East

X Coordinate: -121.31263

Y Coordinate: 38.71328

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 182 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$22,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 407

Location: Grey Oak Ct - North

X Coordinate: -121.31264

Y Coordinate: 38.71330

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 122 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$15,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	408
Location:	Grey Oak Ct - South				
X Coordinate:	-121.31203				
Y Coordinate:	38.71275				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	69	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$8,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	409
Location:	Cornerstone Wy - East				
X Coordinate:	-121.31231				
Y Coordinate:	38.71272				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	353	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$44,125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 410

Location: Carmelwood Dr - North

X Coordinate: -121.31193

Y Coordinate: 38.71168

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 140 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$17,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 411

Location: Zenith Dr - West

X Coordinate: -121.31136

Y Coordinate: 38.71183

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 659 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$82,375.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 412

Location: Zenith Dr - West

X Coordinate: -121.31131

Y Coordinate: 38.71378

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 171 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$21,375.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 413A

Location: Briartree Wy - North

X Coordinate: -121.31188

Y Coordinate: 38.71432

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 1041 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$130,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	413B
Location:	Briartree Wy - North				
X Coordinate:	-121.31311				
Y Coordinate:	38.71432				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - Tree Heaves				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	12	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip due to tree heaves		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$3,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	414
Location:	Summerplace Dr and Villaview Dr - Corner A				
X Coordinate:	-121.31596				
Y Coordinate:	38.71434				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	16.4% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 415

Location: Summerplace Dr and Villaview Dr - Corner B

X Coordinate: -121.31576

Y Coordinate: 38.71431

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Exsiting Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 9.2% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 416

Location: Summerplace Dr and Paco Ct - Corner A

X Coordinate: -121.31677

Y Coordinate: 38.71410

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Exsiting Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 12.8% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	417
Location:	Summerplace Dr and Paco Ct - Corner D				
X Coordinate:	-121.31696				
Y Coordinate:	38.71402				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	13.7% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,D		

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	418
Location:	Paco Ct - North				
X Coordinate:	-121.31677				
Y Coordinate:	38.71410				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	315	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$39,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	419A
Location:	Paco Ct - South				
X Coordinate:	-121.31762				
Y Coordinate:	38.71414				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	223	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$27,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	419B
Location:	Paco Ct - South				
X Coordinate:	-121.31762				
Y Coordinate:	38.71413				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ($\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	1	Quantity:	LF
Description:	Pedestrian route is not min. 48" wide ($\leq 31"$ or less)		
As Built Desc:	30" clear width due to foliage		
Solution:	Trim foliage to provide min. 48" clear width		
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 420

Location: Summerplace Dr - West

X Coordinate: -121.31694

Y Coordinate: 38.71400

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 180 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$22,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 421

Location: Summerplace Dr and Gobi Ct - Corner A

X Coordinate: -121.31721

Y Coordinate: 38.71350

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 13.2% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	422
Location:	Summerplace Dr and Gobi Ct - Corner B				
X Coordinate:	-121.31700				
Y Coordinate:	38.71349				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	13.1% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	423
Location:	Summerplace Dr and Gobi Ct - Corner C				
X Coordinate:	-121.31702				
Y Coordinate:	38.71339				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	10.1% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 424

Location: Summerplace Dr and Gobi Ct - Corner D

X Coordinate: -121.31726

Y Coordinate: 38.71338

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Exsiting Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 12.5% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 425

Location: Gobi Ct - North

X Coordinate: -121.31721

Y Coordinate: 38.71349

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 184 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$23,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	426
Location:	Gobi Ct - South				
X Coordinate:	-121.31776				
Y Coordinate:	38.71341				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	163	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$20,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	427
Location:	Summerplace Dr - West				
X Coordinate:	-121.31725				
Y Coordinate:	38.71335				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	193	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$24,125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	428
Location:	Summerplace Dr and Beta Ct - Corner A				
X Coordinate:	-121.31721				
Y Coordinate:	38.71275				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	13.3% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,D		

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	431
Location:	Summerplace Dr and Beta Ct - Corner D				
X Coordinate:	-121.31727				
Y Coordinate:	38.71263				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	13.9% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,D		

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	429
Location:	Beta Ct - North				
X Coordinate:	-121.31722				
Y Coordinate:	38.71273				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	183	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$22,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	430
Location:	Beta Ct - South				
X Coordinate:	-121.31723				
Y Coordinate:	38.71261				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	144	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.9% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$18,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	432
Location:	Summerplace Dr - West				
X Coordinate:	-121.31689				
Y Coordinate:	38.71187				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	175	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$21,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	433A
Location:	Summerplace Dr - West				
X Coordinate:	-121.31662				
Y Coordinate:	38.71132				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	576	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$72,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 433B

Location: Summerplace Dr - West

X Coordinate: -121.31624

Y Coordinate: 38.71030

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/13/2010 Barrier #: 434

Location: Summerplace Dr and Carmelwood Dr - Corner A

X Coordinate: -121.31647

Y Coordinate: 38.71029

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection corners A,B,C

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	435
Location:	Summerplace Dr and Carmelwood Dr - Corner B				
X Coordinate:	-121.31630				
Y Coordinate:	38.71032				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - New Construction				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (3.1% to 4.0%)		
As Built Desc:	3.9% at 12" grooves		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Three - way intersection corners A,B,C		

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	436
Location:	Summerplace Dr and Carmelwood Dr - Corner C				
X Coordinate:	-121.31348				
Y Coordinate:	38.71123				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - New Construction				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (>5.0%)		
As Built Desc:	5.5% at 12" grooves - New Construction		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Three - way intersection corners A,B,C		

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 437

Location: Carmelwood Dr - North

X Coordinate: -121.31519

Y Coordinate: 38.71058

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 311 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$38,875.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 438A

Location: Peppertree Wy - West

X Coordinate: -121.31545

Y Coordinate: 38.71091

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 1060 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$132,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 438B

Location: Peppertree Wy - West

X Coordinate: -121.31581

Y Coordinate: 38.71171

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 438C

Location: Peppertree Wy - West

X Coordinate: -121.31619

Y Coordinate: 38.71246

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	439
Location:	Ramblewood Wy and Peppertree Wy - Corner C				
X Coordinate:	-121.31631				
Y Coordinate:	38.71336				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	12.3% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners C,D		

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	440
Location:	Ramblewood Wy and Peppertree Wy - Corner D				
X Coordinate:	-121.31647				
Y Coordinate:	38.71330				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	10.9% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners C,D		

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 441A

Location: Peppertree Wy - East

X Coordinate: -121.31631

Y Coordinate: 38.71336

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 1020 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$127,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 441B

Location: Peppertree Wy - East

X Coordinate: -121.31625

Y Coordinate: 38.71309

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - Tree Heaves

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip due to tree heaves

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	442
Location:	Carmelwood Dr - West				
X Coordinate:	-121.31475				
Y Coordinate:	38.71077				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ($\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	1	Quantity:	LF
Description:	Pedestrian route is not min. 48" wide ($\leq 31"$ or less)		
As Built Desc:	26" clear width due to foliage		
Solution:	Trim foliage to provide min. 48" clear width		
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	443
Location:	Carmelwood Dr and Ramblewood Wy - Corner A				
X Coordinate:	-121.31446				
Y Coordinate:	38.71095				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - New Construction				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level ($>5.0\%$)		
As Built Desc:	5.5% at 12" grooves - New Construction		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	Two - way intersection corners A,B. Corner B compliant
--------	--

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	444
Location:	Carmelwood Dr - West				
X Coordinate:	-121.31428				
Y Coordinate:	38.71101				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	200	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$25,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	445A
Location:	Summerplace Dr - South				
X Coordinate:	-121.31370				
Y Coordinate:	38.71141				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	986	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$123,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 445B

Location: Summerplace Dr - South

X Coordinate: -121.31476

Y Coordinate: 38.71342

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 446

Location: Summerplace Dr - South

X Coordinate: -121.31510

Y Coordinate: 38.71399

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 517 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$64,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 447

Location: Summerplace Dr - East

X Coordinate: -121.31681

Y Coordinate: 38.71390

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 168 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$21,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 448

Location: Ramblewood Wy - North

X Coordinate: -121.31700

Y Coordinate: 38.71348

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 163 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$20,375.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 449

Location: Ramblewood Wy - North

X Coordinate: -121.31643

Y Coordinate: 38.71344

Barrier Area: Sidewalks

Barrier Type: Elbow in Sidewalk - Cross Slope (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 10 Quantity: LF

Description: Cross slope at elbow exceeds 2.0% (5.0% or more)

As Built Desc: 11.8% cross slope

Solution: Demolish existing and construct new sidewalk without curb ramp

Bar. Severity: 1 Necessary

Cost Estimate: \$1,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 450

Location: Ramblewood Wy - North

X Coordinate: -121.31640

Y Coordinate: 38.71342

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 189 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$23,625.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 451A

Location: Ramblewood Wy - East

X Coordinate: -121.31556

Y Coordinate: 38.71345

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 955 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$119,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 10/8/2010 Report Date: 10/8/2010 Barrier #: 451B

Location: Ramblewood Wy - East

X Coordinate: -121.31556

Y Coordinate: 38.71345

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing (32" to 35")

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide (32" to 35")

As Built Desc: 34" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 2 Recommended Cost Estimate: \$125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	452
Location:	Ramblewood Wy - West				
X Coordinate:	-121.31446				
Y Coordinate:	38.71095				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	971	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.9% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$121,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	453
Location:	Ramblewood Wy - West				
X Coordinate:	-121.31570				
Y Coordinate:	38.71345				
Barrier Area:	Sidewalks				
Barrier Type:	Elbow in Sidewalk - Cross Slope (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	10	Quantity:	LF
Description:	Cross slope at elbow exceeds 2.0% (5.0% or more)		
As Built Desc:	13.1% cross slope		
Solution:	Demolish existing and construct new sidewalk without curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	10/8/2010	Report Date:	10/8/2010	Barrier #:	454
Location:	Ramblewood Wy - South				
X Coordinate:	-121.31572				
Y Coordinate:	38.71347				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	24	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$3,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	455
Location:	Summerplace Dr - East				
X Coordinate:	-121.31705				
Y Coordinate:	38.71332				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	1063	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.9% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$132,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	456
Location:	Carmelwood Dr - South				
X Coordinate:	-121.31630				
Y Coordinate:	38.71018				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	876	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$109,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	457
Location:	Carmelwood Dr - South				
X Coordinate:	-121.31335				
Y Coordinate:	38.71134				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	311	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$38,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	458
Location:	Candy Cone Ct - West				
X Coordinate:	-121.31222				
Y Coordinate:	38.71149				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	193	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$24,125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	459
Location:	Candy Cone Ct - East				
X Coordinate:	-121.31225				
Y Coordinate:	38.71102				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	176	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$22,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	460
Location:	Carmelwood Dr - South				
X Coordinate:	-121.31209				
Y Coordinate:	38.71152				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	180	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$22,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	461
Location:	Zenith Dr - West				
X Coordinate:	-121.31134				
Y Coordinate:	38.71149				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	453	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$56,625.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	462
Location:	Zenith Dr - North				
X Coordinate:	-121.31208				
Y Coordinate:	38.71043				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	230	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$28,750.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	463
Location:	Zenith Dr and Summerplace Dr - Corner A				
X Coordinate:	-121.31314				
Y Coordinate:	38.71019				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	12.7% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	Two - way intersection corners A,B
--------	------------------------------------

Field Date: ##### Report Date: 10/12/2010 Barrier #: 464

Location: Zenith Dr and Summerplace Dr - Corner B

X Coordinate: -121.31287

Y Coordinate: 38.71027

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Exsiting Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 13.4% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: ##### Report Date: 10/12/2010 Barrier #: 465

Location: Summerplace Dr - East

X Coordinate: -121.31290

Y Coordinate: 38.71027

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 373 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$46,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	466
Location:	Summerplace Dr - West				
X Coordinate:	-121.31359				
Y Coordinate:	38.71103				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	360	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.7% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$45,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	467A
Location:	Zenith Dr - North				
X Coordinate:	-121.31317				
Y Coordinate:	38.71021				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	650	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	6.0% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$81,250.00	Status:
Implementation Priority:	3	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date: ##### Report Date: 10/12/2010 Barrier #: 467B

Location: Zenith Dr - North

X Coordinate: -121.31318

Y Coordinate: 38.71017

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 4 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/12/2010 Barrier #: 468

Location: Sorrell Ct - North

X Coordinate: -121.31504

Y Coordinate: 38.70928

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 264 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$33,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	469
Location:	Sorrell Ct - South				
X Coordinate:	-121.31574				
Y Coordinate:	38.70953				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	211	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$26,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	470
Location:	Zenith Dr - West				
X Coordinate:	-121.31524				
Y Coordinate:	38.70911				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	270	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$33,750.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: ##### Report Date: 10/12/2010 Barrier #: 471A

Location: Zenith Dr and Blackstar Dr - Corner A

X Coordinate: -121.31552

Y Coordinate: 38.70844

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (4.1% to 4.9%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (4.1% to 4.9%)

As Built Desc: 4.7% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 2 Recommended

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date: ##### Report Date: 10/12/2010 Barrier #: 471B

Location: Zenith Dr and Blackstar Dr - Corner A

X Coordinate: -121.31552

Y Coordinate: 38.70844

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level (3.1% to 4.0%)

As Built Desc: 3.4% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 3 Hindrance

Cost Estimate: \$0.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date: ##### Report Date: 10/12/2010 Barrier #: 471C

Location: Zenith Dr and Blackstar Dr - Corner A

X Coordinate: -121.31552

Y Coordinate: 38.70844

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$0.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date: ##### Report Date: 10/13/2010 Barrier #: 472A

Location: Zenith Dr and Blackstar Dr - Corner D

X Coordinate: -121.31551

Y Coordinate: 38.70826

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$1,400.00

Status:

Implementation Priority: 3

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date: ##### Report Date: 10/13/2010 Barrier #: 472B

Location: Zenith Dr and Blackstar Dr - Corner D

X Coordinate: -121.31551

Y Coordinate: 38.70826

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.9% - 6.5%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.9% - 6.5%)

As Built Desc: 5.9% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 3 Hindrance Cost Estimate: \$750.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date: ##### Report Date: 10/12/2010 Barrier #: 473

Location: Blackstar Dr - North

X Coordinate: -121.31554

Y Coordinate: 38.70838

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 164 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$20,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	474A
Location:	Blackstar Dr and Cobra Ct - Corner A				
X Coordinate:	-121.31635				
Y Coordinate:	38.70842				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH		
Description:	12" grooves at top of curb ramp are not level (2.1% to 3.0%)				
As Built Desc:	2.9% at 12" grooves				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Four - way intersection corners A,B,C,D				

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	474B
Location:	Blackstar Dr and Cobra Ct - Corner A				
X Coordinate:	-121.31635				
Y Coordinate:	38.70842				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Four - way intersection corners A,B,C,D				

Field Date: ##### Report Date: 10/12/2010 Barrier #: 475A

Location: Blackstar Dr and Cobra Ct - Corner B

X Coordinate: -121.31614

Y Coordinate: 38.70844

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.8% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: ##### Report Date: 10/12/2010 Barrier #: 475B

Location: Blackstar Dr and Cobra Ct - Corner B

X Coordinate: -121.31614

Y Coordinate: 38.70844

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.5% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: ##### Report Date: 10/12/2010 Barrier #: 475C

Location: Blackstar Dr and Cobra Ct - Corner B

X Coordinate: -121.31614

Y Coordinate: 38.70844

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$0.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: ##### Report Date: 10/13/2010 Barrier #: 476A

Location: Blackstar Dr and Cobra Ct - Corner C

X Coordinate: -121.31613

Y Coordinate: 38.70834

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$1,400.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: ##### Report Date: 10/13/2010 Barrier #: 476B

Location: Blackstar Dr and Cobra Ct - Corner C

X Coordinate: -121.31613

Y Coordinate: 38.70834

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.6% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended

Cost Estimate: \$750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date: ##### Report Date: 10/13/2010 Barrier #: 477

Location: Blackstar Dr and Cobra Ct - Corner D

X Coordinate: -121.31630

Y Coordinate: 38.70827

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$1,400.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	478
Location:	Cobera Ct - East				
X Coordinate:	-121.31615				
Y Coordinate:	38.70847				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	198	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$24,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	479
Location:	Cobera Ct - West				
X Coordinate:	-121.31624				
Y Coordinate:	38.70893				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	192	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$24,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date: ##### Report Date: 10/12/2010 Barrier #: 480

Location: Blackstar Dr - North

X Coordinate: -121.31671

Y Coordinate: 38.70840

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 300 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$37,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/12/2010 Barrier #: 481A

Location: Blackstar Dr and Summerplace Dr - Corner B

X Coordinate: -121.31755

Y Coordinate: 38.70830

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: ##### Report Date: 10/12/2010 Barrier #: 481B

Location: Blackstar Dr and Summerplace Dr - Corner B

X Coordinate: -121.31755

Y Coordinate: 38.70830

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.7% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance

Cost Estimate: \$0.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: ##### Report Date: 10/12/2010 Barrier #: 481C

Location: Blackstar Dr and Summerplace Dr - Corner B

X Coordinate: -121.31755

Y Coordinate: 38.70830

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.7% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended

Cost Estimate: \$0.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: ##### Report Date: 10/12/2010 Barrier #: 481D

Location: Blackstar Dr and Summerplace Dr - Corner B

X Coordinate: -121.31755

Y Coordinate: 38.70830

Barrier Area: Curb Ramps

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 1 Quantity: EACH

Description: Ramp run cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 2 Recommended

Cost Estimate: \$0.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: ##### Report Date: 10/12/2010 Barrier #: 481E

Location: Blackstar Dr and Summerplace Dr - Corner B

X Coordinate: -121.31755

Y Coordinate: 38.70830

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (4.1% to 4.9%)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level(4.1% to 4.9%)

As Built Desc: 4.1% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 2 Recommended

Cost Estimate: \$0.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	482A
Location:	Blackstar Dr and Summerplace Dr - Corner C				
X Coordinate:	-121.31741				
Y Coordinate:	38.70834				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Two - way intersection corners B,C			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	482B
Location:	Blackstar Dr and Summerplace Dr - Corner C				
X Coordinate:	-121.31741				
Y Coordinate:	38.70834				
Barrier Area:	Curb Ramps				
Barrier Type:	Gutter Slope - Existing (8.3% or more)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.2				



As Built Meas:	6	Quantity:	SF	
Description:	Gutter slope exceeds 5.0% (8.3% or more)			
As Built Desc:	10.8% gutter slope			
Solution:	Demolish existing and construct new gutter			
Bar. Severity:	1 Necessary	Cost Estimate:	\$750.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Two - way intersection corners B,C			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	483A
Location:	Summerplace Dr - East				
X Coordinate:	-121.31752				
Y Coordinate:	38.70846				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	679	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.1% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$84,875.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	483B
Location:	Summerplace Dr - East				
X Coordinate:	-121.31698				
Y Coordinate:	38.70920				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - Tree Heaves				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF		
Description:	Change in level greater than 1/2"				
As Built Desc:	1" lip due to tree heaves				
Solution:	Grind or repair sidewalk to remove trip hazard				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date: ##### Report Date: 10/12/2010 Barrier #: 483C

Location: Summerplace Dr - East

X Coordinate: -121.31639

Y Coordinate: 38.71009

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - Tree Heaves

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip due to tree heaves

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/12/2010 Barrier #: 484

Location: Zenith Dr - South

X Coordinate: -121.31180

Y Coordinate: 38.71028

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 107 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$13,375.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	485
Location:	Zenith Dr and Posten Wy - Corner B				
X Coordinate:	-121.31138				
Y Coordinate:	38.71062				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	12.1% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	486
Location:	Zenith Dr and Posten Wy - Corner C				
X Coordinate:	-121.31147				
Y Coordinate:	38.71056				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	12.8% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	487A
Location:	Zenith Dr - East				
X Coordinate:	-121.31136				
Y Coordinate:	38.71065				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	276	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$34,500.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	487B
Location:	Zenith Dr - East				
X Coordinate:	-121.31122				
Y Coordinate:	38.71108				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - Tree Heaves				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip due to tree heaves		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	488
Location:	Carmelwood Dr - South				
X Coordinate:	-121.31106				
Y Coordinate:	38.71155				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	783	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.9% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$97,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	489A
Location:	Lichen Dr - West				
X Coordinate:	-121.30825				
Y Coordinate:	38.71158				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	118	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$14,750.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date: ##### Report Date: 10/12/2010 Barrier #: 489B

Location: Lichen Dr - West

X Coordinate: -121.30820

Y Coordinate: 38.71153

Barrier Area: Sidewalks

Barrier Type: Running Slope (Existing)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 12 Quantity: LF

Description: Running slope exceeds 5.0%

As Built Desc: 6.5% running slope

Solution: No remediation where sidewalk sloped as roadway

Bar. Severity: 5 Technically Infeasible Cost Estimate: \$0.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/12/2010 Barrier #: 490

Location: Lichen Dr and Kaestner Ct - Corner A

X Coordinate: -121.30798

Y Coordinate: 38.71126

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 10.2% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	491
Location:	Lichen Dr and Kaestner Ct - Corner D				
X Coordinate:	-121.30786				
Y Coordinate:	38.71112				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	12.2% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,D		

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	492
Location:	Kaestner Ct - North				
X Coordinate:	-121.30797				
Y Coordinate:	38.71122				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	220	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$27,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	493
Location:	Kaestner Ct - South				
X Coordinate:	-121.30845				
Y Coordinate:	38.71084				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	194	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.9% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$24,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	494
Location:	Lichen Dr - West				
X Coordinate:	-121.30786				
Y Coordinate:	38.71112				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	288	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$36,000.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	495
Location:	Lichen Dr - North				
X Coordinate:	-121.30752				
Y Coordinate:	38.71017				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	252	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$31,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	496
Location:	Lichen Dr and Discus Ct - Corner A				
X Coordinate:	-121.30828				
Y Coordinate:	38.70958				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.0% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	Two - way intersection corners A,B
--------	------------------------------------

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	497
Location:	Lichen Dr and Discus Ct - Corner B				
X Coordinate:	-121.30819				
Y Coordinate:	38.70966				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	12.4% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	498
Location:	Discus Ct - North				
X Coordinate:	-121.30823				
Y Coordinate:	38.70969				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	266	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	7.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$33,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	499
Location:	Discus Ct - South				
X Coordinate:	-121.30846				
Y Coordinate:	38.71027				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	279	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$34,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	500A
Location:	Lichen Dr - West				
X Coordinate:	-121.30831				
Y Coordinate:	38.70953				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	204	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$25,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	500B
Location:	Lichen Dr - West				
X Coordinate:	-121.30852				
Y Coordinate:	38.70937				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	4	Quantity:	LF	
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)			
As Built Desc:	Cracked concrete			
Solution:	Repair surface to make firm and stable			
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	501
Location:	Lichen Dr - North				
X Coordinate:	-121.30892				
Y Coordinate:	38.70912				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	483	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.6% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$60,375.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date: ##### Report Date: 10/12/2010 Barrier #: 502A

Location: Lichen Dr and Brimstone Dr - Corner A

X Coordinate: -121.31145

Y Coordinate: 38.70868

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - New Construction

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (4.1% to 4.9%)

As Built Desc: 4.6% at 12" grooves - New Construction

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection corners A,B,C. Corners B,C compliant

Field Date: ##### Report Date: 10/12/2010 Barrier #: 502B

Location: Lichen Dr and Brimstone Dr - Corner A

X Coordinate: -121.31145

Y Coordinate: 38.70868

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - New Construction

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 1 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.9% - 6.5%)

As Built Desc: 6.0% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection corners A,B,C. Corners B,C compliant

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	503A
Location:	Brimstone Dr - East				
X Coordinate:	-121.31131				
Y Coordinate:	38.70876				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	179	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.7% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$22,375.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	503B
Location:	Brimstone Dr - East				
X Coordinate:	-121.31134				
Y Coordinate:	38.70899				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - Tree Heaves				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF		
Description:	Change in level greater than 1/2"				
As Built Desc:	2" lip due to tree heaves				
Solution:	Grind or repair sidewalk to remove trip hazard				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	504A
Location:	Branchwater Wy - South				
X Coordinate:	-121.31131				
Y Coordinate:	38.70927				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	616	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$77,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	813
Location:	Parkvale Wy - West				
X Coordinate:	-121.32074				
Y Coordinate:	38.69919				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	212	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.9% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$26,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	814
Location:	Parkvale Wy - West				
X Coordinate:	-121.32113				
Y Coordinate:	38.69973				
Barrier Area:	Sidewalks				
Barrier Type:	Elbow in Sidewalk - Cross Slope (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	6	Quantity:	LF
Description:	Cross slope at elbow exceeds 2.0% (5.0% or more)		
As Built Desc:	16.1% cross slope		
Solution:	Demolish existing and construct new sidewalk without curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	815A
Location:	Parkvale Wy - South				
X Coordinate:	-121.32129				
Y Coordinate:	38.69963				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	624	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$78,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	815B
Location:	Parkvale Wy - South				
X Coordinate:	-121.32128				
Y Coordinate:	38.69965				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	8	Quantity:	LF		
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)				
As Built Desc:	Cracked concrete				
Solution:	Repair surface to make firm and stable				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	816
Location:	Parkvale Wy - South				
X Coordinate:	-121.32338				
Y Coordinate:	38.69957				
Barrier Area:	Sidewalks				
Barrier Type:	Elbow in Sidewalk - Cross Slope (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	6	Quantity:	LF		
Description:	Cross slope at elbow exceeds 2.0% (5.0% or more)				
As Built Desc:	5.9% cross slope				
Solution:	Demolish existing and construct new sidewalk without curb ramp				
Bar. Severity:	1 Necessary	Cost Estimate:	\$750.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	817A
Location:	Parkvale Wy - East				
X Coordinate:	-121.32339				
Y Coordinate:	38.69946				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	173	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.8% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$21,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	817B
Location:	Parkvale Wy - East				
X Coordinate:	-121.3234				
Y Coordinate:	38.69947				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - Tree Heaves				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	8	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1/2" lip due to tree heaves		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	818
Location:	Parkvale Wy - East				
X Coordinate:	-121.32065				
Y Coordinate:	38.69911				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	248	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$31,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	819A
Location:	Parkvale Wy - North				
X Coordinate:	-121.32117				
Y Coordinate:	38.69974				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	362	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$45,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	819B
Location:	Parkvale Wy - North				
X Coordinate:	-121.32183				
Y Coordinate:	38.69967				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1/2" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	980
Location:	Parkvale Ct and Parkvale Wy - Corner B				
X Coordinate:	-121.32346				
Y Coordinate:	38.69639				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	10.0% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date: ##### Report Date: 10/19/2010 Barrier #: 981

Location: Parkvale Ct and Parkvale Wy - Corner C

X Coordinate: -121.32346

Y Coordinate: 38.69628

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Exsiting Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 11.2% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: ##### Report Date: 10/19/2010 Barrier #: 982

Location: Parkvale Ct - South

X Coordinate: -121.32338

Y Coordinate: 38.69628

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 117 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$14,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	983
Location:	Parkvale Ct - North				
X Coordinate:	-121.3231				
Y Coordinate:	38.69632				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	112	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$14,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	984A
Location:	Parkvale Wy - East				
X Coordinate:	-121.32346				
Y Coordinate:	38.69642				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	171	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$21,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date: ##### Report Date: 10/19/2010 Barrier #: 984B

Location: Parkvale Wy - East

X Coordinate: -121.32349

Y Coordinate: 38.69644

Barrier Area: Sidewalks

Barrier Type: Protruding Hazard

Code Ref: CBC 1133B.8.6.1 and ADA/ABA 307.2



As Built Meas: 1 Quantity: JOB

Description: Protruding object in route of travel between 27" and 80" high

As Built Desc: 60" protruding hazard at tree branches

Solution: Remove object or provide detectable warning

Bar. Severity: 1 Necessary

Cost Estimate: \$1,400.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/19/2010 Barrier #: 985

Location: Parkway Wy and Shawnda Ct - Corner B

X Coordinate: -121.32341

Y Coordinate: 38.69706

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Exsiting Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 11.1% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	986
Location:	Parkway Wy and Shawnda Ct - Corner C				
X Coordinate:	-121.32343				
Y Coordinate:	38.69693				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	12.9% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	987
Location:	Shawnda Ct - South				
X Coordinate:	-121.32338				
Y Coordinate:	38.69693				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	130	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$16,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	504B
Location:	Branchwater Wy - South				
X Coordinate:	-121.30927				
Y Coordinate:	38.70962				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	505
Location:	Branchwater Wy - East				
X Coordinate:	-121.30921				
Y Coordinate:	38.70966				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	486	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.8% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$60,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	506
Location:	Cranberry Ct - North				
X Coordinate:	-121.30923				
Y Coordinate:	38.71092				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	394	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$49,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	507A
Location:	Cranberry Ct - South				
X Coordinate:	-121.31045				
Y Coordinate:	38.71080				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	351	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$43,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	507B
Location:	Cranberry Ct - South				
X Coordinate:	-121.31021				
Y Coordinate:	38.71082				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - Tree Heaves				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF		
Description:	Change in level greater than 1/2"				
As Built Desc:	1" lip due to tree heaves				
Solution:	Grind or repair sidewalk to remove trip hazard				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	507C
Location:	Cranberry Ct - South				
X Coordinate:	-121.30995				
Y Coordinate:	38.71089				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ($\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	1	Quantity:	LF		
Description:	Pedestrian route is not min. 48" wide ($\leq 31"$ or less)				
As Built Desc:	24" clear width due to foliage				
Solution:	Trim foliage to provide min. 48" clear width				
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	508
Location:	Branchwater Wy - West				
X Coordinate:	-121.30933				
Y Coordinate:	38.71078				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	197	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$24,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	509
Location:	Branchwater Wy and Posten Wy - Corner A				
X Coordinate:	-121.30936				
Y Coordinate:	38.71029				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.0% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	Two - way intersection corners A,D
--------	------------------------------------

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	510
Location:	Branchwater Wy and Posten Wy - Corner D				
X Coordinate:	-121.30941				
Y Coordinate:	38.71022				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	12.1% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,D		

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	511
Location:	Posten Wy - North				
X Coordinate:	-121.30940				
Y Coordinate:	38.71027				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	400	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$50,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	512
Location:	Posten Wy - North				
X Coordinate:	-121.31078				
Y Coordinate:	38.71011				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	265	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$33,125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	513
Location:	Posten Wy - South				
X Coordinate:	-121.31141				
Y Coordinate:	38.71052				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	295	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$36,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	514
Location:	Posten Wy - South				
X Coordinate:	-121.31078				
Y Coordinate:	38.71001				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	412	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$51,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	515
Location:	Branchwater Wy - West				
X Coordinate:	-121.30934				
Y Coordinate:	38.71016				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	162	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$20,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	516
Location:	Branchwater Wy - North				
X Coordinate:	-121.30936				
Y Coordinate:	38.70971				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	599	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.9% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$74,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	517
Location:	Brimstone Dr - East				
X Coordinate:	-121.31142				
Y Coordinate:	38.70939				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	359	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$44,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	518
Location:	Brimstone Dr - West				
X Coordinate:	-121.31189				
Y Coordinate:	38.71019				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	116	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$14,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	519
Location:	Brimstone Dr - West				
X Coordinate:	-121.31184				
Y Coordinate:	38.70994				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	38	Quantity:	LF
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	7.9% cross slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	520
Location:	Brimstone Dr - West				
X Coordinate:	-121.31179				
Y Coordinate:	38.70985				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	213	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.7% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$26,625.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	521
Location:	Brimstone Dr - West				
X Coordinate:	-121.31154				
Y Coordinate:	38.70929				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	37	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	8.2% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,625.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	522
Location:	Brimstone Dr - West				
X Coordinate:	-121.31153				
Y Coordinate:	38.70921				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	182	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$22,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	523
Location:	Lichen Dr - North				
X Coordinate:	-121.31151				
Y Coordinate:	38.70864				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	117	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$14,625.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	524
Location:	Lichen Dr - North				
X Coordinate:	-121.31193				
Y Coordinate:	38.70859				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	33	Quantity:	LF
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	8.4% cross slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,125.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	525
Location:	Lichen Dr - North				
X Coordinate:	-121.31203				
Y Coordinate:	38.70858				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	425	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$53,125.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	526
Location:	Lichen Dr - West				
X Coordinate:	-121.31343				
Y Coordinate:	38.70799				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	128	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.9% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$16,000.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	527
Location:	Zenith Dr - East				
X Coordinate:	-121.31538				
Y Coordinate:	38.70775				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	91	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$11,375.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	528
Location:	Zenith Dr - East				
X Coordinate:	-121.31533				
Y Coordinate:	38.70802				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	38	Quantity:	LF
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	8.8% cross slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,750.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	529
Location:	Zenith Dr - East				
X Coordinate:	-121.31537				
Y Coordinate:	38.70805				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	192	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$24,000.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	530
Location:	Zenith Dr - East				
X Coordinate:	-121.31526				
Y Coordinate:	38.70863				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	38	Quantity:	LF
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	7.8% cross slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,750.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	531A
Location:	Zenith Dr - East				
X Coordinate:	-121.31521				
Y Coordinate:	38.70872				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	202	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$25,250.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	531B
Location:	Zenith Dr - East				
X Coordinate:	-121.31493				
Y Coordinate:	38.70919				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - Tree Heaves				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	5	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip due to tree heaves		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,250.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	532
Location:	Zenith Dr - East				
X Coordinate:	-121.31447				
Y Coordinate:	38.70958				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	38	Quantity:	LF
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.7% cross slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,750.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	533
Location:	Zenith Dr - East				
X Coordinate:	-121.31436				
Y Coordinate:	38.70966				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	428	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.0% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$53,500.00	Status:	
Implementation Priority:	3	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	534
Location:	Zenith Dr - East				
X Coordinate:	-121.31300				
Y Coordinate:	38.71014				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				




As Built Meas:	38	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	7.9% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,750.00	Status:	
Implementation Priority:	3	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/12/2010	Barrier #:	535
Location:	Zenith Dr - East				
X Coordinate:	-121.31285				
Y Coordinate:	38.71017				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	241	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$30,125.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	536A
Location:	Zenith Dr - West				
X Coordinate:	-121.31551				
Y Coordinate:	38.70762				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	207	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	8.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$25,875.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: ##### Report Date: 10/13/2010 Barrier #: 536B

Location: Zenith Dr - West


X Coordinate: -121.31550

Y Coordinate: 38.70791

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 20 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/13/2010 Barrier #: 537

Location: Blackstar Dr - South

X Coordinate: -121.31553

Y Coordinate: 38.70826

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 108 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$13,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/13/2010 Barrier #: 538A

Location: Serrano Ct - East


X Coordinate: -121.31613

Y Coordinate: 38.70834

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 247 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$30,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/13/2010 Barrier #: 538B

Location: Serrano Ct - East

X Coordinate: -121.31618

Y Coordinate: 38.70830

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - Tree Heaves

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip due to tree heaves

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	538C
Location:	Serrano Ct - East				
X Coordinate:	-121.31654				
Y Coordinate:	38.70782				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				




As Built Meas:	8	Quantity:	LF
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)		
As Built Desc:	Cracked concrete		
Solution:	Repair surface to make firm and stable		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	539
Location:	Serrano Ct - West				
X Coordinate:	-121.31648				
Y Coordinate:	38.70802				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	117	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$14,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	540
Location:	Blackstar Dr - South				
X Coordinate:	-121.31634				
Y Coordinate:	38.70830				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	312	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$39,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	541A
Location:	Summerplace Dr - East				
X Coordinate:	-121.31741				
Y Coordinate:	38.70834				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	279	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$34,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	541B
Location:	Summerplace Dr - East				
X Coordinate:	-121.31747				
Y Coordinate:	38.70753				
Barrier Area:	Sidewalks				
Barrier Type:	Running Slope (Existing)				
Code Ref:	CBC 1133B.7.3 and ADA/ABA 403.3				



As Built Meas:	11	Quantity:	LF
Description:	Running slope exceeds 5.0%		
As Built Desc:	10.7% running slope		
Solution:	No remediation where sidewalk sloped as roadway		
Bar. Severity:	5 Technically Infeasible	Cost Estimate:	\$0.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	542
Location:	Summerplace Dr - West				
X Coordinate:	-121.31765				
Y Coordinate:	38.70803				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	373	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.8% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$46,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	543
Location:	Summerplace Dr and Reina Ct - Corner A				
X Coordinate:	-121.31731				
Y Coordinate:	38.70909				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No compliant curb cut at corner (intersection)				
As Built Desc:	13.4% running slope at depressed area				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Two - way intersection corners A,D				

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	544
Location:	Summerplace Dr and Reina Ct - Corner D				
X Coordinate:	-121.31739				
Y Coordinate:	38.70898				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No compliant curb cut at corner (intersection)				
As Built Desc:	10.7% running slope at depressed area				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Two - way intersection corners A,D				

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	545
Location:	Reina Ct - South				
X Coordinate:	-121.31741				
Y Coordinate:	38.70899				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	110	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.0% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$13,750.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--


Field Date:	#####	Report Date:	10/13/2010	Barrier #:	546
Location:	Reina Ct - North				
X Coordinate:	-121.31782				
Y Coordinate:	38.70928				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	112	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.6% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$14,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	547
Location:	Summerplace Dr - West				
X Coordinate:	-121.31730				
Y Coordinate:	38.70910				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	194	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$24,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	548
Location:	Summerplace Dr and Sandridge Dr - Corner A				
X Coordinate:	-121.31677				
Y Coordinate:	38.70961				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	10.2% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			


Notes:	Two - way intersection corners A,D
--------	------------------------------------

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	549
Location:	Summerplace Dr and Sandridge Dr - Corner D				
X Coordinate:	-121.31686				
Y Coordinate:	38.70953				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	10.7% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,D		

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	550
Location:	Summerplace Dr - West				
X Coordinate:	-121.31675				
Y Coordinate:	38.70964				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	254	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.8% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$31,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: ##### Report Date: 10/13/2010 Barrier #: 551A

Location: Sandridge Dr - North

X Coordinate: -121.31678

Y Coordinate: 38.70964

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 832 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$104,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/13/2010 Barrier #: 551B

Location: Sandridge Dr - North

X Coordinate: -121.31763

Y Coordinate: 38.71128

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1-1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/13/2010 Barrier #: 552

Location: Sandridge Wy and Mesaview Dr - Corner C

X Coordinate: -121.31767

Y Coordinate: 38.71168

Barrier Area: Curb Ramps

Barrier Type: Clear Width

Code Ref: CBC 1127B.5.2



As Built Meas: 1 Quantity: EACH

Description: Curb ramp not at least 48" wide

As Built Desc: 6" clear width due to foliage - New Construction

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary

Cost Estimate: \$125.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D. Corner D compliant

Field Date: ##### Report Date: 10/13/2010 Barrier #: 553

Location: Mesaview Dr - South

X Coordinate: -121.31760

Y Coordinate: 38.71177

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 160 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$20,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/13/2010 Barrier #: 554

Location: Mesaview Dr - North

X Coordinate: -121.31711

Y Coordinate: 38.71199

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 577 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$72,125.00

Status:

Implementation Priority: 4


Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:



Field Date: ##### Report Date: 10/13/2010 Barrier #: 555

Location: Ericwood Ct - East

X Coordinate: -121.31896

Y Coordinate: 38.71189

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 150 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$18,750.00

Status:

Implementation Priority: 4


Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:



Field Date:	#####	Report Date:	10/13/2010	Barrier #:	556
Location:	Ericwood Ct and Lovewood Ct - Corner A				
X Coordinate:	-121.31899				
Y Coordinate:	38.71261				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	11.7% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	557
Location:	Ericwood Ct and Lovewood Ct - Corner B				
X Coordinate:	-121.31885				
Y Coordinate:	38.71260				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	11.8% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	558
Location:	Ericwood Ct and Lovewood Ct - Corner C				
X Coordinate:	-121.31894				
Y Coordinate:	38.71250				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	11.7% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	559
Location:	Ericwood Ct and Lovewood Ct - Corner D				
X Coordinate:	-121.31908				
Y Coordinate:	38.71255				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				




As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.7% running slope at depressd area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	560
Location:	Lovewood Ct - South				
X Coordinate:	-121.31892				
Y Coordinate:	38.71249				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	140	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$17,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	561
Location:	Ericwood Ct - East				
X Coordinate:	-121.31885				
Y Coordinate:	38.71260				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	99	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$12,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	562
Location:	Ericwood Ct - West				
X Coordinate:	-121.31892				
Y Coordinate:	38.71273				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	58	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$7,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	563A
Location:	Starwood Ct - North				
X Coordinate:	-121.31903				
Y Coordinate:	38.71262				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	160	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.8% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$20,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	563B
Location:	Starwood Ct - North				
X Coordinate:	-121.31950				
Y Coordinate:	38.71278				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	564
Location:	Starwood Ct - South				
X Coordinate:	-121.31948				
Y Coordinate:	38.71278				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				




As Built Meas:	140	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.9% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$17,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	565
Location:	Wallwood Ct - South				
X Coordinate:	-121.32002				
Y Coordinate:	38.71202				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	4	Quantity:	LF
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)		
As Built Desc:	Cracked concrete		
Solution:	Repair surface to make firm and stable		
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	566
Location:	Mesaview Dr - South				
X Coordinate:	-121.31872				
Y Coordinate:	38.71186				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	70	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$8,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	567
Location:	Sandridge Wy - West				
X Coordinate:	-121.31770				
Y Coordinate:	38.71176				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	241	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$30,125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	568
Location:	Sandridge Wy and Autumn Ct - Corner A				
X Coordinate:	-121.31751				
Y Coordinate:	38.71112				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	12.1% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	Two - way intersection corners A,D
--------	------------------------------------

Field Date: ##### Report Date: 10/13/2010 Barrier #: 569

Location: Sandridge Wy and Autumn Ct - Corner D

X Coordinate: -121.31746

Y Coordinate: 38.71100

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Exsiting Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 13.6% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date: ##### Report Date: 10/13/2010 Barrier #: 570A

Location: Autumn Ct - North

X Coordinate: -121.31755

Y Coordinate: 38.71112

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing (32" to 35")

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide (32" to 35")

As Built Desc: 32" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 2 Recommended Cost Estimate: \$125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	570B
Location:	Autumn Ct - North				
X Coordinate:	-121.31759				
Y Coordinate:	38.71110				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	117	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$14,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	571
Location:	Autumn Ct - South				
X Coordinate:	-121.31779				
Y Coordinate:	38.71095				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	118	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	7.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$14,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: ##### Report Date: 10/13/2010 Barrier #: 572

Location: Sandridge Wy - West


X Coordinate: -121.31744

Y Coordinate: 38.71099

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 247 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$30,875.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/13/2010 Barrier #: 573

Location: Sandridge Wy and Copa Ct - Corner A

X Coordinate: -121.31732

Y Coordinate: 38.71031

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 11.3% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:


Notes: Two - way intersection corners A,D. Corner D compliant

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	574
Location:	Copa Ct - North				
X Coordinate:	-121.31735				
Y Coordinate:	38.71029				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	147	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	6.4% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$18,375.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	575
Location:	Copa Ct - South				
X Coordinate:	-121.31747				
Y Coordinate:	38.71016				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	56	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.3% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$7,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date: ##### Report Date: 10/13/2010 Barrier #: 576

Location: Sandridge Wy - West

X Coordinate: -121.31732

Y Coordinate: 38.71009

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 229 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$28,625.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/13/2010 Barrier #: 577A

Location: Stonehand Wy - North

X Coordinate: -121.31769

Y Coordinate: 38.70798

Barrier Area: Sidewalks

Barrier Type: Running Slope (New Construction)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 4 Quantity: LF

Description: Running slope exceeds 5.0% where roadway slope does not

As Built Desc: 7.7% running slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/13/2010 Barrier #: 577B

Location: Stonehand Wy - North

X Coordinate: -121.31770

Y Coordinate: 38.70799

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 193 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$24,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: ##### Report Date: 10/13/2010 Barrier #: 578A

Location: Ashmont St - East

X Coordinate: -121.31844

Y Coordinate: 38.70802

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 757 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.7% cross slope

Solution: Demolish existing and construct new route


Bar. Severity: 1 Necessary Cost Estimate: \$94,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date:	#####	Report Date:	10/13/2010	Barrier #:	578B
Location:	Ashmont St - East				
X Coordinate:	-121.31844				
Y Coordinate:	38.70931				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	579
Location:	Burntwood Wy - North				
X Coordinate:	-121.31851				
Y Coordinate:	38.71002				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	586	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	10.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$73,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	580
Location:	Burntwood Wy and Blazingwood Dr - Corner B				
X Coordinate:	-121.32049				
Y Coordinate:	38.71011				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	11.0% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	581
Location:	Burntwood Wy and Blazingwood Dr - Corner C				
X Coordinate:	-121.32056				
Y Coordinate:	38.70999				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.1% running slope at depressed curb		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	582
Location:	Blazingwood Dr - East				
X Coordinate:	-121.32045				
Y Coordinate:	38.71028				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	583
Location:	Blazingwood Dr - West				
X Coordinate:	-121.32056				
Y Coordinate:	38.71035				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				




As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	584A
Location:	Blazingwood Dr - West				
X Coordinate:	-121.32057				
Y Coordinate:	38.71038				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ($\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	1	Quantity:	LF
Description:	Pedestrian route is not min. 48" wide ($\leq 31"$ or less)		
As Built Desc:	12" clear width due to foliage		
Solution:	Trim foliage to provide min. 48" clear width		
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	584B
Location:	Blazingwood Dr - West				
X Coordinate:	-121.32066				
Y Coordinate:	38.71021				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	210	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$26,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	585
Location:	Blazingwood Wy and Saybrook Dr - Corner A				
X Coordinate:	-121.32114				
Y Coordinate:	38.70992				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	10.3% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	586
Location:	Blazingwood Wy and Saybrook Dr - Corner B				
X Coordinate:	-121.32107				
Y Coordinate:	38.70977				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.6% running slope at depressed curb		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date: ##### Report Date: 10/13/2010 Barrier #: 587

Location: Saybrook Dr - North


X Coordinate: -121.32115

Y Coordinate: 38.70993

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 173 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$21,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/13/2010 Barrier #: 588

Location: Saybrook Dr and Brockwood Wy - Corner B

X Coordinate: -121.32161

Y Coordinate: 38.71032

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 10.7% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	589
Location:	Saybrook Dr and Brockwood Wy - Corner C				
X Coordinate:	-121.32176				
Y Coordinate:	38.71014				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	10.2% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	590
Location:	Brockwood Wy and Annwood Ct - Corner B				
X Coordinate:	-121.31945				
Y Coordinate:	38.71083				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	10.0% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	591
Location:	Brockwood Wy and Annwood Ct - Corner C				
X Coordinate:	-121.31964				
Y Coordinate:	38.71079				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.3% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	592
Location:	Annwood Ct - North				
X Coordinate:	-121.31862				
Y Coordinate:	38.71075				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	21	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,625.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	593
Location:	Brockwood Wy and Ebonywood Ct - Corner A				
X Coordinate:	-121.31934				
Y Coordinate:	38.71118				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	10.2% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,D		

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	594
Location:	Brockwood Wy and Ebonywood Ct - Corner D				
X Coordinate:	-121.31948				
Y Coordinate:	38.71109				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				




As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	11.2% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,D		

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	595
Location:	Ebonywood Ct - South				
X Coordinate:	-121.32078				
Y Coordinate:	38.71150				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	472	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$59,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	596
Location:	Brockwood Wy - West				
X Coordinate:	-121.32076				
Y Coordinate:	38.71090				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	182	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$22,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	597
Location:	Brockwood Wy - West				
X Coordinate:	-121.32163				
Y Coordinate:	38.71041				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	598
Location:	Brockwood Wy and Softwood Ct - Corner A				
X Coordinate:	-121.32275				
Y Coordinate:	38.70931				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.9% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	Four - way intersection corners A,B,C,D
--------	---

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	599
Location:	Brockwood Wy and Softwood Ct - Corner B				
X Coordinate:	-121.32257				
Y Coordinate:	38.70931				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	11.2% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	600
Location:	Brockwood Wy and Softwood Ct - Corner C				
X Coordinate:	-121.32270				
Y Coordinate:	38.70913				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	11.3% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	601
Location:	Brockwood Wy and Softwood Ct - Corner D				
X Coordinate:	-121.32283				
Y Coordinate:	38.70921				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.1% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	602
Location:	Brockwood Wy and Covewood Ct - Corner A				
X Coordinate:	-121.32290				
Y Coordinate:	38.70860				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	11.1% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	603
Location:	Brockwood Wy and Covewood Ct - Corner B				
X Coordinate:	-121.32276				
Y Coordinate:	38.70859				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No compliant curb cut at corner (intersection)				
As Built Desc:	11.2% running slope at depressed area				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Four - way intersection corners A,B,C,D				

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	604
Location:	Brockwood Wy and Covewood Ct - Corner C				
X Coordinate:	-121.32276				
Y Coordinate:	38.70843				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No compliant curb cut at corner (intersection)				
As Built Desc:	11.0% running slope at depressed area				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Four - way intersection corners A,B,C,D				

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	605
Location:	Brockwood Wy and Covewood Ct - Corner D				
X Coordinate:	-121.32293				
Y Coordinate:	38.70847				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.0% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	606
Location:	Brockwood Wy and Stonehand Ave - Corner A				
X Coordinate:	-121.32289				
Y Coordinate:	38.70790				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	13.2% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	607
Location:	Brockwood Wy and Stonehand Ave - Corner B				
X Coordinate:	-121.32266				
Y Coordinate:	38.70791				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	8.9% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	608
Location:	Stonehand Ave and Lonewood Wy - Corner C				
X Coordinate:	-121.32403				
Y Coordinate:	38.70770				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	10.3% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners C,D		

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	609
Location:	Stonehand Ave and Lonewood Wy - Corner D				
X Coordinate:	-121.32424				
Y Coordinate:	38.70775				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.9% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners C,D		

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	610
Location:	Geoffwodd Ct - North				
X Coordinate:	-121.32422				
Y Coordinate:	38.70791				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	208	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$26,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	611
Location:	Geoffwodd Ct - South				
X Coordinate:	-121.32476				
Y Coordinate:	38.70777				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	166	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$20,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	612
Location:	Lonewood Wy - West				
X Coordinate:	-121.32423				
Y Coordinate:	38.70774				
Barrier Area:	Sidewalks				
Barrier Type:	Running Slope (Existing)				
Code Ref:	CBC 1133B.7.3 and ADA/ABA 403.3				



As Built Meas:	8	Quantity:	LF
Description:	Running slope exceeds 5.0%		
As Built Desc:	10.7% running slope		
Solution:	No remediation where sidewalk sloped as roadway		
Bar. Severity:	5 Technically Infeasible	Cost Estimate:	\$0.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			


Notes:	
--------	--

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	613
Location:	Lonewood Wy - East				
X Coordinate:	-121.32404				
Y Coordinate:	38.70751				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	52	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.8% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$6,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	614
Location:	Stonehead Ave - South				
X Coordinate:	-121.32400				
Y Coordinate:	38.70775				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	30	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$3,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: ##### Report Date: 10/13/2010 Barrier #: 615

Location: Stonehead Ave - South


X Coordinate: -121.32140

Y Coordinate: 38.70782

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 88 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 9.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$11,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/13/2010 Barrier #: 616

Location: Saybrook Dr - West


X Coordinate: -121.32104

Y Coordinate: 38.70776

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 90 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$11,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/13/2010 Barrier #: 617

Location: Stonehead Ave - North

X Coordinate: -121.32117

Y Coordinate: 38.70793

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 109 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$13,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/13/2010 Barrier #: 618A

Location: Brockwood Wy - East


X Coordinate: -121.32274

Y Coordinate: 38.70793

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 78 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$9,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/13/2010 Barrier #: 618B

Location: Brockwood Wy - East

X Coordinate: -121.32275

Y Coordinate: 38.70836

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - Tree Heaves

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 2" lip due to tree heaves

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/13/2010 Barrier #: 619A

Location: Sandwood Ct - South


X Coordinate: -121.32276

Y Coordinate: 38.70847

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 327 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$40,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/13/2010 Barrier #: 619B

Location: Sandwood Ct - South

X Coordinate: -121.32211

Y Coordinate: 38.70852

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 4 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary

Cost Estimate: \$500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/13/2010 Barrier #: 619C

Location: Sandwood Ct - South

X Coordinate: -121.32169

Y Coordinate: 38.70851

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - Tree Heaves

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip due to tree heaves

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	620
Location:	Brockwood Wy - East				
X Coordinate:	-121.32276				
Y Coordinate:	38.70864				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	144	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$18,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--


Field Date:	#####	Report Date:	10/13/2010	Barrier #:	621
Location:	Softwood Ct - South				
X Coordinate:	-121.32267				
Y Coordinate:	38.70915				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	45	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$5,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/13/2010	Barrier #:	622
Location:	Saybrook Dr - West				
X Coordinate:	-121.32175				
Y Coordinate:	38.71016				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				
As Built Meas:	790	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.7% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$98,750.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					



Field Date:	#####	Report Date:	10/14/2010	Barrier #:	623
Location:	Saybrook Dr - East				
X Coordinate:	-121.32110				
Y Coordinate:	38.70977				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				
As Built Meas:	157	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.7% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$19,625.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					



Field Date:	#####	Report Date:	10/14/2010	Barrier #:	624
Location:	Saybrook Dr and Graystone Ave - Corner B				
X Coordinate:	-121.32092				
Y Coordinate:	38.70934				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No compliant curb cut at corner (intersection)				
As Built Desc:	8.4% running slope at depressed area				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Two - way intersection corners B,C				

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	625
Location:	Saybrook Dr and Graystone Ave - Corner C				
X Coordinate:	-121.32088				
Y Coordinate:	38.70922				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No compliant curb cut at corner (intersection)				
As Built Desc:	8.3% running slope at depressed area				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Two - way intersection corners B,C				

Field Date: ##### Report Date: 10/14/2010 Barrier #: 626

Location: Saybrook Dr - East


X Coordinate: -121.32087

Y Coordinate: 38.70922

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 188 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$23,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/14/2010 Barrier #: 627

Location: Saybrook Dr and Ledge wood Wy - Corner B

X Coordinate: -121.32087

Y Coordinate: 38.70869

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 9.1% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: ##### Report Date: 10/14/2010 Barrier #: 628

Location: Saybrook Dr and Ledgewood Wy - Corner C

X Coordinate: -121.32084

Y Coordinate: 38.70852

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Exsiting Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 10.0% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: ##### Report Date: 10/14/2010 Barrier #: 629

Location: Ledgewood Wy - North


X Coordinate: -121.32080

Y Coordinate: 38.70863

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 352 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$44,000.00

Status:

Implementation Priority: 4

Facility Function:


Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	630A
Location:	Ledgewood Wy - West				
X Coordinate:	-121.31948				
Y Coordinate:	38.70874				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	206	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	10.2% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$25,750.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	630B
Location:	Ledgewood Wy - West				
X Coordinate:	-121.31948				
Y Coordinate:	38.70874				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ($\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	1	Quantity:	LF		
Description:	Pedestrian route is not min. 48" wide ($\leq 31"$ or less)				
As Built Desc:	24" clear width due to foliage				
Solution:	Trim foliage to provide min. 48" clear width				
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	631
Location:	Ledgewood Wy and Graystone Ave - Corner D				
X Coordinate:	-121.31952				
Y Coordinate:	38.70921				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	10.3% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners C,D		

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	632
Location:	Ledgewood Wy and Graystone Ave - Corner C				
X Coordinate:	-121.31936				
Y Coordinate:	38.70922				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	11.1% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners C,D		

Field Date: ##### Report Date: 10/14/2010 Barrier #: 633A

Location: Graystone Ave - South


X Coordinate: -121.31936

Y Coordinate: 38.70922

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 583 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 8.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$72,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/14/2010 Barrier #: 633B

Location: Graystone Ave - South

X Coordinate: -121.32055

Y Coordinate: 38.70921

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - Tree Heaves

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip due to tree heaves

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	633C
Location:	Graystone Ave - South				
X Coordinate:	-121.32071				
Y Coordinate:	38.70922				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - Tree Heaves				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1-1/2" lip due to tree heaves		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	634A
Location:	Graystone Ave - North				
X Coordinate:	-121.32084				
Y Coordinate:	38.70932				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	553	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$69,125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: ##### Report Date: 10/14/2010 Barrier #: 634B

Location: Graystone Ave - North

X Coordinate: -121.32046

Y Coordinate: 38.70934

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/14/2010 Barrier #: 635

Location: Graystone Ave and Ashmont St - Corner A

X Coordinate: -121.31862

Y Coordinate: 38.70934

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Exsiting Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 10.3% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	636
Location:	Graystone Ave and Ashmont St - Corner D				
X Coordinate:	-121.31862				
Y Coordinate:	38.70921				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	10.7% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,D		

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	637
Location:	Ashmont St - West				
X Coordinate:	-121.31859				
Y Coordinate:	38.70943				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	192	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	10.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$24,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: ##### Report Date: 10/14/2010 Barrier #: 638

Location: Burntwood Wy - South

X Coordinate: -121.31867

Y Coordinate: 38.70992

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 416 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route


Bar. Severity: 1 Necessary Cost Estimate: \$52,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: ##### Report Date: 10/14/2010 Barrier #: 639

Location: Blazingwood Dr - East

X Coordinate: -121.32075

Y Coordinate: 38.70994

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 151 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$18,875.00 Status:



Implementation Priority: 4 Facility Function:



Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date:	#####	Report Date:	10/14/2010	Barrier #:	640	
Location:	Ledgewood Wy - South					
X Coordinate:	-121.32072					
Y Coordinate:	38.70852					
Barrier Area:	Sidewalks					
Barrier Type:	Cross Slope - Existing (5.0% or more)					
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3					
As Built Meas:	425		Quantity:		LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)					
As Built Desc:	8.8% cross slope					
Solution:	Demolish existing and construct new route					
Bar. Severity:	1 Necessary		Cost Estimate:	\$53,125.00	Status:	
Implementation Priority:	4		Facility Function:			
Implementation Phase:			Implementation Date:			
Official Responsible:						
Notes:						

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	641	
Location:	Ledgewood Wy - East					
X Coordinate:	-121.31934					
Y Coordinate:	38.70869					
Barrier Area:	Sidewalks					
Barrier Type:	Cross Slope - Existing (5.0% or more)					
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3					
As Built Meas:	231		Quantity:		LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)					
As Built Desc:	8.5% cross slope					
Solution:	Demolish existing and construct new route					
Bar. Severity:	1 Necessary		Cost Estimate:	\$28,875.00	Status:	
Implementation Priority:	4		Facility Function:			
Implementation Phase:			Implementation Date:			
Official Responsible:						
Notes:						

Field Date: ##### Report Date: 10/14/2010 Barrier #: 642

Location: Graystone Ave - South

X Coordinate: -121.31925

Y Coordinate: 38.70923

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 187 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$23,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: ##### Report Date: 10/14/2010 Barrier #: 643A

Location: Ashmont St - West

X Coordinate: -121.31860

Y Coordinate: 38.70913

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 446 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.4% cross slope

Solution: Demolish existing and construct new route


Bar. Severity: 1 Necessary Cost Estimate: \$55,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: ##### Report Date: 10/14/2010 Barrier #: 643B

Location: Ashmont St - West

X Coordinate: -121.31861

Y Coordinate: 38.70813

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 8 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/14/2010 Barrier #: 644

Location: Stonehand Ave - North

X Coordinate: -121.31885

Y Coordinate: 38.70793

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 604 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$75,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/14/2010 Barrier #: 645

Location: Saybrook Dr - East

X Coordinate: -121.32088

Y Coordinate: 38.70757

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 195 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$24,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/14/2010 Barrier #: 646

Location: Saybrook Dr - East


X Coordinate: -121.32088

Y Coordinate: 38.70778

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 73 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$9,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/14/2010 Barrier #: 647

Location: Stonehand Ave - South


X Coordinate: -121.32071

Y Coordinate: 38.70780

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 899 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 10.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$112,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/14/2010 Barrier #: 648

Location: Antelope Rd - North

X Coordinate: -121.32507

Y Coordinate: 38.70739

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 95 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$9,500.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	649
Location:	Antelope Rd and Lonewood Wy - Corner A				
X Coordinate:	-121.32431				
Y Coordinate:	38.70740				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - New Construction				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (>5.0%)		
As Built Desc:	6.7% at 12" grooves - New Construction		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B. Corner B compliant		

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	650
Location:	Antelope Rd and Saybrook Dr - Corner A				
X Coordinate:	-121.32106				
Y Coordinate:	38.70748				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - New Construction				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (4.1% to 4.9%)		
As Built Desc:	4.3% at 12" grooves - New Construction		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D. Corner C compliant, Signalized control compliant		

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	651A
Location:	Antelope Rd and Saybrook Dr - Corner B				
X Coordinate:	-121.32082				
Y Coordinate:	38.70748				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - New Construction				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (3.1% to 4.0%)		
As Built Desc:	3.4% at 12" grooves		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D. Corner C compliant, Signalized control compliant		

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	651B
Location:	Antelope Rd and Saybrook Dr - Corner B				
X Coordinate:	-121.32082				
Y Coordinate:	38.70748				
Barrier Area:	Curb Ramps				
Barrier Type:	Gutter Slope - New Construction				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.2				



As Built Meas:	6	Quantity:	SF
Description:	Gutter slope exceeds 5.0% (6.6% to 8.2%)		
As Built Desc:	7.2% gutter slope		
Solution:	Demolish existing and construct new gutter		
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D. Corner C compliant, Signalized control compliant		

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	652
Location:	Antelope Rd and Saybrook Dr - Corner D				
X Coordinate:	-121.32115				
Y Coordinate:	38.70721				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - New Construction				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (>5.0%)		
As Built Desc:	5.2% at 12" grooves - New Construction		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D. Corner C compliant, Signalized control compliant		

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	653
Location:	Antelope Rd and Zenith Dr - Corner A (A-A)				
X Coordinate:	-121.31558				
Y Coordinate:	38.70753				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - New Construction				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (4.1% to 4.9%)		
As Built Desc:	4.5% at 12" grooves - New Construction		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D corners. A A-B,B A-A,C A-A,C A-B compliant		

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	654
Location:	Antelope Rd and Zenith Dr - Corner B (A-B)				
X Coordinate:	-121.31523				
Y Coordinate:	38.70752				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - New Construction				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (>5.0%)		
As Built Desc:	5.1% at 12" grooves - New Construction		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D corners. A A-B,B A-A,C A-A,C A-B compliant		

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	655
Location:	Antelope Rd and Tupelo Dr - Corner D (A-A)				
X Coordinate:	-121.31557				
Y Coordinate:	38.70724				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - New Construction				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (>5.0%)		
As Built Desc:	6.4% at 12" grooves - New Construction		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D corners. A A-B,B A-A,C A-A,C A-B compliant		

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	656
Location:	Antelope Rd and Tupelo Dr - Corner D (A-B)				
X Coordinate:	-121.31557				
Y Coordinate:	38.70724				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - New Construction				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (>5.0%)		
As Built Desc:	6.4% at 12" grooves - New Construction		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D corners. A A-B,B A-A,C A-A,C A-B compliant		

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	657
Location:	Antelope Rd and Lichen Dr - Corner B				
X Coordinate:	-121.31335				
Y Coordinate:	38.70756				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - New Construction				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (>5.0%)		
As Built Desc:	6.3% at 12" grooves - New Construction		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B. Corners A A-A,A A-B compliant		

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	658
Location:	Antelope Rd and Lichen Dr - Corner C				
X Coordinate:	-121.31316				
Y Coordinate:	38.70730				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - New Construction				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (>5.0%)		
As Built Desc:	7.9% at 12" grooves - New Construction		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners C,D. Corner D compliant		

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	659
Location:	Lichen Dr - East				
X Coordinate:	-121.31054				
Y Coordinate:	38.70862				
Barrier Area:	Sidewalks				
Barrier Type:	No Sidewalk - No Barricade				
Code Ref:	MUTCD Section 6D.01				



As Built Meas:	1	Quantity:	JOB
Description:	No barricade provided where sidewalk ends in hazardous location		
As Built Desc:	No barricade or other warning provided at end of sidewalk for the visually impaired		
Solution:	Provide barricade with cane detectable warning at end of sidewalk		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,350.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	660
Location:	Lichen Dr - East				
X Coordinate:	-121.31065				
Y Coordinate:	38.70858				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - New Construction				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	29	Quantity:	LF
Description:	Driveway cross/running slope exceeds 2.0%		
As Built Desc:	4.5% cross slope, 10.7% running slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	1 Necessary	Cost Estimate:	\$3,625.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	661
Location:	Lichen Dr - East				
X Coordinate:	-121.31065				
Y Coordinate:	38.70858				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - New Construction				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	26	Quantity:	LF
Description:	Driveway cross/running slope exceeds 2.0%		
As Built Desc:	4.5% cross slope, 10.6% running slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	1 Necessary	Cost Estimate:	\$3,250.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	662
Location:	Lichen Dr - East				
X Coordinate:	-121.31088				
Y Coordinate:	38.70860				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Running Slope in New Construction				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	5	Quantity:	LF		
Description:	Transition ramp into driveway not compliant (slope exceeds 8.3%)				
As Built Desc:	11.3% running slope				
Solution:	Demolish existing and construct new transition ramp				
Bar. Severity:	1 Necessary	Cost Estimate:	\$625.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	663
Location:	Lichen Dr - East				
X Coordinate:	-121.31141				
Y Coordinate:	38.70852				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Running Slope in New Construction				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	5	Quantity:	LF		
Description:	Transition ramp into driveway not compliant (slope exceeds 8.3%)				
As Built Desc:	10.8% running slope				
Solution:	Demolish existing and construct new transition ramp				
Bar. Severity:	1 Necessary	Cost Estimate:	\$625.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	664
Location:	Lichen Dr - East				
X Coordinate:	-121.31142				
Y Coordinate:	38.70851				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - New Construction				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	36	Quantity:	LF
Description:	Driveway cross/running slope exceeds 2.0%		
As Built Desc:	6.1% cross slope, 13.1% running slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	665
Location:	Lichen Dr - East				
X Coordinate:	-121.31251				
Y Coordinate:	38.70838				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - New Construction				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	42	Quantity:	LF
Description:	Driveway cross/running slope exceeds 2.0%		
As Built Desc:	9.4% cross slope, 9.5% running slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	1 Necessary	Cost Estimate:	\$5,250.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	666
Location:	Lichen Dr - East				
X Coordinate:	-121.31276				
Y Coordinate:	38.70831				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - New Construction				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	31	Quantity:	LF
Description:	Driveway cross/running slope exceeds 2.0%		
As Built Desc:	9.5% cross slope, 10.8% running slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	1 Necessary	Cost Estimate:	\$3,875.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	667
Location:	Lichen Dr - East				
X Coordinate:	-121.31312				
Y Coordinate:	38.70811				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	44	Quantity:	LF
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.9% cross slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	4 Low Severity	Cost Estimate:	\$5,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	668
Location:	Lichen Dr - East				
X Coordinate:	-121.31322				
Y Coordinate:	38.70799				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	3	Quantity:	LF		
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)				
As Built Desc:	Cracked concrete				
Solution:	Repair surface to make firm and stable				
Bar. Severity:	1 Necessary	Cost Estimate:	\$375.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	669
Location:	Lichen Dr - East				
X Coordinate:	-121.31326				
Y Coordinate:	38.70797				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - New Construction				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	41	Quantity:	LF		
Description:	Driveway cross/running slope exceeds 2.0%				
As Built Desc:	6.6% cross slope, 8.6% running slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	1 Necessary	Cost Estimate:	\$5,125.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	670A
Location:	Antelope Rd and I-80 West exit ramp - Corner A				
X Coordinate:	-121.31115				
Y Coordinate:	38.70759				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH
Description:	No truncated domes provided at curb ramp		
As Built Desc:	No detectable warnings at curb ramp		
Solution:	Provide compliant truncated domes		
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	670B
Location:	Antelope Rd and I-80 West exit ramp - Corner A (A-B)				
X Coordinate:	-121.31115				
Y Coordinate:	38.70759				
Barrier Area:	Signalized Intersections				
Barrier Type:	Ped Controls - Push Button				
Code Ref:	CBC 1117B.6.4 & PROWAG R306.2				



As Built Meas:	1	Quantity:	EACH
Description:	Pedestrian control push button mechanism not operable with a fist		
As Built Desc:	Not operable with a fist		
Solution:	Replace accessible pedestrian controls		
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,700.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	670C
Location:	Antelope Rd and I-80 West exit ramp - Corner A (A-B)				
X Coordinate:	-121.31115				
Y Coordinate:	38.70759				
Barrier Area:	Signalized Intersections				
Barrier Type:	APS Audible - East/West				
Code Ref:	MUTCD 3B.17				



As Built Meas:	1	Quantity:	EACH
Description:	No "Peep-Peep" walk sound provided for East-West direction		
As Built Desc:	No audible warning provided		
Solution:	Provide compliant audible controls		
Bar. Severity:	2 Recommended	Cost Estimate:	\$7,500.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	670D
Location:	Antelope Rd and I-80 West exit ramp - Corner A (A-B)				
X Coordinate:	-121.31115				
Y Coordinate:	38.70759				
Barrier Area:	Signalized Intersections				
Barrier Type:	Ped Control Arrow				
Code Ref:	PROWAG R306.2				



As Built Meas:	1	Quantity:	JOB
Description:	Pedestrian control arrow does not point in direction of travel		
As Built Desc:	Arrow does not point in direction of travel		
Solution:	Relocate accessible pedestrian controls		
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,700.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	670E
Location:	Antelope Rd and I-80 West exit ramp - Corner A (A-B)				
X Coordinate:	-121.31115				
Y Coordinate:	38.70759				
Barrier Area:	Signalized Intersections				
Barrier Type:	Ped Head - Countdown				
Code Ref:	N/A				



As Built Meas:	1	Quantity:	EACH	
Description:	No countdown (LED) provided at intersection			
As Built Desc:	No countdown provided			
Solution:	Provide countdown (LED) provided at intersection			
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Two - way intersection corners A,B			

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	671A
Location:	Antelope Rd and I-80 West exit ramp - Corner B				
X Coordinate:	-121.31082				
Y Coordinate:	38.70756				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (>5.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH	
Description:	12" grooves at top of curb ramp are not level (>5.0%)			
As Built Desc:	6.3% at 12" grooves			
Solution:	Demolish existing and construct new curb ramp			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Two - way intersection corners A,B			

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	671B
Location:	Antelope Rd and I-80 West exit ramp - Corner B				
X Coordinate:	-121.31082				
Y Coordinate:	38.70756				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH
Description:	No truncated domes provided at curb ramp		
As Built Desc:	No detectable warnings at curb ramp		
Solution:	Provide compliant truncated domes		
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	671C
Location:	Antelope Rd and I-80 West exit ramp - Corner B				
X Coordinate:	-121.31082				
Y Coordinate:	38.70756				
Barrier Area:	Curb Ramps				
Barrier Type:	Lip - Gutter to Asphalt Transition				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 303.3				



As Built Meas:	1	Quantity:	EACH
Description:	Transition at transition into asphalt not flush and free of any lip		
As Built Desc:	1" lip at asphalt transition into roadway		
Solution:	Remove lip to create flush transition		
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date: ##### Report Date: 10/14/2010 Barrier #: 671D

Location: Antelope Rd and I-80 West exit ramp - Corner B (B-A)

X Coordinate: -121.31082

Y Coordinate: 38.70756

Barrier Area: Signalized Intersections

Barrier Type: Ped Controls - Push Button

Code Ref: CBC 1117B.6.4 & PROWAG R306.2



As Built Meas: 1 Quantity: EACH

Description: Pedestrian control push button mechanism not operable with a fist

As Built Desc: Not operable with a fist

Solution: Replace accessible pedestrian controls

Bar. Severity: 1 Necessary Cost Estimate: \$4,700.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: ##### Report Date: 10/14/2010 Barrier #: 672

Location: Antelope Rd - North

X Coordinate: -121.31086

Y Coordinate: 38.70755

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 75 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$9,375.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	673
Location:	I-80 West entrance and Antelope Rd - Corner A				
X Coordinate:	-121.31053				
Y Coordinate:	38.70756				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH
Description:	No truncated domes provided at curb ramp		
As Built Desc:	No detectable warnings at curb ramp		
Solution:	Provide compliant truncated domes		
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	675A
Location:	I-80 West entrance and Antelope Rd - Corner B				
X Coordinate:	-121.31043				
Y Coordinate:	38.70760				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH
Description:	No truncated domes provided at curb ramp		
As Built Desc:	No detectable warnings at curb ramp		
Solution:	Provide compliant truncated domes		
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date: ##### Report Date: 10/14/2010 Barrier #: 675B

Location: I-80 West entrance and Antelope Rd - Corner B

X Coordinate: -121.31043

Y Coordinate: 38.70760

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (>5.0% or more)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level (>5.0% or more)

As Built Desc: 6.1% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary Cost Estimate: \$250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: ##### Report Date: 10/14/2010 Barrier #: 674

Location: Antelope Rd - North

X Coordinate: -121.31052

Y Coordinate: 38.70757

Barrier Area: Curb Ramps

Barrier Type: Crosswalk Placement

Code Ref: CBC 1127B.5.1 and ADA/ABA 406.6



As Built Meas: 22 Quantity: LF

Description: No min. 48" route of travel between gutter and crosswalk stripe

As Built Desc: No crosswalk provided

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,750.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/14/2010 Barrier #: 676A

Location: Antelope Rd - North

X Coordinate: -121.31038

Y Coordinate: 38.70758

Barrier Area: Sidewalks

Barrier Type: Running Slope (Existing)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 4 Quantity: LF

Description: Running slope exceeds 5.0%

As Built Desc: 14.4% running slope

Solution: No remediation where sidewalk sloped as roadway

Bar. Severity: 5 Technically Infeasible Cost Estimate: \$0.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/14/2010 Barrier #: 676B

Location: Antelope Rd - North

X Coordinate: -121.31027

Y Coordinate: 38.70757

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	677
Location:	Antelope Rd - North				
X Coordinate:	-121.31027				
Y Coordinate:	38.70756				
Barrier Area:	Sidewalks				
Barrier Type:	Running Slope (Existing)				
Code Ref:	CBC 1133B.7.3 and ADA/ABA 403.3				



As Built Meas:	4	Quantity:	LF
Description:	Running slope exceeds 5.0%		
As Built Desc:	8.0% running slope		
Solution:	No remediation where sidewalk sloped as roadway		
Bar. Severity:	5 Technically Infeasible	Cost Estimate:	\$0.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	678
Location:	Antelope Rd - North				
X Coordinate:	-121.30868				
Y Coordinate:	38.70756				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	3	Quantity:	LF
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)		
As Built Desc:	Cracked concrete		
Solution:	Repair surface to make firm and stable		
Bar. Severity:	1 Necessary	Cost Estimate:	\$375.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/14/2010	Barrier #:	679
Location:	Antelope Rd - North				
X Coordinate:	-121.30623				
Y Coordinate:	38.70758				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	4	Quantity:	LF
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)		
As Built Desc:	Cracked concrete		
Solution:	Repair surface to make firm and stable		
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	680A
Location:	Antelope Rd and Mango Tree Wy - Corner D				
X Coordinate:	-121.32415				
Y Coordinate:	38.70712				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - New Construction				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (>5.0%)		
As Built Desc:	5.8% at 12" grooves - New Construction		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners C,D. Corner C compliant		

Field Date: ##### Report Date: 10/15/2010 Barrier #: 680B

Location: Antelope Rd and Mango Tree Wy - Corner D

X Coordinate: -121.32415

Y Coordinate: 38.70712

Barrier Area: Curb Ramps

Barrier Type: Running Slope (New Construction)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.1



As Built Meas: 1 Quantity: EACH

Description: Ramp run cross slope exceeds 2.0% (8.6% to 8.9%)

As Built Desc: 8.8% running slope

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D. Corner C compliant

Field Date: ##### Report Date: 10/15/2010 Barrier #: 681

Location: Antelope Rd and Pompei Ct - Corner C

X Coordinate: -121.31758

Y Coordinate: 38.70718

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - New Construction

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (>5.0%)

As Built Desc: 7.2% at 12" grooves - New Construction

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D. Corner C compliant

Field Date: ##### Report Date: 10/15/2010 Barrier #: 682

Location: Zenith Dr - West


X Coordinate: -121.31553

Y Coordinate: 38.70648

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 396 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$49,500.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/15/2010 Barrier #: 683

Location: Tupelo Dr and Cunano Wy - Corner D

X Coordinate: -121.31559

Y Coordinate: 38.70551

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - New Construction

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (4.1% to 4.9%)

As Built Desc: 4.9% at 12" grooves - New Construction

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:


Notes: Three - way intersection corners A,B,D. Corners A,B compliant

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	684
Location:	Cunano Wy - North				
X Coordinate:	-121.31596				
Y Coordinate:	38.70561				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ($\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	1	Quantity:	LF
Description:	Pedestrian route is not min. 48" wide ($\leq 31"$ or less)		
As Built Desc:	24" clear width due to foliage		
Solution:	Trim foliage to provide min. 48" clear width		
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	685
Location:	Las Lilas Ct - East				
X Coordinate:	-121.31628				
Y Coordinate:	38.70561				
Barrier Area:	Sidewalks				
Barrier Type:	Elbow in Sidewalk - Cross Slope (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	16	Quantity:	LF
Description:	Cross slope at elbow exceeds 2.0% (5.0% or more)		
As Built Desc:	8.1% cross slope		
Solution:	Demolish existing and construct new sidewalk without curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	686
Location:	Cunano Wy - South				
X Coordinate:	-121.31628				
Y Coordinate:	38.70551				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - New Construction				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	44	Quantity:	LF
Description:	Driveway cross/running slope exceeds 2.0%		
As Built Desc:	10.1% cross slope, 8.8% running slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	1 Necessary	Cost Estimate:	\$5,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	687A
Location:	Tupelo Dr - East				
X Coordinate:	-121.31556				
Y Coordinate:	38.70495				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	44	Quantity:	LF
Description:	Driveway cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.6% cross slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$5,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: ##### Report Date: 10/15/2010 Barrier #: 687B

Location: Tupelo Dr - East

X Coordinate: -121.31556

Y Coordinate: 38.70496

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 8 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/15/2010 Barrier #: 688

Location: Tupelo Dr and Millwood Dr - Corner A

X Coordinate: -121.31556

Y Coordinate: 38.70465

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - New Construction

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (>5.0%)

As Built Desc: 7.3% at 12" grooves - New Construction

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date: ##### Report Date: 10/15/2010 Barrier #: 689

Location: Tupelo Dr and Millwood Dr - Corner D

X Coordinate: -121.31561

Y Coordinate: 38.70454

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - New Construction

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (4.1% to 4.9%)

As Built Desc: 4.9% at 12" grooves - New Construction

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date: ##### Report Date: 10/15/2010 Barrier #: 690

Location: Millwood Dr - North

X Coordinate: -121.31696

Y Coordinate: 38.70473

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 100 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$12,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	691
Location:	Millwood Dr and Bierston St - Corner B				
X Coordinate:	-121.31847				
Y Coordinate:	38.70514				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	692
Location:	Millwood Dr and Bierston St - Corner C				
X Coordinate:	-121.31845				
Y Coordinate:	38.70505				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date: ##### Report Date: 10/15/2010 Barrier #: 693

Location: Bierston St - East

X Coordinate: -121.31846

Y Coordinate: 38.70541

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 523 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.6% cross slope

Solution: Demolish existing and construct new route


Bar. Severity: 1 Necessary Cost Estimate: \$65,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: ##### Report Date: 10/15/2010 Barrier #: 694

Location: Quincewood Cir - North

X Coordinate: -121.31854

Y Coordinate: 38.70684

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 498 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.8% cross slope

Solution: Demolish existing and construct new route


Bar. Severity: 1 Necessary Cost Estimate: \$62,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: ##### Report Date: 10/15/2010 Barrier #: 695

Location: Quincewood Cir - West


X Coordinate: -121.32015

Y Coordinate: 38.7067

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 490 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$61,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/15/2010 Barrier #: 696

Location: Rumford Ave and Quincewood Cir - Corner A

X Coordinate: -121.32013

Y Coordinate: 38.70619

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	697
Location:	Rumford Ave and Quincewood Cir - Corner B				
X Coordinate:	-121.32				
Y Coordinate:	38.70619				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	698A
Location:	Rumford Ave - North				
X Coordinate:	-121.31988				
Y Coordinate:	38.70617				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	371	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$46,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: ##### Report Date: 10/15/2010 Barrier #: 698B

Location: Rumford Ave - North

X Coordinate: -121.31944

Y Coordinate: 38.70618

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/15/2010 Barrier #: 698C

Location: Rumford Ave - North

X Coordinate: -121.31942

Y Coordinate: 38.70618

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/15/2010 Barrier #: 699

Location: Rumford Ave and Quincewood Cir - Corner A

X Coordinate: -121.31865

Y Coordinate: 38.70618

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: ##### Report Date: 10/15/2010 Barrier #: 700

Location: Rumford Ave and Quincewood Cir - Corner B

X Coordinate: -121.31863

Y Coordinate: 38.70608

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: ##### Report Date: 10/15/2010 Barrier #: 701

Location: Quincewood Cir - West

X Coordinate: -121.31863

Y Coordinate: 38.70614

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 188 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.9% cross slope

Solution: Demolish existing and construct new route


Bar. Severity: 2 Recommended Cost Estimate: \$23,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: ##### Report Date: 10/15/2010 Barrier #: 702

Location: Quincewood Cir - South

X Coordinate: -121.31891

Y Coordinate: 38.70673

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 311 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.2% cross slope

Solution: Demolish existing and construct new route


Bar. Severity: 1 Necessary Cost Estimate: \$38,875.00 Status:

Implementation Priority: 4 Facility Function:


Implementation Phase: Implementation Date:

Official Responsible:


Notes:



Field Date:	#####	Report Date:	10/15/2010	Barrier #:	703
Location:	Quincewood Cir - East				
X Coordinate:	-121.32001				
Y Coordinate:	38.7067				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				
As Built Meas:	166	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	7.3% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$20,750.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					



Field Date:	#####	Report Date:	10/15/2010	Barrier #:	704
Location:	Rumford Ave - North				
X Coordinate:	-121.32021				
Y Coordinate:	38.70622				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				
As Built Meas:	182	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.2% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$22,750.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					



Field Date:	#####	Report Date:	10/15/2010	Barrier #:	705
Location:	Saybrook Dr and Rumford Ave - Corner B				
X Coordinate:	-121.32083				
Y Coordinate:	38.7062				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				




As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	706
Location:	Saybrook Dr and Rumford Ave - Corner C				
X Coordinate:	-121.32086				
Y Coordinate:	38.70607				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	707A
Location:	Saybrook Dr - East				
X Coordinate:	-121.32089				
Y Coordinate:	38.70623				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	318	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	6.4% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$39,750.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	707B
Location:	Saybrook Dr - East				
X Coordinate:	-121.32089				
Y Coordinate:	38.70663				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF	
Description:	Change in level greater than 1/2"			
As Built Desc:	1" lip in sidewalk surface			
Solution:	Grind or repair sidewalk to remove trip hazard			
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				


Notes:	
--------	--

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	707C
Location:	Saybrook Dr - East				
X Coordinate:	-121.32088				
Y Coordinate:	38.70684				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	708A
Location:	Pompei Ct - West				
X Coordinate:	-121.31772				
Y Coordinate:	38.70709				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	364	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$45,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	708B
Location:	Pompei Ct - West				
X Coordinate:	-121.3177				
Y Coordinate:	38.70638				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	709
Location:	Pompei Ct - South				
X Coordinate:	-121.31766				
Y Coordinate:	38.70616				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	221	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	7.8% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$27,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	710
Location:	Pompei Ct - North				
X Coordinate:	-121.31722				
Y Coordinate:	38.70626				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	170	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	8.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$21,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	712
Location:	Pompei Ct and Pompei Ct - Corner B				
X Coordinate:	-121.31758				
Y Coordinate:	38.70689				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	13.3% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	Two - way intersection corners B,C
--------	------------------------------------

Field Date: ##### Report Date: 10/15/2010 Barrier #: 711

Location: Pompei Ct and Pompei Ct - Corner C

X Coordinate: -121.31761

Y Coordinate: 38.70675

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Exsiting Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 9.2% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: ##### Report Date: 10/15/2010 Barrier #: 713

Location: Pompei Ct - East


X Coordinate: -121.31759

Y Coordinate: 38.70696

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 46 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$5,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/15/2010 Barrier #: 714

Location: Saybrook Dr - East


X Coordinate: -121.32084

Y Coordinate: 38.70594

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 183 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$22,875.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/15/2010 Barrier #: 715

Location: Saybrook Dr and Pinecreek Wy - Corner B

X Coordinate: -121.32082

Y Coordinate: 38.7055

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	716
Location:	Saybrook Dr and Pinecreek Wy - Corner C				
X Coordinate:	-121.32087				
Y Coordinate:	38.70538				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	717
Location:	Saybrook Dr - East				
X Coordinate:	-121.32087				
Y Coordinate:	38.70536				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				




As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	718
Location:	Saybrook Dr - East				
X Coordinate:	-121.32087				
Y Coordinate:	38.70536				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	719
Location:	Saybrook Dr - East				
X Coordinate:	-121.32085				
Y Coordinate:	38.70516				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	459	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$57,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	720
Location:	Saybrook Dr and Pinecreek Wy - Corner B				
X Coordinate:	-121.32067				
Y Coordinate:	38.7039				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	721
Location:	Saybrook Dr and Pinecreek Wy - Corner C				
X Coordinate:	-121.32067				
Y Coordinate:	38.7038				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date: ##### Report Date: 10/15/2010 Barrier #: 722A

Location: Saybrook Dr - East


X Coordinate: -121.32065

Y Coordinate: 38.70372

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 405 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$50,625.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/15/2010 Barrier #: 722B

Location: Saybrook Dr - East

X Coordinate: -121.32042

Y Coordinate: 38.70275

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	723
Location:	Glenhurst Wy and Saybrook Dr - Corner B				
X Coordinate:	-121.32043				
Y Coordinate:	38.7026				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Two - way intersection corners B,C				

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	724
Location:	Glenhurst Wy and Saybrook Dr - Corner C				
X Coordinate:	-121.32035				
Y Coordinate:	38.70251				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Two - way intersection corners B,C				

Field Date: ##### Report Date: 10/15/2010 Barrier #: 725

Location: Saybrook Dr - East


X Coordinate: -121.32035

Y Coordinate: 38.70235

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 1012 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 12.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$126,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/15/2010 Barrier #: 726

Location: Saybrook Dr and Tupelo Dr - Corner A

X Coordinate: -121.31905

Y Coordinate: 38.69989

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Three - way intersection corners A,B,C

Field Date: ##### Report Date: 10/15/2010 Barrier #: 727

Location: Saybrook Dr and Tupelo Dr - Corner B

X Coordinate: -121.31893

Y Coordinate: 38.70001

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection corners A,B,C

Field Date: ##### Report Date: 10/15/2010 Barrier #: 728

Location: Saybrook Dr and Tupelo Dr - Corner C

X Coordinate: -121.31881

Y Coordinate: 38.69994

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection corners A,B,C

Field Date: ##### Report Date: 10/15/2010 Barrier #: 729A

Location: Tupelo Dr - North


X Coordinate: -121.31885

Y Coordinate: 38.70006

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 175 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 9.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$21,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/15/2010 Barrier #: 729B

Location: Tupelo Dr - North

X Coordinate: -121.31881

Y Coordinate: 38.7001

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/15/2010 Barrier #: 729C

Location: Tupelo Dr - North

X Coordinate: -121.31862

Y Coordinate: 38.70019

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/15/2010 Barrier #: 731

Location: Tupelo Dr and Mar Vista Wy - Corner A

X Coordinate: -121.31832

Y Coordinate: 38.70049

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Exsiting Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 10.7% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:


Notes: Two - way intersection corners A,D

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	730
Location:	Tupelo Dr and Mar Vista Wy - Corner D				
X Coordinate:	-121.31843				
Y Coordinate:	38.70042				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No compliant curb cut at corner (intersection)				
As Built Desc:	11.4% running slope at depressed area				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Two - way intersection corners A,D				

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	732A
Location:	Tupelo Dr - North				
X Coordinate:	-121.31827				
Y Coordinate:	38.70055				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	528	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.4% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$66,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	732B
Location:	Tupelo Dr - North				
X Coordinate:	-121.31779				
Y Coordinate:	38.70098				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ($\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	1	Quantity:	LF		
Description:	Pedestrian route is not min. 48" wide ($\leq 31"$ or less)				
As Built Desc:	24" clear width due to foliage				
Solution:	Trim foliage to provide min. 48" clear width				
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	733
Location:	Tupelo Dr and Wild Oak Dr - Corner A				
X Coordinate:	-121.3172				
Y Coordinate:	38.70173				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					


Notes:	Two - way intersection corners A,B				
--------	------------------------------------	--	--	--	--

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	734
Location:	Tupelo Dr and Wild Oak Dr - Corner B				
X Coordinate:	-121.31711				
Y Coordinate:	38.70185				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	735A
Location:	Tupelo Dr - North				
X Coordinate:	-121.31703				
Y Coordinate:	38.70191				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	282	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$35,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	735B
Location:	Tupelo Dr - North				
X Coordinate:	-121.31673				
Y Coordinate:	38.70219				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	736
Location:	Tupelo Dr and Stoneridge Wy - Corner A				
X Coordinate:	-121.31639				
Y Coordinate:	38.70242				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date: ##### Report Date: 10/15/2010 Barrier #: 737

Location: Tupelo Dr and Stoneridge Wy - Corner B


X Coordinate: -121.31629

Y Coordinate: 38.70248

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: ##### Report Date: 10/15/2010 Barrier #: 738A

Location: Tupelo Dr - North

X Coordinate: -121.31617

Y Coordinate: 38.70256

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 778 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$97,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/15/2010 Barrier #: 738B

Location: Tupelo Dr - North

X Coordinate: -121.31557

Y Coordinate: 38.70324

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 20" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary Cost Estimate: \$125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/15/2010 Barrier #: 738C

Location: Tupelo Dr - West

X Coordinate: -121.31555

Y Coordinate: 38.70338

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 28" clear width due to pole

Solution: Make alterations to provide min.. 32" clear width

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/15/2010 Barrier #: 738D

Location: Tupelo Dr - West

X Coordinate: -121.31559

Y Coordinate: 38.7038

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 30" clear width due to pole

Solution: Make alterations to provide min. 32" clear width

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/15/2010 Barrier #: 738E

Location: Tupelo Dr - West

X Coordinate: -121.31557

Y Coordinate: 38.70414

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 30" clear width due to pole

Solution: Make alterations to provide min. 32" clear width

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/15/2010 Barrier #: 738F

Location: Tupelo Dr - West

X Coordinate: -121.31556

Y Coordinate: 38.70437

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 8 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 30" clear width due to pole

Solution: Make alterations to provide min. 32" clear width

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/15/2010 Barrier #: 739

Location: Mango Tree Wy - West

X Coordinate: -121.32429

Y Coordinate: 38.70698

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 82 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$10,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	740
Location:	Mango Tree Wy and Woodglade Ave - Corner A				
X Coordinate:	-121.32425				
Y Coordinate:	38.70683				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	13.7% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	741
Location:	Mango Tree Wy and Woodglade Ave - Corner B				
X Coordinate:	-121.32403				
Y Coordinate:	38.70683				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	14.5% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	742
Location:	Woodglade Ave - North				
X Coordinate:	-121.32429				
Y Coordinate:	38.70681				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	345	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$43,125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	743A
Location:	Woodbriar Wy - South				
X Coordinate:	-121.32535				
Y Coordinate:	38.70597				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	41	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	8.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$5,125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	743B
Location:	Woodbriar Wy - South				
X Coordinate:	-121.32534				
Y Coordinate:	38.70597				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	8	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1/2" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	744
Location:	Woodbriar Wy - South				
X Coordinate:	-121.32453				
Y Coordinate:	38.70604				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	372	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$46,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	745
Location:	Woodbriar Way - East				
X Coordinate:	-121.3232				
Y Coordinate:	38.70606				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	211	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$26,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	746
Location:	Woodbriar Wy and Woodglade Ave - Corner C				
X Coordinate:	-121.32316				
Y Coordinate:	38.70665				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	11.6% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	Two - way intersection corners C,D
--------	------------------------------------

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	747
Location:	Woodbriar Wy and Woodglade Ave - Corner D				
X Coordinate:	-121.32325				
Y Coordinate:	38.70667				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				




As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	12.5% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners C,D		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	748
Location:	Woodbriar Wy - West				
X Coordinate:	-121.32327				
Y Coordinate:	38.70665				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	182	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$22,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	749A
Location:	Woodbriar Wy - North				
X Coordinate:	-121.32331				
Y Coordinate:	38.70618				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	356	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.2% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$44,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	749B
Location:	Woodbriar Wy - North				
X Coordinate:	-121.32345				
Y Coordinate:	38.70614				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing (32" to 35")				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	1	Quantity:	LF		
Description:	Pedestrian route is not min. 48" wide (32" to 35")				
As Built Desc:	35" clear width due to foliage				
Solution:	Trim foliage to provide min. 48" clear width				
Bar. Severity:	2 Recommended	Cost Estimate:	\$125.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	750A
Location:	Woodbriar Wy - East				
X Coordinate:	-121.32544				
Y Coordinate:	38.7062				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	602	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$75,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	750B
Location:	Woodbriar Wy - East				
X Coordinate:	-121.32536				
Y Coordinate:	38.7064				
Barrier Area:	Sidewalks				
Barrier Type:	Running Slope (New Construction)				
Code Ref:	CBC 1133B.7.3 and ADA/ABA 403.3				



As Built Meas:	30	Quantity:	LF
Description:	Running slope exceeds 5.0% where roadway slope does not		
As Built Desc:	6.7% running slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$3,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: ##### Report Date: 10/15/2010 Barrier #: 750C

Location: Woodbriar Wy - East

X Coordinate: -121.32513

Y Coordinate: 38.70663

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - Tree Heaves

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip due to tree heaves

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/15/2010 Barrier #: 751

Location: Woodglade Ave - South

X Coordinate: -121.32425

Y Coordinate: 38.70673

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 266 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$33,250.00 Status:


Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	752A
Location:	Woodglade Ave - South				
X Coordinate:	-121.3231				
Y Coordinate:	38.70665				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	322	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.1% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$40,250.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	752B
Location:	Woodglade Ave - South				
X Coordinate:	-121.32209				
Y Coordinate:	38.70673				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF		
Description:	Change in level greater than 1/2"				
As Built Desc:	1/2" lip in sidewalk surface				
Solution:	Grind or repair sidewalk to remove trip hazard				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	753
Location:	Blackthorne Wy and Woodglade Ave - Corner C				
X Coordinate:	-121.3218				
Y Coordinate:	38.70668				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners C,D		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	754
Location:	Blackthorne Wy and Woodglade Ave - Corner D				
X Coordinate:	-121.32194				
Y Coordinate:	38.70664				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners C,D		

Field Date: ##### Report Date: 10/15/2010 Barrier #: 755

Location: Blackthorne Wy - West


X Coordinate: -121.32191

Y Coordinate: 38.70657

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 221 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$27,625.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/15/2010 Barrier #: 756

Location: Blackthorne Wy and Len Ct - Corner A

X Coordinate: -121.32197

Y Coordinate: 38.70604

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 9.0% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	757
Location:	Blackthorne Wy and Len Ct - Corner D				
X Coordinate:	-121.32194				
Y Coordinate:	38.70595				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	10.7% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,D		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	758
Location:	Len Ct - North				
X Coordinate:	-121.322				
Y Coordinate:	38.70604				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	150	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.8% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$18,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	759
Location:	Len Ct - South				
X Coordinate:	-121.32232				
Y Coordinate:	38.70587				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	262	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$32,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	760
Location:	Blackthorne Wy - West				
X Coordinate:	-121.32191				
Y Coordinate:	38.70589				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	675	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$84,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	761
Location:	Blackthorne Wy - West				
X Coordinate:	-121.32191				
Y Coordinate:	38.70588				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF		
Description:	Change in level greater than 1/2"				
As Built Desc:	1/2" lip in sidewalk surface				
Solution:	Grind or repair sidewalk to remove trip hazard				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	762
Location:	Blackthorne Wy - West				
X Coordinate:	-121.32179				
Y Coordinate:	38.70385				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	654	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.5% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$81,750.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	763
Location:	Blackthorne Wy and Birchglade Wy - Corner A				
X Coordinate:	-121.32133				
Y Coordinate:	38.70205				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	13.5% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	764
Location:	Blackthorne Wy and Birchglade Wy - Corner B				
X Coordinate:	-121.3212				
Y Coordinate:	38.70208				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	16.7% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	765
Location:	Blackthorne Wy and Birchglade Wy - Corner C				
X Coordinate:	-121.32115				
Y Coordinate:	38.70195				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	15.9% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	766
Location:	Blackthorne Wy and Birchglade Wy - Corner D				
X Coordinate:	-121.32132				
Y Coordinate:	38.70193				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	15.1% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	767
Location:	Birchglade Wy - North				
X Coordinate:	-121.32142				
Y Coordinate:	38.70203				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	511	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$63,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	768
Location:	Birchglade Wy and Rigging Ct - Corner A				
X Coordinate:	-121.32346				
Y Coordinate:	38.70178				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.0% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	Two - way intersection corners A,B
--------	------------------------------------

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	769
Location:	Birchglade Wy and Rigging Ct - Corner B				
X Coordinate:	-121.32319				
Y Coordinate:	38.70181				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	12.5% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	770
Location:	Rigging Ct - East				
X Coordinate:	-121.32324				
Y Coordinate:	38.70183				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	102	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$12,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	771
Location:	Rigging Ct - West				
X Coordinate:	-121.32337				
Y Coordinate:	38.70202				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	119	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$14,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	772
Location:	Birchglade Wy - North				
X Coordinate:	-121.32346				
Y Coordinate:	38.70171				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	220	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$27,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	773
Location:	Birchglade Wy and Ketch Ct - Corner A				
X Coordinate:	-121.32446				
Y Coordinate:	38.70175				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.7% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	774
Location:	Birchglade Wy and Ketch Ct - Corner B				
X Coordinate:	-121.3243				
Y Coordinate:	38.70171				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.0% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	775
Location:	Ketch Ct - East				
X Coordinate:	-121.32431				
Y Coordinate:	38.70177				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	123	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$15,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	776
Location:	Ketch Ct - West				
X Coordinate:	-121.3244				
Y Coordinate:	38.70201				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	123	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$15,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	777
Location:	Birchglade Wy - North				
X Coordinate:	-121.32444				
Y Coordinate:	38.7017				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	215	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$26,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	778
Location:	Birchglade Wy and Sloop Ct -Corner A				
X Coordinate:	-121.32543				
Y Coordinate:	38.70173				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	11.8% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	Two - way intersection corners A,B
--------	------------------------------------

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	779
Location:	Birchglade Wy and Sloop Ct -Corner B				
X Coordinate:	-121.32526				
Y Coordinate:	38.70172				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	11.1% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	780
Location:	Sloop Ct - East				
X Coordinate:	-121.32529				
Y Coordinate:	38.70177				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	109	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$13,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	781
Location:	Sloop Ct - East				
X Coordinate:	-121.32529				
Y Coordinate:	38.70177				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	109	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$13,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	782
Location:	Sloop Ct - West				
X Coordinate:	-121.32543				
Y Coordinate:	38.70198				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	104	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$13,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	783
Location:	Birchglade Wy - North				
X Coordinate:	-121.32551				
Y Coordinate:	38.7017				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	204	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$25,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	784
Location:	Birchglade Wy and Daly Ave - Corner B				
X Coordinate:	-121.32624				
Y Coordinate:	38.70173				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.5% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	785
Location:	Birchglade Wy and Daly Ave - Corner C				
X Coordinate:	-121.32625				
Y Coordinate:	38.70154				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.7% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	786
Location:	Daly Ave - East				
X Coordinate:	-121.32626				
Y Coordinate:	38.70181				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	285	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$35,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	787
Location:	Daly Ave - East				
X Coordinate:	-121.32619				
Y Coordinate:	38.70545				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	58	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$7,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	788
Location:	Birchglade Wy - South				
X Coordinate:	-121.32621				
Y Coordinate:	38.70156				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	1397	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$174,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	789
Location:	Blackthorn Wy - West				
X Coordinate:	-121.32127				
Y Coordinate:	38.70187				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	182	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$22,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	790
Location:	Blackthorn Wy - West				
X Coordinate:	-121.32118				
Y Coordinate:	38.70164				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1/2" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	791
Location:	Blackthorn Wy and Miravale Ct - Corner A				
X Coordinate:	-121.32116				
Y Coordinate:	38.70132				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	15.4% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,D		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	792
Location:	Blackthorn Wy and Miravale Ct - Corner D				
X Coordinate:	-121.32111				
Y Coordinate:	38.7012				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	14.7% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,D		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	793A
Location:	Miravale Ct - North				
X Coordinate:	-121.32122				
Y Coordinate:	38.70132				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	413	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.9% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$51,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	793B
Location:	Miravale Ct - North				
X Coordinate:	-121.32233				
Y Coordinate:	38.70116				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	4	Quantity:	LF
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)		
As Built Desc:	Cracked concrete		
Solution:	Repair surface to make firm and stable		
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	794
Location:	Miravale Ct - South				
X Coordinate:	-121.32245				
Y Coordinate:	38.70095				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	399	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.7% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$49,875.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	795
Location:	Blackthorn Wy - West				
X Coordinate:	-121.32109				
Y Coordinate:	38.7012				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	581	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	6.2% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$72,625.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	796
Location:	Blackthorn Wy and Springvale Wy - Corner A				
X Coordinate:	-121.32086				
Y Coordinate:	38.70068				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	14.2% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,D		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	797
Location:	Blackthorn Wy and Springvale Wy - Corner D				
X Coordinate:	-121.32079				
Y Coordinate:	38.70062				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	13.1% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,D		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	798
Location:	Springvale Wy - North				
X Coordinate:	-121.32088				
Y Coordinate:	38.7007				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	456	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.9% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$57,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	799
Location:	Springvale Wy - West				
X Coordinate:	-121.32247				
Y Coordinate:	38.70022				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	172	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$21,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	800
Location:	Springvale Wy and Parkvale Wy - Corner A				
X Coordinate:	-121.32249				
Y Coordinate:	38.69971				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	15.3% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	801
Location:	Springvale Wy and Parkvale Wy - Corner B				
X Coordinate:	-121.32236				
Y Coordinate:	38.69966				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	14.9% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	802
Location:	Parkvale Wy - North				
X Coordinate:	-121.32252				
Y Coordinate:	38.69968				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	263	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$32,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	803
Location:	Parkvale Wy - West				
X Coordinate:	-121.32344				
Y Coordinate:	38.69965				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	242	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$30,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	804
Location:	Parkvale Wy and Tupelo Dr - Corner A				
X Coordinate:	-121.32356				
Y Coordinate:	38.69897				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No compliant curb cut at corner (intersection)				
As Built Desc:	13.4% running slope at depressed area				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Four - way intersection corners A,B,C,D				

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	805
Location:	Parkvale Wy and Tupelo Dr - Corner B				
X Coordinate:	-121.32338				
Y Coordinate:	38.69897				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No compliant curb cut at corner (intersection)				
As Built Desc:	12.7% running slope at depressed area				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Four - way intersection corners A,B,C,D				

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	806
Location:	Parkvale Wy and Tupelo Dr - Corner C				
X Coordinate:	-121.32334				
Y Coordinate:	38.69881				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	12.9% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	807
Location:	Parkvale Wy and Tupelo Dr - Corner D				
X Coordinate:	-121.32354				
Y Coordinate:	38.69883				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	14.1% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	808
Location:	Tupelo Dr - North				
X Coordinate:	-121.32331				
Y Coordinate:	38.69898				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	487	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.9% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$60,875.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	809
Location:	Tupelo Dr - North				
X Coordinate:	-121.32153				
Y Coordinate:	38.69901				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	231	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.5% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$28,875.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	810
Location:	Tupelo Dr - North				
X Coordinate:	-121.32152				
Y Coordinate:	38.69901				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ($\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	1	Quantity:	LF
Description:	Pedestrian route is not min. 48" wide ($\leq 31"$ or less)		
As Built Desc:	30" clear width due to foliage		
Solution:	Trim foliage to provide min. 48" clear width		
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/15/2010	Barrier #:	811
Location:	Tupelo Dr and Parkvale Wy - Corner A				
X Coordinate:	-121.32081				
Y Coordinate:	38.69918				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	13.7% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	Two - way intersection corners A,B
--------	------------------------------------

Field Date: ##### Report Date: 10/15/2010 Barrier #: 812

Location: Tupelo Dr and Parkvale Wy - Corner B

X Coordinate: -121.32057

Y Coordinate: 38.69917

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Exsiting Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 15.6% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: ##### Report Date: 10/18/2010 Barrier #: 819C

Location: Parkvale Wy - North

X Coordinate: -121.32223

Y Coordinate: 38.6996

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	820
Location:	Springvale Wy - East				
X Coordinate:	-121.32238				
Y Coordinate:	38.69964				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	175	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$21,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	821
Location:	Springvale Wy - East				
X Coordinate:	-121.32236				
Y Coordinate:	38.70019				
Barrier Area:	Sidewalks				
Barrier Type:	Elbow in Sidewalk - Cross Slope (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	6	Quantity:	LF
Description:	Cross slope at elbow exceeds 2.0% (5.0% or more)		
As Built Desc:	13.7% cross slope		
Solution:	Demolish existing and construct new sidewalk without curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	822
Location:	Springvale Wy - South				
X Coordinate:	-121.32226				
Y Coordinate:	38.70021				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	451	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$56,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	823
Location:	Blackthorne Wy - West				
X Coordinate:	-121.32074				
Y Coordinate:	38.70051				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	514	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$64,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	824
Location:	Blackthorne Wy and Tupelo Dr - Corner A				
X Coordinate:	-121.31975				
Y Coordinate:	38.69936				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No compliant curb cut at corner (intersection)				
As Built Desc:	12.5% running slope at depressed area				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Two - way intersection corners A,B				

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	825A
Location:	Blackthorne Wy and Tupelo Dr - Corner B				
X Coordinate:	-121.31962				
Y Coordinate:	38.69944				
Barrier Area:	Curb Ramps				
Barrier Type:	Parallel Ramp Landing - New Construction				
Code Ref:	CBC 1127B.5.9 and ADA/ABA 406.4				



As Built Meas:	1	Quantity:	EACH		
Description:	Curb ramp pan is not level (2.0% in all directions)				
As Built Desc:	3.1% landing slope				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Two - way intersection corners A,B				

Field Date: ##### Report Date: 10/18/2010 Barrier #: 825B

Location: Blackthorne Wy and Tupelo Dr - Corner B

X Coordinate: -121.31962

Y Coordinate: 38.69944

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$0.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: ##### Report Date: 10/18/2010 Barrier #: 825C

Location: Blackthorne Wy and Tupelo Dr - Corner B

X Coordinate: -121.31962

Y Coordinate: 38.69944

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.9% - 6.5%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.9% - 6.5%)

As Built Desc: 6.5% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 3 Hindrance

Cost Estimate: \$0.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	826A
Location:	Tupelo Dr - North				
X Coordinate:	-121.31966				
Y Coordinate:	38.69939				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	264	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	6.6% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$33,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	826B
Location:	Tupelo Dr - North				
X Coordinate:	-121.3204				
Y Coordinate:	38.69922				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF		
Description:	Change in level greater than 1/2"				
As Built Desc:	1/2" lip in sidewalk surface				
Solution:	Grind or repair sidewalk to remove trip hazard				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	827
Location:	Tupelo Dr - North				
X Coordinate:	-121.3236				
Y Coordinate:	38.69898				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	180	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$22,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	828
Location:	Tupelo Dr and Windjammer Wy - Corner A				
X Coordinate:	-121.32436				
Y Coordinate:	38.69898				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	6.5% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	829
Location:	Tupelo Dr and Windjammer Wy - Corner B				
X Coordinate:	-121.32427				
Y Coordinate:	38.69894				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No compliant curb cut at corner (intersection)				
As Built Desc:	9.8% running slope at depressed area				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Four - way intersection corners A,B,C,D				

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	830
Location:	Tupelo Dr and Windjammer Wy - Corner C				
X Coordinate:	-121.32422				
Y Coordinate:	38.6988				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No compliant curb cut at corner (intersection)				
As Built Desc:	9.7% running slope at depressed area				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Four - way intersection corners A,B,C,D				

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	831
Location:	Tupelo Dr and Windjammer Wy - Corner D				
X Coordinate:	-121.32437				
Y Coordinate:	38.69884				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.5% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	832
Location:	Tupelo Dr - North				
X Coordinate:	-121.32445				
Y Coordinate:	38.69896				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	589	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.8% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$73,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	833
Location:	Tupelo Dr and Daly Ave - Corner A				
X Coordinate:	-121.32664				
Y Coordinate:	38.69851				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No compliant curb cut at corner (intersection)				
As Built Desc:	9.6% running slope at depressed area				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Two - way intersection corners A,B				

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	834
Location:	Tupelo Dr and Daly Ave - Corner B				
X Coordinate:	-121.32639				
Y Coordinate:	38.69858				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No compliant curb cut at corner (intersection)				
As Built Desc:	8.8% running slope at depressed area				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Two - way intersection corners A,B				

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	835
Location:	Daly Ave - East				
X Coordinate:	-121.32643				
Y Coordinate:	38.69856				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	596	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$74,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	836
Location:	Daly Ave and Trawler Wy - Corner B				
X Coordinate:	-121.3263				
Y Coordinate:	38.70033				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	7.5% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	Two - way intersection corners B,C
--------	------------------------------------

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	837
Location:	Daly Ave and Trawler Wy - Corner C				
X Coordinate:	-121.32626				
Y Coordinate:	38.70023				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	7.7% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	838
Location:	Daly Ave - East				
X Coordinate:	-121.32631				
Y Coordinate:	38.70032				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	181	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$22,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	839
Location:	Daly Ave and Windjammer Wy - Corner B				
X Coordinate:	-121.32625				
Y Coordinate:	38.70098				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	7.7% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	840
Location:	Daly Ave and Windjammer Wy - Corner C				
X Coordinate:	-121.32626				
Y Coordinate:	38.70089				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	10.9% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	841
Location:	Daly Ave - East				
X Coordinate:	-121.32627				
Y Coordinate:	38.70107				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	189	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.1% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$23,625.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	842
Location:	Windjammer Wy - North				
X Coordinate:	-121.32623				
Y Coordinate:	38.70095				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	554	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.6% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$69,250.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	843A
Location:	Windjammer Wy - East				
X Coordinate:	-121.32428				
Y Coordinate:	38.70099				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	210	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	8.0% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$26,250.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	843B
Location:	Windjammer Wy - East				
X Coordinate:	-121.32421				
Y Coordinate:	38.70082				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - New Construction				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	1	Quantity:	LF	
Description:	Pedestrian route is not min. 48" wide			
As Built Desc:	24" clear width due to foliage			
Solution:	Trim foliage to provide min. 48" clear width			
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date: ##### Report Date: 10/18/2010 Barrier #: 843C

Location: Windjammer Wy - East

X Coordinate: -121.3242

Y Coordinate: 38.70078

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 4 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary

Cost Estimate: \$500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/18/2010 Barrier #: 844

Location: Windjammer Wy and Windlass Ct - Corner A

X Coordinate: -121.32434

Y Coordinate: 38.70038

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 7.9% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Four - way intersection corners A,B,C,D

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	845
Location:	Windjammer Wy and Windlass Ct - Corner B				
X Coordinate:	-121.32419				
Y Coordinate:	38.70038				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	6.2% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	846
Location:	Windjammer Wy and Windlass Ct - Corner C				
X Coordinate:	-121.32419				
Y Coordinate:	38.70027				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.3% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	847
Location:	Windjammer Wy and Windlass Ct - Corner D				
X Coordinate:	-121.32433				
Y Coordinate:	38.70026				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	8.1% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Four - way intersection corners A,B,C,D		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	848
Location:	Windlass Ct - North				
X Coordinate:	-121.32415				
Y Coordinate:	38.70035				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	226	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$28,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	849
Location:	Windlass Ct - North				
X Coordinate:	-121.3234				
Y Coordinate:	38.7004				
Barrier Area:	Sidewalks				
Barrier Type:	Elbow in Sidewalk - Cross Slope (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	10	Quantity:	LF
Description:	Cross slope at elbow exceeds 2.0% (5.0% or more)		
As Built Desc:	8.0% cross slope		
Solution:	Demolish existing and construct new sidewalk without curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	850
Location:	Windlass Ct - West				
X Coordinate:	-121.32339				
Y Coordinate:	38.70044				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	259	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$32,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	851
Location:	Windless Ct - East				
X Coordinate:	-121.32331				
Y Coordinate:	38.70101				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	529	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$66,125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	852
Location:	Windless Ct - East				
X Coordinate:	-121.32334				
Y Coordinate:	38.70031				
Barrier Area:	Sidewalks				
Barrier Type:	Elbow in Sidewalk - Cross Slope (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	10	Quantity:	LF
Description:	Cross slope at elbow exceeds 2.0% (5.0% or more)		
As Built Desc:	9.2% cross slope		
Solution:	Demolish existing and construct new sidewalk without curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	853
Location:	Windless Ct - South				
X Coordinate:	-121.32334				
Y Coordinate:	38.70031				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	245	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$30,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	854
Location:	Windjammer Wy - East				
X Coordinate:	-121.32422				
Y Coordinate:	38.70022				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	428	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$53,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	855
Location:	Windjammer Wy - East				
X Coordinate:	-121.32433				
Y Coordinate:	38.69908				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	183	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$22,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	856
Location:	Windjammer Wy and Whaler Ct - Corner A				
X Coordinate:	-121.3244				
Y Coordinate:	38.69969				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.4% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	Two - way intersection corners A,D
--------	------------------------------------

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	857
Location:	Windjammer Wy and Whaler Ct - Corner D				
X Coordinate:	-121.32435				
Y Coordinate:	38.69958				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	8.7% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,D		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	858
Location:	Whaler Ct - South				
X Coordinate:	-121.32444				
Y Coordinate:	38.69961				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	315	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	4.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$39,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: ##### Report Date: 10/18/2010 Barrier #: 859

Location: Whaler Ct - North

X Coordinate: -121.32438

Y Coordinate: 38.6997

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing (32" to 35")

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide (32" to 35")

As Built Desc: 35" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 2 Recommended Cost Estimate: \$125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/18/2010 Barrier #: 860

Location: Windjammer Wy - West

X Coordinate: -121.3243

Y Coordinate: 38.69973

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 174 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 4.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$21,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	861A
Location:	Trawler Wy - South				
X Coordinate:	-121.32444				
Y Coordinate:	38.70027				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	531	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.5% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$66,375.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	861B
Location:	Trawler Wy - South				
X Coordinate:	-121.3248				
Y Coordinate:	38.70026				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF		
Description:	Change in level greater than 1/2"				
As Built Desc:	1/2" lip in sidewalk surface				
Solution:	Grind or repair sidewalk to remove trip hazard				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date: ##### Report Date: 10/18/2010 Barrier #: 862

Location: Trawler Wy - North

X Coordinate: -121.32618

Y Coordinate: 38.70035

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 519 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 4.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$64,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/18/2010 Barrier #: 863

Location: Windjammer Wy - West

X Coordinate: -121.32434

Y Coordinate: 38.70042

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 134 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$16,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	864
Location:	Windjammer Wy - West				
X Coordinate:	-121.32435				
Y Coordinate:	38.70091				
Barrier Area:	Sidewalks				
Barrier Type:	Elbow in Sidewalk - Cross Slope (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	10	Quantity:	LF
Description:	Cross slope at elbow exceeds 2.0% (5.0% or more)		
As Built Desc:	10.9% cross slope		
Solution:	Demolish existing and construct new sidewalk without curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	865
Location:	Windjammer Wy - South				
X Coordinate:	-121.3244				
Y Coordinate:	38.70093				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	520	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$65,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: ##### Report Date: 10/18/2010 Barrier #: 866A

Location: Tupelo Dr - South

X Coordinate: -121.32623

Y Coordinate: 38.69842

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 264 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$33,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/18/2010 Barrier #: 866B

Location: Tupelo Dr - South

X Coordinate: -121.32621

Y Coordinate: 38.69841

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 24" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary Cost Estimate: \$125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/18/2010 Barrier #: 867

Location: Tupelo Dr and Catermaran Dr - Corner C

X Coordinate: -121.32515

Y Coordinate: 38.6987

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$1,400.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D

Field Date: ##### Report Date: 10/18/2010 Barrier #: 868A

Location: Tupelo Dr and Catermaran Dr - Corner D

X Coordinate: -121.32538

Y Coordinate: 38.69857

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.5% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D

Field Date: ##### Report Date: 10/18/2010 Barrier #: 868B

Location: Tupelo Dr and Catermaran Dr - Corner D

X Coordinate: -121.32538

Y Coordinate: 38.69857

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$0.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D

Field Date: ##### Report Date: 10/18/2010 Barrier #: 869

Location: Catamaran Dr - West

X Coordinate: -121.32527

Y Coordinate: 38.69856

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 242 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$30,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	870
Location:	Catamaran Dr and Catboat Cir - Corner A				
X Coordinate:	-121.32529				
Y Coordinate:	38.69787				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Two - way intersection corners A,D				

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	871A
Location:	Catamaran Dr and Catboat Cir - Corner D				
X Coordinate:	-121.32527				
Y Coordinate:	38.69776				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH		
Description:	12" grooves at top of curb ramp are not level (3.1% to 4.0%)				
As Built Desc:	3.9% at 12" grooves				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Two - way intersection corners A,D				

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	871B
Location:	Catamaran Dr and Catboat Cir - Corner D				
X Coordinate:	-121.32527				
Y Coordinate:	38.69776				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				
As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Two - way intersection corners A,D				



Field Date:	#####	Report Date:	10/18/2010	Barrier #:	872
Location:	Catboat Cir - North				
X Coordinate:	-121.32536				
Y Coordinate:	38.69787				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				
As Built Meas:	221	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.7% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$27,625.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					



Field Date:	#####	Report Date:	10/18/2010	Barrier #:	873
Location:	Catboat Cir - North				
X Coordinate:	-121.32612				
Y Coordinate:	38.69785				
Barrier Area:	Sidewalks				
Barrier Type:	Elbow in Sidewalk - Cross Slope (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	10	Quantity:	LF		
Description:	Cross slope at elbow exceeds 2.0% (5.0% or more)				
As Built Desc:	8.1% cross slope				
Solution:	Demolish existing and construct new sidewalk without curb ramp				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,250.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	874
Location:	Catboat Cir - West				
X Coordinate:	-121.32615				
Y Coordinate:	38.69781				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	470	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.2% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$58,750.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	875
Location:	Catboat Cir - West				
X Coordinate:	-121.32615				
Y Coordinate:	38.69651				
Barrier Area:	Sidewalks				
Barrier Type:	Elbow in Sidewalk - Cross Slope (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	10	Quantity:	LF
Description:	Cross slope at elbow exceeds 2.0% (5.0% or more)		
As Built Desc:	12.5% cross slope		
Solution:	Demolish existing and construct new sidewalk without curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	876
Location:	Catboat Cir - South				
X Coordinate:	-121.32615				
Y Coordinate:	38.69651				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	215	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$26,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	877
Location:	Catboat Cir - North				
X Coordinate:	-121.32537				
Y Coordinate:	38.69661				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	183	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$22,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	878
Location:	Catboat Cir - North				
X Coordinate:	-121.32599				
Y Coordinate:	38.69664				
Barrier Area:	Sidewalks				
Barrier Type:	Elbow in Sidewalk - Cross Slope (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	10	Quantity:	LF
Description:	Cross slope at elbow exceeds 2.0% (5.0% or more)		
As Built Desc:	10.5% cross slope		
Solution:	Demolish existing and construct new sidewalk without curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	879
Location:	Catboat Cir - East				
X Coordinate:	-121.32601				
Y Coordinate:	38.69665				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	415	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.2% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$51,875.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	880
Location:	Catboat Cir - East				
X Coordinate:	-121.32599				
Y Coordinate:	38.69775				
Barrier Area:	Sidewalks				
Barrier Type:	Elbow in Sidewalk - Cross Slope (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	10	Quantity:	LF	
Description:	Cross slope at elbow exceeds 2.0% (5.0% or more)			
As Built Desc:	11.7% cross slope			
Solution:	Demolish existing and construct new sidewalk without curb ramp			
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,250.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	881
Location:	Catboat Cir - South				
X Coordinate:	-121.32596				
Y Coordinate:	38.69776				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	185	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$23,125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	882
Location:	Catamaran Dr - West				
X Coordinate:	-121.32526				
Y Coordinate:	38.69771				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	412	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$51,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	883
Location:	Catamaran Dr - West				
X Coordinate:	-121.32529				
Y Coordinate:	38.69643				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	330	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$41,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	884
Location:	Catamaran Dr and Yawl Ct - Corner A				
X Coordinate:	-121.32574				
Y Coordinate:	38.69561				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH
Description:	No truncated domes provided at curb ramp		
As Built Desc:	No detectable warnings at curb ramp		
Solution:	Provide compliant truncated domes		
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	Two - way intersection corners A,D
--------	------------------------------------

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	885
Location:	Catamaran Dr and Yawl Ct - Corner D				
X Coordinate:	-121.32586				
Y Coordinate:	38.69554				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH
Description:	No truncated domes provided at curb ramp		
As Built Desc:	No detectable warnings at curb ramp		
Solution:	Provide compliant truncated domes		
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,D		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	886
Location:	Yawl Ct - North				
X Coordinate:	-121.32578				
Y Coordinate:	38.6956				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	158	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$19,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	887
Location:	Yawl Ct - South				
X Coordinate:	-121.32612				
Y Coordinate:	38.69575				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	95	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.9% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$11,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	888
Location:	Catamaran Dr - West				
X Coordinate:	-121.32585				
Y Coordinate:	38.69553				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				




As Built Meas:	177	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$22,125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	889
Location:	Catamaran Dr and Pikes Peak Wy - Corner B				
X Coordinate:	-121.32599				
Y Coordinate:	38.6953				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH
Description:	No truncated domes provided at curb ramp		
As Built Desc:	No detectable warnings at curb ramp		
Solution:	Provide compliant truncated domes		
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	890A
Location:	Catamaran Dr and Pikes Peak Wy - Corner C				
X Coordinate:	-121.3262				
Y Coordinate:	38.69525				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (4.1% to 4.9%)		
As Built Desc:	4.1% at 12" grooves		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	2 Recommended	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date: ##### Report Date: 10/18/2010 Barrier #: 890B

Location: Catamaran Dr and Pikes Peak Wy - Corner C

X Coordinate: -121.3262

Y Coordinate: 38.69525

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: ##### Report Date: 10/18/2010 Barrier #: 891

Location: Pikes Peak Wy - South

X Coordinate: -121.32618

Y Coordinate: 38.69473

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 592 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$74,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	892
Location:	Pikes Peak Wy - West				
X Coordinate:	-121.32615				
Y Coordinate:	38.69314				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	121	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.8% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$15,125.00
Status:			
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	893
Location:	Pikes Peak Wy - East				
X Coordinate:	-121.32658				
Y Coordinate:	38.693				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	130	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$16,250.00
Status:			
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date: ##### Report Date: 10/18/2010 Barrier #: 894

Location: Pikes Peak Wy - North

X Coordinate: -121.32616

Y Coordinate: 38.6931

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 400 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$50,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/18/2010 Barrier #: 895

Location: Pikes Peak Wy and Sassy Ct - Corner B

X Coordinate: -121.32601

Y Coordinate: 38.69418

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 8.9% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	896
Location:	Pikes Peak Wy and Sassy Ct - Corner C				
X Coordinate:	-121.32603				
Y Coordinate:	38.69409				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.2% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	897
Location:	Sassy Ct - East				
X Coordinate:	-121.32596				
Y Coordinate:	38.69412				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	208	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$26,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	898
Location:	Sassy Ct - West				
X Coordinate:	-121.32535				
Y Coordinate:	38.69417				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	227	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.9% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$28,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	899
Location:	Pikes Peak Wy - East				
X Coordinate:	-121.32602				
Y Coordinate:	38.69424				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	187	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$23,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	900
Location:	Pikes Peak Wy and Desiree Ct - Corner B				
X Coordinate:	-121.32602				
Y Coordinate:	38.69488				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.3% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	901
Location:	Pikes Peak Wy and Desiree Ct - Corner C				
X Coordinate:	-121.32599				
Y Coordinate:	38.69478				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.5% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	902
Location:	Desiree Ct - East				
X Coordinate:	-121.32598				
Y Coordinate:	38.69479				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	366	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.7% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$45,750.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	903
Location:	Desiree Ct - West				
X Coordinate:	-121.32473				
Y Coordinate:	38.6948				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	410	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.9% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$51,250.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	904
Location:	Pikes Peak Wy - East				
X Coordinate:	-121.32599				
Y Coordinate:	38.69489				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	137	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	4.0% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$17,125.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	905A
Location:	Catamaran Dr - East				
X Coordinate:	-121.32599				
Y Coordinate:	38.69527				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	222	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.0% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$27,750.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	905B
Location:	Catamaran Dr - East				
X Coordinate:	-121.32554				
Y Coordinate:	38.69554				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - Tree Heaves				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF	
Description:	Change in level greater than 1/2"			
As Built Desc:	1/2" lip due to tree heaves			
Solution:	Grind or repair sidewalk to remove trip hazard			
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	906
Location:	Catamaran Dr and Parkvale - Corner B				
X Coordinate:	-121.32528				
Y Coordinate:	38.69577				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Two - way intersection corners B,C			

Field Date: ##### Report Date: 10/18/2010 Barrier #: 907

Location: Catamaran Dr and Parkvale - Corner C

X Coordinate: -121.32534

Y Coordinate: 38.69569

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: ##### Report Date: 10/18/2010 Barrier #: 908

Location: Catamaran Dr - East

X Coordinate: -121.3253

Y Coordinate: 38.69579

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 225 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$28,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	909A
Location:	Catamaran Dr - East				
X Coordinate:	-121.32513				
Y Coordinate:	38.6966				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	184	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$23,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	909B
Location:	Catamaran Dr - East				
X Coordinate:	-121.3251				
Y Coordinate:	38.69672				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - Tree Heaves				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1/2" lip due to tree heaves		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	910
Location:	Catamaran Dr and Windjammer Wy - Corner B				
X Coordinate:	-121.32513				
Y Coordinate:	38.69725				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes (New Const)				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH
Description:	No truncated domes provided at curb ramp		
As Built Desc:	No detectable warnings at curb ramp - New Construction		
Solution:	Provide compliant truncated domes		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,400.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	911A
Location:	Catamaran Dr and Windjammer Wy - Corner C				
X Coordinate:	-121.32508				
Y Coordinate:	38.69718				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - New Construction				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (3.1% to 4.0%)		
As Built Desc:	3.3% at 12" grooves		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date: ##### Report Date: 10/18/2010 Barrier #: 911B

Location: Catamaran Dr and Windjammer Wy - Corner C

X Coordinate: -121.32508

Y Coordinate: 38.69718

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes (New Const)

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp - New Construction

Solution: Provide compliant truncated domes

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: ##### Report Date: 10/18/2010 Barrier #: 912

Location: Catamaran Dr - East

X Coordinate: -121.32512

Y Coordinate: 38.69729

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 497 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$62,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/18/2010 Barrier #: 913A

Location: Millwood Dr - South


X Coordinate: -121.31572

Y Coordinate: 38.7045

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 541 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$67,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/18/2010 Barrier #: 913B

Location: Millwood Dr - South

X Coordinate: -121.31593

Y Coordinate: 38.70449

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	914
Location:	Millwood Dr and Glenhurst Wy - Corner C				
X Coordinate:	-121.31739				
Y Coordinate:	38.70488				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	13.1% running slopeat depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners C,D		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	915
Location:	Millwood Dr and Glenhurst Wy - Corner D				
X Coordinate:	-121.3176				
Y Coordinate:	38.70499				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	13.4% running slopeat depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners C,D		

Field Date: ##### Report Date: 10/18/2010 Barrier #: 916

Location: Millwood Dr - South

X Coordinate: -121.3177

Y Coordinate: 38.705

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 199 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.4% cross slope

Solution: Demolish existing and construct new route


Bar. Severity: 2 Recommended Cost Estimate: \$24,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: ##### Report Date: 10/18/2010 Barrier #: 917

Location: Bierston St - East

X Coordinate: -121.31852

Y Coordinate: 38.70486

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 729 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new route


Bar. Severity: 2 Recommended Cost Estimate: \$91,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date:	#####	Report Date:	10/18/2010	Barrier #:	918
Location:	Bierston St - South				
X Coordinate:	-121.31962				
Y Coordinate:	38.70333				
Barrier Area:	Sidewalks				
Barrier Type:	Elbow in Sidewalk - Cross Slope (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	6	Quantity:	LF
Description:	Cross slope at elbow exceeds 2.0% (5.0% or more)		
As Built Desc:	9.3% cross slope		
Solution:	Demolish existing and construct new sidewalk without curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	919
Location:	Bierston St and Glenhurst Wy - Corner A				
X Coordinate:	-121.31972				
Y Coordinate:	38.70277				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	11.8% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,B		

Field Date: ##### Report Date: 10/18/2010 Barrier #: 920

Location: Bierston St and Glenhurst Wy - Corner B

X Coordinate: -121.31958

Y Coordinate: 38.70283

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Exsiting Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 12.1% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date: ##### Report Date: 10/18/2010 Barrier #: 921

Location: Glenhurst Wy - West


X Coordinate: -121.31977

Y Coordinate: 38.70271

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 175 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$21,875.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	922
Location:	Pinecreek Ct and Pinecreek Wy - Corner A				
X Coordinate:	-121.31954				
Y Coordinate:	38.70467				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				







As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	12.3% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,D		



Field Date:	#####	Report Date:	10/18/2010	Barrier #:	923
Location:	Pinecreek Ct and Pinecreek Wy - Corner D				
X Coordinate:	-121.31956				
Y Coordinate:	38.70457				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				





As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	13.7% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,D		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	924	
Location:	Pinecreek Wy - West					
X Coordinate:	-121.31951					
Y Coordinate:	38.70474					
Barrier Area:	Sidewalks					
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)					
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3					
As Built Meas:	213		Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)					
As Built Desc:	4.7% cross slope					
Solution:	Demolish existing and construct new route					
Bar. Severity:	2 Recommended		Cost Estimate:	\$26,625.00	Status:	
Implementation Priority:	4		Facility Function:			
Implementation Phase:			Implementation Date:			
Official Responsible:						
Notes:						

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	925	
Location:	Pinecreek Wy - West					
X Coordinate:	-121.31949					
Y Coordinate:	38.70479					
Barrier Area:	Sidewalks					
Barrier Type:	Abrupt Change in Level - > 1/2"					
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3					
As Built Meas:	4		Quantity:	LF		
Description:	Change in level greater than 1/2"					
As Built Desc:	1" lip in sidewalk surface					
Solution:	Grind or repair sidewalk to remove trip hazard					
Bar. Severity:	1 Necessary		Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	4		Facility Function:			
Implementation Phase:			Implementation Date:			
Official Responsible:						
Notes:						

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	926	
Location:	Pinecreek Wy - South					
X Coordinate:	-121.31976					
Y Coordinate:	38.70537					
Barrier Area:	Sidewalks					
Barrier Type:	Cross Slope - Existing (5.0% or more)					
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3					
As Built Meas:	313		Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)					
As Built Desc:	10.8% cross slope					
Solution:	Demolish existing and construct new route					
Bar. Severity:	1 Necessary		Cost Estimate:	\$39,125.00	Status:	
Implementation Priority:	4		Facility Function:			
Implementation Phase:			Implementation Date:			
Official Responsible:						
Notes:						

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	927	
Location:	Pinecreek Wy - North					
X Coordinate:	-121.32037					
Y Coordinate:	38.70549					
Barrier Area:	Sidewalks					
Barrier Type:	Cross Slope - Existing (5.0% or more)					
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3					
As Built Meas:	283		Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)					
As Built Desc:	6.4% cross slope					
Solution:	Demolish existing and construct new route					
Bar. Severity:	1 Necessary		Cost Estimate:	\$35,375.00	Status:	
Implementation Priority:	4		Facility Function:			
Implementation Phase:			Implementation Date:			
Official Responsible:						
Notes:						

Field Date: ##### Report Date: 10/18/2010 Barrier #: 928

Location: Pinecreek Wy - East


X Coordinate: -121.31934

Y Coordinate: 38.70498

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 213 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$26,625.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/18/2010 Barrier #: 929A

Location: Pinecreek Wy - East


X Coordinate: -121.31979

Y Coordinate: 38.70408

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 24 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 9.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$3,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:


Notes:

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	929B
Location:	Pinecreek Wy - East				
X Coordinate:	-121.3198				
Y Coordinate:	38.70408				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				




As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	930
Location:	Pinecreek Wy - South				
X Coordinate:	-121.32035				
Y Coordinate:	38.70385				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	92	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$11,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	931A
Location:	Rumford Ave - South				
X Coordinate:	-121.32073				
Y Coordinate:	38.70609				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	711	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	7.2% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$88,875.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	931B
Location:	Rumford Ave - South				
X Coordinate:	-121.3194				
Y Coordinate:	38.70609				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF		
Description:	Change in level greater than 1/2"				
As Built Desc:	1" lip in sidewalk surface				
Solution:	Grind or repair sidewalk to remove trip hazard				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date: ##### Report Date: 10/18/2010 Barrier #: 932

Location: Bierston St - East


X Coordinate: -121.31862

Y Coordinate: 38.70598

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 528 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$66,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/18/2010 Barrier #: 933A

Location: Glenhurst Wy - North

X Coordinate: -121.31952

Y Coordinate: 38.7028

Barrier Area: Sidewalks

Barrier Type: Running Slope (Existing)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 16 Quantity: LF

Description: Running slope exceeds 5.0%

As Built Desc: 14.3% running slope

Solution: No remediation where sidewalk sloped as roadway

Bar. Severity: 5 Technically Infeasible Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/18/2010 Barrier #: 933B

Location: Glenhurst Wy - North


X Coordinate: -121.31952

Y Coordinate: 38.70279

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 1004 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$125,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/18/2010 Barrier #: 934A

Location: Glenhurst Wy - East


X Coordinate: -121.31756

Y Coordinate: 38.70487

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 197 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$24,625.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	934B
Location:	Glenhurst Wy - East				
X Coordinate:	-121.31759				
Y Coordinate:	38.70481				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing (32" to 35")				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	1	Quantity:	LF
Description:	Pedestrian route is not min. 48" wide (32" to 35")		
As Built Desc:	32" clear width due to foliage		
Solution:	Trim foliage to provide min. 48" clear width		
Bar. Severity:	2 Recommended	Cost Estimate:	\$125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	935
Location:	Stoneridge Wy and Glenhurst Wy - Corner B				
X Coordinate:	-121.31762				
Y Coordinate:	38.70438				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	12.7% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			


Notes:	Two - way intersection corners B,C
--------	------------------------------------

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	936
Location:	Stoneridge Wy and Glenhurst Wy - Corner C				
X Coordinate:	-121.31765				
Y Coordinate:	38.70425				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				




As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	10.3% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	937
Location:	Stoneridge Wy - North				
X Coordinate:	-121.31754				
Y Coordinate:	38.70427				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				




As Built Meas:	335	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$41,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	938
Location:	Stoneridge Wy - East				
X Coordinate:	-121.31645				
Y Coordinate:	38.70373				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				
As Built Meas:	463	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.6% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$57,875.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					



Field Date:	#####	Report Date:	10/18/2010	Barrier #:	939A
Location:	Stoneridge Wy - West				
X Coordinate:	-121.3166				
Y Coordinate:	38.70326				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				
As Built Meas:	1215	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	7.3% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$151,875.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					



Field Date:	#####	Report Date:	10/18/2010	Barrier #:	939B
Location:	Stoneridge Wy - West				
X Coordinate:	-121.3166				
Y Coordinate:	38.70324				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	939C
Location:	Stoneridge Wy - West				
X Coordinate:	-121.31652				
Y Coordinate:	38.70364				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: ##### Report Date: 10/18/2010 Barrier #: 940

Location: Stoneridge Wy - South

X Coordinate: -121.31671

Y Coordinate: 38.70382

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 332 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$41,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/18/2010 Barrier #: 941

Location: Glenhurst St - East


X Coordinate: -121.31768

Y Coordinate: 38.70412

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 155 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$19,375.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	942
Location:	Glenhurst Wy and Mar Vista Wy - Corner B				
X Coordinate:	-121.31791				
Y Coordinate:	38.70375				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				




As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	12.5% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C GPS 036		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	943
Location:	Glenhurst Wy and Mar Vista Wy - Corner C				
X Coordinate:	-121.31801				
Y Coordinate:	38.70367				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				




As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	13.7% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C GPS 037		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	944
Location:	Mar Vista Wy - North				
X Coordinate:	-121.31787				
Y Coordinate:	38.70366				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	214	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$26,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	945
Location:	Mar Vista Wy - East				
X Coordinate:	-121.31741				
Y Coordinate:	38.70318				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	224	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$28,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	946
Location:	Mar Vista Wy and Wild Oak Dr - Corner B				
X Coordinate:	-121.3179				
Y Coordinate:	38.70268				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				




As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	11.3% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	947
Location:	Mar Vista Wy and Wild Oak Dr - Corner C				
X Coordinate:	-121.31803				
Y Coordinate:	38.70257				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				




As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	9.3% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	948
Location:	Wild Oak Dr - West				
X Coordinate:	-121.31788				
Y Coordinate:	38.70265				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	362	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$45,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	949
Location:	Wild Oak Dr - East				
X Coordinate:	-121.31733				
Y Coordinate:	38.70185				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	354	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$44,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: ##### Report Date: 10/18/2010 Barrier #: 950

Location: Mar Vista Wy - South


X Coordinate: -121.31807

Y Coordinate: 38.70256

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 401 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$50,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/18/2010 Barrier #: 951

Location: Mar Vista Wy - South

X Coordinate: -121.31919

Y Coordinate: 38.70201

Barrier Area: Sidewalks

Barrier Type: Elbow in Sidewalk - Cross Slope (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 6 Quantity: LF

Description: Cross slope at elbow exceeds 2.0% (5.0% or more)

As Built Desc: 10.6% cross slope

Solution: Demolish existing and construct new sidewalk without curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$750.00 Status:


Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	952
Location:	Mar Vista Wy - East				
X Coordinate:	-121.31931				
Y Coordinate:	38.70184				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				
As Built Meas:	242	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	6.3% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$30,250.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					



Field Date:	#####	Report Date:	10/18/2010	Barrier #:	953
Location:	Mar Vista Wy and Sky Vista Ct - Corner B				
X Coordinate:	-121.31891				
Y Coordinate:	38.70115				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				
As Built Meas:	1	Quantity:	EACH		
Description:	No compliant curb cut at corner (intersection)				
As Built Desc:	14.4% running slope at depressed area				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:	Two - way intersection corners B,C				




Field Date:	#####	Report Date:	10/18/2010	Barrier #:	954
Location:	Mar Vista Wy and Sky Vista Ct - Corner C				
X Coordinate:	-121.31883				
Y Coordinate:	38.70108				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Exsiting Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	10.1% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners B,C		

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	955
Location:	Sky Vista - North				
X Coordinate:	-121.31885				
Y Coordinate:	38.7012				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	299	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$37,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: ##### Report Date: 10/18/2010 Barrier #: 956

Location: Sky Vista - South

X Coordinate: -121.31823

Y Coordinate: 38.70154

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 254 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route


Bar. Severity: 1 Necessary Cost Estimate: \$31,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: ##### Report Date: 10/18/2010 Barrier #: 957

Location: Mar Vista Wy - East

X Coordinate: -121.31877

Y Coordinate: 38.70094

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 104 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.5% cross slope

Solution: Demolish existing and construct new route


Bar. Severity: 2 Recommended Cost Estimate: \$13,000.00 Status:

Implementation Priority: 4 Facility Function:


Implementation Phase: Implementation Date:

Official Responsible:


Notes:



Field Date:	#####	Report Date:	10/18/2010	Barrier #:	958
Location:	Mar Vista Wy- West				
X Coordinate:	-121.31849				
Y Coordinate:	38.70053				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				
As Built Meas:	625	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.3% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$78,125.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					



Field Date:	#####	Report Date:	10/18/2010	Barrier #:	959
Location:	Mar Vista Wy- North				
X Coordinate:	-121.31947				
Y Coordinate:	38.702				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				
As Built Meas:	776	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	7.1% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$97,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					



Field Date: ##### Report Date: 10/18/2010 Barrier #: 960

Location: Mar Vista Wy- South


X Coordinate: -121.31751

Y Coordinate: 38.70335

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 124 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$15,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/18/2010 Barrier #: 961A

Location: Glenhurst Wy - South


X Coordinate: -121.31806

Y Coordinate: 38.70361

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 769 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$96,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/18/2010	Barrier #:	961B
Location:	Glenhurst Wy - South				
X Coordinate:	-121.31994				
Y Coordinate:	38.70262				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ($\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	4	Quantity:	LF
Description:	Pedestrian route is not min. 48" wide ($\leq 31"$ or less)		
As Built Desc:	30" clear width due to pole		
Solution:	Make alterations to provide min. 32" clear width		
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	962
Location:	Tupelo Dr - South				
X Coordinate:	-121.32516				
Y Coordinate:	38.69867				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	217	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$27,125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	963
Location:	Windjammer Wy - West				
X Coordinate:	-121.3244				
Y Coordinate:	38.69879				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	560	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$70,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	964
Location:	Windjammer Wy - West				
X Coordinate:	-121.32459				
Y Coordinate:	38.69712				
Barrier Area:	Sidewalks				
Barrier Type:	Elbow in Sidewalk - Cross Slope (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	8	Quantity:	LF
Description:	Cross slope at elbow exceeds 2.0% (5.0% or more)		
As Built Desc:	10.5% cross slope		
Solution:	Demolish existing and construct new sidewalk without curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	965
Location:	Windjammer Wy - North				
X Coordinate:	-121.32453				
Y Coordinate:	38.69713				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	174	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$21,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	966
Location:	Windjammer Wy - South				
X Coordinate:	-121.32509				
Y Coordinate:	38.69712				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	214	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$26,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: ##### Report Date: 10/19/2010 Barrier #: 967

Location: Windjammer Wy - South

X Coordinate: -121.32437

Y Coordinate: 38.69713

Barrier Area: Sidewalks

Barrier Type: Elbow in Sidewalk - Cross Slope (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 10 Quantity: LF

Description: Cross slope at elbow exceeds 2.0% (5.0% or more)

As Built Desc: 10.5% cross slope

Solution: Demolish existing and construct new sidewalk without curb ramp

Bar. Severity: 1 Necessary

Cost Estimate: \$1,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/19/2010 Barrier #: 968

Location: Windjammer Wy - East

X Coordinate: -121.32433

Y Coordinate: 38.69717

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 607 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$75,875.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	969
Location:	Tupelo Dr - South				
X Coordinate:	-121.32421				
Y Coordinate:	38.69887				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	188	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$23,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	970A
Location:	Parkvale Wy - West				
X Coordinate:	-121.32352				
Y Coordinate:	38.69882				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	1136	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$142,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	970B
Location:	Parkvale Wy - West				
X Coordinate:	-121.32358				
Y Coordinate:	38.69782				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - Tree Heaves				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF		
Description:	Change in level greater than 1/2"				
As Built Desc:	1/2" lip due to tree heaves				
Solution:	Grind or repair sidewalk to remove trip hazard				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	971A
Location:	Parkvale Wy - North				
X Coordinate:	-121.32377				
Y Coordinate:	38.69571				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	176	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.6% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$22,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date: ##### Report Date: 10/19/2010 Barrier #: 971B

Location: Parkvale Wy - North

X Coordinate: -121.32425

Y Coordinate: 38.69558

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 24" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary Cost Estimate: \$125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/19/2010 Barrier #: 972

Location: Schooner Wy - East

X Coordinate: -121.32433

Y Coordinate: 38.69562

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 303 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$37,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	973
Location:	Schooner Wy - East				
X Coordinate:	-121.32433				
Y Coordinate:	38.6964				
Barrier Area:	Sidewalks				
Barrier Type:	Elbow in Sidewalk - Cross Slope (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	10	Quantity:	LF
Description:	Cross slope at elbow exceeds 2.0% (5.0% or more)		
As Built Desc:	11.3% cross slope		
Solution:	Demolish existing and construct new sidewalk without curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	974A
Location:	Schooner Wy - North				
X Coordinate:	-121.32427				
Y Coordinate:	38.69651				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	257	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$32,125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: ##### Report Date: 10/19/2010 Barrier #: 974B

Location: Schooner Wy - North

X Coordinate: -121.32466

Y Coordinate: 38.69647

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 0" clear width due to foilage growth

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary Cost Estimate: \$125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/19/2010 Barrier #: 975

Location: Schooner Wy - South

X Coordinate: -121.32511

Y Coordinate: 38.69645

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 186 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$23,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	976
Location:	Schooner Wy - West				
X Coordinate:	-121.3244				
Y Coordinate:	38.69639				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	286	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$35,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	977
Location:	Parkvale Wy - North				
X Coordinate:	-121.32453				
Y Coordinate:	38.69562				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	228	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$28,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	978
Location:	Parkvale Wy - South				
X Coordinate:	-121.32528				
Y Coordinate:	38.69568				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	430	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$53,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	979A
Location:	Parkvale Wy - East				
X Coordinate:	-121.32378				
Y Coordinate:	38.69559				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	467	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$58,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	979B
Location:	Parkvale Wy - East				
X Coordinate:	-121.32351				
Y Coordinate:	38.69593				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - Tree Heaves				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1/2" lip due to tree heaves		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	988
Location:	Shawnda Ct - South				
X Coordinate:	-121.32279				
Y Coordinate:	38.69699				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - New Construction				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	114	Quantity:	LF
Description:	Cross slope exceeds 2.0% in new construction		
As Built Desc:	4.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$14,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	989
Location:	Shawnda Ct - North				
X Coordinate:	-121.32233				
Y Coordinate:	38.69696				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	330	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$41,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	990
Location:	Parkvale Wy - East				
X Coordinate:	-121.32346				
Y Coordinate:	38.69711				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	179	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$22,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	991
Location:	Sierravale Wy - South				
X Coordinate:	-121.32333				
Y Coordinate:	38.69765				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	426	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$53,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	992A
Location:	Sierravale Wy - East				
X Coordinate:	-121.32181				
Y Coordinate:	38.69768				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	423	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$52,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: ##### Report Date: 10/19/2010 Barrier #: 992B

Location: Sierravale Wy - East

X Coordinate: -121.32182

Y Coordinate: 38.69771

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/19/2010 Barrier #: 992C

Location: Sierravale Wy - East

X Coordinate: -121.32169

Y Coordinate: 38.69814

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 24" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary Cost Estimate: \$125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	993
Location:	Sierravale Wy - West				
X Coordinate:	-121.32168				
Y Coordinate:	38.69884				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	411	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$51,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	994
Location:	Sierravale Wy - North				
X Coordinate:	-121.32194				
Y Coordinate:	38.69773				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	394	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$49,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	995
Location:	Parkvale Wy - East				
X Coordinate:	-121.32343				
Y Coordinate:	38.69778				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	390	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$48,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	996A
Location:	Tupelo Dr - South				
X Coordinate:	-121.32328				
Y Coordinate:	38.69886				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	192	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$24,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: ##### Report Date: 10/19/2010 Barrier #: 996B

Location: Tupelo Dr - South

X Coordinate: -121.32305

Y Coordinate: 38.69888

Barrier Area: Sidewalks

Barrier Type: Protruding Hazard

Code Ref: CBC 1133B.8.6.1 and ADA/ABA 307.2



As Built Meas: 1 Quantity: JOB

Description: Protruding object in route of travel between 27" and 80" high

As Built Desc: 40" protruding hazard at tree branches

Solution: Remove object or provide detectable warning

Bar. Severity: 1 Necessary

Cost Estimate: \$1,400.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/19/2010 Barrier #: 997

Location: Tupelo Dr and Lillivale Ct - Corner C

X Coordinate: -121.3225

Y Coordinate: 38.69887

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Exsiting Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 13.4% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D

Field Date: ##### Report Date: 10/19/2010 Barrier #: 998

Location: Tupelo Dr and Lillivale Ct - Corner D

X Coordinate: -121.32261

Y Coordinate: 38.69885

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Exsiting Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 13.2% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D

Field Date: ##### Report Date: 10/19/2010 Barrier #: 999

Location: Lillivale Ct - West

X Coordinate: -121.32257

Y Coordinate: 38.69881

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 133 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$16,625.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1000
Location:	Lillivale Ct - East				
X Coordinate:	-121.32245				
Y Coordinate:	38.69852				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	120	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$15,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1001
Location:	Tupelo Dr - South				
X Coordinate:	-121.32241				
Y Coordinate:	38.6989				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	195	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$24,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1002
Location:	Tupelo Dr - South				
X Coordinate:	-121.32149				
Y Coordinate:	38.6989				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	727	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	6.7% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$90,875.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1003
Location:	Tupelo Dr - South				
X Coordinate:	-121.31879				
Y Coordinate:	38.6999				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	16	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.6% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$2,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1004A

Location: Woodglade Ave - North


X Coordinate: -121.32393

Y Coordinate: 38.70686

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 823 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$102,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1004B

Location: Woodglade Ave - North

X Coordinate: -121.32182

Y Coordinate: 38.70678

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 3/4" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1004C
Location:	Woodglade Ave - North				
X Coordinate:	-121.32144				
Y Coordinate:	38.70681				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	3/4" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1005A
Location:	Woodglade Ave and Saybrook Dr - Corner A				
X Coordinate:	-121.32108				
Y Coordinate:	38.70683				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,D		

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1005B
Location:	Woodglade Ave and Saybrook Dr - Corner A				
X Coordinate:	-121.32108				
Y Coordinate:	38.70683				
Barrier Area:	Curb Ramps				
Barrier Type:	Surface Condition				
Code Ref:	CBC 1127B.5 and ADA/ABA 403.2				



As Built Meas:	4	Quantity:	SF	
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)			
As Built Desc:	Cracked concrete			
Solution:	Repair surface to make firm and stable			
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Two - way intersection corners A,D			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1006
Location:	Woodglade Ave and Saybrook Dr - Corner D				
X Coordinate:	-121.3211				
Y Coordinate:	38.70671				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Two - way intersection corners A,D			

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1007A

Location: Saybrook Dr - West


X Coordinate: -121.32108

Y Coordinate: 38.70696

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 79 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$9,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1007B

Location: Saybrook Dr - West

X Coordinate: -121.32107

Y Coordinate: 38.70693

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - Tree Heaves

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip due to tree heaves

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1008A

Location: Saybrook Dr - West


X Coordinate: -121.32103

Y Coordinate: 38.7066

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 787 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$98,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1008B

Location: Saybrook Dr - West

X Coordinate: -121.32104

Y Coordinate: 38.70594

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 4 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1009
Location:	Saybrook Dr and Biglow Dr - Corner A				
X Coordinate:	-121.32105				
Y Coordinate:	38.70443				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,D		

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1010
Location:	Saybrook Dr and Biglow Dr - Corner D				
X Coordinate:	-121.32105				
Y Coordinate:	38.70426				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection corners A,D		

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1011

Location: Biglow Dr - North


X Coordinate: -121.32114

Y Coordinate: 38.7044

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 145 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$18,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1012

Location: Blackthorne Wy - East

X Coordinate: -121.32182

Y Coordinate: 38.70442

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 820 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$102,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1013

Location: Woodglade Ave - South


X Coordinate: -121.32171

Y Coordinate: 38.7067

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 175 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$21,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1014A

Location: Saybrook Dr - West

X Coordinate: -121.32095

Y Coordinate: 38.70411

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 763 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$95,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1014B

Location: Saybrook Dr - West

X Coordinate: -121.32088

Y Coordinate: 38.70374

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 4 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1015

Location: Saybrook Dr and Birchglade Wy - Corner A

X Coordinate: -121.32047

Y Coordinate: 38.70217

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1016

Location: Saybrook Dr and Birchglade Wy - Corner D

X Coordinate: -121.32044

Y Coordinate: 38.70204

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1017A

Location: Birchglade Wy - North

X Coordinate: -121.32054

Y Coordinate: 38.70216

Barrier Area: Sidewalks

Barrier Type: Running Slope (Existing)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 16 Quantity: LF

Description: Running slope exceeds 5.0%

As Built Desc: 8.0% running slope

Solution: No remediation where sidewalk sloped as roadway

Bar. Severity: 5 Technically Infeasible Cost Estimate: \$0.00 Status:


Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1017B
Location:	Birchglade Wy - North				
X Coordinate:	-121.32122				
Y Coordinate:	38.70209				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	177	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$22,125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1018
Location:	Blackthorne Wy - East				
X Coordinate:	-121.32123				
Y Coordinate:	38.70208				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	760	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$95,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1019

Location: Biglow Dr - South


X Coordinate: -121.32134

Y Coordinate: 38.70425

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 78 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$9,750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1020

Location: Saybrook Dr - West


X Coordinate: -121.32043

Y Coordinate: 38.70197

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 856 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$107,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1021

Location: Tupelo Dr - West


X Coordinate: -121.31905

Y Coordinate: 38.69985

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 165 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$20,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1022A

Location: Blackthorne Wy - North

X Coordinate: -121.31962

Y Coordinate: 38.69954

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 994 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 9.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$124,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:


Notes:

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1022B
Location:	Blackthorne Wy - North				
X Coordinate:	-121.32094				
Y Coordinate:	38.7012				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF		
Description:	Change in level greater than 1/2"				
As Built Desc:	1" lip in sidewalk surface				
Solution:	Grind or repair sidewalk to remove trip hazard				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1022C
Location:	Blackthorne Wy - North				
X Coordinate:	-121.32114				
Y Coordinate:	38.70166				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ($\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	1	Quantity:	LF		
Description:	Pedestrian route is not min. 48" wide ($\leq 31"$ or less)				
As Built Desc:	30" clear width due to foliage				
Solution:	Trim foliage to provide min. 48" clear width				
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					
Notes:					

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1023A

Location: Birchglade Wy - South

X Coordinate: -121.32112

Y Coordinate: 38.70195

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 195 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$24,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1023B

Location: Birchglade Wy - South

X Coordinate: -121.32051

Y Coordinate: 38.70205

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 24" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary Cost Estimate: \$125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1024A
Location:	Tupelo Dr - East				
X Coordinate:	-121.31869				
Y Coordinate:	38.69995				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - New Construction				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	1615	Quantity:	LF	
Description:	Cross slope exceeds 2.0% in new construction			
As Built Desc:	5.6% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$201,875.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1024B
Location:	Tupelo Dr - East				
X Coordinate:	-121.31578				
Y Coordinate:	38.70263				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	4	Quantity:	LF	
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)			
As Built Desc:	Cracked concrete			
Solution:	Repair surface to make firm and stable			
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1025

Location: Tupelo Dr - East

X Coordinate: -121.31536

Y Coordinate: 38.70339

Barrier Area: Sidewalks

Barrier Type: Driveway - New Construction

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 39 Quantity: LF

Description: Driveway cross/running slope exceeds 2.0%

As Built Desc: 5.0% cross slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 1 Necessary

Cost Estimate: \$4,875.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1026

Location: Tupelo Dr - East

X Coordinate: -121.31536

Y Coordinate: 38.7035

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 37 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$4,625.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1027
Location:	Tupelo Dr - East				
X Coordinate:	-121.31536				
Y Coordinate:	38.7036				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - New Construction				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	39	Quantity:	LF
Description:	Driveway cross/running slope exceeds 2.0%		
As Built Desc:	4.6% cross slope, 9.9% running slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1028
Location:	Tupelo Dr - East				
X Coordinate:	-121.31537				
Y Coordinate:	38.70371				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	10	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1029

Location: Tupelo Dr - East

X Coordinate: -121.31535

Y Coordinate: 38.70376

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 42 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.7% cross slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 4 Low Severity

Cost Estimate: \$5,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1030

Location: Tupelo Dr - East


X Coordinate: -121.31534

Y Coordinate: 38.70387

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 235 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$29,375.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1031
Location:	Tupelo Dr - East				
X Coordinate:	-121.31536				
Y Coordinate:	38.70462				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway -12" Grooves Incorrect Application				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	0	Quantity:	JOB
Description:	12" grooves required only at curb ramps identified at transition into driveway		
As Built Desc:	12" grooves incorrectly provided where no curb ramp exists		
Solution:	No remediation recommended, until new construction is performed in area		
Bar. Severity:	4 Low Severity	Cost Estimate:	\$0.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	New construction project		

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1032
Location:	Tupelo Dr - East				
X Coordinate:	-121.31535				
Y Coordinate:	38.70492				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	8	Quantity:	LF
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)		
As Built Desc:	Cracked concrete		
Solution:	Repair surface to make firm and stable		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1033
Location:	Tupelo Dr - East				
X Coordinate:	-121.31535				
Y Coordinate:	38.70506				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	45	Quantity:	LF
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.4% cross slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	4 Low Severity	Cost Estimate:	\$5,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1034
Location:	Tupelo Dr - East				
X Coordinate:	-121.31533				
Y Coordinate:	38.70539				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	99	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$12,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1035
Location:	Tupelo Dr - East				
X Coordinate:	-121.31534				
Y Coordinate:	38.70555				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - New Construction				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	49	Quantity:	LF
Description:	Driveway cross/running slope exceeds 2.0%		
As Built Desc:	7.1% cross slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	1 Necessary	Cost Estimate:	\$6,125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1036
Location:	Tupelo Dr - East				
X Coordinate:	-121.3153				
Y Coordinate:	38.70673				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway -12" Grooves Incorrect Application				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	0	Quantity:	JOB
Description:	12" grooves required only at curb ramps identified at transition into driveway		
As Built Desc:	12" grooves incorrectly provided where no curb ramp exists		
Solution:	No remediation recommended, until new construction is performed in area		
Bar. Severity:	4 Low Severity	Cost Estimate:	\$0.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	New construction project		

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1037
Location:	Antelope Rd - South				
X Coordinate:	-121.3119				
Y Coordinate:	38.70723				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				







As Built Meas:	4	Quantity:	LF
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)		
As Built Desc:	Cracked concrete		
Solution:	Repair surface to make firm and stable		
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1038
Location:	Antelope Rd - South				
X Coordinate:	-121.30891				
Y Coordinate:	38.70727				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	4	Quantity:	LF
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)		
As Built Desc:	Cracked concrete		
Solution:	Repair surface to make firm and stable		
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1039	
Location:	Antelope Rd - South					
X Coordinate:	-121.30764					
Y Coordinate:	38.70726					
Barrier Area:	Sidewalks					
Barrier Type:	Cross Slope - Existing (5.0% or more)					
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3					
As Built Meas:	40	Quantity:	LF			
Description:	Cross slope exceeds 2.0% (5.0% or more)					
As Built Desc:	5.1% cross slope					
Solution:	Demolish existing and construct new route					
Bar. Severity:	1 Necessary	Cost Estimate:	\$5,000.00	Status:		
Implementation Priority:	1	Facility Function:				
Implementation Phase:		Implementation Date:				
Official Responsible:						
Notes:						

Field Date:	#####	Report Date:	10/19/2010	Barrier #:	1040A	
Location:	Antelope Rd - South					
X Coordinate:	-121.30675					
Y Coordinate:	38.70727					
Barrier Area:	Sidewalks					
Barrier Type:	Cross Slope - Existing (5.0% or more)					
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3					
As Built Meas:	214	Quantity:	LF			
Description:	Cross slope exceeds 2.0% (5.0% or more)					
As Built Desc:	7.1% cross slope					
Solution:	Demolish existing and construct new route					
Bar. Severity:	1 Necessary	Cost Estimate:	\$26,750.00	Status:		
Implementation Priority:	1	Facility Function:				
Implementation Phase:		Implementation Date:				
Official Responsible:						
Notes:						

Field Date: ##### Report Date: 10/19/2010 Barrier #: 1040B

Location: Antelope Rd - South

X Coordinate: -121.30603

Y Coordinate: 38.70728

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 4 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary

Cost Estimate: \$500.00

Status:

Implementation Priority: 1

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Cost Estimate Total Summary :\$26,212,575.00

Cost Estimate - Priority 1:

\$114,875.00

Cost Estimate - Priority 2:

\$2,173,475.00

Cost Estimate - Priority 3:

\$1,510,700.00

Cost Estimate - Priority 4:\$22,413,525.00
