


SZS CONSULTING GROUP

DRAFT ADA TRANSITION PLAN UPDATE
NEIGHBORHOOD AREA 3 CHANT
SEPTEMBER 20, 2011



CITY OF CITRUS HEIGHTS

Citrus Heights Area Three (CHANT)

The Citrus Heights Neighborhood Area Three (CHANT) is primarily a residential area with multiple commercial/retail centers, one elementary school, two mobile home parks, and a cemetery. The area borders are Van Maren Lane, Auburn Boulevard, Greenback Lane, and Interstate 80.


Conditions

Most of the sidewalks in the CHANT Area are of pre-1992 construction, which were identified with common issues such as non-compliant cross slopes, clear width issues, abrupt changes of level, and poor surface conditions. Many pre-1992 curb ramps were identified with multiple barriers to access.

Built elements found within the public rights-of-way in the CHANT Neighborhood Area were “depressed curbs” which are not actual curb cuts but depressed areas in the concrete at intersection corners that it is assumed were intended to assist with travel over the existing vertical or rolled curb. Also, a number of locations were identified with “elbows” that were altered into curb ramps. These locations are in residential areas, in which 90 degree turns in the sidewalk were actually altered into curb ramps without a crossing through the roadway that the curb ramp would be intended to enable.

The north section of the CHANT Area interior streets lacked sidewalks, blended transitions at intersections where no vertical or rolled curb existed, and the roadway shoulder cross slopes were also identified as non-compliant.

A residential segment of Van Maren Lane was identified with post-1992 construction providing compliant sidewalks but the curb ramps consistently lacked detectable warnings. In the west portion of Greenback Lane, an area north of Auburn Boulevard was identified with non-compliant sidewalk cross slopes and utility poles in the sidewalk that created clear width issues along Westbrook Drive. The last area of the CHANT Area was north of Greenback Lane. This area lacked improved sidewalk, compliant running slope within the roadway shoulder used as pedestrian route, and lacked blended transitions leading to the Cemetery entrance, which may be needed for those who visit that facility and cannot drive due to a disability. Bus stops along Greenback Lane and Auburn Boulevard were also identified as non-compliant.



Statistics

An intersection inventory was compiled as part of the field assessment process. In the CHANT Neighborhood Area, 15 intersections were found to have no barriers to access and a total of 898 barriers were identified. The compliant intersections are identified as follows:

#	Location	Notes
1	Auburn Blvd Frontage Rd and Halifax St - Corner A,B,C,D	Four - way intersection corners A,B,C,D compliant
2	Navion Dr and Mugho Ct - Corners A,D	Two - way intersection corners A,D compliant
3	Twin Wood Wy and Pebblebrook Wy - Corners A,B	Two - way intersection corners A,B compliant
4	Silkwood Wy and Shady Springs Wy - Corners A,B	Two - way intersection corners A,B compliant
5	Flaming Arrow Dr and Tall Brave Ct - Corners A,D	Two - way intersection corners A,D compliant
6	Starflower Wy and Hillspire Ct - Corners A,D	Two - way intersection corners A,D compliant
7	Indian River Dr and Little Squaw Ct - Corner B,C	Two - way intersection corners B,C compliant
8	Blowing Wind Wy and Brokenfeather Wy - Corners B,C	Two - way intersection corners B,C compliant
9	Indian River Dr and Broken Bow Dr - Corners A,B,C,D	Four - way intersection corners A,B,C,D compliant
10	Sunburst Wy and Silkwood Wy - Corner A,D	Two - way intersection corners A,D compliant
11	Sunmist Wy and Pebblebrook Wy - Corners A,B,C	Three - way intersection corners A,B,C compliant
12	Sunwood Wy and Starflower Dr - Corners B,C	Two - way intersection corners B,C compliant
13	Auburn Blvd and Creekbed - Corners A,D	Two - way intersection corners A,D compliant
14	Navion Dr and Misty Creek Dr - Corners A,B,C,D	Four - way intersection corners A,B,C,D under construction
15	Navion Dr and Tanbark Ct - Corners A,D	Two - way intersection corners A,D compliant

Barrier severity ratings were calculated for the 5 ratings assigned as follows:

<i>Severity 1 (Necessary to Remove)</i>	<i>442 or 49% of total barriers</i>
<i>Severity 2 (Recommended to Remove)</i>	<i>279 or 31% of total barriers</i>
<i>Severity 3 (Hindrance to Access)</i>	<i>146 or 16% of total barriers</i>
<i>Severity 4 (Low Severity Barrier)</i>	<i>23 or 3% of total barriers</i>
<i>Severity 5 (Technically Infeasible to Remove)</i>	<i>14 or 2% of total barriers</i>

Barrier Removal Priority Assignment

The draft barrier removal priorities were assigned to the pedestrian facilities using the criteria described below:

Priority 1 - Primary arterial roadways where the majority of bus routes are located

Auburn Blvd
Greenback Blvd
Van Maren Blvd

Priority 2 – Major collectors where remaining bus routes are located or where commercial centers, schools, parks, churches, state or local agency facilities exist

Crosswoods Circle

Priority 3 - Pedestrian routes leading from points of arrival at bus routes to schools, parks or other public accommodations

Donagal Drive

Mercedes Avenue

Priority 4 - Remaining residential public rights-of-way

Cost Estimates

The total cost for barrier removal within this draft ADA Transition Plan update was calculated as follows:

Cost Estimate Total: \$13,080,175.00

Barrier removal takes place through annual phases that are determined according to the barrier priority assigned and existing budgetary constraints. Draft barrier removal priorities have the following costs associated with each priority assigned:

Cost Estimate - Priority 1: \$1,205,125.00

Cost Estimate - Priority 2: \$2,332,950.00

Cost Estimate - Priority 3: \$635,200.00

Cost Estimate - Priority 4: \$8,906,900.00

Further input is required to complete the ADA Transition Plan. Each Neighborhood Area (NA) must be reviewed by designated Citrus Heights City staff to determine whether overall priorities shall be set per NA or overall throughout the city. Other constraints were taken into consideration while compiling the cost estimates.

1. Currently all barriers are assigned a priority for removal. Some areas may not be used as pedestrian facilities, may be unimproved and could remain so until a request for accommodations is received by the City.
 - a. Assistance in prioritizing areas that lack sidewalk is required. Some segments are lengthy and may not be planned for improvements in the long or short term.
2. Cost estimates have been manually reviewed and corrected
 - a. In instances where more than one barrier exists at a curb ramp, cost estimates for curb ramp barriers are often manually changed to ensure that cost estimates do not exceed \$2,500. In these instances, the cost estimate for the first barrier (i.e. 24A, of 24B, 24C and 25D) is listed with a cost estimate of \$2,500 and the remaining barriers are listed with a cost of \$0. This may occur even when the first barrier listed is not ordinarily estimated as high as \$2,500.
 - b. Driveways with multiple slopes were assigned a severity 1 rating, rather than a rating that corresponded to the slope of only one of the measurements taken.
 - c. Bus stop benches with multiple barriers were only assigned one cost estimate for one accessible bench.

The following barrier data sheets must be reviewed in draft form to provide input for the final report.

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2301

Location: Garden Gate Dr - West


X Coordinate: -121.30591

Y Coordinate: 38.70717

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 40 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 8.8% cross slope, 18.5% running slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 1 Necessary Cost Estimate: \$5,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2302

Location: Garden Gate Dr - West


X Coordinate: -121.30596

Y Coordinate: 38.70686

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 30 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$3,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2303

Location: Garden Gate Dr - West


X Coordinate: -121.30597

Y Coordinate: 38.70668

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 41 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 14.0% cross slope, 16.0% running slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 1 Necessary Cost Estimate: \$5,125.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2304A

Location: Malia Ct and Purslane Wy - Corner A

X Coordinate: -121.30677

Y Coordinate: 38.70626

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - New Construction

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (>5.0%)

As Built Desc: 9.1% at 12" grooves - New Construction

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2304B

Location: Malia Ct and Purslane Wy - Corner A

X Coordinate: -121.30677

Y Coordinate: 38.70626

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - New Construction

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level (3.1% to 4.0%)

As Built Desc: 3.8% landing slope - New Construction

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2304C

Location: Malia Ct and Purslane Wy - Corner A

X Coordinate: -121.30677

Y Coordinate: 38.70626

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - New Construction

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.1% - 5.8%)

As Built Desc: 5.6% gutter slope - New Construction

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2305

Location: Malia Ct and Purslane Wy - Corner B

X Coordinate: -121.30665

Y Coordinate: 38.70625

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - New Construction

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (4.1% to 4.9%)

As Built Desc: 4.8% at 12" grooves - New Construction

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2306

Location: Malia Ct - East


X Coordinate: -121.30671

Y Coordinate: 38.70637

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 113 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$14,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2307A

Location: Malia Ct - West


X Coordinate: -121.30677

Y Coordinate: 38.70670

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 86 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$10,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2307B

Location: Malia Ct - West


X Coordinate: -121.30677

Y Coordinate: 38.70635

Barrier Area: Sidewalks

Barrier Type: Running Slope (Existing)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 8 Quantity: LF

Description: Running slope exceeds 5.0%

As Built Desc: 9.0% running slope

Solution: No remediation where sidewalk sloped as roadway

Bar. Severity: 5 Technically Infeasible Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2308

Location: Purslane Wy - North


X Coordinate: -121.30704

Y Coordinate: 38.70626

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 102 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$12,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2309

Location: Purslane Wy - North


X Coordinate: -121.30738

Y Coordinate: 38.70628

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 21 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 15.1% cross slope, 12.3% running slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 1 Necessary Cost Estimate: \$2,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2310

Location: Purslane Wy - North

X Coordinate: -121.30763

Y Coordinate: 38.70627

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 46 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 8.1% cross slope, 9.6% running slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 1 Necessary Cost Estimate: \$5,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2311

Location: Purslane Wy - North


X Coordinate: -121.30781

Y Coordinate: 38.70629

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 73 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$9,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2312

Location: Purslane Wy - North


X Coordinate: -121.30808

Y Coordinate: 38.70630

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 50 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 9.5% cross slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 4 Low Severity Cost Estimate: \$6,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2313

Location: Purslane Wy - North


X Coordinate: -121.30810

Y Coordinate: 38.70626

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 64 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$8,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2314

Location: Purslane Wy - North


X Coordinate: -121.30865

Y Coordinate: 38.70616

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 36 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 9.8% cross slope at cracked concrete

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 4 Low Severity Cost Estimate: \$4,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2315A

Location: Van Maren Ln and Navion Dr - Corner A

X Coordinate: -121.30879

Y Coordinate: 38.70582

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - New Construction

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (>5.0%)

As Built Desc: 5.3% at 12" grooves - New Construction

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2315B

Location: Van Maren Ln and Navion Dr - Corner A

X Coordinate: -121.30879

Y Coordinate: 38.70582

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - New Construction

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.1% - 5.8%)

As Built Desc: 5.7% gutter slope - New Construction

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2316

Location: Van Maren Ln and Navion Dr - Corner D

X Coordinate: -121.30880

Y Coordinate: 38.70573

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2317

Location: Navion Dr - North

X Coordinate: -121.30897

Y Coordinate: 38.70581

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 2968 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$296,800.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2318A

Location: Navion Dr - North


X Coordinate: -121.31597

Y Coordinate: 38.69994

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 270 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$33,750.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2318B

Location: Navion Dr - North

X Coordinate: -121.31591

Y Coordinate: 38.69996

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 4 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2318C

Location: Navion Dr - North

X Coordinate: -121.31599

Y Coordinate: 38.69974

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2319A

Location: Navion Dr and Willowleaf Dr - Corner B

X Coordinate: -121.31579

Y Coordinate: 38.69982

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.8% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2319B

Location: Navion Dr and Willowleaf Dr - Corner B

X Coordinate: -121.31579

Y Coordinate: 38.69982

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2320A

Location: Navion Dr and Willowleaf Dr - Corner C

X Coordinate: -121.31582

Y Coordinate: 38.69971

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2320B

Location: Navion Dr and Willowleaf Dr - Corner C

X Coordinate: -121.31582

Y Coordinate: 38.69971

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.1% - 5.8%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.1% - 5.8%)

As Built Desc: 5.3% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 4 Low Severity Cost Estimate: \$750.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2321

Location: Willowleaf Dr - South


X Coordinate: -121.31544

Y Coordinate: 38.69971

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 910 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$113,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2322A

Location: Willowleaf Dr and Dew Drop Wy - Corner C

X Coordinate: -121.31211

Y Coordinate: 38.69969

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.8% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2322B

Location: Willowleaf Dr and Dew Drop Wy - Corner C

X Coordinate: -121.31211

Y Coordinate: 38.69969

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2323A

Location: Willowleaf Dr and Dew Drop Wy - Corner D


X Coordinate: -121.31203

Y Coordinate: 38.69969

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.8% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2323B

Location: Willowleaf Dr and Dew Drop Wy - Corner D

X Coordinate: -121.31203

Y Coordinate: 38.69969

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2324

Location: Dew Drop Wy - West


X Coordinate: -121.31211

Y Coordinate: 38.69953

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 186 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$23,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2325

Location: Dew Drop Wy and Misty Creek Dr - Corner A

X Coordinate: -121.31211

Y Coordinate: 38.69904

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2326

Location: Dew Drop Wy and Misty Creek Dr - Corner B

X Coordinate: -121.31202

Y Coordinate: 38.69903

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2327

Location: Dew Drop Wy - East


X Coordinate: -121.31202

Y Coordinate: 38.69914

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 171 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$21,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2328

Location: Willowleaf Dr - South


X Coordinate: -121.31201

Y Coordinate: 38.69962

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 487 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$60,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2329

Location: Willowleaf Dr - West


X Coordinate: -121.30975

Y Coordinate: 38.69950

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 188 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$23,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2330A

Location: Willowleaf Dr and Misty Creek Dr - Corner A

X Coordinate: -121.30974

Y Coordinate: 38.69904

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (4.1% to 4.9%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (4.1% to 4.9%)

As Built Desc: 4.8% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 2 Recommended Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2330B

Location: Willowleaf Dr and Misty Creek Dr - Corner A

X Coordinate: -121.30974

Y Coordinate: 38.69904

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2331A

Location: Willowleaf Dr and Misty Creek Dr - Corner B

X Coordinate: -121.30966

Y Coordinate: 38.69904

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.1% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2331B

Location: Willowleaf Dr and Misty Creek Dr - Corner B

X Coordinate: -121.30966

Y Coordinate: 38.69904

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2332

Location: Willowleaf Dr - East

X Coordinate: -121.30966

Y Coordinate: 38.69918

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 217 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$27,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2333

Location: Willowleaf Dr - North


X Coordinate: -121.30988

Y Coordinate: 38.69978

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 821 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$102,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2334

Location: Willowleaf Dr and Stinson Wy - Corner A

X Coordinate: -121.31280

Y Coordinate: 38.69978

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2335

Location: Willowleaf Dr and Stinson Wy - Corner B

X Coordinate: -121.31269

Y Coordinate: 38.69978

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2336

Location: Willowleaf Dr - North


X Coordinate: -121.31299

Y Coordinate: 38.69978

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 811 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$101,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2337

Location: Navion Dr - East


X Coordinate: -121.31568

Y Coordinate: 38.70002

Barrier Area: Sidewalks

Barrier Type: No Sidewalk - No Barricade

Code Ref: MUTCD Section 6D.01



As Built Meas: 1 Quantity: JOB

Description: No barricade provided where sidewalk ends in hazardous location

As Built Desc: No barricade or other warning provided for the visually impaired at end of sidewalk

Solution: Provide barricade with cane detectable warning at end of sidewalk

Bar. Severity: 1 Necessary Cost Estimate: \$1,350.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2338

Location: Navion Dr - East

X Coordinate: -121.31562

Y Coordinate: 38.70011

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 345 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$34,500.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2339

Location: Navion Dr and Skylane Dr - Corner B

X Coordinate: -121.31477

Y Coordinate: 38.70093

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2340

Location: Navion Dr and Skylane Dr - Corner C

X Coordinate: -121.31485

Y Coordinate: 38.70088

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2341

Location: Skylane Dr - South

X Coordinate: -121.31446

Y Coordinate: 38.70064

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 589 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$58,900.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2342

Location: Skylane Dr and Stinson Wy - Corner C

X Coordinate: -121.31272

Y Coordinate: 38.70054

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2343

Location: Skylane Dr and Stinson Wy - Corner D

X Coordinate: -121.31278

Y Coordinate: 38.70055

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2344

Location: Stinson Wy - West


X Coordinate: -121.31279

Y Coordinate: 38.70043

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 136 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$13,600.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2345

Location: Stinson Wy - East


X Coordinate: -121.31270

Y Coordinate: 38.70014

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 137 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$13,700.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2346

Location: Skylane Dr - South


X Coordinate: -121.31253

Y Coordinate: 38.70056

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 1074 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$107,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/12/2010	Report Date:	11/12/2010	Barrier #:	2347
Location:	Skylane Dr and Van Maren Ln - Corner A				
X Coordinate:	-121.30878				
Y Coordinate:	38.70067				
Barrier Area:	Blended Transitions				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at transition into roadway			
As Built Desc:	No detectable warning provided			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Two - way intersection. Corners A,D			

Field Date:	11/12/2010	Report Date:	11/12/2010	Barrier #:	2348
Location:	Skylane Dr and Van Maren Ln - Corner D				
X Coordinate:	-121.30878				
Y Coordinate:	38.70058				
Barrier Area:	Blended Transitions				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at transition into roadway			
As Built Desc:	No detectable warning provided			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Two - way intersection. Corners A,D			

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2349

Location: Skylane Dr - North


X Coordinate: -121.30917

Y Coordinate: 38.70066

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 247 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$24,700.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2350

Location: Skylane Dr and Convair Wy - Corner A

X Coordinate: -121.30996

Y Coordinate: 38.70062

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2351

Location: Skylane Dr and Convair Wy - Corner B

X Coordinate: -121.30987

Y Coordinate: 38.70063

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2352

Location: Skylane Dr - North


X Coordinate: -121.31027

Y Coordinate: 38.70062

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 265 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$26,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2353

Location: Skyline Dr and Apache Wy - Corner A

X Coordinate: -121.31109

Y Coordinate: 38.70064

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2354

Location: Skyline Dr and Apache Wy - Corner B

X Coordinate: -121.31100

Y Coordinate: 38.70063

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:


Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date:	11/12/2010	Report Date:	11/12/2010	Barrier #:	2355
Location:	Skylane Dr - North				
X Coordinate:	-121.31138				
Y Coordinate:	38.70063				
Barrier Area:	Sidewalks				
Barrier Type:	No sidewalk				
Code Ref:	CBC 1127B.1 and ADA/ABA 206.2.1				



As Built Meas:	246	Quantity:	LF	
Description:	No pedestrian route provided			
As Built Desc:	No sidewalk provided			
Solution:	Construct new firm and stable pedestrian route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$24,600.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	11/12/2010	Report Date:	11/12/2010	Barrier #:	2356
Location:	Skylane Dr and Stearman Wy - Corner A				
X Coordinate:	-121.31224				
Y Coordinate:	38.70065				
Barrier Area:	Blended Transitions				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at transition into roadway			
As Built Desc:	No detectable warning provided			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection. Corners A,B
--------	-------------------------------------

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2357

Location: Skylane Dr and Stearman Wy - Corner B

X Coordinate: -121.31216

Y Coordinate: 38.70063

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2358

Location: Skylane Dr - North


X Coordinate: -121.31255

Y Coordinate: 38.70063

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 261 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$26,100.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/12/2010	Report Date:	11/12/2010	Barrier #:	2359
Location:	Skylane Dr and Voyager Wy - Corner A				
X Coordinate:	-121.31335				
Y Coordinate:	38.70065				
Barrier Area:	Blended Transitions				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at transition into roadway			
As Built Desc:	No detectable warning provided			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Two - way intersection. Corners A,B			

Field Date:	11/12/2010	Report Date:	11/12/2010	Barrier #:	2360
Location:	Skylane Dr and Voyager Wy - Corner B				
X Coordinate:	-121.31326				
Y Coordinate:	38.70064				
Barrier Area:	Blended Transitions				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at transition into roadway			
As Built Desc:	No detectable warning provided			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Two - way intersection. Corners A,B			

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2361

Location: Skylane Dr - North


X Coordinate: -121.31357

Y Coordinate: 38.70061

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 412 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$41,200.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2362

Location: Navion Dr - East


X Coordinate: -121.31470

Y Coordinate: 38.70101

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 403 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$40,300.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2363

Location: Navion Dr and Voyager Wy - Corner C

X Coordinate: -121.31382

Y Coordinate: 38.70201

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2364

Location: Navion Dr and Voyager Wy - Corner D

X Coordinate: -121.31386

Y Coordinate: 38.70196

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2365

Location: Voyager Wy - West


X Coordinate: -121.31376

Y Coordinate: 38.70184

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 490 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$49,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2366

Location: Voyager Wy - East


X Coordinate: -121.31327

Y Coordinate: 38.70087

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 493 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$49,300.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2367

Location: Navion Dr - East

X Coordinate: -121.31358

Y Coordinate: 38.70229

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 403 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$40,300.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2368

Location: Navion Dr and Stearman Wy - Corner C

X Coordinate: -121.31281

Y Coordinate: 38.70302

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2369

Location: Navion Dr and Stearman Wy - Corner D

X Coordinate: -121.31288

Y Coordinate: 38.70298

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2370

Location: Stearman Wy - West


X Coordinate: -121.31265

Y Coordinate: 38.70277

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 874 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$87,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2371

Location: Stearman Wy - East

X Coordinate: -121.31215

Y Coordinate: 38.70102

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 879 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$87,900.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2372

Location: Navion Dr - East


X Coordinate: -121.31264

Y Coordinate: 38.70315

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 237 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$23,700.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2373

Location: Novian Dr and Apache Wy - Corner C

X Coordinate: -121.31204

Y Coordinate: 38.70364

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2374

Location: Novian Dr and Apache Wy - Corner D

X Coordinate: -121.31210

Y Coordinate: 38.70359

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2375

Location: Apache Wy - West


X Coordinate: -121.31175

Y Coordinate: 38.70332

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 1153 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$115,300.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2376

Location: Apache Wy - East


X Coordinate: -121.31099

Y Coordinate: 38.70106

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 1172 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$117,200.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2377

Location: Navion Dr - East


X Coordinate: -121.31193

Y Coordinate: 38.70374

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 246 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$24,600.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2378

Location: Navion Dr and Convair Wy - Corner C

X Coordinate: -121.31130

Y Coordinate: 38.70433

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2379

Location: Navion Dr and Convair Wy - Corner D

X Coordinate: -121.31139

Y Coordinate: 38.70427

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2380

Location: Convair Wy - West


X Coordinate: -121.31112

Y Coordinate: 38.70406

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 1416 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$141,600.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2381

Location: Convair Wy - East

X Coordinate: -121.30989

Y Coordinate: 38.70087

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 1054 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$105,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2382

Location: Piper Ct and Convair Wy - Corner B

X Coordinate: -121.31047

Y Coordinate: 38.70373

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2383

Location: Piper Ct and Convair Wy - Corner C

X Coordinate: -121.31042

Y Coordinate: 38.70367

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2384

Location: Piper Ct - South


X Coordinate: -121.31027

Y Coordinate: 38.70376

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 334 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$33,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2385

Location: Piper Ct - North


X Coordinate: -121.30983

Y Coordinate: 38.70445

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 327 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$32,700.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2386

Location: Convair Wy - East


X Coordinate: -121.31006

Y Coordinate: 38.70404

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 278 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$27,800.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2387

Location: Navion Dr - East


X Coordinate: -121.31120

Y Coordinate: 38.70442

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 868 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$86,800.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/12/2010 Report Date: 11/12/2010 Barrier #: 2388

Location: Van Maren Ln - West

X Coordinate: -121.30878

Y Coordinate: 38.70551

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 756 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 2 Recommended Cost Estimate: \$94,500.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2389

Location: Van Maren Ln - West

X Coordinate: -121.30885

Y Coordinate: 38.7005

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 91 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.9% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 3 Hindrance Cost Estimate: \$11,375.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2390

Location: Van Maren Ln - East

X Coordinate: -121.30888

Y Coordinate: 38.70017

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 90 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$11,250.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/15/2010	Report Date:	11/15/2010	Barrier #:	2391
Location:	Van Maren Ln - West				
X Coordinate:	-121.30886				
Y Coordinate:	38.69989				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	271	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$33,875.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/15/2010	Report Date:	11/15/2010	Barrier #:	2392
Location:	Van Maren Ln and Misty Creek Dr - Corner A				
X Coordinate:	-121.30881				
Y Coordinate:	38.69909				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - New Construction				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (4.1% to 4.9%)		
As Built Desc:	4.4% at 12" grooves - New Construction		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection. Corners A,D		

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2393

Location: Van Maren Ln and Misty Creek Dr - Corner D

X Coordinate: -121.3088

Y Coordinate: 38.69893

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2394

Location: Misty Creek Dr - North

X Coordinate: -121.30894

Y Coordinate: 38.69907

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 175 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$21,875.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2395A

Location: Misty Creek Dr - North

X Coordinate: -121.30978

Y Coordinate: 38.69909

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 609 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$76,125.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2395B

Location: Misty Creek Dr - North

X Coordinate: -121.31059

Y Coordinate: 38.69908

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 30" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary Cost Estimate: \$125.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2396A

Location: Misty Creek Dr - North

X Coordinate: -121.31202

Y Coordinate: 38.69908

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 976 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$122,000.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2396B

Location: Misty Creek Dr - North

X Coordinate: -121.31237

Y Coordinate: 38.69906

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - Tree Heaves

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip due to tree heaves

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2397

Location: Navion Dr - West

X Coordinate: -121.31319

Y Coordinate: 38.69904

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 142 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$17,750.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2398

Location: Navion Dr - West

X Coordinate: -121.31658

Y Coordinate: 38.69845

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 80 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$10,000.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2399A

Location: Tanbark Ct - North

X Coordinate: -121.31737

Y Coordinate: 38.6984

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 53 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$6,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2399B

Location: Tanbark Ct - North

X Coordinate: -121.31737

Y Coordinate: 38.6984

Barrier Area: Sidewalks

Barrier Type: Running Slope (Existing)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 53 Quantity: LF

Description: Running slope exceeds 5.0%

As Built Desc: 8.1% running slope

Solution: No remediation where sidewalk sloped as roadway

Bar. Severity: 5 Technically Infeasible Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2400

Location: Mugho Ct - North

X Coordinate: -121.31739

Y Coordinate: 38.69763

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 107 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$13,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2401

Location: Mugho Ct - South


X Coordinate: -121.31769

Y Coordinate: 38.69751

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 86 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$10,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/15/2010	Report Date:	11/15/2010	Barrier #:	2402A
Location:	Sunmist Wy - West				
X Coordinate:	-121.31721				
Y Coordinate:	38.69728				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	53	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$6,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/15/2010	Report Date:	11/15/2010	Barrier #:	2402B
Location:	Sunmist Wy - West				
X Coordinate:	-121.31727				
Y Coordinate:	38.69719				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1/2" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2403

Location: Sunmist Wy and Ironbark Ct - Corner A

X Coordinate: -121.31712

Y Coordinate: 38.69676

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 7.7% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2404

Location: Sunmist Wy and Ironbark Ct - Corner D

X Coordinate: -121.31721

Y Coordinate: 38.69681

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 7.0% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2405

Location: Sunmist Wy and Maranta Ct - Corner D

X Coordinate: -121.31723

Y Coordinate: 38.69673

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - New Construction

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (>5.0%)

As Built Desc: 6.4% at 12" grooves - New Construction

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D. Corner A compliant

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2406A

Location: Sunmist Wy - West

X Coordinate: -121.31723

Y Coordinate: 38.69591

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 80 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$10,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2406B

Location: Sunmist Wy - West

X Coordinate: -121.31727

Y Coordinate: 38.69582

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 30" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary Cost Estimate: \$125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2407

Location: Sunmist Wy and Twin Wood Wy - Corner A

X Coordinate: -121.31736

Y Coordinate: 38.6952

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 13.8% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2408

Location: Sunmist Wy and Twin Wood Wy - Corner B

X Coordinate: -121.31727

Y Coordinate: 38.69517

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 11.7% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2409

Location: Sunmist Wy and Twin Wood Wy - Corner C


X Coordinate: -121.31731

Y Coordinate: 38.69507

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 11.1% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2410

Location: Sunmist Wy and Twin Wood Wy - Corner D

X Coordinate: -121.3174

Y Coordinate: 38.6951

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 11.0% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2411A

Location: Sunmist Wy - West

X Coordinate: -121.3176

Y Coordinate: 38.69412

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 115 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$14,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2411B

Location: Sunmist Wy - West

X Coordinate: -121.31761

Y Coordinate: 38.69403

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2412

Location: Misty Wood Wy - South

X Coordinate: -121.31764

Y Coordinate: 38.6937

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 996 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 4.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$124,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/15/2010	Report Date:	11/15/2010	Barrier #:	2413
Location:	Sunburst Wy - East				
X Coordinate:	-121.31397				
Y Coordinate:	38.693				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	429	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$53,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:

--

Field Date:	11/15/2010	Report Date:	11/15/2010	Barrier #:	2414
Location:	Sunburst Wy - East				
X Coordinate:	-121.3142				
Y Coordinate:	38.69438				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	435	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$54,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:

--

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2415

Location: Sunburst Wy and Twin Park Dr - Corner B

X Coordinate: -121.31401

Y Coordinate: 38.6957

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - New Construction

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (>5.0%)

As Built Desc: 5.7% at 12" grooves - New Construction

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C. Corner C compliant

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2416A

Location: Sunburst Wy - East

X Coordinate: -121.31409

Y Coordinate: 38.69595

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 850 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$106,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2416B

Location: Sunburst Wy - East

X Coordinate: -121.3161

Y Coordinate: 38.69722

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 28" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary Cost Estimate: \$125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2417

Location: Sunburst Wy and Springleaf Ct - Corner A

X Coordinate: -121.3162

Y Coordinate: 38.6972

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - New Construction

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.6% at 12" grooves - New Construction

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B. Corner B compliant

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2418

Location: Springleaf Ct - East

X Coordinate: -121.31626

Y Coordinate: 38.69747

Barrier Area: Sidewalks

Barrier Type: Running Slope (Existing)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 49 Quantity: LF

Description: Running slope exceeds 5.0%

As Built Desc: 8.7% running slope

Solution: No remediation where sidewalk sloped as roadway

Bar. Severity: 5 Technically Infeasible Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2419

Location: Springleaf Ct - West

X Coordinate: -121.31625

Y Coordinate: 38.69747

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2420

Location: Springleaf Ct - West

X Coordinate: -121.31629

Y Coordinate: 38.6977

Barrier Area: Sidewalks

Barrier Type: Running Slope (Existing)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 49 Quantity: LF

Description: Running slope exceeds 5.0%

As Built Desc: 6.8% running slope

Solution: No remediation where sidewalk sloped as roadway

Bar. Severity: 5 Technically Infeasible Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2421

Location: Springleaf Ct - West

X Coordinate: -121.31639

Y Coordinate: 38.69748

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/15/2010	Report Date:	11/15/2010	Barrier #:	2422
Location:	Sunmist Wy and Sunburst Wy - Corner B				
X Coordinate:	-121.31713				
Y Coordinate:	38.69718				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No compliant curb cut at corner (intersection)			
As Built Desc:	7.9% running slope at depressed area			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Two - way intersection. Corners B,C			

Field Date:	11/15/2010	Report Date:	11/15/2010	Barrier #:	2423
Location:	Sunmist Wy and Sunburst Wy - Corner C				
X Coordinate:	-121.31712				
Y Coordinate:	38.69712				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No compliant curb cut at corner (intersection)			
As Built Desc:	8.4% running slope at depressed area			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Two - way intersection. Corners B,C			

Field Date:	11/15/2010	Report Date:	11/15/2010	Barrier #:	2424
Location:	Sunburst Wy - West				
X Coordinate:	-121.31698				
Y Coordinate:	38.69713				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	923	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	7.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$115,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/15/2010	Report Date:	11/15/2010	Barrier #:	2425
Location:	Sunburst Wy and Twin Wood Wy - Corner A				
X Coordinate:	-121.31412				
Y Coordinate:	38.69494				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	16.4% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection. Corners A,D		

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2426

Location: Sunburst Wy and Twin Wood Wy - Corner D

X Coordinate: -121.31412

Y Coordinate: 38.69502

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 14.7% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2427A

Location: Twin Wood Wy - North

X Coordinate: -121.3143

Y Coordinate: 38.69501

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 152 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$19,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2427B

Location: Twin Wood Wy - North

X Coordinate: -121.31445

Y Coordinate: 38.69502

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2428

Location: Pebblebrook Wy - East

X Coordinate: -121.31487

Y Coordinate: 38.69513

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 530 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$66,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2429

Location: Pebblebrook Wy - North

X Coordinate: -121.31549

Y Coordinate: 38.69631

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 151 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$18,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2430

Location: Pebblebrook Wy - South

X Coordinate: -121.31598

Y Coordinate: 38.69646

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 603 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$75,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/15/2010	Report Date:	11/15/2010	Barrier #:	2431
Location:	Twin Wood Wy - North				
X Coordinate:	-121.31509				
Y Coordinate:	38.69504				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	183	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.8% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$22,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/15/2010	Report Date:	11/15/2010	Barrier #:	2432
Location:	Dawn View Ct and Twin Wood Wy - Corner A				
X Coordinate:	-121.31571				
Y Coordinate:	38.69504				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	14.1% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection. Corners A,B		

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2433

Location: Dawn View Ct and Twin Wood Wy - Corner B

X Coordinate: -121.31579

Y Coordinate: 38.69504

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 11.9% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2434

Location: Dawn View Ct - East

X Coordinate: -121.31572

Y Coordinate: 38.69511

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2435A

Location: Twin Wood Wy - South

X Coordinate: -121.31617

Y Coordinate: 38.69507

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 546 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$68,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2435B

Location: Twin Wood Wy - South

X Coordinate: -121.31524

Y Coordinate: 38.695

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2436A

Location: Sunburst Wy - West

X Coordinate: -121.31412

Y Coordinate: 38.69494

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 190 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$23,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2436B

Location: Sunburst Wy - West

X Coordinate: -121.31413

Y Coordinate: 38.69484

Barrier Area: Sidewalks

Barrier Type: Running Slope (Existing)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 12 Quantity: LF

Description: Running slope exceeds 5.0%

As Built Desc: 9.9% running slope

Solution: No remediation where sidewalk sloped as roadway

Bar. Severity: 5 Technically Infeasible Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/15/2010	Report Date:	11/15/2010	Barrier #:	2437
Location:	Silkwood Wy - North				
X Coordinate:	-121.31489				
Y Coordinate:	38.69437				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	214	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.9% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$26,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/15/2010	Report Date:	11/15/2010	Barrier #:	2438
Location:	Silkwood Wy - South				
X Coordinate:	-121.3159				
Y Coordinate:	38.69435				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	287	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$35,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2439

Location: Sunburst Wy - West

X Coordinate: -121.31408

Y Coordinate: 38.69386

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 45 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$5,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2440

Location: Sunburst Wy and Shady Springs Wy - Corner A

X Coordinate: -121.31406

Y Coordinate: 38.69369

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 10.5% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2441

Location: Sunburst Wy and Shady Springs Wy - Corner D

X Coordinate: -121.31403

Y Coordinate: 38.69361

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 15.9% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2442

Location: Shady Springs Wy - North

X Coordinate: -121.31421

Y Coordinate: 38.69369

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 153 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$19,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/15/2010	Report Date:	11/15/2010	Barrier #:	2443
Location:	Shady Springs Wy - North				
X Coordinate:	-121.31566				
Y Coordinate:	38.69371				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	137	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.9% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$17,125.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	11/15/2010	Report Date:	11/15/2010	Barrier #:	2444
Location:	Shady Springs Wy and Sunmist Wy - Corner B				
X Coordinate:	-121.31756				
Y Coordinate:	38.69372				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No compliant curb cut at corner (intersection)			
As Built Desc:	9.0% running slope at depressed area			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection. Corners B,C
--------	-------------------------------------

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2445

Location: Shady Springs Wy and Sunmist Wy - Corner C

X Coordinate: -121.31757

Y Coordinate: 38.69365

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 9.5% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2446

Location: Shady Springs Wy - South

X Coordinate: -121.31738

Y Coordinate: 38.69366

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 720 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$90,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2447

Location: Sunburst Wy - West

X Coordinate: -121.314

Y Coordinate: 38.69351

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 162 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$20,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2448

Location: Sunburst Wy - West

X Coordinate: -121.31407

Y Coordinate: 38.69303

Barrier Area: Sidewalks

Barrier Type: Elbow in Sidewalk - Cross Slope (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 8 Quantity: LF

Description: Cross slope at elbow exceeds 2.0% (5.0% or more)

As Built Desc: 11.2% cross slope

Solution: Demolish existing and construct new sidewalk without curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2449A

Location: Misty Wood Wy - North

X Coordinate: -121.3144

Y Coordinate: 38.69302

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 695 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$86,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2449B

Location: Misty Wood Wy - North

X Coordinate: -121.3175

Y Coordinate: 38.69308

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2450

Location: Sunmist Wy and Misty Wood Wy

X Coordinate: -121.31756

Y Coordinate: 38.69307

Barrier Area: Sidewalks

Barrier Type: Elbow in Sidewalk - Cross Slope (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 8 Quantity: LF

Description: Cross slope at elbow exceeds 2.0% (5.0% or more)

As Built Desc: 10.2% cross slope

Solution: Demolish existing and construct new sidewalk without curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2451

Location: Sunmist Wy - East

X Coordinate: -121.31757

Y Coordinate: 38.6932

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 176 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$22,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2452

Location: Sunmist Wy - East

X Coordinate: -121.31754

Y Coordinate: 38.69378

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2453

Location: Navion Dr - East

X Coordinate: -121.3169

Y Coordinate: 38.69812

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 56 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$7,000.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2454

Location: Navion Dr - East

X Coordinate: -121.31613

Y Coordinate: 38.6987

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2455

Location: Misty Creek Dr and Court - Corner C

X Coordinate: -121.31484

Y Coordinate: 38.69893

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 10.7% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2456

Location: Misty Creek Dr and Court - Corner D

X Coordinate: -121.31479

Y Coordinate: 38.69893

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 9.7% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2457

Location: Misty Creek Dr - South

X Coordinate: -121.31483

Y Coordinate: 38.69889

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2458A

Location: Misty Creek Dr - South

X Coordinate: -121.31422

Y Coordinate: 38.69894

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 71 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 9.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$8,875.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2458B

Location: Misty Creek Dr - South

X Coordinate: -121.31407

Y Coordinate: 38.69893

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2459

Location: Misty Creek Dr and Starflower Wy - Corner C

X Coordinate: -121.31367

Y Coordinate: 38.69893

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2460A

Location: Misty Creek Dr and Starflower Wy - Corner D

X Coordinate: -121.31378

Y Coordinate: 38.69893

Barrier Area: Curb Ramps

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1127B.5.3 and ADA/ABA 303.3



As Built Meas: 4 Quantity: SF

Description: Change in level greater than 1/2" in curb ramp

As Built Desc: 1/2" lip in curb ramp surface

Solution: Grind or repair to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2460B

Location: Misty Creek Dr and Starflower Wy - Corner D

X Coordinate: -121.31378

Y Coordinate: 38.69893

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$1,400.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2461

Location: Starflower Wy - West

X Coordinate: -121.31375

Y Coordinate: 38.69881

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 445 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$55,625.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	11/15/2010	Report Date:	11/15/2010	Barrier #:	2462
Location:	Hillspire Ct - North				
X Coordinate:	-121.31325				
Y Coordinate:	38.69764				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	221	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$27,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/15/2010	Report Date:	11/15/2010	Barrier #:	2463
Location:	Hillspire Ct - South				
X Coordinate:	-121.31371				
Y Coordinate:	38.6973				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	197	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.9% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$24,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/15/2010	Report Date:	11/15/2010	Barrier #:	2464
Location:	Starflower Dr - West				
X Coordinate:	-121.31317				
Y Coordinate:	38.69756				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	177	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$22,125.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/15/2010	Report Date:	11/15/2010	Barrier #:	2465A
Location:	Starflower Dr - West				
X Coordinate:	-121.31276				
Y Coordinate:	38.69722				
Barrier Area:	Sidewalks				
Barrier Type:	No Sidewalk - No Barricade				
Code Ref:	MUTCD Section 6D.01				



As Built Meas:	1	Quantity:	JOB
Description:	No barricade provided where sidewalk ends in hazardous location		
As Built Desc:	No barricade or other warning provided for the visually impaired at end of sidewalk		
Solution:	Provide barricade with cane detectable warning at end of sidewalk		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,350.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2465B

Location: Starflower Dr - West

X Coordinate: -121.31276

Y Coordinate: 38.69722

Barrier Area: Sidewalks

Barrier Type: No Sidewalk - Transition to Shoulder

Code Ref: CBC 1121B.2 and ADA/ABA 206.2.1



As Built Meas: 1 Quantity: JOB

Description: Sidewalk ends and no ramp to pedestrian shoulder is provided

As Built Desc: No ramp to shoulder to enable pedestrian travel onto existing shoulder

Solution: Provide transition ramp to paved shoulder where no opposite sidewalk exists

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2466

Location: Starflower Dr - West

X Coordinate: -121.31225

Y Coordinate: 38.69673

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (2.1% to 3.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 297 Quantity: LF

Description: Cross slope exceeds 2.0% (2.1% to 3.0%)

As Built Desc: 2.4% cross slope

Solution: Low severity barrier - no remediation recommended

Bar. Severity: 4 Low Severity Cost Estimate: \$0.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2467

Location: Creekmont Wy and Starflower Dr - Corner B

X Coordinate: -121.3121

Y Coordinate: 38.69658

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (4.1% to 4.9%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (4.1% to 4.9%)

As Built Desc: 4.4% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 2 Recommended

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,D

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2468A

Location: Creekmont Wy and Starflower Dr - Corner D

X Coordinate: -121.3121

Y Coordinate: 38.6965

Barrier Area: Curb Ramps

Barrier Type: Lip - Bottom of Ramp at Flow Line

Code Ref: CBC 1127B.5.3 and ADA/ABA 303.3



As Built Meas: 1 Quantity: EACH

Description: Transition at ramp bottom (flow line) is not flush and free of any lip

As Built Desc: 1" lip at flow line

Solution: Remove lip to create flush transition

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,D

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2468B

Location: Creekmont Wy and Starflower Dr - Corner D

X Coordinate: -121.3121

Y Coordinate: 38.6965

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,D

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2468C

Location: Creekmont Wy and Starflower Dr - Corner D

X Coordinate: -121.3121

Y Coordinate: 38.6965

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (>5.0% or more)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level (>5.0% or more)

As Built Desc: 6.9% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2469

Location: Creekmont Wy - South

X Coordinate: -121.31196

Y Coordinate: 38.69656

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 522 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$65,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2470A

Location: Creekmont Wy - East

X Coordinate: -121.31002

Y Coordinate: 38.69669

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 594 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$74,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2470B

Location: Creekmont Wy - East

X Coordinate: -121.30994

Y Coordinate: 38.69713

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2471

Location: Creekmont Wy - North

X Coordinate: -121.30964

Y Coordinate: 38.69834

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 256 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$32,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2472

Location: Sunwood Wy and Creekmont Wy - Corner B

X Coordinate: -121.31057

Y Coordinate: 38.69835

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 16.4% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2473

Location: Sunwood Wy and Creekmont Wy - Corner C

X Coordinate: -121.31057

Y Coordinate: 38.69829

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 10.9% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date:	11/15/2010	Report Date:	11/15/2010	Barrier #:	2474
Location:	Creekmont Wy - South				
X Coordinate:	-121.31042				
Y Coordinate:	38.69828				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	208	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$26,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/15/2010	Report Date:	11/15/2010	Barrier #:	2475
Location:	Creekmont Wy - South				
X Coordinate:	-121.30966				
Y Coordinate:	38.69828				
Barrier Area:	Sidewalks				
Barrier Type:	Elbow in Sidewalk - Cross Slope (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	6	Quantity:	LF
Description:	Cross slope at elbow exceeds 2.0% (5.0% or more)		
As Built Desc:	12.2% cross slope		
Solution:	Demolish existing and construct new sidewalk without curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2476A

Location: Creekmont Wy - West

X Coordinate: -121.30965

Y Coordinate: 38.69815

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 544 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$68,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2476B

Location: Creekmont Wy - West

X Coordinate: -121.31009

Y Coordinate: 38.69695

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2477

Location: Creekmont Wy - West

X Coordinate: -121.31007

Y Coordinate: 38.69672

Barrier Area: Sidewalks

Barrier Type: Elbow in Sidewalk - Cross Slope (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 6 Quantity: LF

Description: Cross slope at elbow exceeds 2.0% (5.0% or more)

As Built Desc: 13.1% cross slope

Solution: Demolish existing and construct new sidewalk without curb ramp

Bar. Severity: 1 Necessary

Cost Estimate: \$750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2478

Location: Creekmont Wy - North

X Coordinate: -121.31031

Y Coordinate: 38.69671

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 493 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$61,625.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2479

Location: Starflower Dr - East

X Coordinate: -121.31211

Y Coordinate: 38.69666

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 179 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$22,375.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2480A

Location: Starflower Dr - East

X Coordinate: -121.31254

Y Coordinate: 38.69714

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 711 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$88,875.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/15/2010 Report Date: 11/15/2010 Barrier #: 2480B

Location: Starflower Dr - East

X Coordinate: -121.313

Y Coordinate: 38.69762

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2481

Location: Misty Creek Dr - South

X Coordinate: -121.31392

Y Coordinate: 38.69894

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 173 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$21,625.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2482A

Location: Mossview Wy and Misty Creek Dr - Corner C

X Coordinate: -121.31285

Y Coordinate: 38.69894

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.8% in 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2482B

Location: Mossview Wy and Misty Creek Dr - Corner C

X Coordinate: -121.31285

Y Coordinate: 38.69894

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2482C

Location: Mossview Wy and Misty Creek Dr - Corner C

X Coordinate: -121.31285

Y Coordinate: 38.69894

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 8.1% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2483

Location: Mossview Wy and Misty Creek Dr - Corner D

X Coordinate: -121.31299

Y Coordinate: 38.69895

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2484

Location: Mossview Wy - West

X Coordinate: -121.31291

Y Coordinate: 38.69876

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 364 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$45,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2485

Location: Mossview Wy - South


X Coordinate: -121.31205

Y Coordinate: 38.69796

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 433 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$54,125.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2486A

Location: Mossview Wy and Sunwood Wy - Corner A

X Coordinate: -121.31073

Y Coordinate: 38.69808

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (>5.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (>5.0%)

As Built Desc: 7.0% in 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2486B

Location: Mossview Wy and Sunwood Wy - Corner A

X Coordinate: -121.31073

Y Coordinate: 38.69808

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2487A

Location: Mossview Wy and Sunwood Wy - Corner D

X Coordinate: -121.31072

Y Coordinate: 38.698

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2487B

Location: Mossview Wy and Sunwood Wy - Corner D

X Coordinate: -121.31072

Y Coordinate: 38.698

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (8.3% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (8.3% or more)

As Built Desc: 9.0% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2488

Location: Sunwood Wy - West


X Coordinate: -121.31066

Y Coordinate: 38.69785

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 169 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$21,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2489

Location: Sunwood Wy - West

X Coordinate: -121.31082

Y Coordinate: 38.69741

Barrier Area: Sidewalks

Barrier Type: Elbow in Sidewalk - Cross Slope (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 8 Quantity: LF

Description: Cross slope at elbow exceeds 2.0% (5.0% or more)

As Built Desc: 14.9% cross slope

Solution: Demolish existing and construct new sidewalk without curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2490

Location: Sunwood Wy - North


X Coordinate: -121.31106

Y Coordinate: 38.6974

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 453 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$56,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2491

Location: Sunwood Wy - South


X Coordinate: -121.31126

Y Coordinate: 38.69735

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 477 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$59,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2492

Location: Sunwood Wy - East


X Coordinate: -121.31071

Y Coordinate: 38.69753

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 447 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$55,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2493

Location: Sunwood Wy - East

X Coordinate: -121.3106

Y Coordinate: 38.69856

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 194 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$24,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2494A

Location: Sunwood Wy and Misty Creek Dr - Corner C

X Coordinate: -121.31058

Y Coordinate: 38.69893

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.6% in 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2494B

Location: Sunwood Wy and Misty Creek Dr - Corner C

X Coordinate: -121.31058

Y Coordinate: 38.69893

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2495A

Location: Sunwood Wy and Misty Creek Dr - Corner D

X Coordinate: -121.31069

Y Coordinate: 38.69894

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.4% in 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2495B

Location: Sunwood Wy and Misty Creek Dr - Corner D

X Coordinate: -121.31069

Y Coordinate: 38.69894

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$0.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2496

Location: Sunwood Wy - West


X Coordinate: -121.31069

Y Coordinate: 38.69869

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 250 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$31,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2497

Location: Mossview Wy - North


X Coordinate: -121.3109

Y Coordinate: 38.69808

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 162 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$20,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2498

Location: Mossview Wy and Sage Oak Ct - Corner A

X Coordinate: -121.31161

Y Coordinate: 38.69806

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2499

Location: Mossview Wy and Sage Oak Ct - Corner B

X Coordinate: -121.3115

Y Coordinate: 38.69807

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2500

Location: Sage Oak Ct - East


X Coordinate: -121.31141

Y Coordinate: 38.69819

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 97 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$12,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2501

Location: Sage Oak Ct - West

X Coordinate: -121.31164

Y Coordinate: 38.69819

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 77 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$9,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2502A

Location: Mossview Wy - North


X Coordinate: -121.31171

Y Coordinate: 38.69807

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 172 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$21,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2502B

Location: Mossview Wy - North

X Coordinate: -121.31178

Y Coordinate: 38.69806

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2503

Location: Mossview Wy - North

X Coordinate: -121.31231

Y Coordinate: 38.69806

Barrier Area: Sidewalks

Barrier Type: Elbow in Sidewalk - Cross Slope (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 8 Quantity: LF

Description: Cross slope at elbow exceeds 2.0% (5.0% or more)

As Built Desc: 18.6% cross slope

Solution: Demolish existing and construct new sidewalk without curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2504

Location: Mossview Wy - East


X Coordinate: -121.31242

Y Coordinate: 38.69817

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 318 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$39,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2505

Location: Misty Creek Dr - South


X Coordinate: -121.31281

Y Coordinate: 38.69875

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 556 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$69,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2506

Location: Misty Creek Dr - South


X Coordinate: -121.31025

Y Coordinate: 38.69896

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 428 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$53,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2507

Location: Van Maren Ln - West

X Coordinate: -121.30878

Y Coordinate: 38.69867

Barrier Area: Sidewalks

Barrier Type: Drop-off Along Ped Route (> 4")

Code Ref: CBC 1133B.8.1



As Built Meas: 1313 Quantity: LF

Description: Drop of more than 4" along pedestrian route lacks warning curb

As Built Desc: 7" drop off creates hazardous condition for the visually impaired

Solution: Provide curb projecting at least 6" above the walk or sidewalk surface to warn the blind of a potent

Bar. Severity: 1 Necessary Cost Estimate: \$229,775.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2508

Location: Bridgemont Wy and Van Maren Ln - Corner A

X Coordinate: -121.30886

Y Coordinate: 38.69524

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2509

Location: Bridgemont Wy and Van Maren Ln - Corner D

X Coordinate: -121.30882

Y Coordinate: 38.69515

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2510

Location: Bridgemont Wy - North


X Coordinate: -121.30904

Y Coordinate: 38.69526

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 497 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$62,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2511

Location: Bridgemont Wy - North

X Coordinate: -121.31054

Y Coordinate: 38.69538

Barrier Area: Sidewalks

Barrier Type: No Sidewalk - Transition to Shoulder

Code Ref: CBC 1121B.2 and ADA/ABA 206.2.1



As Built Meas: 1 Quantity: JOB

Description: Sidewalk ends and no ramp to pedestrian shoulder is provided

As Built Desc: No ramp to shoulder to enable pedestrian travel onto existing shoulder

Solution: Provide transition ramp to paved shoulder where no opposite sidewalk exists

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2512

Location: Bridgemont Wy - North


X Coordinate: -121.31082

Y Coordinate: 38.69536

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 119 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$14,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2513A

Location: Bridgemont Wy and Wonner Wy - Corner A

X Coordinate: -121.31142

Y Coordinate: 38.69527

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2513B

Location: Bridgemont Wy and Wonner Wy - Corner A

X Coordinate: -121.31142

Y Coordinate: 38.69527

Barrier Area: Curb Ramps

Barrier Type: Lip - Bottom of Ramp at Flow Line

Code Ref: CBC 1127B.5.3 and ADA/ABA 303.3



As Built Meas: 1 Quantity: EACH

Description: Transition at ramp bottom (flow line) is not flush and free of any lip

As Built Desc: 1/2" lip at flow line

Solution: Remove lip to create flush transition

Bar. Severity: 1 Necessary Cost Estimate: \$250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2513C

Location: Bridgemont Wy and Wonner Wy - Corner A

X Coordinate: -121.31142

Y Coordinate: 38.69527

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.3% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2514A

Location: Bridgemont Wy and Wonner Wy - Corner B

X Coordinate: -121.31128

Y Coordinate: 38.69533

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (4.1% to 4.9%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (4.1% to 4.9%)

As Built Desc: 4.3% in 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 2 Recommended Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2514B

Location: Bridgemont Wy and Wonner Wy - Corner B

X Coordinate: -121.31128

Y Coordinate: 38.69533

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level (3.1% to 4.0%)

As Built Desc: 3.6% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 3 Hindrance Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2514C

Location: Bridgemont Wy and Wonner Wy - Corner B

X Coordinate: -121.31128

Y Coordinate: 38.69533

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2514D

Location: Bridgemont Wy and Wonner Wy - Corner B

X Coordinate: -121.31128

Y Coordinate: 38.69533

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 8.0% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2515A

Location: Bridgemont Wy and Wonner Wy - Corner C

X Coordinate: -121.3112

Y Coordinate: 38.69516

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (>5.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (>5.0%)

As Built Desc: 5.8% in 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2515B

Location: Bridgemont Wy and Wonner Wy - Corner C

X Coordinate: -121.3112

Y Coordinate: 38.69516

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level (3.1% to 4.0%)

As Built Desc: 3.6% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 3 Hindrance Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2515C

Location: Bridgemont Wy and Wonner Wy - Corner C

X Coordinate: -121.3112

Y Coordinate: 38.69516

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2515D

Location: Bridgemont Wy and Wonner Wy - Corner C

X Coordinate: -121.3112

Y Coordinate: 38.69516

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.5% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2516A

Location: Bridgemont Wy and Wonner Wy - Corner D

X Coordinate: -121.31137

Y Coordinate: 38.69514

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2516B

Location: Bridgemont Wy and Wonner Wy - Corner D

X Coordinate: -121.31137

Y Coordinate: 38.69514

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.1% - 5.8%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.1% - 5.8%)

As Built Desc: 5.4% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 4 Low Severity

Cost Estimate: \$750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2517

Location: Twin Brook Ct and Twin Park Dr - Corner A

X Coordinate: -121.31167

Y Coordinate: 38.69586

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$1,400.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2518A

Location: Twin Brook Ct and Twin Park Dr - Corner B

X Coordinate: -121.3115

Y Coordinate: 38.69589

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (4.1% to 4.9%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (4.1% to 4.9%)

As Built Desc: 4.3% in 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 2 Recommended Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2518B

Location: Twin Brook Ct and Twin Park Dr - Corner B

X Coordinate: -121.3115

Y Coordinate: 38.69589

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level (3.1% to 4.0%)

As Built Desc: 3.6% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 3 Hindrance Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2518C

Location: Twin Brook Ct and Twin Park Dr - Corner B

X Coordinate: -121.3115

Y Coordinate: 38.69589

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2518D

Location: Twin Brook Ct and Twin Park Dr - Corner B

X Coordinate: -121.3115

Y Coordinate: 38.69589

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (8.3% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (8.3% or more)

As Built Desc: 8.5% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2519A

Location: Twin Brook Ct and Twin Park Dr - Corner C

X Coordinate: -121.31146

Y Coordinate: 38.69578

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.8% in 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2519B

Location: Twin Brook Ct and Twin Park Dr - Corner C

X Coordinate: -121.31146

Y Coordinate: 38.69578

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2519C

Location: Twin Brook Ct and Twin Park Dr - Corner C

X Coordinate: -121.31146

Y Coordinate: 38.69578

Barrier Area: Curb Ramps

Barrier Type: Lip - Bottom of Ramp at Flow Line

Code Ref: CBC 1127B.5.3 and ADA/ABA 303.3



As Built Meas: 1 Quantity: EACH

Description: Transition at ramp bottom (flow line) is not flush and free of any lip

As Built Desc: 1/2" lip at flow line

Solution: Remove lip to create flush transition

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2519D

Location: Twin Brook Ct and Twin Park Dr - Corner C

X Coordinate: -121.31146

Y Coordinate: 38.69578

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.9% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2520A

Location: Twin Brook Ct and Twin Park Dr - Corner D

X Coordinate: -121.31161

Y Coordinate: 38.69571

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (4.1% to 4.9%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (4.1% to 4.9%)

As Built Desc: 4.1% in 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 2 Recommended Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2520B

Location: Twin Brook Ct and Twin Park Dr - Corner D

X Coordinate: -121.31161

Y Coordinate: 38.69571

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level (3.1% to 4.0%)

As Built Desc: 3.8% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 3 Hindrance Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2520C

Location: Twin Brook Ct and Twin Park Dr - Corner D

X Coordinate: -121.31161

Y Coordinate: 38.69571

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2520D

Location: Twin Brook Ct and Twin Park Dr - Corner D

X Coordinate: -121.31161

Y Coordinate: 38.69571

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (8.3% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (8.3% or more)

As Built Desc: 9.7% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2521

Location: Oak Branch Ct - South


X Coordinate: -121.31069

Y Coordinate: 38.69594

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 278 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$34,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2522

Location: Oak Branch Ct - North

X Coordinate: -121.31035

Y Coordinate: 38.69606

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 117 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$14,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2523

Location: Twin Park Dr - North


X Coordinate: -121.31241

Y Coordinate: 38.69589

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 55 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$6,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2524A

Location: Twin Park Dr and Rollingside Ct - Corner A

X Coordinate: -121.31272

Y Coordinate: 38.69591

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2524B

Location: Twin Park Dr and Rollingside Ct - Corner A

X Coordinate: -121.31272

Y Coordinate: 38.69591

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 6.7% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2525A

Location: Twin Park Dr and Rollingside Ct - Corner B

X Coordinate: -121.31259

Y Coordinate: 38.69593

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2525B

Location: Twin Park Dr and Rollingside Ct - Corner B

X Coordinate: -121.31259

Y Coordinate: 38.69593

Barrier Area: Curb Ramps

Barrier Type: Lip - Bottom of Ramp at Flow Line

Code Ref: CBC 1127B.5.3 and ADA/ABA 303.3



As Built Meas: 1 Quantity: EACH

Description: Transition at ramp bottom (flow line) is not flush and free of any lip

As Built Desc: 1/2" lip at flow line

Solution: Remove lip to create flush transition

Bar. Severity: 1 Necessary Cost Estimate: \$250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2525C

Location: Twin Park Dr and Rollingside Ct - Corner B

X Coordinate: -121.31259

Y Coordinate: 38.69593

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.9% - 6.5%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.9% - 6.5%)

As Built Desc: 6.2% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 3 Hindrance Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:


Notes: Two - way intersection. Corners A,B

Field Date:	11/16/2010	Report Date:	11/16/2010	Barrier #:	2526
Location:	Rollingside Ct - East				
X Coordinate:	-121.3126				
Y Coordinate:	38.69611				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	36	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$4,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/16/2010	Report Date:	11/16/2010	Barrier #:	2527
Location:	Rollingside Ct - East				
X Coordinate:	-121.31266				
Y Coordinate:	38.6963				
Barrier Area:	Sidewalks				
Barrier Type:	Elbow in Sidewalk - Cross Slope (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	12	Quantity:	LF
Description:	Cross slope at elbow exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.5% cross slope		
Solution:	Demolish existing and construct new sidewalk without curb ramp		
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2528A

Location: Twin Park Dr - North


X Coordinate: -121.31277

Y Coordinate: 38.69623

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 175 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$21,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2528B

Location: Twin Park Dr - North

X Coordinate: -121.31369

Y Coordinate: 38.69582

Barrier Area: Sidewalks

Barrier Type: Running Slope (Existing)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 8 Quantity: LF

Description: Running slope exceeds 5.0%

As Built Desc: 6.3% running slope

Solution: No remediation where sidewalk sloped as roadway

Bar. Severity: 5 Technically Infeasible Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2529A

Location: Twin Park Dr - South


X Coordinate: -121.31384

Y Coordinate: 38.6957

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 238 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$29,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2529B

Location: Twin Park Dr - South

X Coordinate: -121.31319

Y Coordinate: 38.69578

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2530

Location: Twin Park Dr - South


X Coordinate: -121.31297

Y Coordinate: 38.69573

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 290 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$36,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2531

Location: Wonner Wy - West


X Coordinate: -121.31155

Y Coordinate: 38.69561

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 33 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance

Cost Estimate: \$4,125.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2532A

Location: Treetop Ct and Oak Bend Wy - Corner C

X Coordinate: -121.31217

Y Coordinate: 38.69502

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2532B

Location: Treetop Ct and Oak Bend Wy - Corner C

X Coordinate: -121.31217

Y Coordinate: 38.69502

Barrier Area: Curb Ramps

Barrier Type: Lip - Bottom of Ramp at Flow Line

Code Ref: CBC 1127B.5.3 and ADA/ABA 303.3



As Built Meas: 1 Quantity: EACH

Description: Transition at ramp bottom (flow line) is not flush and free of any lip

As Built Desc: 1" lip at flow line

Solution: Remove lip to create flush transition

Bar. Severity: 1 Necessary Cost Estimate: \$250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2532C

Location: Treetop Ct and Oak Bend Wy - Corner C

X Coordinate: -121.31217

Y Coordinate: 38.69502

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 6.6% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2533

Location: Treetop Ct and Oak Bend Wy - Corner D

X Coordinate: -121.31238

Y Coordinate: 38.69503

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2534

Location: Wonner Wy - West


X Coordinate: -121.31131

Y Coordinate: 38.69498

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 190 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$23,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2535

Location: Bridgemont Wy - South

X Coordinate: -121.31066

Y Coordinate: 38.6953

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2536

Location: Bridgemont Wy - South


X Coordinate: -121.31036

Y Coordinate: 38.69525

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 22 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.9% cross slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 4 Low Severity Cost Estimate: \$2,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2537

Location: Bridgemont Wy - South

X Coordinate: -121.31019

Y Coordinate: 38.69521

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 2 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Broken concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2538

Location: Bridgemont Wy - South


X Coordinate: -121.31011

Y Coordinate: 38.69521

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 174 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$21,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2539A

Location: Bridgemont Wy and Dancing Creek Ct - Corner C

X Coordinate: -121.30935

Y Coordinate: 38.69508

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (4.1% to 4.9%)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level(4.1% to 4.9%)

As Built Desc: 4.1% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 2 Recommended Cost Estimate: \$250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2539B

Location: Bridgemont Wy and Dancing Creek Ct - Corner C

X Coordinate: -121.30935

Y Coordinate: 38.69508

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2539C

Location: Bridgemont Wy and Dancing Creek Ct - Corner C

X Coordinate: -121.30935

Y Coordinate: 38.69508

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.1% - 5.8%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.1% - 5.8%)

As Built Desc: 5.5% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 4 Low Severity Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2540A

Location: Bridgemont Wy and Dancing Creek Ct - Corner D

X Coordinate: -121.30948

Y Coordinate: 38.6951

Barrier Area: Curb Ramps

Barrier Type: Running Slope - Existing (9.0% to 9.4%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.1



As Built Meas: 1 Quantity: EACH

Description: Ramp run cross slope exceeds 2.0% (9.0% to 9.4%)

As Built Desc: 9.0% running slope

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 2 Recommended Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2540B

Location: Bridgemont Wy and Dancing Creek Ct - Corner D


X Coordinate: -121.30948

Y Coordinate: 38.6951

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2540C

Location: Bridgemont Wy and Dancing Creek Ct - Corner D

X Coordinate: -121.30948

Y Coordinate: 38.6951

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.1% - 5.8%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.1% - 5.8%)

As Built Desc: 5.5% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 4 Low Severity Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2541

Location: Dancing Creek Ct - East


X Coordinate: -121.30938

Y Coordinate: 38.69478

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 98 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$12,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2542

Location: Bridgemont Wy - South

X Coordinate: -121.30917

Y Coordinate: 38.69515

Barrier Area: Sidewalks

Barrier Type: Cross Slope - New Construction

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 100 Quantity: LF

Description: Cross slope exceeds 2.0% in new construction

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$12,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2543

Location: Van Maren Ln - West

X Coordinate: -121.30879

Y Coordinate: 38.69489

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 534 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.3% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 3 Hindrance Cost Estimate: \$66,750.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2544

Location: Van Maren Ln - West


X Coordinate: -121.30889

Y Coordinate: 38.69339

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 35 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$4,375.00

Status:

Implementation Priority: 1

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2545

Location: Van Maren Ln - West


X Coordinate: -121.3089

Y Coordinate: 38.69276

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 185 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$23,125.00

Status:

Implementation Priority: 1

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2546A

Location: Van Maren Ln - West

X Coordinate: -121.30891

Y Coordinate: 38.69252

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2546B

Location: Van Maren Ln - West

X Coordinate: -121.30891

Y Coordinate: 38.69252

Barrier Area: Curb Ramps

Barrier Type: Lip - Bottom of Ramp at Flow Line

Code Ref: CBC 1127B.5.3 and ADA/ABA 303.3



As Built Meas: 1 Quantity: EACH

Description: Transition at ramp bottom (flow line) is not flush and free of any lip

As Built Desc: 1/2" lip at flow line

Solution: Remove lip to create flush transition

Bar. Severity: 1 Necessary Cost Estimate: \$250.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2546C

Location: Van Maren Ln - West

X Coordinate: -121.30891

Y Coordinate: 38.69252

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (8.3% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (8.3% or more)

As Built Desc: 11.1% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary

Cost Estimate: \$750.00

Status:

Implementation Priority: 1

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2547

Location: Van Maren Ln - West


X Coordinate: -121.30893

Y Coordinate: 38.69246

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 53 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$6,625.00

Status:

Implementation Priority: 1

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2548

Location: Van Maren Ln and Campfire Wy - Corner A

X Coordinate: -121.30894

Y Coordinate: 38.69226

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2549

Location: Van Maren Ln and Campfire Wy - Corner D

X Coordinate: -121.30893

Y Coordinate: 38.69214

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2550

Location: Campfire Wy - North


X Coordinate: -121.30937

Y Coordinate: 38.69228

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 436 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$54,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2551A

Location: Campfire Wy and Ranch House Wy - Corner B

X Coordinate: -121.31116

Y Coordinate: 38.69195

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2551B

Location: Campfire Wy and Ranch House Wy - Corner B

X Coordinate: -121.31116

Y Coordinate: 38.69195

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.6% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2552A

Location: Campfire Wy and Ranch House Wy - Corner C

X Coordinate: -121.31109

Y Coordinate: 38.69185

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2552B

Location: Campfire Wy and Ranch House Wy - Corner C

X Coordinate: -121.31109

Y Coordinate: 38.69185

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.9% - 6.5%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.9% - 6.5%)

As Built Desc: 6.3% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 3 Hindrance Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2553A

Location: Campfire Wy and Ranch House Wy - Corner D

X Coordinate: -121.3112

Y Coordinate: 38.69181

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2553B

Location: Campfire Wy and Ranch House Wy - Corner D

X Coordinate: -121.3112

Y Coordinate: 38.69181

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.0% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2554A

Location: Campfire Wy and Barnwood Ct - Corner B

X Coordinate: -121.31238

Y Coordinate: 38.69125

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2554B

Location: Campfire Wy and Barnwood Ct - Corner B

X Coordinate: -121.31238

Y Coordinate: 38.69125

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.2% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2555A

Location: Campfire Wy and Barnwood Ct - Corner C

X Coordinate: -121.31222

Y Coordinate: 38.69121

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2555B

Location: Campfire Wy and Barnwood Ct - Corner C

X Coordinate: -121.31222

Y Coordinate: 38.69121

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.6% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2556A

Location: Campfire Wy and Barnwood Ct - Corner D

X Coordinate: -121.31233

Y Coordinate: 38.6911

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2556B

Location: Campfire Wy and Barnwood Ct - Corner D

X Coordinate: -121.31233

Y Coordinate: 38.6911

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.9% - 6.5%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.9% - 6.5%)

As Built Desc: 5.9% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 3 Hindrance Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2557A

Location: Campfire Wy and Ranch Hand Wy - Corner B

X Coordinate: -121.31293

Y Coordinate: 38.69056

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2557B

Location: Campfire Wy and Ranch Hand Wy - Corner B

X Coordinate: -121.31293

Y Coordinate: 38.69056

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.9% - 6.5%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.9% - 6.5%)

As Built Desc: 6.4% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 3 Hindrance Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2558A

Location: Campfire Wy and Ranch Hand Wy - Corner C

X Coordinate: -121.31278

Y Coordinate: 38.69049

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2558B

Location: Campfire Wy and Ranch Hand Wy - Corner C

X Coordinate: -121.31278

Y Coordinate: 38.69049

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.9% - 6.5%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.9% - 6.5%)

As Built Desc: 6.2% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 3 Hindrance Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2559A

Location: Campfire Wy and Ranch Hand Wy - Corner D


X Coordinate: -121.31286

Y Coordinate: 38.69041

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2559B

Location: Campfire Wy and Ranch Hand Wy - Corner D

X Coordinate: -121.31286

Y Coordinate: 38.69041

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.9% - 6.5%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.9% - 6.5%)

As Built Desc: 6.2% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 3 Hindrance Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2560

Location: Campfire Wy - West


X Coordinate: -121.3132

Y Coordinate: 38.6901

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 23 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$2,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2561

Location: Cowboy Wy and Silver Saddle Wy - Corner B

X Coordinate: -121.3129

Y Coordinate: 38.68967

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2562A

Location: Cowboy Wy and Silver Saddle Wy - Corner C

X Coordinate: -121.31278

Y Coordinate: 38.68963

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2562B

Location: Cowboy Wy and Silver Saddle Wy - Corner C

X Coordinate: -121.31278

Y Coordinate: 38.68963

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.3% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended

Cost Estimate: \$750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2563A

Location: Cowboy Wy and Silver Saddle Wy - Corner D

X Coordinate: -121.3129

Y Coordinate: 38.68967

Barrier Area: Curb Ramps

Barrier Type: Running Slope - Existing (9.5% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.1



As Built Meas: 1 Quantity: EACH

Description: Ramp run cross slope exceeds 2.0% (9.5% or more)

As Built Desc: 9.9% running slope

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2563B

Location: Cowboy Wy and Silver Saddle Wy - Corner D

X Coordinate: -121.3129

Y Coordinate: 38.68967

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2563C

Location: Cowboy Wy and Silver Saddle Wy - Corner D

X Coordinate: -121.3129

Y Coordinate: 38.68967

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.3% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2564A

Location: Silver Saddle Wy and Trailride Wy - Corner B

X Coordinate: -121.31333

Y Coordinate: 38.68907

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2564B

Location: Silver Saddle Wy and Trailride Wy - Corner B

X Coordinate: -121.31333

Y Coordinate: 38.68907

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (8.3% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (8.3% or more)

As Built Desc: 8.6% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date:	11/16/2010	Report Date:	11/16/2010	Barrier #:	2565A
Location:	Silver Saddle Wy and Trailride Wy - Corner C				
X Coordinate:	-121.31322				
Y Coordinate:	38.68904				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH	
Description:	12" grooves at top of curb ramp are not level (3.1% to 4.0%)			
As Built Desc:	3.8% in 12" grooves			
Solution:	Demolish existing and construct new curb ramp			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Three - way intersection. Corners B,C,D			

Field Date:	11/16/2010	Report Date:	11/16/2010	Barrier #:	2565B
Location:	Silver Saddle Wy and Trailride Wy - Corner C				
X Coordinate:	-121.31322				
Y Coordinate:	38.68904				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Three - way intersection. Corners B,C,D			

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2565C

Location: Silver Saddle Wy and Trailride Wy - Corner C

X Coordinate: -121.31322

Y Coordinate: 38.68904

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.8% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2566

Location: Silver Saddle Wy and Trailride Wy - Corner D

X Coordinate: -121.31326

Y Coordinate: 38.68894

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2567

Location: Silver Saddle Wy and Oak Lake Ln - Corner A

X Coordinate: -121.3134

Y Coordinate: 38.68859

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2568A

Location: Silver Saddle Wy and Oak Lake Ln - Corner B

X Coordinate: -121.31333

Y Coordinate: 38.68858

Barrier Area: Curb Ramps

Barrier Type: Running Slope - Existing (9.5% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.1



As Built Meas: 1 Quantity: EACH

Description: Ramp run cross slope exceeds 2.0% (9.5% or more)

As Built Desc: 11.1% running slope

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2568B

Location: Silver Saddle Wy and Oak Lake Ln - Corner B

X Coordinate: -121.31333

Y Coordinate: 38.68858

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 4.0% in 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2568C

Location: Silver Saddle Wy and Oak Lake Ln - Corner B

X Coordinate: -121.31333

Y Coordinate: 38.68858

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level (3.1% to 4.0%)

As Built Desc: 3.8% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 3 Hindrance Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2568D

Location: Silver Saddle Wy and Oak Lake Ln - Corner B

X Coordinate: -121.31333

Y Coordinate: 38.68858

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2568E

Location: Silver Saddle Wy and Oak Lake Ln - Corner B

X Coordinate: -121.31333

Y Coordinate: 38.68858

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.0% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2569A

Location: Oak Lake Ln and Van Maren Ln - Corner A

X Coordinate: -121.30889

Y Coordinate: 38.68854

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level (3.1% to 4.0%)

As Built Desc: 3.9% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 3 Hindrance

Cost Estimate: \$250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2569B

Location: Oak Lake Ln and Van Maren Ln - Corner A

X Coordinate: -121.30889

Y Coordinate: 38.68854

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$1,400.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2570

Location: Oak Lake Ln and Van Maren Ln - Corner D

X Coordinate: -121.30887

Y Coordinate: 38.68842

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 15.6% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2571

Location: Van Maren Ln - West


X Coordinate: -121.30888

Y Coordinate: 38.68877

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 30 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$3,750.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2572

Location: Van Maren Ln - West


X Coordinate: -121.30896

Y Coordinate: 38.68987

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 105 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$13,125.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2573A

Location: Van Maren Ln and Horseman Wy - Corner A

X Coordinate: -121.30889

Y Coordinate: 38.69049

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (4.1% to 4.9%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (4.1% to 4.9%)

As Built Desc: 4.2% in 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 2 Recommended Cost Estimate: \$2,500.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2573B

Location: Van Maren Ln and Horseman Wy - Corner A

X Coordinate: -121.30889

Y Coordinate: 38.69049

Barrier Area: Curb Ramps

Barrier Type: Running Slope - Existing (9.5% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.1



As Built Meas: 1 Quantity: EACH

Description: Ramp run cross slope exceeds 2.0% (9.5% or more)

As Built Desc: 10.3% running slope

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2573C

Location: Van Maren Ln and Horseman Wy - Corner A

X Coordinate: -121.30889

Y Coordinate: 38.69049

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2573D

Location: Van Maren Ln and Horseman Wy - Corner A

X Coordinate: -121.30889

Y Coordinate: 38.69049

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.6% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2574A

Location: Van Maren Ln and Horseman Wy - Corner D

X Coordinate: -121.30891

Y Coordinate: 38.69037

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2574B

Location: Van Maren Ln and Horseman Wy - Corner D

X Coordinate: -121.30891

Y Coordinate: 38.69037

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.9% - 6.5%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.9% - 6.5%)

As Built Desc: 6.2% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 3 Hindrance Cost Estimate: \$750.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/16/2010 Report Date: 11/16/2010 Barrier #: 2575

Location: Van Maren Ln - West


X Coordinate: -121.30891

Y Coordinate: 38.69059

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 531 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$66,375.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2576

Location: Campfire Wy - South


X Coordinate: -121.30911

Y Coordinate: 38.69212

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 65 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$8,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2577A

Location: Campfire Wy and Trailride Wy - Corner C

X Coordinate: -121.30933

Y Coordinate: 38.69211

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (>5.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (>5.0%)

As Built Desc: 6.4% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2577B

Location: Campfire Wy and Trailride Wy - Corner C

X Coordinate: -121.30933

Y Coordinate: 38.69211

Barrier Area: Curb Ramps

Barrier Type: Running Slope - Existing (9.0% to 9.4%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.1



As Built Meas: 1 Quantity: EACH

Description: Ramp run cross slope exceeds 2.0% (9.0% to 9.4%)

As Built Desc: 9.4% landing slope

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 2 Recommended

Cost Estimate: \$0.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2577C

Location: Campfire Wy and Trailride Wy - Corner C

X Coordinate: -121.30933

Y Coordinate: 38.69211

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level (3.1% to 4.0%)

As Built Desc: 3.5% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 3 Hindrance

Cost Estimate: \$0.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2577D

Location: Campfire Wy and Trailride Wy - Corner C

X Coordinate: -121.30933

Y Coordinate: 38.69211

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2577E

Location: Campfire Wy and Trailride Wy - Corner C

X Coordinate: -121.30933

Y Coordinate: 38.69211

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 8.0% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2578A

Location: Campfire Wy and Trailride Wy - Corner D

X Coordinate: -121.30947

Y Coordinate: 38.69211

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (>5.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (>5.0%)

As Built Desc: 5.2% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2578B

Location: Campfire Wy and Trailride Wy - Corner D

X Coordinate: -121.30947

Y Coordinate: 38.69211

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level (3.1% to 4.0%)

As Built Desc: 3.2% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 3 Hindrance Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2578C

Location: Campfire Wy and Trailride Wy - Corner D

X Coordinate: -121.30947

Y Coordinate: 38.69211

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$0.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2578D

Location: Campfire Wy and Trailride Wy - Corner D

X Coordinate: -121.30947

Y Coordinate: 38.69211

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (8.3% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (8.3% or more)

As Built Desc: 9.3% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary

Cost Estimate: \$0.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2579A

Location: Campfire Wy and Saddle Horse Wy - Corner C

X Coordinate: -121.31022

Y Coordinate: 38.69204

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (4.1% to 4.9%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (4.1% to 4.9%)

As Built Desc: 4.6% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 2 Recommended Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2579B

Location: Campfire Wy and Saddle Horse Wy - Corner C

X Coordinate: -121.31022

Y Coordinate: 38.69204

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level (3.1% to 4.0%)

As Built Desc: 4.0% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 3 Hindrance Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2579C

Location: Campfire Wy and Saddle Horse Wy - Corner C

X Coordinate: -121.31022

Y Coordinate: 38.69204

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2579D

Location: Campfire Wy and Saddle Horse Wy - Corner C

X Coordinate: -121.31022

Y Coordinate: 38.69204

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.8% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2580A

Location: Campfire Wy and Saddle Horse Wy - Corner D

X Coordinate: -121.31034

Y Coordinate: 38.69204

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level (3.1% to 4.0%)

As Built Desc: 3.9% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 3 Hindrance Cost Estimate: \$250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2580B

Location: Campfire Wy and Saddle Horse Wy - Corner D

X Coordinate: -121.31034

Y Coordinate: 38.69204

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2580C

Location: Campfire Wy and Saddle Horse Wy - Corner D

X Coordinate: -121.31034

Y Coordinate: 38.69204

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.0% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2581A

Location: Campfire Wy - East


X Coordinate: -121.3124

Y Coordinate: 38.69104

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 28" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary Cost Estimate: \$125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2581B

Location: Campfire Wy - East

X Coordinate: -121.31245

Y Coordinate: 38.691

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 63 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$7,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2582A

Location: Ranch House Wy and Cowboy Wy - Corner A

X Coordinate: -121.31114

Y Coordinate: 38.68965

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2582B

Location: Ranch House Wy and Cowboy Wy - Corner A

X Coordinate: -121.31114

Y Coordinate: 38.68965

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.1% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended

Cost Estimate: \$750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2583A

Location: Ranch House Wy and Cowboy Wy - Corner B

X Coordinate: -121.31102

Y Coordinate: 38.68967

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$1,400.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2583B

Location: Ranch House Wy and Cowboy Wy - Corner B

X Coordinate: -121.31102

Y Coordinate: 38.68967

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (8.3% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (8.3% or more)

As Built Desc: 8.3% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2584A

Location: Ranch House Wy and Cowboy Wy - Corner C

X Coordinate: -121.31102

Y Coordinate: 38.68956

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2584B

Location: Ranch House Wy and Cowboy Wy - Corner C

X Coordinate: -121.31102

Y Coordinate: 38.68956

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.1% - 5.8%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.1% - 5.8%)

As Built Desc: 5.5% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 4 Low Severity Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2585A

Location: Ranch House Wy and Cowboy Wy - Corner D

X Coordinate: -121.31115

Y Coordinate: 38.68956

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2585B

Location: Ranch House Wy and Cowboy Wy - Corner D

X Coordinate: -121.31115

Y Coordinate: 38.68956

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.0% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended

Cost Estimate: \$750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2586A

Location: Ranch House Wy and Ranch Hand Wy - Corner A

X Coordinate: -121.31118

Y Coordinate: 38.69031

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$1,400.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2586B

Location: Ranch House Wy and Ranch Hand Wy - Corner A

X Coordinate: -121.31118

Y Coordinate: 38.69031

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.0% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended

Cost Estimate: \$750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2587A

Location: Ranch House Wy and Ranch Hand Wy - Corner D

X Coordinate: -121.31117

Y Coordinate: 38.69021

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$1,400.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2587B

Location: Ranch House Wy and Ranch Hand Wy - Corner D

X Coordinate: -121.31117

Y Coordinate: 38.69021

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.0% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2588

Location: Saddle Horse Wy - West

X Coordinate: -121.31036

Y Coordinate: 38.69186

Barrier Area: Sidewalks

Barrier Type: Running Slope (Existing)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 55 Quantity: LF

Description: Running slope exceeds 5.0%

As Built Desc: 6.0% running slope

Solution: No remediation where sidewalk sloped as roadway

Bar. Severity: 5 Technically Infeasible Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2589

Location: Saddle Horse Wy - East

X Coordinate: -121.31025

Y Coordinate: 38.69188

Barrier Area: Sidewalks

Barrier Type: Running Slope (Existing)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 41 Quantity: LF

Description: Running slope exceeds 5.0%

As Built Desc: 6.3% running slope

Solution: No remediation where sidewalk sloped as roadway

Bar. Severity: 5 Technically Infeasible Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2590A

Location: Saddle Horse Wy and Horseman Wy - Corner B

X Coordinate: -121.31012

Y Coordinate: 38.69039

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level (3.1% to 4.0%)

As Built Desc: 3.8% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 3 Hindrance Cost Estimate: \$250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date:	11/17/2010	Report Date:	11/17/2010	Barrier #:	2590B
Location:	Saddle Horse Wy and Horseman Wy - Corner B				
X Coordinate:	-121.31012				
Y Coordinate:	38.69039				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH
Description:	No truncated domes provided at curb ramp		
As Built Desc:	No detectable warnings at curb ramp		
Solution:	Provide compliant truncated domes		
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection. Corners B,C		

Field Date:	11/17/2010	Report Date:	11/17/2010	Barrier #:	2590C
Location:	Saddle Horse Wy and Horseman Wy - Corner B				
X Coordinate:	-121.31012				
Y Coordinate:	38.69039				
Barrier Area:	Curb Ramps				
Barrier Type:	Gutter Slope - Existing (5.9% - 6.5%)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.2				



As Built Meas:	6	Quantity:	SF
Description:	Gutter slope exceeds 5.0% (5.9% - 6.5%)		
As Built Desc:	6.0% gutter slope		
Solution:	Demolish existing and construct new gutter		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection. Corners B,C		

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2591A

Location: Saddle Horse Wy and Horseman Wy - Corner C

X Coordinate: -121.31014

Y Coordinate: 38.69028

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (4.1% to 4.9%)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level(4.1% to 4.9%)

As Built Desc: 4.3% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 2 Recommended Cost Estimate: \$250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2591B

Location: Saddle Horse Wy and Horseman Wy - Corner C

X Coordinate: -121.31014

Y Coordinate: 38.69028

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2591C

Location: Saddle Horse Wy and Horseman Wy - Corner C

X Coordinate: -121.31014

Y Coordinate: 38.69028

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.9% - 6.5%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.9% - 6.5%)

As Built Desc: 6.0% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 3 Hindrance Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2592A

Location: Trailride Wy and Horseman Wy - Corner A

X Coordinate: -121.3095

Y Coordinate: 38.6904

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2592B

Location: Trailride Wy and Horseman Wy - Corner A

X Coordinate: -121.3095

Y Coordinate: 38.6904

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.9% - 6.5%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.9% - 6.5%)

As Built Desc: 6.5% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 3 Hindrance Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2593A

Location: Trailride Wy and Horseman Wy - Corner B

X Coordinate: -121.30928

Y Coordinate: 38.6904

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level (3.1% to 4.0%)

As Built Desc: 3.8% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 3 Hindrance Cost Estimate: \$250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2593B

Location: Trailride Wy and Horseman Wy - Corner B

X Coordinate: -121.30928

Y Coordinate: 38.6904

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2593C

Location: Trailride Wy and Horseman Wy - Corner B

X Coordinate: -121.30928

Y Coordinate: 38.6904

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.9% - 6.5%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.9% - 6.5%)

As Built Desc: 6.2% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 3 Hindrance Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2594A

Location: Trailride Wy and Horseman Wy - Corner C

X Coordinate: -121.30928

Y Coordinate: 38.69028

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (4.1% to 4.9%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (4.1% to 4.9%)

As Built Desc: 4.8% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 2 Recommended

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2594B

Location: Trailride Wy and Horseman Wy - Corner C

X Coordinate: -121.30928

Y Coordinate: 38.69028

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level (3.1% to 4.0%)

As Built Desc: 3.8% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 3 Hindrance

Cost Estimate: \$0.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2594C

Location: Trailride Wy and Horseman Wy - Corner C

X Coordinate: -121.30928

Y Coordinate: 38.69028

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2594D

Location: Trailride Wy and Horseman Wy - Corner C

X Coordinate: -121.30928

Y Coordinate: 38.69028

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 6.9% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2595A

Location: Trailride Wy and Horseman Wy - Corner D

X Coordinate: -121.30948

Y Coordinate: 38.6903

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2595B

Location: Trailride Wy and Horseman Wy - Corner D

X Coordinate: -121.30948

Y Coordinate: 38.6903

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.1% - 5.8%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.1% - 5.8%)

As Built Desc: 5.5% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 4 Low Severity Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2596A

Location: Ranch House Wy and Trailride Wy - Corner A

X Coordinate: -121.31117

Y Coordinate: 38.68898

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2596B

Location: Ranch House Wy and Trailride Wy - Corner A

X Coordinate: -121.31117

Y Coordinate: 38.68898

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.9% - 6.5%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.9% - 6.5%)

As Built Desc: 6.3% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 3 Hindrance Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2597A

Location: Ranch House Wy and Trailride Wy - Corner B

X Coordinate: -121.31103

Y Coordinate: 38.68898

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2597B

Location: Ranch House Wy and Trailride Wy - Corner B

X Coordinate: -121.31103

Y Coordinate: 38.68898

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.9% - 6.5%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.9% - 6.5%)

As Built Desc: 6.4% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 3 Hindrance Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2598

Location: Ranch House Wy - West

X Coordinate: -121.31101

Y Coordinate: 38.68927

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 54 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.4% cross slope

Solution: Demolish existing and construct new route


Bar. Severity: 3 Hindrance Cost Estimate: \$6,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2599

Location: Trailride Wy - East

X Coordinate: -121.30934

Y Coordinate: 38.6894

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1

As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 24" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width


Bar. Severity: 1 Necessary Cost Estimate: \$125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2600A

Location: Trailride Wy and Lasso Ct - Corner B

X Coordinate: -121.30956

Y Coordinate: 38.68904

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2600B

Location: Trailride Wy and Lasso Ct - Corner B

X Coordinate: -121.30956

Y Coordinate: 38.68904

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.9% - 6.5%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.9% - 6.5%)

As Built Desc: 6.4% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 3 Hindrance Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2601A

Location: Trailride Wy and Lasso Ct - Corner C

X Coordinate: -121.3097

Y Coordinate: 38.68895

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.8% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2601B

Location: Trailride Wy and Lasso Ct - Corner C

X Coordinate: -121.3097

Y Coordinate: 38.68895

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level (3.1% to 4.0%)

As Built Desc: 3.4% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 3 Hindrance Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2601C

Location: Trailride Wy and Lasso Ct - Corner C

X Coordinate: -121.3097

Y Coordinate: 38.68895

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2602

Location: Trailride Wy - East


X Coordinate: -121.30989

Y Coordinate: 38.6889

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing (32" to 35")

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide (32" to 35")

As Built Desc: 24" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 2 Recommended Cost Estimate: \$125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2603

Location: Oak Lake Ln - South


X Coordinate: -121.31346

Y Coordinate: 38.68844

Barrier Area: Sidewalks

Barrier Type: No Sidewalk - No Barricade

Code Ref: MUTCD Section 6D.01



As Built Meas: 1 Quantity: JOB

Description: No barricade provided where sidewalk ends in hazardous location

As Built Desc: No barricade or other warning provided for the visually impaired at end of sidewalk

Solution: Provide barricade with cane detectable warning at end of sidewalk

Bar. Severity: 1 Necessary Cost Estimate: \$1,350.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2604

Location: Oak Lake Ln - North


X Coordinate: -121.31327

Y Coordinate: 38.68844

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 1287 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$160,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2605

Location: Van Maren Ln - West


X Coordinate: -121.30885

Y Coordinate: 38.68828

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 78 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$9,750.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2606

Location: Van Maren Ln - West


X Coordinate: -121.30887

Y Coordinate: 38.68812

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 6 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 4 Low Severity Cost Estimate: \$750.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2607

Location: Auburn Blvd - North

X Coordinate: -121.30925

Y Coordinate: 38.68681

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 59 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$7,375.00

Status:

Implementation Priority: 1

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2608

Location: Auburn Blvd - North

X Coordinate: -121.30952

Y Coordinate: 38.68661

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 96 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$12,000.00

Status:

Implementation Priority: 1

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2609A

Location: Auburn Blvd and Chatham Wy - Corner A

X Coordinate: -121.30994

Y Coordinate: 38.68643

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (>5.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (>5.0%)

As Built Desc: 5.8% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2609B

Location: Auburn Blvd and Chatham Wy - Corner A

X Coordinate: -121.30994

Y Coordinate: 38.68643

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (8.3% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (8.3% or more)

As Built Desc: 19.3% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2610

Location: Auburn Blvd and Chatham Wy - Corner B

X Coordinate: -121.30986

Y Coordinate: 38.68649

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (>5.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (>5.0%)

As Built Desc: 5.8% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2611

Location: Chatham Wy - East


X Coordinate: -121.30992

Y Coordinate: 38.68657

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 64 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$8,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2612A

Location: Chatham Wy - East


X Coordinate: -121.31022

Y Coordinate: 38.68675

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 79 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$9,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2612B

Location: Chatham Wy - East

X Coordinate: -121.3104

Y Coordinate: 38.68686

Barrier Area: Sidewalks

Barrier Type: Running Slope (Existing)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 8 Quantity: LF

Description: Running slope exceeds 5.0%

As Built Desc: 6.0% running slope

Solution: No remediation where sidewalk sloped as roadway

Bar. Severity: 5 Technically Infeasible Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2613

Location: Chatham Wy and Melbourne Wy - Corner C

X Coordinate: -121.31048

Y Coordinate: 38.6869

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (>5.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (>5.0%)

As Built Desc: 6.9% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2614

Location: Chatham Wy and Melbourne Wy - Corner D

X Coordinate: -121.31055

Y Coordinate: 38.68678

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2615

Location: Melbourne Wy - South


X Coordinate: -121.31045

Y Coordinate: 38.68716

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 90 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$11,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2616A

Location: Melbourne Wy and Westbrook Dr - Corner C

X Coordinate: -121.31043

Y Coordinate: 38.68771

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (4.1% to 4.9%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (4.1% to 4.9%)

As Built Desc: 4.4% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 2 Recommended Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2616B

Location: Melbourne Wy and Westbrook Dr - Corner C

X Coordinate: -121.31043

Y Coordinate: 38.68771

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (8.3% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (8.3% or more)

As Built Desc: 9.3% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2617A

Location: Melbourne Wy and Westbrook Dr - Corner D

X Coordinate: -121.31058

Y Coordinate: 38.68771

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - New Construction

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.8% at 12" grooves - New Construction

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2617B

Location: Melbourne Wy and Westbrook Dr - Corner D

X Coordinate: -121.31058

Y Coordinate: 38.68771

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - New Construction

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.9% - 6.5%)

As Built Desc: 6.4% gutter slope - New Construction

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2618A

Location: Westbrook Dr - North


X Coordinate: -121.31032

Y Coordinate: 38.68772

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 530 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$66,250.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2618B

Location: Westbrook Dr - North

X Coordinate: -121.31021

Y Coordinate: 38.68772

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2618C

Location: Westbrook Dr - North

X Coordinate: -121.31013

Y Coordinate: 38.68774

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 30" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2619

Location: Westbrook Dr - North

X Coordinate: -121.31034

Y Coordinate: 38.68784

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 808 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$101,000.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2620

Location: Westbrook Dr and Halifax St - Corner C

X Coordinate: -121.31317

Y Coordinate: 38.68778

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2621

Location: Westbrook Dr and Halifax St - Corner D

X Coordinate: -121.31337

Y Coordinate: 38.68776

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2622

Location: Westbrook Dr - South


X Coordinate: -121.31294

Y Coordinate: 38.6878

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 467 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$58,375.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2623

Location: Westbrook Dr and Wellsboro Wy - Corner C

X Coordinate: -121.31127

Y Coordinate: 38.68775

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2624

Location: Westbrook Dr and Wellsboro Wy - Corner D

X Coordinate: -121.3114

Y Coordinate: 38.68775

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2625

Location: Westbrook Dr - South


X Coordinate: -121.31111

Y Coordinate: 38.68777

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 166 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$20,750.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2626

Location: Melbourne Wy - West

X Coordinate: -121.31076

Y Coordinate: 38.68676

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 449 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 8.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$56,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2627

Location: Wellsboro Wy and Melbourne Wy - Corner A

X Coordinate: -121.31199

Y Coordinate: 38.68581

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2628

Location: Wellsboro Wy and Melbourne Wy - Corner B

X Coordinate: -121.31189

Y Coordinate: 38.68591

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2629

Location: Wellsboro Wy - East


X Coordinate: -121.31197

Y Coordinate: 38.68599

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 735 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$91,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2630A

Location: Wellsboro Wy - South

X Coordinate: -121.31223

Y Coordinate: 38.68621

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 505 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$63,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2630B

Location: Wellsboro Wy - East


X Coordinate: -121.31137

Y Coordinate: 38.68711

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 28" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary Cost Estimate: \$125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2630C

Location: Wellsboro Wy - East

X Coordinate: -121.3113

Y Coordinate: 38.68733

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - $> 1/2"$

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than $1/2"$

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2630D

Location: Wellsboro Wy - East

X Coordinate: -121.31129

Y Coordinate: 38.68741

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2631

Location: Wellsboro Wy - West


X Coordinate: -121.3114

Y Coordinate: 38.68754

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 322 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$40,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2632

Location: Wellsboro Wy and Derby Ct - Corner A

X Coordinate: -121.31202

Y Coordinate: 38.68673

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2633

Location: Wellsboro Wy and Derby Ct - Corner B

X Coordinate: -121.31192

Y Coordinate: 38.68681

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2634

Location: Derby Ct - East

X Coordinate: -121.3121

Y Coordinate: 38.68696

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 172 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$21,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2635A

Location: Derby Ct - West

X Coordinate: -121.31247

Y Coordinate: 38.68699

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 202 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$25,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2635B

Location: Derby Ct - West

X Coordinate: -121.31234

Y Coordinate: 38.68694

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2636A

Location: Wellsboro Wy - West

X Coordinate: -121.31243

Y Coordinate: 38.68638

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 382 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$47,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2636B

Location: Wellsboro Wy - West

X Coordinate: -121.31207

Y Coordinate: 38.68595

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2637A

Location: Melbourne Wy - North


X Coordinate: -121.31215

Y Coordinate: 38.68573

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 350 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$43,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2637B

Location: Melbourne Wy - North

X Coordinate: -121.31269

Y Coordinate: 38.68549

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2638

Location: Melbourne Wy and Halifax St - Corner B

X Coordinate: -121.3132

Y Coordinate: 38.68535

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2639

Location: Melbourne Wy and Halifax St - Corner C

X Coordinate: -121.31317

Y Coordinate: 38.68525

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2640

Location: Melbourne Wy - South


X Coordinate: -121.31287

Y Coordinate: 38.68533

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 903 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$112,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/17/2010 Report Date: 11/17/2010 Barrier #: 2641

Location: Chatham Wy - West


X Coordinate: -121.31041

Y Coordinate: 38.68675

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 108 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$13,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2642A

Location: Van Maren Ln - West

X Coordinate: -121.3093

Y Coordinate: 38.68681

Barrier Area: Bus Stops and Shelters

Barrier Type: Bench Seat Depth

Code Ref: ADAAG 4.37.1 and ADA/ABA 903.4



As Built Meas: 1 Quantity: EACH

Description: Bench seat depth not 20" - 24" deep

As Built Desc: 9-1/2" bench seat depth

Solution: Provide min. 1 accessible bench at bench stop

Bar. Severity: 3 Hindrance Cost Estimate: \$775.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2642B

Location: Van Maren Ln - West

X Coordinate: -121.3093

Y Coordinate: 38.68681

Barrier Area: Bus Stops and Shelters

Barrier Type: Bench Back Support

Code Ref: ADAAG 4.37.4 and ADA/ABA 903.4



As Built Meas: 1 Quantity: EACH

Description: Bench has no back support of at least 18" high

As Built Desc: No back support provided

Solution: Provide min. 1 accessible bench at bench stop or shelter

Bar. Severity: 3 Hindrance Cost Estimate: \$0.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2643A

Location: Auburn Blvd - Frontage Rd - North

X Coordinate: -121.31007

Y Coordinate: 38.6863

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 1012 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$126,500.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2643B

Location: Auburn Blvd - Frontage Rd - North

X Coordinate: -121.31009

Y Coordinate: 38.68628

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 30" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary Cost Estimate: \$125.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2643C

Location: Auburn Blvd - Frontage Rd - North

X Coordinate: -121.31216

Y Coordinate: 38.68478

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - $> 1/2"$

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than $1/2"$

As Built Desc: $1/2"$ lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2643D

Location: Auburn Blvd - Frontage Rd - North

X Coordinate: -121.31257

Y Coordinate: 38.68445

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2644

Location: Halifax St - East

X Coordinate: -121.31279

Y Coordinate: 38.68444

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 307 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$38,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2645

Location: Halifax St - East

X Coordinate: -121.31327

Y Coordinate: 38.68544

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 460 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$57,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2646

Location: Halifax St - East

X Coordinate: -121.31323

Y Coordinate: 38.6868

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 390 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$48,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/18/2010	Report Date:	11/18/2010	Barrier #:	2647A
Location:	Westbrook Dr - North				
X Coordinate:	-121.31322				
Y Coordinate:	38.68789				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	1336	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.0% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$167,000.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	11/18/2010	Report Date:	11/18/2010	Barrier #:	2647B
Location:	Westbrook Dr - North				
X Coordinate:	-121.31365				
Y Coordinate:	38.68792				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ($\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	4	Quantity:	LF	
Description:	Pedestrian route is not min. 48" wide ($\leq 31"$ or less)			
As Built Desc:	28" clear width due to pole			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2647C

Location: Westbrook Dr - North

X Coordinate: -121.31407

Y Coordinate: 38.68791

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 28" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2647D

Location: Westbrook Dr - North

X Coordinate: -121.31452

Y Coordinate: 38.6879

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 26" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2647E

Location: Westbrook Dr - North

X Coordinate: -121.31491

Y Coordinate: 38.68791

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 24" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2647F

Location: Westbrook Dr - North

X Coordinate: -121.3153

Y Coordinate: 38.68783

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 28" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2647G

Location: Westbrook Dr - North

X Coordinate: -121.31565

Y Coordinate: 38.68766

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 28" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2647H

Location: Westbrook Dr - North

X Coordinate: -121.31598

Y Coordinate: 38.68746

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 30" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 26471

Location: Westbrook Dr - North

X Coordinate: -121.31664

Y Coordinate: 38.68704

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 30" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 26471

Location: Westbrook Dr - North

X Coordinate: -121.31698

Y Coordinate: 38.68683

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 28" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2647K

Location: Westbrook Dr - North

X Coordinate: -121.31729

Y Coordinate: 38.68665

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 30" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2648A

Location: Westbrook Dr - West

X Coordinate: -121.31735

Y Coordinate: 38.68655

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 995 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$124,375.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2648B

Location: Westbrook Dr - West

X Coordinate: -121.31742

Y Coordinate: 38.68643

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 30" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2648C

Location: Westbrook Dr - West

X Coordinate: -121.31762

Y Coordinate: 38.6854

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 31" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2648D

Location: Westbrook Dr - West

X Coordinate: -121.31765

Y Coordinate: 38.68517

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2648E

Location: Westbrook Dr - West

X Coordinate: -121.31767

Y Coordinate: 38.68507

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 30" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2648F

Location: Westbrook Dr - West

X Coordinate: -121.31769

Y Coordinate: 38.68478

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 30" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2648G

Location: Westbrook Dr - West

X Coordinate: -121.31766

Y Coordinate: 38.68441

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 30" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2648H

Location: Westbrook Dr - West

X Coordinate: -121.31766

Y Coordinate: 38.6844

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2648I

Location: Westbrook Dr - West

X Coordinate: -121.31765

Y Coordinate: 38.68423

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2648J

Location: Westbrook Dr - West

X Coordinate: -121.31764

Y Coordinate: 38.68407

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 28" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2649

Location: Westbrook Dr and Brantford Wy - Corner A

X Coordinate: -121.31767

Y Coordinate: 38.68391

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2650

Location: Westbrook Dr and Brantford Wy - Corner D

X Coordinate: -121.31766

Y Coordinate: 38.68375

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2651

Location: Brantford Wy - North

X Coordinate: -121.31779

Y Coordinate: 38.68389

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 88 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$11,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2652

Location: Brantford Wy - South

X Coordinate: -121.318

Y Coordinate: 38.68378

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 86 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$10,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2653A

Location: Westbrook Dr - West

X Coordinate: -121.31771

Y Coordinate: 38.68371

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 121 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$15,125.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2653B

Location: Westbrook Dr - West

X Coordinate: -121.31764

Y Coordinate: 38.68361

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 31" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2654A

Location: Westbrook Wy and Appleby Wy - Corner C

X Coordinate: -121.31738

Y Coordinate: 38.68339

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date:	11/18/2010	Report Date:	11/18/2010	Barrier #:	2654B
Location:	Westbrook Wy and Appleby Wy - Corner C				
X Coordinate:	-121.31738				
Y Coordinate:	38.68339				
Barrier Area:	Curb Ramps				
Barrier Type:	Gutter Slope - Existing (6.6% to 8.2%)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.2				



As Built Meas:	6	Quantity:	SF	
Description:	Gutter slope exceeds 5.0% (6.6% to 8.2%)			
As Built Desc:	8.0% gutter slope			
Solution:	Demolish existing and construct new gutter			
Bar. Severity:	2 Recommended	Cost Estimate:	\$750.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Two - way intersection. Corners C,D			

Field Date:	11/18/2010	Report Date:	11/18/2010	Barrier #:	2655A
Location:	Westbrook Wy and Appleby Wy - Corner D				
X Coordinate:	-121.31747				
Y Coordinate:	38.68343				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Two - way intersection. Corners C,D			

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2655B

Location: Westbrook Wy and Appleby Wy - Corner D

X Coordinate: -121.31747

Y Coordinate: 38.68343

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 8.2% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$750.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2656A

Location: Appleby Wy - West

X Coordinate: -121.31749

Y Coordinate: 38.68338

Barrier Area: Sidewalks

Barrier Type: Cross Slope - New Construction

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 209 Quantity: LF

Description: Cross slope exceeds 2.0% in new construction

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$26,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2656B

Location: Appleby Wy - West

X Coordinate: -121.318

Y Coordinate: 38.68308

Barrier Area: Sidewalks

Barrier Type: No Sidewalk - No Barricade

Code Ref: MUTCD Section 6D.01



As Built Meas: 1 Quantity: JOB

Description: No barricade provided where sidewalk ends in hazardous location

As Built Desc: No barricade or other warning provided for the visually impaired at end of sidewalk

Solution: Provide barricade with cane detectable warning at end of sidewalk

Bar. Severity: 1 Necessary Cost Estimate: \$1,350.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2657

Location: Appleby Wy - East


X Coordinate: -121.318

Y Coordinate: 38.68298

Barrier Area: Sidewalks

Barrier Type: No Sidewalk - No Barricade

Code Ref: MUTCD Section 6D.01



As Built Meas: 1 Quantity: JOB

Description: No barricade provided where sidewalk ends in hazardous location

As Built Desc: No barricade or other warning provided for the visually impaired at end of sidewalk

Solution: Provide barricade with cane detectable warning at end of sidewalk

Bar. Severity: 1 Necessary Cost Estimate: \$1,350.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2658

Location: Appleby Wy - East

X Coordinate: -121.31787

Y Coordinate: 38.683

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 146 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$18,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2659

Location: Appleby Wy - East

X Coordinate: -121.31743

Y Coordinate: 38.68329

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 39 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$4,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2660A

Location: Westbrook Dr - South

X Coordinate: -121.31721

Y Coordinate: 38.68339

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 1010 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$126,250.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2660B

Location: Westbrook Dr - South

X Coordinate: -121.31672

Y Coordinate: 38.68345

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 26" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2660C

Location: Westbrook Dr - South

X Coordinate: -121.31631

Y Coordinate: 38.68352

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 30" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2660D

Location: Westbrook Dr - South


X Coordinate: -121.31631

Y Coordinate: 38.68352

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 4 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/18/2010	Report Date:	11/18/2010	Barrier #:	2660E
Location:	Westbrook Dr - South				
X Coordinate:	-121.31593				
Y Coordinate:	38.68363				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ($\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	4	Quantity:	LF	
Description:	Pedestrian route is not min. 48" wide ($\leq 31"$ or less)			
As Built Desc:	30" clear width due to pole			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	11/18/2010	Report Date:	11/18/2010	Barrier #:	2660F
Location:	Westbrook Dr - South				
X Coordinate:	-121.31557				
Y Coordinate:	38.68375				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ($\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	4	Quantity:	LF	
Description:	Pedestrian route is not min. 48" wide ($\leq 31"$ or less)			
As Built Desc:	28" clear width due to pole			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2660G

Location: Westbrook Dr - South

X Coordinate: -121.31517

Y Coordinate: 38.68394

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 30" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2660H

Location: Westbrook Dr - South

X Coordinate: -121.31477

Y Coordinate: 38.68408

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 30" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2660I

Location: Westbrook Dr - South

X Coordinate: -121.31426

Y Coordinate: 38.68427

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2660J

Location: Westbrook Dr - South

X Coordinate: -121.31398

Y Coordinate: 38.68438

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 28" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2660K

Location: Westbrook Dr - South

X Coordinate: -121.31398

Y Coordinate: 38.68438

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 4 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2660L

Location: Westbrook Dr - South

X Coordinate: -121.31355

Y Coordinate: 38.68456

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31''$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31''$ or less)

As Built Desc: 30" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2661

Location: Westbrook Dr and Halifax St - Corner A

X Coordinate: -121.31327

Y Coordinate: 38.6848

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2662

Location: Westbrook Dr and Halifax St - Corner D

X Coordinate: -121.31321

Y Coordinate: 38.68467

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2663A

Location: Westbrook Dr - North

X Coordinate: -121.31335

Y Coordinate: 38.68472

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 1232 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$154,000.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2663B

Location: Westbrook Dr - North

X Coordinate: -121.31336

Y Coordinate: 38.68471

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/18/2010	Report Date:	11/18/2010	Barrier #:	2664
Location:	Westbrook Dr - East				
X Coordinate:	-121.3174				
Y Coordinate:	38.68355				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	194	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$24,250.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	11/18/2010	Report Date:	11/18/2010	Barrier #:	2665
Location:	Westbrook Dr and Cheltenham Wy - Corner B				
X Coordinate:	-121.3175				
Y Coordinate:	38.68417				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	Two - way intersection. Corners B,C
--------	-------------------------------------

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2666

Location: Westbrook Dr and Cheltenham Wy - Corner C

X Coordinate: -121.31752

Y Coordinate: 38.68407

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2667

Location: Chetelham Wy - South

X Coordinate: -121.31745

Y Coordinate: 38.68407

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 43 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$5,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2668A

Location: Chetelham Wy - South

X Coordinate: -121.317

Y Coordinate: 38.68411

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 903 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$112,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2668B

Location: Chetelham Wy - South

X Coordinate: -121.31698

Y Coordinate: 38.68411

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2668C

Location: Chetelham Wy - East

X Coordinate: -121.31411

Y Coordinate: 38.68509

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 276 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$34,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2669A

Location: Cheltenham Wy and Trenton Wy - Corner B

X Coordinate: -121.31437

Y Coordinate: 38.68598

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.8% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2669B

Location: Cheltenham Wy and Trenton Wy - Corner B

X Coordinate: -121.31437

Y Coordinate: 38.68598

Barrier Area: Curb Ramps

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 1 Quantity: EACH

Description: Ramp run cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 2 Recommended

Cost Estimate: \$0.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2669C

Location: Cheltenham Wy and Trenton Wy - Corner B

X Coordinate: -121.31437

Y Coordinate: 38.68598

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$0.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Three - way intersection corners B,C,D

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2669D

Location: Cheltenham Wy and Trenton Wy - Corner B

X Coordinate: -121.31437

Y Coordinate: 38.68598

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (8.3% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (8.3% or more)

As Built Desc: 11.6% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2670A

Location: Cheltenham Wy and Trenton Wy - Corner C (A-B)

X Coordinate: -121.31429

Y Coordinate: 38.68587

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (>5.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (>5.0%)

As Built Desc: 5.4% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection corners B,C,D

Field Date:	11/18/2010	Report Date:	11/18/2010	Barrier #:	2670B
Location:	Cheltenham Wy and Trenton Wy - Corner C (A-B)				
X Coordinate:	-121.31429				
Y Coordinate:	38.68587				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH
Description:	No truncated domes provided at curb ramp		
As Built Desc:	No detectable warnings at curb ramp		
Solution:	Provide compliant truncated domes		
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Three - way intersection corners B,C,D		

Field Date:	11/18/2010	Report Date:	11/18/2010	Barrier #:	2671A
Location:	Cheltenham Wy and Trenton Wy - Corner C (A-A)				
X Coordinate:	-121.31432				
Y Coordinate:	38.68579				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (2.1% to 3.0%)		
As Built Desc:	3.0% at 12" grooves		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	4 Low Severity	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Three - way intersection. Corners B,C,D		

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2671B

Location: Cheltenham Wy and Trenton Wy - Corner C (A-A)

X Coordinate: -121.31432

Y Coordinate: 38.68579

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (4.1% to 4.9%)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level(4.1% to 4.9%)

As Built Desc: 4.8% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 2 Recommended

Cost Estimate: \$0.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2671C

Location: Cheltenham Wy and Trenton Wy - Corner C (A-A)

X Coordinate: -121.31432

Y Coordinate: 38.68579

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$0.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Three - way intersection corners B,C,D

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2672A

Location: Cheltenham Wy and Trenton Wy - Corner D

X Coordinate: -121.31443

Y Coordinate: 38.68573

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection corners B,C,D

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2672B

Location: Cheltenham Wy and Trenton Wy - Corner D

X Coordinate: -121.31443

Y Coordinate: 38.68573

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (8.3% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (8.3% or more)

As Built Desc: 8.3% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners B,C,D

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2673

Location: Cheltenham Wy - West

X Coordinate: -121.31433

Y Coordinate: 38.68565

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 221 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$27,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2674

Location: Cheltenham Wy - North

X Coordinate: -121.31431

Y Coordinate: 38.68509

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 821 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$102,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/18/2010	Report Date:	11/18/2010	Barrier #:	2675
Location:	Westbrook Dr - West				
X Coordinate:	-121.31752				
Y Coordinate:	38.68434				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	150	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$18,750.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	11/18/2010	Report Date:	11/18/2010	Barrier #:	2676A
Location:	Westbrook Dr and Trenton Wy - Corner B				
X Coordinate:	-121.31751				
Y Coordinate:	38.68482				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (4.1% to 4.9%)		
As Built Desc:	4.2% at 12" grooves		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	2 Recommended	Cost Estimate:	\$2,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	Two - way intersection. Corners B,C
--------	-------------------------------------

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2676B

Location: Westbrook Dr and Trenton Wy - Corner B

X Coordinate: -121.31751

Y Coordinate: 38.68482

Barrier Area: Curb Ramps

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 1 Quantity: EACH

Description: Ramp run cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.2% cross slope

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$0.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2676C

Location: Westbrook Dr and Trenton Wy - Corner B

X Coordinate: -121.31751

Y Coordinate: 38.68482

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (>5.0% or more)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level (>5.0% or more)

As Built Desc: 5.2% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2676D

Location: Westbrook Dr and Trenton Wy - Corner B

X Coordinate: -121.31751

Y Coordinate: 38.68482

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2676E

Location: Westbrook Dr and Trenton Wy - Corner B

X Coordinate: -121.31751

Y Coordinate: 38.68482

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (8.3% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (8.3% or more)

As Built Desc: 10.0% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2677A

Location: Westbrook Dr and Trenton Wy - Corner C

X Coordinate: -121.31749

Y Coordinate: 38.6847

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.8% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2677B

Location: Westbrook Dr and Trenton Wy - Corner C

X Coordinate: -121.31749

Y Coordinate: 38.6847

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2677C

Location: Westbrook Dr and Trenton Wy - Corner C

X Coordinate: -121.31749

Y Coordinate: 38.6847

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 6.8% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2678

Location: Trenton Wy - South

X Coordinate: -121.31735

Y Coordinate: 38.6847

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 877 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$109,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2679

Location: Trenton Wy - South

X Coordinate: -121.3142

Y Coordinate: 38.68583

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 217 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$27,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2680A

Location: Trenton Wy and Halifax St - Corner A

X Coordinate: -121.31348

Y Coordinate: 38.68611

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (4.1% to 4.9%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (4.1% to 4.9%)

As Built Desc: 4.8% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 2 Recommended Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners A,B,D

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2680B

Location: Trenton Wy and Halifax St - Corner A

X Coordinate: -121.31348

Y Coordinate: 38.68611

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners A,B,D

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2681

Location: Trenton Wy and Halifax St - Corner B

X Coordinate: -121.31323

Y Coordinate: 38.68617

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners A,B,D

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2682A

Location: Trenton Wy and Halifax St - Corner D

X Coordinate: -121.31341

Y Coordinate: 38.68602

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners A,B,D

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2682B

Location: Trenton Wy and Halifax St - Corner D

X Coordinate: -121.31341

Y Coordinate: 38.68602

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (8.3% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (8.3% or more)

As Built Desc: 8.4% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection. Corners A,B,D

Field Date:	11/18/2010	Report Date:	11/18/2010	Barrier #:	2683
Location:	Trenton Wy - North				
X Coordinate:	-121.3135				
Y Coordinate:	38.68617				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	121	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$15,125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/18/2010	Report Date:	11/18/2010	Barrier #:	2684
Location:	Trenton Wy - North				
X Coordinate:	-121.31395				
Y Coordinate:	38.68609				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	36	Quantity:	LF
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	7.2% cross slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/18/2010	Report Date:	11/18/2010	Barrier #:	2685
Location:	Trenton Wy - North				
X Coordinate:	-121.31406				
Y Coordinate:	38.68606				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	87	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$10,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/18/2010	Report Date:	11/18/2010	Barrier #:	2686
Location:	Trenton Wy - North				
X Coordinate:	-121.31442				
Y Coordinate:	38.68589				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	229	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	8.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$28,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2687

Location: Trenton Wy - North

X Coordinate: -121.315

Y Coordinate: 38.6856

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 31 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 8.9% cross slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 4 Low Severity Cost Estimate: \$3,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2688

Location: Trenton Wy - North

X Coordinate: -121.31518

Y Coordinate: 38.68553

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 143 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$17,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2689

Location: Trenton Wy - North

X Coordinate: -121.31558

Y Coordinate: 38.68537

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 43 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 4 Low Severity Cost Estimate: \$5,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2690

Location: Trenton Wy - North

X Coordinate: -121.31575

Y Coordinate: 38.68534

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 519 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$64,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/18/2010	Report Date:	11/18/2010	Barrier #:	2691
Location:	Westbrook Dr - East				
X Coordinate:	-121.31754				
Y Coordinate:	38.6849				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	306	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	7.0% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$38,250.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	11/18/2010	Report Date:	11/18/2010	Barrier #:	2692
Location:	Westbrook Dr and Cardigan Ct - Corner B				
X Coordinate:	-121.31739				
Y Coordinate:	38.68587				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection. Corners B,C
--------	-------------------------------------

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2693

Location: Westbrook Dr and Cardigan Ct - Corner C

X Coordinate: -121.31746

Y Coordinate: 38.68578

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2694

Location: Carigan Ct - South

X Coordinate: -121.3173

Y Coordinate: 38.68575

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 265 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$33,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2695

Location: Cardigan Ct - North

X Coordinate: -121.31659

Y Coordinate: 38.6858

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 263 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$32,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2696A

Location: Westbrook Dr - East

X Coordinate: -121.31738

Y Coordinate: 38.68598

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 266 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$33,250.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2696B

Location: Westbrook Dr - North

X Coordinate: -121.31734

Y Coordinate: 38.68616

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 30" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2697A

Location: Westbrook Dr - South

X Coordinate: -121.31701

Y Coordinate: 38.6867

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 1156 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$144,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2697B

Location: Westbrook Dr - South

X Coordinate: -121.3169

Y Coordinate: 38.68677

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2697C

Location: Westbrook Dr - South

X Coordinate: -121.31541

Y Coordinate: 38.68766

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2698A

Location: Halifax St - West

X Coordinate: -121.31339

Y Coordinate: 38.68769

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 546 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$68,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2698B

Location: Halifax St - West

X Coordinate: -121.31339

Y Coordinate: 38.68766

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/18/2010	Report Date:	11/18/2010	Barrier #:	2699
Location:	Halifax St - West				
X Coordinate:	-121.3134				
Y Coordinate:	38.68593				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	436	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$54,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/18/2010	Report Date:	11/18/2010	Barrier #:	2700
Location:	Halifax St - West				
X Coordinate:	-121.31307				
Y Coordinate:	38.68459				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	116	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	7.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$14,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2701A

Location: Auburn Blvd Frontage Rd - North

X Coordinate: -121.31295

Y Coordinate: 38.68417

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 222 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$27,750.00

Status:

Implementation Priority: 1

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/18/2010 Report Date: 11/18/2010 Barrier #: 2701B

Location: Auburn Blvd Frontage Rd - North

X Coordinate: -121.31342

Y Coordinate: 38.6839

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 4 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary

Cost Estimate: \$500.00

Status:

Implementation Priority: 1

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2702

Location: Matheny Wy - East


X Coordinate: -121.3221

Y Coordinate: 38.68086

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 37 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 3 Hindrance Cost Estimate: \$4,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2703

Location: Matheny Wy - East


X Coordinate: -121.3221

Y Coordinate: 38.68101

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 54 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$6,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2704

Location: Matheny Wy - East


X Coordinate: -121.32211

Y Coordinate: 38.68118

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 39 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 4 Low Severity Cost Estimate: \$4,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2705

Location: Matheny Wy - East

X Coordinate: -121.3221

Y Coordinate: 38.68121

Barrier Area: Sidewalks

Barrier Type: No Sidewalk - No Barricade

Code Ref: MUTCD Section 6D.01



As Built Meas: 1 Quantity: JOB

Description: No barricade provided where sidewalk ends in hazardous location

As Built Desc: No barricade or other warning provided for the visually impaired at end of sidewalk

Solution: Provide barricade with cane detectable warning at end of sidewalk

Bar. Severity: 1 Necessary Cost Estimate: \$1,350.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2706

Location: Matheny Wy - East

X Coordinate: -121.32206

Y Coordinate: 38.68173

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 1231 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$153,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2707

Location: Matheny Wy - West


X Coordinate: -121.3207

Y Coordinate: 38.68348

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 151 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.6% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 3 Hindrance Cost Estimate: \$18,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2708

Location: Matheny Wy and Mi Ct - Corner A

X Coordinate: -121.32093

Y Coordinate: 38.68347

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2709

Location: Matheny Wy and Mi Ct - Corner B

X Coordinate: -121.32086

Y Coordinate: 38.68348

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:


Notes: Two - way intersection. Corners A,B

Field Date:	11/24/2010	Report Date:	11/24/2010	Barrier #:	2710
Location:	Mi Ct - East				
X Coordinate:	-121.32105				
Y Coordinate:	38.68401				
Barrier Area:	Sidewalks				
Barrier Type:	Shoulder Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	260	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.2% cross slope			
Solution:	Demolish existing and construct new pedestrian route			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$32,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	11/24/2010	Report Date:	11/24/2010	Barrier #:	2711
Location:	Mi Ct - West				
X Coordinate:	-121.32088				
Y Coordinate:	38.68362				
Barrier Area:	Sidewalks				
Barrier Type:	Shoulder Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	240	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.6% cross slope			
Solution:	Demolish existing and construct new pedestrian route			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$30,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2712

Location: Matheny Wy - West


X Coordinate: -121.32217

Y Coordinate: 38.68281

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 643 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.3% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$80,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2713

Location: Matheny Wy - West


X Coordinate: -121.3222

Y Coordinate: 38.68219

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 43 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.3% cross slope, 10.1% running slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 1 Necessary Cost Estimate: \$5,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2714

Location: Matheny Wy - West

X Coordinate: -121.32221

Y Coordinate: 38.68208

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 74 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$9,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2715

Location: Matheny Wy - West

X Coordinate: -121.32217

Y Coordinate: 38.68186

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2716

Location: Matheny Wy - West

X Coordinate: -121.32219

Y Coordinate: 38.68179

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2717

Location: Matheny Wy - West


X Coordinate: -121.32219

Y Coordinate: 38.68167

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 43 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.0% cross slope, 10.9% running slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 1 Necessary Cost Estimate: \$5,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2718

Location: Matheny Wy - West

X Coordinate: -121.32221

Y Coordinate: 38.68156

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2880

Location: Tall Tree Cir - North

X Coordinate: -121.32473

Y Coordinate: 38.68236

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 257 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.7% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$32,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2881

Location: Tall Tree Cir - West

X Coordinate: -121.32561

Y Coordinate: 38.6822

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 229 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$28,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2882

Location: Tall Tree Cir - South

X Coordinate: -121.32572

Y Coordinate: 38.68154

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 313 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.8% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$39,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2883
Location:	Tall Tree Cir - North				
X Coordinate:	-121.32471				
Y Coordinate:	38.68165				
Barrier Area:	Sidewalks				
Barrier Type:	Shoulder Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	257	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.5% cross slope		
Solution:	Demolish existing and construct new pedestrian route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$32,125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2884
Location:	Tall Tree Cir - East				
X Coordinate:	-121.32569				
Y Coordinate:	38.68165				
Barrier Area:	Sidewalks				
Barrier Type:	Shoulder Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	189	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.4% cross slope		
Solution:	Demolish existing and construct new pedestrian route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$23,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2885

Location: Tall Tree Cir - South

X Coordinate: -121.32551

Y Coordinate: 38.6822

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 237 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$29,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2886

Location: Indian River Dr - West

X Coordinate: -121.32457

Y Coordinate: 38.68222

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 203 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$25,375.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2887

Location: Indian River Dr - West

X Coordinate: -121.3246

Y Coordinate: 38.68146

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 95 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$11,875.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2888

Location: Flaming Arrow Dr - North


X Coordinate: -121.32466

Y Coordinate: 38.68997

Barrier Area: Sidewalks

Barrier Type: No sidewalk (end of path)

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 1 Quantity: JOB

Description: Sidewalk route ends and no opposite sidewalk exists

As Built Desc: Directional sign lacking forcing pedestrians to retrace their steps

Solution: Provide directional sign at junction in route to allow travel in shoulder

Bar. Severity: 1 Necessary Cost Estimate: \$100.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2889

Location: Flaming Arrow Dr - North


X Coordinate: -121.32474

Y Coordinate: 38.69005

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 58 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$7,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2899B

Location: Greenback Ln - North

X Coordinate: -121.32313

Y Coordinate: 38.6809

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2900A

Location: Greenback Ln and Matheny Wy - Corner A

X Coordinate: -121.32248

Y Coordinate: 38.68059

Barrier Area: Curb Ramps

Barrier Type: Running Slope - Existing (9.5% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.1



As Built Meas: 1 Quantity: EACH

Description: Ramp run cross slope exceeds 2.0% (9.5% or more)

As Built Desc: 9.6% running slope

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary

Cost Estimate: \$2,500.00

Status:

Implementation Priority: 1

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2900B

Location: Greenback Ln and Matheny Wy - Corner A

X Coordinate: -121.32248

Y Coordinate: 38.68059

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended

Cost Estimate: \$0.00

Status:

Implementation Priority: 1

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2900C

Location: Greenback Ln and Matheny Wy - Corner A

X Coordinate: -121.32248

Y Coordinate: 38.68059

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (8.3% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (8.3% or more)

As Built Desc: 8.7% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2901A

Location: Greenback Ln and Matheny Wy - Corner B

X Coordinate: -121.32226

Y Coordinate: 38.68048

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.4% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2901B

Location: Greenback Ln and Matheny Wy - Corner B

X Coordinate: -121.32226

Y Coordinate: 38.68048

Barrier Area: Curb Ramps

Barrier Type: Running Slope - Existing (9.0% to 9.4%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.1



As Built Meas: 1 Quantity: EACH

Description: Ramp run cross slope exceeds 2.0% (9.0% to 9.4%)

As Built Desc: 9.4% running slope

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2901C

Location: Greenback Ln and Matheny Wy - Corner B

X Coordinate: -121.32226

Y Coordinate: 38.68048

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2901D

Location: Greenback Ln and Matheny Wy - Corner B

X Coordinate: -121.32226

Y Coordinate: 38.68048

Barrier Area: Curb Ramps

Barrier Type: Lip - Gutter to Asphalt Transition

Code Ref: CBC 1127B.5.3 and ADA/ABA 303.3



As Built Meas: 1 Quantity: EACH

Description: Transition at transition into asphalt not flush and free of any lip

As Built Desc: 1/2" lip at asphalt transition into roadway

Solution: Remove lip to create flush transition

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2902

Location: Greenback Ln - North


X Coordinate: -121.32203

Y Coordinate: 38.68031

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 35 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 4 Low Severity Cost Estimate: \$4,375.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2719

Location: Matheny Wy - West


X Coordinate: -121.32221

Y Coordinate: 38.68148

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 115 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$14,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2720

Location: Matheny Wy - West


X Coordinate: -121.32227

Y Coordinate: 38.68112

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 39 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 10.1% cross slope, 19.1% running slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 1 Necessary Cost Estimate: \$4,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2721

Location: Matheny Wy - West


X Coordinate: -121.32228

Y Coordinate: 38.68103

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 172 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$21,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2722

Location: Indian River Dr and Broken Arrow Ct - Corner B

X Coordinate: -121.32445

Y Coordinate: 38.68161

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D. Corners A,C,D compliant

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2723

Location: Broken Arrow Ct - South


X Coordinate: -121.32436

Y Coordinate: 38.68151

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 329 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$41,125.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2724

Location: Broken Arrow Ct - North

X Coordinate: -121.32367

Y Coordinate: 38.68143

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 327 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.8% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 3 Hindrance

Cost Estimate: \$40,875.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date:	11/24/2010	Report Date:	11/24/2010	Barrier #:	2725
Location:	Indian River Dr - East				
X Coordinate:	-121.32457				
Y Coordinate:	38.68246				
Barrier Area:	Sidewalks				
Barrier Type:	No sidewalk				
Code Ref:	CBC 1127B.1 and ADA/ABA 206.2.1				



As Built Meas:	739	Quantity:	LF
Description:	No pedestrian route provided		
As Built Desc:	No sidewalk provided		
Solution:	Construct new firm and stable pedestrian route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$73,900.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	11/24/2010	Report Date:	11/24/2010	Barrier #:	2726
Location:	Indian River Dr and Little Arrow Ct - Corner B				
X Coordinate:	-121.32523				
Y Coordinate:	38.68367				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	Four - way intersection. Corners A,B,C,D. Corners A,D compliant
--------	---

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2727

Location: Indian River Dr and Little Arrow Ct - Corner C

X Coordinate: -121.32519

Y Coordinate: 38.68356

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D. Corners A,D compliant

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2728

Location: Little Arrow Ct - North

X Coordinate: -121.32505

Y Coordinate: 38.6836

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 91 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.7% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 3 Hindrance Cost Estimate: \$11,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2729

Location: Little Arrow Ct - South


X Coordinate: -121.32507

Y Coordinate: 38.68367

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 93 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$11,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2730

Location: Indian River Dr - East

X Coordinate: -121.32531

Y Coordinate: 38.68401

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 175 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$21,875.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2731

Location: Broken Bow Dr - South


X Coordinate: -121.3252

Y Coordinate: 38.68425

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 197 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$24,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2732A

Location: Broken Bow Dr - West


X Coordinate: -121.32457

Y Coordinate: 38.6842

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 13 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$1,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2732B

Location: Broken Bow Dr - West

X Coordinate: -121.32447

Y Coordinate: 38.68417

Barrier Area: Sidewalks

Barrier Type: Running Slope (New Construction)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 8 Quantity: LF

Description: Running slope exceeds 5.0% where roadway slope does not

As Built Desc: 6.3% running slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2733A

Location: Broken Bow Dr - West


X Coordinate: -121.32425

Y Coordinate: 38.684

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 266 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 4.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$33,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2733B

Location: Broken Bow Dr - West


X Coordinate: -121.32416

Y Coordinate: 38.68396

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 1 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 24" clear width due to foliage

Solution: Trim foliage to provide min. 48" clear width

Bar. Severity: 1 Necessary Cost Estimate: \$125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2734

Location: Pretty Girl Ct - West

X Coordinate: -121.32364

Y Coordinate: 38.68325

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 152 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.6% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 3 Hindrance Cost Estimate: \$19,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2735

Location: Pretty Girl Ct - East


X Coordinate: -121.32359

Y Coordinate: 38.68315

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 160 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.7% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 3 Hindrance Cost Estimate: \$20,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2736

Location: Broken Bow Dr - East

X Coordinate: -121.32356

Y Coordinate: 38.68351

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 117 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$14,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2737

Location: Broken Bow Dr and Sudden Wind Ct - Corner B

X Coordinate: -121.32365

Y Coordinate: 38.68369

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,D

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2738

Location: Broken Bow Dr and Sudden Wind Ct - Corner D

X Coordinate: -121.3236

Y Coordinate: 38.68365

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,D

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2739

Location: Sudden Wind Ct - South


X Coordinate: -121.3235

Y Coordinate: 38.6837

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 133 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.5% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 2 Recommended

Cost Estimate: \$16,625.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2740

Location: Sudden Wind Ct - North


X Coordinate: -121.32342

Y Coordinate: 38.68393

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 132 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.8% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 3 Hindrance

Cost Estimate: \$16,500.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2741

Location: Broken Bow Dr - East


X Coordinate: -121.32423

Y Coordinate: 38.68412

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 341 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.6% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 3 Hindrance Cost Estimate: \$42,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2742

Location: Broken Bow Dr and Fast Water Ct - Corner A

X Coordinate: -121.32479

Y Coordinate: 38.68441

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2743

Location: Broken Bow Dr and Fast Water Ct - Corner B

X Coordinate: -121.32469

Y Coordinate: 38.68433

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2744

Location: Fast Water Ct - East

X Coordinate: -121.32457

Y Coordinate: 38.68446

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 106 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.7% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 3 Hindrance Cost Estimate: \$13,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2745

Location: Fast Water Ct - West


X Coordinate: -121.32457

Y Coordinate: 38.68455

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 107 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 2 Recommended Cost Estimate: \$13,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2746

Location: Broken Bow Dr - North


X Coordinate: -121.32502

Y Coordinate: 38.68432

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 156 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.8% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 3 Hindrance Cost Estimate: \$19,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2747

Location: Indian River Dr - East

X Coordinate: -121.32539

Y Coordinate: 38.6844

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 156 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$19,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2748

Location: Indian River Dr and Pretty Bush Ct - Corner A

X Coordinate: -121.32566

Y Coordinate: 38.68494

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 16.8% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2749

Location: Indian River Dr and Clay Basket Dr - Corner B

X Coordinate: -121.32554

Y Coordinate: 38.68494

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 14.0% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2750

Location: Indian River Dr and Clay Basket Dr - Corner C

X Coordinate: -121.32551

Y Coordinate: 38.68486

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 7.6% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2751

Location: Indian River Dr and Pretty Bush Ct - Corner D

X Coordinate: -121.32564

Y Coordinate: 38.68483

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 8.5% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2752

Location: Clay Basket Dr - South


X Coordinate: -121.3253

Y Coordinate: 38.6849

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 600 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$60,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2753

Location: Clay Basket Dr and Shadow Hawk - Corner A

X Coordinate: -121.32331

Y Coordinate: 38.68513

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2754

Location: Clay Basket Dr and Shadow Hawk - Corner D

X Coordinate: -121.32329

Y Coordinate: 38.68506

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:


Notes: Two - way intersection. Corners A,D

Field Date:	11/24/2010	Report Date:	11/24/2010	Barrier #:	2755
Location:	Shadow Hawk - South				
X Coordinate:	-121.32245				
Y Coordinate:	38.68482				
Barrier Area:	Sidewalks				
Barrier Type:	Shoulder Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	1032	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.1% cross slope		
Solution:	Demolish existing and construct new pedestrian route		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$129,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/24/2010	Report Date:	11/24/2010	Barrier #:	2756
Location:	Shadow Hawk - North				
X Coordinate:	-121.32019				
Y Coordinate:	38.68512				
Barrier Area:	Sidewalks				
Barrier Type:	Shoulder Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	1028	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.3% cross slope		
Solution:	Demolish existing and construct new pedestrian route		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$128,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2757

Location: Clay Basket - North


X Coordinate: -121.32345

Y Coordinate: 38.68514

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 614 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$76,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2758

Location: Indian River Dr - East

X Coordinate: -121.32554

Y Coordinate: 38.68505

Barrier Area: Sidewalks

Barrier Type: No sidewalk

Code Ref: CBC 1127B.1 and ADA/ABA 206.2.1



As Built Meas: 298 Quantity: LF

Description: No pedestrian route provided

As Built Desc: No sidewalk provided

Solution: Construct new firm and stable pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$29,800.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/24/2010	Report Date:	11/24/2010	Barrier #:	2759
Location:	Running Water Ct and Indian River Dr - Corner B				
X Coordinate:	-121.32557				
Y Coordinate:	38.68591				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Two - way intersection. Corners B,C			

Field Date:	11/24/2010	Report Date:	11/24/2010	Barrier #:	2760
Location:	Running Water Ct and Indian River Dr - Corner C				
X Coordinate:	-121.32557				
Y Coordinate:	38.68584				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Two - way intersection. Corners B,C			

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2761

Location: Running Water Ct - South


X Coordinate: -121.32542

Y Coordinate: 38.68584

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 197 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.2% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 3 Hindrance Cost Estimate: \$24,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2762

Location: Running Water Ct - North

X Coordinate: -121.32511

Y Coordinate: 38.68586

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 195 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$24,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2763A

Location: Indian River Dr - East

X Coordinate: -121.32559

Y Coordinate: 38.68599

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 193 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$24,125.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2763B

Location: Indian River Dr - East

X Coordinate: -121.32556

Y Coordinate: 38.68651

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/24/2010	Report Date:	11/24/2010	Barrier #:	2764
Location:	Indian River Dr and Flaming Arrow Dr - Corner B				
X Coordinate:	-121.32556				
Y Coordinate:	38.68662				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No compliant curb cut at corner (intersection)			
As Built Desc:	12.8% running slope at depressed area			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Two - way intersection corners B,C			

Field Date:	11/24/2010	Report Date:	11/24/2010	Barrier #:	2765
Location:	Indian River Dr and Flaming Arrow Dr - Corner C				
X Coordinate:	-121.32555				
Y Coordinate:	38.68656				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No compliant curb cut at corner (intersection)			
As Built Desc:	11.0% running slope at depressed area			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Two - way intersection corners B,C			

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2766A

Location: Flaming Arrow Dr - South


X Coordinate: -121.32533

Y Coordinate: 38.68653

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 618 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$77,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2766B

Location: Flaming Arrow Dr - South

X Coordinate: -121.32491

Y Coordinate: 38.68648

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2766C

Location: Flaming Arrow Dr - South

X Coordinate: -121.32481

Y Coordinate: 38.68647

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2766D

Location: Flaming Arrow Dr - South

X Coordinate: -121.32475

Y Coordinate: 38.68645

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2766E

Location: Flaming Arrow Dr - South


X Coordinate: -121.32458

Y Coordinate: 38.68641

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 20 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2767

Location: Flaming Arrow Dr and Shadow Hawk Dr - Corner A

X Coordinate: -121.32337

Y Coordinate: 38.68651

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2768

Location: Flaming Arrow Dr and Shadow Hawk Dr - Corner B

X Coordinate: -121.32332

Y Coordinate: 38.68656

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 12.2% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2769

Location: Flaming Arrow Dr and Shadow Hawk Dr - Corner C

X Coordinate: -121.32326

Y Coordinate: 38.68655

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2770

Location: Flaming Arrow Dr and Shadow Hawk Dr - Corner D

X Coordinate: -121.32331

Y Coordinate: 38.68647

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2771

Location: Shadow Hawk Ct - West


X Coordinate: -121.32313

Y Coordinate: 38.6862

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 490 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$61,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2772

Location: Shadow Hawk Ct - East


X Coordinate: -121.32317

Y Coordinate: 38.68543

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 510 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 1 Necessary

Cost Estimate: \$63,750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2773

Location: Redskin Ct - East


X Coordinate: -121.32343

Y Coordinate: 38.68669

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 106 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.7% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 2 Recommended

Cost Estimate: \$13,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2774

Location: Redskin Ct - West


X Coordinate: -121.32349

Y Coordinate: 38.68663

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 104 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$13,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2775

Location: Flaming Arrow Dr - North


X Coordinate: -121.32513

Y Coordinate: 38.68659

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 604 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$75,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2776

Location: Indian River Dr - East


X Coordinate: -121.32554

Y Coordinate: 38.68674

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 295 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$36,875.00

Status:

Implementation Priority: 2

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2777

Location: Little Squaw Ct - South


X Coordinate: -121.32517

Y Coordinate: 38.68751

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 178 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.8% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 3 Hindrance

Cost Estimate: \$22,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2778

Location: Little Squaw Ct - North


X Coordinate: -121.32497

Y Coordinate: 38.68754

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 170 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.2% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 3 Hindrance Cost Estimate: \$21,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2779

Location: Indian River Dr - East


X Coordinate: -121.32518

Y Coordinate: 38.68768

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 604 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$75,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2780

Location: Flaming Arrow Dr - South


X Coordinate: -121.32406

Y Coordinate: 38.68898

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 721 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$90,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2781

Location: Tall Brave Ct - North


X Coordinate: -121.3234

Y Coordinate: 38.68751

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 269 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$33,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2782

Location: Tall Brave Ct - South

X Coordinate: -121.32383

Y Coordinate: 38.68756

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 272 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.4% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 3 Hindrance Cost Estimate: \$34,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2783

Location: Flaming Arrow - West


X Coordinate: -121.32315

Y Coordinate: 38.68731

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 258 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$32,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2784

Location: Flaming Arrow - East


X Coordinate: -121.32318

Y Coordinate: 38.68663

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 30 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$3,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2785

Location: Flaming Arrow Dr and Little Beaver Ct - Corner B

X Coordinate: -121.32308

Y Coordinate: 38.68676

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2786

Location: Flaming Arrow Dr and Little Beaver Ct - Corner C

X Coordinate: -121.32313

Y Coordinate: 38.6867

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2787

Location: Little Beaver Ct - North


X Coordinate: -121.32299

Y Coordinate: 38.68667

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 121 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 2 Recommended Cost Estimate: \$15,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2788

Location: Little Beaver Ct - South


X Coordinate: -121.32284

Y Coordinate: 38.68673

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 119 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.5% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 3 Hindrance Cost Estimate: \$14,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2789A

Location: Flaming Arrow Dr - East


X Coordinate: -121.3231

Y Coordinate: 38.68688

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 655 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$81,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2789B

Location: Flaming Arrow Dr - East

X Coordinate: -121.32304

Y Coordinate: 38.68755

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2789C

Location: Flaming Arrow Dr - East

X Coordinate: -121.32334

Y Coordinate: 38.68844

Barrier Area: Curb Ramps

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1127B.5.3 and ADA/ABA 303.3



As Built Meas: 4 Quantity: SF

Description: Change in level greater than 1/2" in curb ramp

As Built Desc: 1/2" lip in curb ramp surface

Solution: Grind or repair to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2790

Location: Flaming Arrow Dr and Blowing Wind Wy - Corner B

X Coordinate: -121.32353

Y Coordinate: 38.68862

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 9.7% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2791

Location: Flaming Arrow Dr and Blowing Wind Wy - Corner C

X Coordinate: -121.32347

Y Coordinate: 38.68857

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 9.9% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2792

Location: Blowing Wind Wy - South


X Coordinate: -121.32335

Y Coordinate: 38.68872

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 201 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$25,125.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2793A

Location: Blowing Wind Wy - East


X Coordinate: -121.32313

Y Coordinate: 38.6891

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 247 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$30,875.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2793B

Location: Blowing Wind Wy - East


X Coordinate: -121.32332

Y Coordinate: 38.68957

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2794

Location: Brokenfeather Wy - South


X Coordinate: -121.3233

Y Coordinate: 38.68978

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 219 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 2 Recommended Cost Estimate: \$27,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2795

Location: Brokenfeather Wy - North


X Coordinate: -121.32305

Y Coordinate: 38.68984

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 221 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.7% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 3 Hindrance Cost Estimate: \$27,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2796

Location: Blowing Wind Wy - East


X Coordinate: -121.32367

Y Coordinate: 38.69002

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 127 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$15,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2797

Location: Blowing Wind Wy and Big Arrow Ct - Corner C

X Coordinate: -121.32399

Y Coordinate: 38.69025

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 18.7% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2798

Location: Blowing Wind Wy and Big Arrow Ct - Corner D

X Coordinate: -121.32405

Y Coordinate: 38.69021

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 17.5% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2799

Location: Blowing Wind Wy - West


X Coordinate: -121.32388

Y Coordinate: 38.69009

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 458 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$57,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2800

Location: Blowing Wind Wy - North

X Coordinate: -121.3232

Y Coordinate: 38.68903

Barrier Area: Sidewalks

Barrier Type: Elbow in Sidewalk - Cross Slope (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 6 Quantity: LF

Description: Cross slope at elbow exceeds 2.0% (5.0% or more)

As Built Desc: 9.7% cross slope

Solution: Demolish existing and construct new sidewalk without curb ramp

Bar. Severity: 1 Necessary

Cost Estimate: \$750.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2801

Location: Blowing Wind Wy - North


X Coordinate: -121.32321

Y Coordinate: 38.68896

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 266 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary

Cost Estimate: \$33,250.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/24/2010 Report Date: 11/24/2010 Barrier #: 2802

Location: Flaming Arrow Dr - East


X Coordinate: -121.32377

Y Coordinate: 38.68878

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 191 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$23,875.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2803A

Location: Verner Ave - East

X Coordinate: -121.33104

Y Coordinate: 38.68693

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 120 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$15,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2803B

Location: Verner Ave - East

X Coordinate: -121.33088

Y Coordinate: 38.68703

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2804

Location: Verner Ave - East

X Coordinate: -121.3307

Y Coordinate: 38.68726

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 26" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2805A

Location: Verner Ave and Goldenwood Cir - Corner B

X Coordinate: -121.33052

Y Coordinate: 38.6874

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (4.1% to 4.9%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (4.1% to 4.9%)

As Built Desc: 4.5% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 2 Recommended Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2805B

Location: Verner Ave and Goldenwood Cir - Corner B

X Coordinate: -121.33052

Y Coordinate: 38.6874

Barrier Area: Curb Ramps

Barrier Type: Perpendicular Ramp Landing - New Construction

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp top landing not min. 48" deep

As Built Desc: No top landing provided

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2805C

Location: Verner Ave and Goldenwood Cir - Corner B

X Coordinate: -121.33052

Y Coordinate: 38.6874

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2805D

Location: Verner Ave and Goldenwood Cir - Corner B

X Coordinate: -121.33052

Y Coordinate: 38.6874

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.3% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2806A

Location: Verner Ave and Goldenwood Cir - Corner C

X Coordinate: -121.33062

Y Coordinate: 38.68733

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 4.0% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2806B

Location: Verner Ave and Goldenwood Cir - Corner C

X Coordinate: -121.33062

Y Coordinate: 38.68733

Barrier Area: Curb Ramps

Barrier Type: Perpendicular Ramp Landing - New Construction

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp top landing not min. 48" deep

As Built Desc: No top landing provided

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2806C

Location: Verner Ave and Goldenwood Cir - Corner C

X Coordinate: -121.33062

Y Coordinate: 38.68733

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners B,C

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2807A

Location: Goldenwood Cir and Woodendale Ct - Corner C

X Coordinate: -121.33023

Y Coordinate: 38.68713

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2807B

Location: Goldenwood Cir and Woodendale Ct - Corner C

X Coordinate: -121.33023

Y Coordinate: 38.68713

Barrier Area: Curb Ramps

Barrier Type: Perpendicular Ramp Landing - New Construction

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp top landing not min. 48" deep

As Built Desc: No top landing provided

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary Cost Estimate: \$250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2807C

Location: Goldenwood Cir and Woodendale Ct - Corner C

X Coordinate: -121.33023

Y Coordinate: 38.68713

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.6% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2808A

Location: Goldenwood Cir and Woodendale Ct - Corner D

X Coordinate: -121.33036

Y Coordinate: 38.68718

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.8% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2808B

Location: Goldenwood Cir and Woodendale Ct - Corner D

X Coordinate: -121.33036

Y Coordinate: 38.68718

Barrier Area: Curb Ramps

Barrier Type: Perpendicular Ramp Landing - New Construction

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp top landing not min. 48" deep

As Built Desc: No top landing provided

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2808C

Location: Goldenwood Cir and Woodendale Ct - Corner D

X Coordinate: -121.33036

Y Coordinate: 38.68718

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2809

Location: Woodendale Ct - East

X Coordinate: -121.33045

Y Coordinate: 38.68683

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 8 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2810

Location: Goldenwood Cir - South

X Coordinate: -121.329

Y Coordinate: 38.68706

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary

Cost Estimate: \$1,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2811A

Location: Goldenwood Cir and Foxwood Ct - Corner A

X Coordinate: -121.32889

Y Coordinate: 38.68721

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (>5.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (>5.0%)

As Built Desc: 5.9% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2811B

Location: Goldenwood Cir and Foxwood Ct - Corner A

X Coordinate: -121.32889

Y Coordinate: 38.68721

Barrier Area: Curb Ramps

Barrier Type: Perpendicular Ramp Landing - New Construction

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp top landing not min. 48" deep

As Built Desc: No top landing provided

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2811C

Location: Goldenwood Cir and Foxwood Ct - Corner A

X Coordinate: -121.32889

Y Coordinate: 38.68721

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2811D

Location: Goldenwood Cir and Foxwood Ct - Corner A

X Coordinate: -121.32889

Y Coordinate: 38.68721

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.9% - 6.5%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.9% - 6.5%)

As Built Desc: 6.3% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 3 Hindrance Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2812A

Location: Goldenwood Cir and Foxwood Ct - Corner B

X Coordinate: -121.32871

Y Coordinate: 38.68725

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (4.1% to 4.9%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (4.1% to 4.9%)

As Built Desc: 4.2% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 2 Recommended Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2812B

Location: Goldenwood Cir and Foxwood Ct - Corner B

X Coordinate: -121.32871

Y Coordinate: 38.68725

Barrier Area: Curb Ramps

Barrier Type: Perpendicular Ramp Landing - New Construction

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp top landing not min. 48" deep

As Built Desc: No top landing provided

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2812C

Location: Goldenwood Cir and Foxwood Ct - Corner B

X Coordinate: -121.32871

Y Coordinate: 38.68725

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2813A

Location: Goldenwood Cir and Woodenfield Ct - Corner C

X Coordinate: -121.32865

Y Coordinate: 38.68711

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (4.1% to 4.9%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (4.1% to 4.9%)

As Built Desc: 4.7% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 2 Recommended Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2813B

Location: Goldenwood Cir and Woodenfield Ct - Corner C

X Coordinate: -121.32865

Y Coordinate: 38.68711

Barrier Area: Curb Ramps

Barrier Type: Perpendicular Ramp Landing - New Construction

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp top landing not min. 48" deep

As Built Desc: No top landing provided

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2813C

Location: Goldenwood Cir and Woodenfield Ct - Corner C

X Coordinate: -121.32865

Y Coordinate: 38.68711

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2814A
Location:	Goldenwood Cir and Woodenfield Ct - Corner D				
X Coordinate:	-121.32881				
Y Coordinate:	38.6871				
Barrier Area:	Curb Ramps				
Barrier Type:	Perpendicular Ramp Landing - New Construction				
Code Ref:	CBC 1127B.5.4 and ADA/ABA 406.4				



As Built Meas:	1	Quantity:	EACH
Description:	Curb ramp top landing not min. 48" deep		
As Built Desc:	No top landing provided		
Solution:	Demolish existing and construct new transition		
Bar. Severity:	1 Necessary	Cost Estimate:	\$250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection. Corners C,D		

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2814B
Location:	Goldenwood Cir and Woodenfield Ct - Corner D				
X Coordinate:	-121.32881				
Y Coordinate:	38.6871				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH
Description:	No truncated domes provided at curb ramp		
As Built Desc:	No detectable warnings at curb ramp		
Solution:	Provide compliant truncated domes		
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection. Corners C,D		

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2815A

Location: Tree Hill Ct and Goldenwood Cir - Corner A

X Coordinate: -121.32765

Y Coordinate: 38.68905

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 4.0% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2815B

Location: Tree Hill Ct and Goldenwood Cir - Corner A

X Coordinate: -121.32765

Y Coordinate: 38.68905

Barrier Area: Curb Ramps

Barrier Type: Perpendicular Ramp Landing - New Construction

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp top landing not min. 48" deep

As Built Desc: No top landing provided

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2815C

Location: Tree Hill Ct and Goldenwood Cir - Corner A

X Coordinate: -121.32765

Y Coordinate: 38.68905

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2816A

Location: Tree Hill Ct and Goldenwood Cir - Corner B

X Coordinate: -121.32752

Y Coordinate: 38.68896

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.6% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2816B

Location: Tree Hill Ct and Goldenwood Cir - Corner B

X Coordinate: -121.32752

Y Coordinate: 38.68896

Barrier Area: Curb Ramps

Barrier Type: Perpendicular Ramp Landing - New Construction

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp top landing not min. 48" deep

As Built Desc: No top landing provided

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2816C

Location: Tree Hill Ct and Goldenwood Cir - Corner B

X Coordinate: -121.32752

Y Coordinate: 38.68896

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2816D

Location: Tree Hill Ct and Goldenwood Cir - Corner B

X Coordinate: -121.32752

Y Coordinate: 38.68896

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.9% - 6.5%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.9% - 6.5%)

As Built Desc: 6.1% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 3 Hindrance Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2817

Location: Tree Hill Ct - East


X Coordinate: -121.32736

Y Coordinate: 38.68909

Barrier Area: Sidewalks

Barrier Type: Running Slope (Existing)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 8 Quantity: LF

Description: Running slope exceeds 5.0%

As Built Desc: 7.1% running slope

Solution: No remediation where sidewalk sloped as roadway

Bar. Severity: 5 Technically Infeasible Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2818

Location: Tree Hill Ct - West

X Coordinate: -121.32746

Y Coordinate: 38.68927

Barrier Area: Sidewalks

Barrier Type: Running Slope (Existing)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 16 Quantity: LF

Description: Running slope exceeds 5.0%

As Built Desc: 7.3% running slope

Solution: No remediation where sidewalk sloped as roadway

Bar. Severity: 5 Technically Infeasible Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2819

Location: Goldenwood Cir - North

X Coordinate: -121.32824

Y Coordinate: 38.68947

Barrier Area: Sidewalks

Barrier Type: Running Slope (Existing)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 8 Quantity: LF

Description: Running slope exceeds 5.0%

As Built Desc: 9.8% running slope

Solution: No remediation where sidewalk sloped as roadway

Bar. Severity: 5 Technically Infeasible Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2820A

Location: Goldenwood Cir and Verner Ave - Corner A

X Coordinate: -121.32736

Y Coordinate: 38.68909

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (>5.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (>5.0%)

As Built Desc: 7.4% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2820B

Location: Goldenwood Cir and Verner Ave - Corner A

X Coordinate: -121.32736

Y Coordinate: 38.68909

Barrier Area: Curb Ramps

Barrier Type: Flares - Existing (11.1% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.3



As Built Meas: 1 Quantity: EACH

Description: Ramp flare slope exceeds 10.0% (11.1% or more)

As Built Desc: 12.6% flare slope

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2820C

Location: Goldenwood Cir and Verner Ave - Corner A

X Coordinate: -121.32736

Y Coordinate: 38.68909

Barrier Area: Curb Ramps

Barrier Type: Perpendicular Ramp Landing - New Construction

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp top landing not min. 48" deep

As Built Desc: No top landing provided

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2820D

Location: Goldenwood Cir and Verner Ave - Corner A

X Coordinate: -121.32736

Y Coordinate: 38.68909

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2821A

Location: Goldenwood Cir and Verner Ave - Corner B

X Coordinate: -121.32835

Y Coordinate: 38.68937

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (2.1% to 3.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (2.1% to 3.0%)

As Built Desc: 3.0% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 4 Low Severity Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2821B

Location: Goldenwood Cir and Verner Ave - Corner B

X Coordinate: -121.32835

Y Coordinate: 38.68937

Barrier Area: Curb Ramps

Barrier Type: Perpendicular Ramp Landing - New Construction

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp top landing not min. 48" deep

As Built Desc: No top landing provided

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2821C

Location: Goldenwood Cir and Verner Ave - Corner B

X Coordinate: -121.32835

Y Coordinate: 38.68937

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2822A

Location: Goldenwood Cir and Woodbrook Ct - Corner C

X Coordinate: -121.32796

Y Coordinate: 38.68908

Barrier Area: Curb Ramps

Barrier Type: Perpendicular Ramp Landing - New Construction

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp top landing not min. 48" deep

As Built Desc: No top landing provided

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary Cost Estimate: \$250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2822B

Location: Goldenwood Cir and Woodbrook Ct - Corner C

X Coordinate: -121.32796

Y Coordinate: 38.68908

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2823A

Location: Goldenwood Cir and Woodbrook Ct - Corner D

X Coordinate: -121.32809

Y Coordinate: 38.68917

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.8% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2823B

Location: Goldenwood Cir and Woodbrook Ct - Corner D

X Coordinate: -121.32809

Y Coordinate: 38.68917

Barrier Area: Curb Ramps

Barrier Type: Perpendicular Ramp Landing - New Construction

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp top landing not min. 48" deep

As Built Desc: No top landing provided

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2823C

Location: Goldenwood Cir and Woodbrook Ct - Corner D

X Coordinate: -121.32809

Y Coordinate: 38.68917

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2824A

Location: Goldenwood Cir and Hill Shade Ct - Corner A

X Coordinate: -121.32747

Y Coordinate: 38.68798

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.5% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2824B

Location: Goldenwood Cir and Hill Shade Ct - Corner A

X Coordinate: -121.32747

Y Coordinate: 38.68798

Barrier Area: Curb Ramps

Barrier Type: Perpendicular Ramp Landing - New Construction

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp top landing not min. 48" deep

As Built Desc: No top landing provided

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2824C

Location: Goldenwood Cir and Hill Shade Ct - Corner A

X Coordinate: -121.32747

Y Coordinate: 38.68798

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2825A

Location: Goldenwood Cir and Hill Shade Ct - Corner B

X Coordinate: -121.32758

Y Coordinate: 38.68788

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.3% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2825B
Location:	Goldenwood Cir and Hill Shade Ct - Corner B				
X Coordinate:	-121.32758				
Y Coordinate:	38.68788				
Barrier Area:	Curb Ramps				
Barrier Type:	Perpendicular Ramp Landing - New Construction				
Code Ref:	CBC 1127B.5.4 and ADA/ABA 406.4				



As Built Meas:	1	Quantity:	EACH	
Description:	Curb ramp top landing not min. 48" deep			
As Built Desc:	No top landing provided			
Solution:	Demolish existing and construct new transition			
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Two - way intersection. Corners A,B			

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2825C
Location:	Goldenwood Cir and Hill Shade Ct - Corner B				
X Coordinate:	-121.32758				
Y Coordinate:	38.68788				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:	Two - way intersection. Corners A,B			

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2826

Location: Foxwood Ct - East

X Coordinate: -121.32885

Y Coordinate: 38.68783

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2827A

Location: Goldenwood Cir and Glen Hollow Ct - Corner A

X Coordinate: -121.32992

Y Coordinate: 38.6872

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.5% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2827B

Location: Goldenwood Cir and Glen Hollow Ct - Corner A

X Coordinate: -121.32992

Y Coordinate: 38.6872

Barrier Area: Curb Ramps

Barrier Type: Perpendicular Ramp Landing - New Construction

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp top landing not min. 48" deep

As Built Desc: No top landing provided

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2827C

Location: Goldenwood Cir and Glen Hollow Ct - Corner A

X Coordinate: -121.32992

Y Coordinate: 38.6872

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2827D

Location: Goldenwood Cir and Glen Hollow Ct - Corner A

X Coordinate: -121.32992

Y Coordinate: 38.6872

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.9% - 6.5%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.9% - 6.5%)

As Built Desc: 5.9% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 3 Hindrance Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2828A

Location: Goldenwood Cir and Glen Hollow Ct - Corner B

X Coordinate: -121.32972

Y Coordinate: 38.68717

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.6% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2828B

Location: Goldenwood Cir and Glen Hollow Ct - Corner B

X Coordinate: -121.32972

Y Coordinate: 38.68717

Barrier Area: Curb Ramps

Barrier Type: Perpendicular Ramp Landing - New Construction

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp top landing not min. 48" deep

As Built Desc: No top landing provided

Solution: Demolish existing and construct new transition

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2828C

Location: Goldenwood Cir and Glen Hollow Ct - Corner B

X Coordinate: -121.32972

Y Coordinate: 38.68717

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2828D

Location: Goldenwood Cir and Glen Hollow Ct - Corner B

X Coordinate: -121.32972

Y Coordinate: 38.68717

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 6.6% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,B

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2829

Location: Verner Ave - East

X Coordinate: -121.33036

Y Coordinate: 38.68754

Barrier Area: Sidewalks

Barrier Type: Running Slope (Existing)

Code Ref: CBC 1133B.7.3 and ADA/ABA 403.3



As Built Meas: 80 Quantity: LF

Description: Running slope exceeds 5.0%

As Built Desc: 6.9% running slope

Solution: No remediation where sidewalk sloped as roadway

Bar. Severity: 5 Technically Infeasible Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:


Notes:

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2830
Location:	Verner Ave - East				
X Coordinate:	-121.32974				
Y Coordinate:	38.68812				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ($\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	4	Quantity:	LF	
Description:	Pedestrian route is not min. 48" wide ($\leq 31"$ or less)			
As Built Desc:	26" clear width due to pole			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2831
Location:	Verner Ave - East				
X Coordinate:	-121.32955				
Y Coordinate:	38.68832				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - $> 1/2"$				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF	
Description:	Change in level greater than $1/2"$			
As Built Desc:	$1/2"$ lip in sidewalk surface			
Solution:	Grind or repair sidewalk to remove trip hazard			
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2832

Location: Verner Ave - East

X Coordinate: -121.32896

Y Coordinate: 38.68881

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 26" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2833

Location: Verner Ave - East

X Coordinate: -121.32889

Y Coordinate: 38.68891

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 4 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Broken concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2834
Location:	Verner Ave - East - Corner B				
X Coordinate:	-121.32796				
Y Coordinate:	38.68974				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - New Construction				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (3.1% to 4.0%)		
As Built Desc:	3.8% at 12" grooves - New Construction		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2835
Location:	Verner Ave - East - Corner C				
X Coordinate:	-121.32806				
Y Coordinate:	38.68969				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - New Construction				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (3.1% to 4.0%)		
As Built Desc:	3.5% at 12" grooves - New Construction		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2836
Location:	Verner Ave - East				
X Coordinate:	-121.32676				
Y Coordinate:	38.69089				
Barrier Area:	Sidewalks				
Barrier Type:	Running Slope (Existing)				
Code Ref:	CBC 1133B.7.3 and ADA/ABA 403.3				



As Built Meas:	80	Quantity:	LF
Description:	Running slope exceeds 5.0%		
As Built Desc:	8.8% running slope		
Solution:	No remediation where sidewalk sloped as roadway		
Bar. Severity:	5 Technically Infeasible	Cost Estimate:	\$0.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2837
Location:	Verner Ave - East				
X Coordinate:	-121.32653				
Y Coordinate:	38.69103				
Barrier Area:	Sidewalks				
Barrier Type:	Elbow in Sidewalk - Cross Slope (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	8	Quantity:	LF
Description:	Cross slope at elbow exceeds 2.0% (5.0% or more)		
As Built Desc:	10.0% cross slope		
Solution:	Demolish existing and construct new sidewalk without curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2838

Location: Flaming Arrow Dr - South

X Coordinate: -121.32643

Y Coordinate: 38.69099

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 593 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$74,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2839

Location: Flaming Arrow Dr and High Sun Ct - Corner A

X Coordinate: -121.32473

Y Coordinate: 38.68998

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 13.4% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2840

Location: Flaming Arrow Dr and High Sun Ct - Corner B

X Coordinate: -121.32464

Y Coordinate: 38.68992

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 11.0% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2841

Location: Flaming Arrow Dr and High Sun Ct - Corner C

X Coordinate: -121.32476

Y Coordinate: 38.68984

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 14.1% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2842

Location: Flaming Arrow Dr and High Sun Ct - Corner D

X Coordinate: -121.32487

Y Coordinate: 38.68989

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 11.3% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Four - way intersection. Corners A,B,C,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2843

Location: High Sun Ct - West

X Coordinate: -121.3249

Y Coordinate: 38.68986

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 181 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$22,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2844A
Location:	High Sun Ct - East				
X Coordinate:	-121.32528				
Y Coordinate:	38.68943				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	228	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.5% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$28,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2844B
Location:	High Sun Ct - East				
X Coordinate:	-121.32502				
Y Coordinate:	38.68971				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF	
Description:	Change in level greater than 1/2"			
As Built Desc:	1/2" lip in sidewalk surface			
Solution:	Grind or repair sidewalk to remove trip hazard			
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2845

Location: Flaming Arrow Dr - South

X Coordinate: -121.32472

Y Coordinate: 38.68976

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 159 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$19,875.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2846

Location: Indian River Dr and Flaming Arrow Dr - Corner C

X Coordinate: -121.32421

Y Coordinate: 38.68907

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 10.7% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2847

Location: Indian River Dr and Flaming Arrow Dr - Corner D

X Coordinate: -121.32436

Y Coordinate: 38.68917

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - New Construction

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.1% at 12" grooves - New Construction

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2848

Location: Indian River Dr - West

X Coordinate: -121.32438

Y Coordinate: 38.6891

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 195 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$24,375.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2849

Location: Moon Rock Wy and Indian River Dr - Corner A

X Coordinate: -121.32485

Y Coordinate: 38.68872

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2850

Location: Moon Rock Wy and Indian River Dr - Corner D

X Coordinate: -121.32493

Y Coordinate: 38.68862

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2851

Location: Indian River Dr - West

X Coordinate: -121.32494

Y Coordinate: 38.68854

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 163 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$20,375.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2852

Location: Indian River Dr and Walking Stick Ct - Corner A


X Coordinate: -121.32518

Y Coordinate: 38.68809

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2853

Location: Indian River Dr and Walking Stick Ct - Corner D

X Coordinate: -121.32524

Y Coordinate: 38.68797

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2854

Location: Walking Stick Ct - South

X Coordinate: -121.32611

Y Coordinate: 38.68788

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 80 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.3% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$10,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2855
Location:	Indian River Dr - West				
X Coordinate:	-121.32524				
Y Coordinate:	38.68792				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	343	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$42,875.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2856A
Location:	Indian River Dr and Fire Water - Corner A				
X Coordinate:	-121.3257				
Y Coordinate:	38.68703				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (3.1% to 4.0%)		
As Built Desc:	3.6% at 12" grooves		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$2,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:	Two - way intersection. Corners A,D		

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2856B

Location: Indian River Dr and Fire Water - Corner A

X Coordinate: -121.3257

Y Coordinate: 38.68703

Barrier Area: Curb Ramps

Barrier Type: Parallel Ramp Landing - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.4 and ADA/ABA 406.4



As Built Meas: 1 Quantity: EACH

Description: Curb ramp landing or pan not level (3.1% to 4.0%)

As Built Desc: 3.6% landing slope

Solution: Demolish existing and construct new transition

Bar. Severity: 3 Hindrance Cost Estimate: \$0.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2856C

Location: Indian River Dr and Fire Water - Corner A

X Coordinate: -121.3257

Y Coordinate: 38.68703

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2856D

Location: Indian River Dr and Fire Water - Corner A

X Coordinate: -121.3257

Y Coordinate: 38.68703

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (8.3% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (8.3% or more)

As Built Desc: 11.7% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2857A

Location: Indian River Dr and Fire Water - Corner D

X Coordinate: -121.32569

Y Coordinate: 38.6869

Barrier Area: Curb Ramps

Barrier Type: Cross Slope - Existing (2.1% to 3.0%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 1 Quantity: EACH

Description: Ramp run cross slope exceeds 2.0% (2.1% to 3.0%)

As Built Desc: 3.0% cross slope

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 4 Low Severity Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2857B

Location: Indian River Dr and Fire Water - Corner D

X Coordinate: -121.32569

Y Coordinate: 38.6869

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2857C

Location: Indian River Dr and Fire Water - Corner D

X Coordinate: -121.32569

Y Coordinate: 38.6869

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (6.6% to 8.2%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (6.6% to 8.2%)

As Built Desc: 7.7% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2858
Location:	Fire Water Ct - North				
X Coordinate:	-121.32578				
Y Coordinate:	38.68699				
Barrier Area:	Sidewalks				
Barrier Type:	Shoulder Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	142	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.5% cross slope		
Solution:	Demolish existing and construct new pedestrian route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$17,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2859
Location:	Fire Water Ct - South				
X Coordinate:	-121.32643				
Y Coordinate:	38.68713				
Barrier Area:	Sidewalks				
Barrier Type:	Shoulder Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	140	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	7.1% cross slope		
Solution:	Demolish existing and construct new pedestrian route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$17,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2860

Location: Indian River Dr - West

X Coordinate: -121.3257

Y Coordinate: 38.68688

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 196 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$24,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2861

Location: Indian River Dr and Fire Stick Ct - Corner A

X Coordinate: -121.32575

Y Coordinate: 38.68629

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2862

Location: Indian River Dr and Fire Stick Ct - Corner D

X Coordinate: -121.32572

Y Coordinate: 38.68621

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2863

Location: Fire Stick Ct - North

X Coordinate: -121.32636

Y Coordinate: 38.68648

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 60 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.8% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 2 Recommended Cost Estimate: \$7,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2864

Location: Fire Stick Ct - South

X Coordinate: -121.3264

Y Coordinate: 38.68638

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 45 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.5% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 3 Hindrance Cost Estimate: \$5,625.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2865

Location: Indian River Dr - West

X Coordinate: -121.32573

Y Coordinate: 38.68616

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 269 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$33,625.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2866

Location: Indian River Dr and Papoose Ct - Corner A

X Coordinate: -121.32575

Y Coordinate: 38.68554

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2867

Location: Indian River Dr and Papoose Ct - Corner D

X Coordinate: -121.32569

Y Coordinate: 38.68539

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2868
Location:	Papoose Ct - North				
X Coordinate:	-121.32612				
Y Coordinate:	38.68563				
Barrier Area:	Sidewalks				
Barrier Type:	Shoulder Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	71	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.5% cross slope			
Solution:	Demolish existing and construct new pedestrian route			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$8,875.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2869
Location:	Indian River Dr - West				
X Coordinate:	-121.32575				
Y Coordinate:	38.68541				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	169	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.7% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$21,125.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				
Notes:				

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2870

Location: Pretty Bush Ct - North

X Coordinate: -121.32613

Y Coordinate: 38.68488

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 70 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.5% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$8,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2871

Location: Pretty Bush Ct - South

X Coordinate: -121.32621

Y Coordinate: 38.6848

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 36 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.4% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$4,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2872
Location:	Indian River Dr - West				
X Coordinate:	-121.32566				
Y Coordinate:	38.68472				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	137	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$17,125.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2873
Location:	Small Hill Ct - North				
X Coordinate:	-121.32619				
Y Coordinate:	38.68413				
Barrier Area:	Sidewalks				
Barrier Type:	Shoulder Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	41	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.7% cross slope		
Solution:	Demolish existing and construct new pedestrian route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$5,125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2874
Location:	Small Hill Ct - South				
X Coordinate:	-121.3263				
Y Coordinate:	38.68403				
Barrier Area:	Sidewalks				
Barrier Type:	Shoulder Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	38	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.6% cross slope		
Solution:	Demolish existing and construct new pedestrian route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$4,750.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/29/2010	Report Date:	11/29/2010	Barrier #:	2875A
Location:	Indian River Dr - West				
X Coordinate:	-121.32549				
Y Coordinate:	38.68411				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	174	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$21,750.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2875B

Location: Indian River Dr - West

X Coordinate: -121.32541

Y Coordinate: 38.68375

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - Tree Heaves

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip due to tree heaves

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2876

Location: Little River Ct - South

X Coordinate: -121.32646

Y Coordinate: 38.68311

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 104 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.5% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 2 Recommended Cost Estimate: \$13,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2877

Location: Indian River Dr - West

X Coordinate: -121.3251

Y Coordinate: 38.68285

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 187 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 4.0% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$23,375.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2878

Location: Indian River Dr and Tall Tree Cir - Corner A

X Coordinate: -121.32471

Y Coordinate: 38.68239

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/29/2010 Report Date: 11/29/2010 Barrier #: 2879

Location: Indian River Dr and Tall Tree Cir - Corner D

X Coordinate: -121.32464

Y Coordinate: 38.68229

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners A,D

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2890

Location: Flaming Arrow Dr - North

X Coordinate: -121.32486

Y Coordinate: 38.69014

Barrier Area: Sidewalks

Barrier Type: No Sidewalk - Cane Detectable Barricade

Code Ref: CBC 1133B.8.6 and MUTCD Section 6D.02



As Built Meas: 5 Quantity: LF

Description: No cane detectable warning on existing barricade

As Built Desc: Existing barricade lacks warning for the visually impaired

Solution: Provide cane detectable warning on barricade (max. 6" above ground)

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2891

Location: Big Arrow Ct - West

X Coordinate: -121.32452

Y Coordinate: 38.69004

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 604 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$75,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2892

Location: Big Arrow Ct - West

X Coordinate: -121.32318

Y Coordinate: 38.6911

Barrier Area: Sidewalks

Barrier Type: Elbow in Sidewalk - Cross Slope (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 8 Quantity: LF

Description: Cross slope at elbow exceeds 2.0% (5.0% or more)

As Built Desc: 8.8% cross slope

Solution: Demolish existing and construct new sidewalk without curb ramp

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/30/2010	Report Date:	11/30/2010	Barrier #:	2893
Location:	Big Arrow Ct - East				
X Coordinate:	-121.32326				
Y Coordinate:	38.6909				
Barrier Area:	Sidewalks				
Barrier Type:	Shoulder Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	164	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.4% cross slope			
Solution:	Demolish existing and construct new pedestrian route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$20,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	11/30/2010	Report Date:	11/30/2010	Barrier #:	2894
Location:	Big Arrow Ct and White Cloud Ct - Corner C				
X Coordinate:	-121.32347				
Y Coordinate:	38.69073				
Barrier Area:	Blended Transitions				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at transition into roadway			
As Built Desc:	No detectable warning provided			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection. Corners C,D
--------	-------------------------------------

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2895

Location: Big Arrow Ct and White Cloud Ct - Corner D

X Coordinate: -121.32355

Y Coordinate: 38.69066

Barrier Area: Blended Transitions

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at transition into roadway

As Built Desc: No detectable warning provided

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection. Corners C,D

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2896

Location: White Cloud Ct - East


X Coordinate: -121.32336

Y Coordinate: 38.69067

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 182 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.4% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 1 Necessary Cost Estimate: \$22,750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2897

Location: White Cloud Ct - West


X Coordinate: -121.32307

Y Coordinate: 38.69048

Barrier Area: Sidewalks

Barrier Type: Shoulder Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 184 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.4% cross slope

Solution: Demolish existing and construct new pedestrian route

Bar. Severity: 1 Necessary

Cost Estimate: \$23,000.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2898

Location: Greenback Ln - North

X Coordinate: -121.32682

Y Coordinate: 38.68122

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 585 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.6% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended

Cost Estimate: \$73,125.00

Status:

Implementation Priority: 1

Facility Function:

Implementation Phase:

Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2899A

Location: Greenback Ln - North

X Coordinate: -121.32313

Y Coordinate: 38.6809

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 578 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.7% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$72,250.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2903

Location: Greenback Ln - North


X Coordinate: -121.32195

Y Coordinate: 38.68025

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 140 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$17,500.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2904

Location: Greenback Ln - North


X Coordinate: -121.32138

Y Coordinate: 38.67986

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 62 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$7,750.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2905

Location: Greenback Ln - North

X Coordinate: -121.32123

Y Coordinate: 38.6797

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 40 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 8.7% cross slope, 9.1% running slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 1 Necessary Cost Estimate: \$5,000.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2906

Location: Greenback Ln - North

X Coordinate: -121.32116

Y Coordinate: 38.67964

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 40 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.4% cross slope, 14.3 running slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 1 Necessary Cost Estimate: \$5,000.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2907

Location: Greenback Ln - North

X Coordinate: -121.32108

Y Coordinate: 38.67957

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 51 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$6,375.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2908A

Location: Greenback Ln - North

X Coordinate: -121.32102

Y Coordinate: 38.6795

Barrier Area: Bus Stops and Shelters

Barrier Type: Bench Seat Depth

Code Ref: ADAAG 4.37.1 and ADA/ABA 903.4



As Built Meas: 1 Quantity: EACH

Description: Bench seat depth not 20" - 24" deep

As Built Desc: 9" bench seat depth

Solution: Provide min. 1 accessible bench at bench stop

Bar. Severity: 3 Hindrance Cost Estimate: \$775.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2908B

Location: Greenback Ln - North

X Coordinate: -121.32102

Y Coordinate: 38.6795

Barrier Area: Bus Stops and Shelters

Barrier Type: Bench Back Support

Code Ref: ADAAG 4.37.4 and ADA/ABA 903.4



As Built Meas: 1 Quantity: EACH

Description: Bench has no back support of at least 18" high

As Built Desc: No back support provided

Solution: Provide min. 1 accessible bench at bench stop or shelter

Bar. Severity: 3 Hindrance Cost Estimate: \$0.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2909

Location: Greenback Ln - North

X Coordinate: -121.32090

Y Coordinate: 38.67935

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 39 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 8.3% cross slope, 14.8% running slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 1 Necessary Cost Estimate: \$4,875.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2910

Location: Auburn Blvd - West

X Coordinate: -121.32056

Y Coordinate: 38.67927

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 50 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.5% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$6,250.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2911

Location: Auburn Blvd - West

X Coordinate: -121.32039

Y Coordinate: 38.67939

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 41 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 11.3% cross slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 4 Low Severity Cost Estimate: \$5,125.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2912A

Location: Auburn Blvd - West


X Coordinate: -121.32030

Y Coordinate: 38.67948

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 150 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$18,750.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2912B

Location: Auburn Blvd - West

X Coordinate: -121.32015

Y Coordinate: 38.67958

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing ($\leq 31"$ or less)

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide ($\leq 31"$ or less)

As Built Desc: 31" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2913

Location: Auburn Blvd - West


X Coordinate: -121.32010

Y Coordinate: 38.67961

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 124 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$15,500.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2914A

Location: Auburn Blvd - West

X Coordinate: -121.31916

Y Coordinate: 38.68016

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 44 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.2% cross slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 4 Low Severity Cost Estimate: \$5,500.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2914B

Location: Auburn Blvd - West

X Coordinate: -121.31916

Y Coordinate: 38.68016

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 88 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$11,000.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2915

Location: Auburn Blvd - West


X Coordinate: -121.31882

Y Coordinate: 38.68041

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 12 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Loose soil

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$1,500.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2916

Location: Auburn Blvd - West

X Coordinate: -121.31878

Y Coordinate: 38.68045

Barrier Area: Sidewalks

Barrier Type: Clear Width - Existing (32" to 35")

Code Ref: CBC 1133B.7.1



As Built Meas: 4 Quantity: LF

Description: Pedestrian route is not min. 48" wide (32" to 35")

As Built Desc: 34" clear width due to pole

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$500.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2917

Location: Auburn Blvd - West


X Coordinate: -121.31872

Y Coordinate: 38.68048

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 83 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hindrance Cost Estimate: \$10,375.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2918

Location: Auburn Blvd - West


X Coordinate: -121.31851

Y Coordinate: 38.68061

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 32 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 3 Hindrance Cost Estimate: \$4,000.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	11/30/2010	Report Date:	11/30/2010	Barrier #:	2919
Location:	Auburn Blvd - West				
X Coordinate:	-121.31840				
Y Coordinate:	38.6807				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	59	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.8% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$7,375.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	11/30/2010	Report Date:	11/30/2010	Barrier #:	2920
Location:	Auburn Blvd - West				
X Coordinate:	-121.31822				
Y Coordinate:	38.68079				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	42	Quantity:	LF
Description:	Driveway cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.6% cross slope, 10.6% running slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	1 Necessary	Cost Estimate:	\$5,250.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2921

Location: Auburn Blvd - West


X Coordinate: -121.31670

Y Coordinate: 38.68175

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 40 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.6% cross slope, 11.5% running slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 1 Necessary Cost Estimate: \$5,000.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2922A

Location: Auburn Blvd - West


X Coordinate: -121.31661

Y Coordinate: 38.6818

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 351 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$43,875.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2922B

Location: Auburn Blvd - West

X Coordinate: -121.31610

Y Coordinate: 38.68214

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2922C

Location: Auburn Blvd - West

X Coordinate: -121.31558

Y Coordinate: 38.68244

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 4 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2923

Location: Auburn Blvd - West

X Coordinate: -121.31553

Y Coordinate: 38.6825

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 40 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.4% cross slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 4 Low Severity Cost Estimate: \$5,000.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2924

Location: Auburn Blvd - West


X Coordinate: -121.31553

Y Coordinate: 38.6825

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 148 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.2% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$18,500.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2925

Location: Auburn Blvd - West


X Coordinate: -121.31504

Y Coordinate: 38.68281

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 39 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 8.2% cross slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 4 Low Severity Cost Estimate: \$4,875.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2926A

Location: Auburn Blvd - West

X Coordinate: -121.31487

Y Coordinate: 38.68294

Barrier Area: Bus Stops and Shelters

Barrier Type: Bench Seat Depth

Code Ref: ADAAG 4.37.1 and ADA/ABA 903.4



As Built Meas: 1 Quantity: EACH

Description: Bench seat depth not 20" - 24" deep

As Built Desc: 12-1/2" bench seat depth

Solution: Provide min. 1 accessible bench at bench stop

Bar. Severity: 3 Hindrance Cost Estimate: \$775.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2926B

Location: Auburn Blvd - West

X Coordinate: -121.31487

Y Coordinate: 38.68294

Barrier Area: Bus Stops and Shelters

Barrier Type: Bench Back Support

Code Ref: ADAAG 4.37.4 and ADA/ABA 903.4



As Built Meas: 1 Quantity: EACH

Description: Bench has no back support of at least 18" high

As Built Desc: 16-1/2" back support height

Solution: Provide min. 1 accessible bench at bench stop or shelter

Bar. Severity: 3 Hindrance Cost Estimate: \$0.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 11/30/2010 Report Date: 11/30/2010 Barrier #: 2926C

Location: Auburn Blvd - West


X Coordinate: -121.31480

Y Coordinate: 38.68293

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 447 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$55,875.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

<hr/>	
<hr/>	
Cost Estimate Total Summary :	\$13,080,175.00
<hr/>	
Cost Estimate - Priority 1:	\$1,205,125.00
Cost Estimate - Priority 2:	\$2,332,950.00
Cost Estimate - Priority 3:	\$635,200.00
Cost Estimate - Priority 4:	\$8,906,900.00
<hr/>	
<hr/>	