


# SZS CONSULTING GROUP



**DRAFT ADA TRANSITION PLAN UPDATE  
NEIGHBORHOOD AREA 4 ARCADE CREEK  
SEPTEMBER 20, 2011**

CITY OF CITRUS HEIGHTS


## Arcade Creek Neighborhood Area

The Arcade Creek Neighborhood Area is a residential area with one commercial/retail center, office park, City Hall, and one recreational park area. The areas borders are Auburn Boulevard, Greenback Lane, and Sylvan Road.

### Conditions

Most of the sidewalks in the Arcade Creek Neighborhood Area are of pre-1992 construction, which were identified with common issues such as non-compliant cross slopes, clear width issues, abrupt changes of level, and poor surface conditions. Many pre-1992 curb ramps were identified with multiple barriers to access.

A post-1992 residential area north of City Hall was identified with non-compliant sidewalk cross slopes and curb ramps. The primary arterial roadways were identified with compliance issues at driveways along both sides of the roadway. Bus stops on both Auburn Boulevard and Greenback Lane were identified with compliance issues.



### Statistics

An intersection inventory was compiled as part of the field assessment process. In the Arcade Creek Neighborhood Area, 23 intersections were found to have no barriers to access and a total of 622 barriers were identified. The compliant intersections are identified as follows:

#	Location	Notes
1	Auburn Boulevard and Costco Entrance - Corners C,D	Two - way intersection corners C,D compliant
2	Auburn Boulevard and Devecchi Wy - Corners A,D	Two - way intersection corners A,D compliant
3	Bremen Dr and Charwood Ln - Corners A,D	Two - way intersection corners A,D compliant
4	Carlow Dr and Donegal Dr - Corner C,D	Two - way intersection corners C,D compliant
5	Cavan Dr and Donegal Dr - Corners A,B	Two - way intersection corners A,B compliant
6	Donegal Dr and Van Maren Ln - Corners A,D	Two - way intersection corners A,D compliant
7	Fountain Square Dr and City Hall Entrance - Corners A,D	Two - way intersection corners C,D compliant
8	Fountain Square Dr and Post Office Entrance - Corners C,D	Two - way intersection corners C,D compliant
9	Fountain Square Dr and Sam's Club Entrance - Corners B,C	Two - way intersection corners B,C compliant
10	Fountain Square Dr and Sam's Club Entrance - Corners B,C	Two - way intersection corners B,C compliant

11	Hespera Wy and Hespera Wy - Corners A,B,C	Three - way intersection corners A,B,C compliant
12	Hespera Wy and Hespera Wy - Corners B,C,D	Three - way intersection corners B,C,D compliant
13	Longford Dr and Donegal Dr - Corners C,D	Two - way intersection corners C,D compliant
14	Louth Wy and Donegal Dr - Corners C,D	Two - way intersection corners C,D compliant
15	San Juan Ave and San Juan Plaza Shopping Center Entrance - Corners A,D	Two - way intersection corners A,D compliant
16	Sol Wy and Poseidon Ct - Corners A,C,D	Three - way intersection corners A,C,D compliant
17	Stock Ranch Rd and Sol Wy - Corners A,B	Two - way intersection corners A,B compliant
18	Stock Ranch Rd and Woodside Dr - Corners A,B,C,D	Four - way intersection corners A,B,C,D compliant
19	Thalia Ct and Sol Wy - Corners B,C,D	Three - way intersection corners B,C,D compliant
20	Thalia Wy and Hera Ct - Corner B,C,D	Three - way intersection corners B,C,D compliant
21	Thalia Wy and Hespera Wy - Corners A,B,C	Three - way intersection corners A,B,C compliant
22	Woodside Dr and Demeter Ct - Corners A,B,C	Three - way intersection corners A,B,C compliant
23	Woodside Dr and Thalia Wy - Corners A,B,C,D	Four - way intersection corners A,B,C,D compliant

Barrier severity ratings were calculated for the 5 ratings assigned as follows:

<i>Severity 1 (Necessary to Remove)</i>	<i>261 or 44% of total barriers</i>
<i>Severity 2 (Recommended to Remove)</i>	<i>143 or 24% of total barriers</i>
<i>Severity 3 (Hindrance to Access)</i>	<i>131 or 22% of total barriers</i>
<i>Severity 4 (Low Severity Barrier)</i>	<i>54 or 9% of total barriers</i>
<i>Severity 5 (Technically Infeasible to Remove)</i>	<i>10 or 2% of total barriers</i>

### Barrier Removal Priority Assignment

The draft barrier removal priorities were assigned to the pedestrian facilities using the criteria described below:

**Priority 1** - Primary arterial roadways where the majority of bus routes are located

*Auburn Boulevard*  
*Dewey Boulevard*  
*Greenback Boulevard*  
*Sylvan Boulevard*

**Priority 2** – Major collectors where remaining bus routes are located or where commercial centers, schools, parks, churches, state or local agency facilities exist

*Indian River Drive*  
*Misty Creek Drive*  
*Starflower Drive*  
*Westbrook Drive*

**Priority 3** - Pedestrian routes leading from points of arrival at bus routes to schools, parks or other public accommodations  
*Navion Drive*

**Priority 4** - Remaining residential public rights-of-way

## Cost Estimates

The total cost for barrier removal within this draft ADA Transition Plan update was calculated as follows:

**Cost Estimate Total:** \$6,402,025.00

Barrier removal takes place through annual phases that are determined according to the barrier priority assigned and existing budgetary constraints. Draft barrier removal priorities have the following costs associated with each priority assigned:

**Cost Estimate - Priority 1:** \$1,421,875.00

**Cost Estimate - Priority 2:** \$854,875.00

**Cost Estimate - Priority 3:** \$738,550.00

**Cost Estimate - Priority 4:** \$3,386,225.00

Further input is required to complete the ADA Transition Plan. Each Neighborhood Area (NA) must be reviewed by designated Citrus Heights City staff to determine whether overall priorities shall be set per NA or overall throughout the city. Other constraints were taken into consideration while compiling the cost estimates.

1. Currently all barriers are assigned a priority for removal. Some areas may not be used as pedestrian facilities, may be unimproved and could remain so until a request for accommodations is received by the City.
  - a. Assistance in prioritizing areas that lack sidewalk is required. Some segments are lengthy and may not be planned for improvements in the long or short term.
2. Cost estimates have been manually reviewed and corrected
  - a. In instances where more than one barrier exists at a curb ramp, cost estimates for curb ramp barriers are often manually changed to ensure that cost estimates do not exceed \$2,500. In these instances, the cost estimate for the first barrier (i.e. 24A, of 24B, 24C and 25D) is listed with a cost estimate of \$2,500 and the remaining barriers are listed with a cost of \$0. This may occur even when the first barrier listed is not ordinarily estimated as high as \$2,500.
  - b. Driveways with multiple slopes were assigned a severity 1 rating, rather than a rating that corresponded to the slope of only one of the measurements taken.
  - c. Bus stop benches with multiple barriers were only assigned one cost estimate for one accessible bench.

The following barrier data sheets must be reviewed in draft form to provide input for the final report.

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2927A
Location:	Greenback Ln - South				
X Coordinate:	-121.32428				
Y Coordinate:	38.68082				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Seat Height				
Code Ref:	ADAAG 4.37.3* and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH		
Description:	Bench seat height not between 17" - 19"				
As Built Desc:	20" bench seat height				
Solution:	Provide new compliant bench or remount at compliant height where possible				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$775.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2927B
Location:	Greenback Ln - South				
X Coordinate:	-121.32428				
Y Coordinate:	38.68082				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Seat Depth				
Code Ref:	ADAAG 4.37.1 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH		
Description:	Bench seat depth not 20" - 24" deep				
As Built Desc:	9" bench seat depth				
Solution:	Provide min. 1 accessible bench at bench stop				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--


Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2927C
Location:	Greenback Ln - South				
X Coordinate:	-121.32428				
Y Coordinate:	38.68082				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Back Support				
Code Ref:	ADAAG 4.37.4 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH	
Description:	Bench has no back support of at least 18" high			
As Built Desc:	No back support provided			
Solution:	Provide min. 1 accessible bench at bench stop or shelter			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2928
Location:	Greenback Ln - South				
X Coordinate:	-121.32139				
Y Coordinate:	38.67949				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	40	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.8% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	2 Recommended	Cost Estimate:	\$5,000.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2929
Location:	Greenback Ln - South				
X Coordinate:	-121.32111				
Y Coordinate:	38.67917				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	40	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	4.0% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	2 Recommended	Cost Estimate:	\$5,000.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2930
Location:	Auburn Blvd - West				
X Coordinate:	-121.32109				
Y Coordinate:	38.67899				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	39	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (2.1% to 3.0%)			
As Built Desc:	2.7% cross slope, 10.1% running slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,875.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2931A
Location:	Auburn Blvd - West				
X Coordinate:	-121.32132				
Y Coordinate:	38.67884				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	41	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.4% cross slope, 8.5% running slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	1 Necessary	Cost Estimate:	\$5,125.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2931B
Location:	Auburn Blvd - West				
X Coordinate:	-121.32132				
Y Coordinate:	38.67882				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	10	Quantity:	LF		
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)				
As Built Desc:	Cracked concrete				
Solution:	Repair surface to make firm and stable				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,250.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--



Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2932A
Location:	Auburn Blvd - West				
X Coordinate:	-121.32171				
Y Coordinate:	38.67865				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Seat Height				
Code Ref:	ADAAG 4.37.3* and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH
Description:	Bench seat height not between 17" - 19"		
As Built Desc:	21" bench seat height		
Solution:	Provide new compliant bench or remount at compliant height where possible		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$775.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2932B
Location:	Auburn Blvd - West				
X Coordinate:	-121.32171				
Y Coordinate:	38.67865				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Seat Depth				
Code Ref:	ADAAG 4.37.1 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH
Description:	Bench seat depth not 20" - 24" deep		
As Built Desc:	15" bench seat depth		
Solution:	Provide min. 1 accessible bench at bench stop		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2932C
Location:	Auburn Blvd - West				
X Coordinate:	-121.32171				
Y Coordinate:	38.67865				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Back Support				
Code Ref:	ADAAG 4.37.4 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH	
Description:	Bench has no back support of at least 18" high			
As Built Desc:	No back support provided			
Solution:	Provide min. 1 accessible bench at bench stop or shelter			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2933
Location:	Auburn Blvd - West				
X Coordinate:	-121.32269				
Y Coordinate:	38.6778				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	36	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.1% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$4,500.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2934
Location:	Auburn Blvd - West				
X Coordinate:	-121.32277				
Y Coordinate:	38.67776				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	83	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.3% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$10,375.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2935
Location:	Auburn Blvd - West				
X Coordinate:	-121.32301				
Y Coordinate:	38.67756				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	37	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	7.3% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,625.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2936
Location:	Auburn Blvd - West				
X Coordinate:	-121.32306				
Y Coordinate:	38.67749				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	54	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.3% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$6,750.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2937
Location:	Auburn Blvd - West				
X Coordinate:	-121.32332				
Y Coordinate:	38.67727				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	37	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	7.3% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,625.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2938
Location:	Auburn Blvd - West				
X Coordinate:	-121.32372				
Y Coordinate:	38.67691				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	38	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	8.0% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,750.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2939
Location:	Auburn Blvd - West				
X Coordinate:	-121.32378				
Y Coordinate:	38.67685				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	38	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	8.0% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,750.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2940
Location:	Auburn Blvd - West				
X Coordinate:	-121.32385				
Y Coordinate:	38.67679				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	36	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	6.9% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,500.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2941
Location:	Auburn Blvd - West				
X Coordinate:	-121.324				
Y Coordinate:	38.67662				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	33	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	6.3% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,125.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2942
Location:	Auburn Blvd and Imperial Wy - Corner A				
X Coordinate:	-121.32509				
Y Coordinate:	38.67565				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,D. Corner D compliant

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2943
Location:	Auburn Blvd - West				
X Coordinate:	-121.32549				
Y Coordinate:	38.67535				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	43	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	8.8% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$5,375.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:




Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2944
Location:	Auburn Blvd - West				
X Coordinate:	-121.32561				
Y Coordinate:	38.67522				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Seat Depth				
Code Ref:	ADAAG 4.37.1 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH
Description:	Bench seat depth not 20" - 24" deep		
As Built Desc:	16" bench seat depth		
Solution:	Provide min. 1 accessible bench at bench stop		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$775.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2945
Location:	Auburn Blvd - West				
X Coordinate:	-121.32572				
Y Coordinate:	38.67514				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	37	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	7.8% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,625.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			




Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2946
Location:	Auburn Blvd - West				
X Coordinate:	-121.32578				
Y Coordinate:	38.67508				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ( $\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	4	Quantity:	LF		
Description:	Pedestrian route is not min. 48" wide ( $\leq 31"$ or less)				
As Built Desc:	31" clear width due to pole				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--


Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2947
Location:	Auburn Blvd - West				
X Coordinate:	-121.32587				
Y Coordinate:	38.675				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	38	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.5% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$4,750.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2948
Location:	Auburn Blvd - West				
X Coordinate:	-121.32601				
Y Coordinate:	38.67489				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	36	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.3% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,500.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2949
Location:	Auburn Blvd - West				
X Coordinate:	-121.32627				
Y Coordinate:	38.67468				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	36	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	8.8% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,500.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2950
Location:	Bremen Dr - West				
X Coordinate:	-121.31615				
Y Coordinate:	38.67945				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	43	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.8% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$5,375.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2951
Location:	Bremen Dr - West				
X Coordinate:	-121.31592				
Y Coordinate:	38.67952				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	11	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.0% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$1,375.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2952
Location:	Bremen Dr and Cavan Dr - Corner B				
X Coordinate:	-121.31502				
Y Coordinate:	38.67955				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH	
Description:	12" grooves at top of curb ramp are not level (3.1% to 4.0%)			
As Built Desc:	3.8% at 12" grooves			
Solution:	Demolish existing and construct new curb ramp			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,B. Corner A compliant

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2953
Location:	Bremen Dr and Longford Dr - Corner D				
X Coordinate:	-121.31439				
Y Coordinate:	38.67925				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Four - way intersection corners A,B,C,D. Corners A,B,C compliant

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2954
Location:	Carlow Dr and Bremen Dr - Corner A				
X Coordinate:	-121.31317				
Y Coordinate:	38.6791				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2955
Location:	Carlow Dr and Bremen Dr - Corner B				
X Coordinate:	-121.31289				
Y Coordinate:	38.67909				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2956
Location:	Carlow Dr - East				
X Coordinate:	-121.31289				
Y Coordinate:	38.67982				
Barrier Area:	Sidewalks				
Barrier Type:	Protruding Hazard				
Code Ref:	CBC 1133B.8.6.1 and ADA/ABA 307.2				



As Built Meas:	1	Quantity:	JOB		
Description:	Protruding object in route of travel between 27" and 80" high				
As Built Desc:	32" high at tree branches				
Solution:	Remove object or provide detectable warning				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,400.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2957
Location:	Bremen Dr - North				
X Coordinate:	-121.3125				
Y Coordinate:	38.67908				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	32	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (2.1% to 3.0%)				
As Built Desc:	3.0% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2958
Location:	Bremen Dr and Louth Wy - Corner A				
X Coordinate:	-121.31208				
Y Coordinate:	38.67915				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2959
Location:	Bremen Dr and Louth Wy - Corner B				
X Coordinate:	-121.31183				
Y Coordinate:	38.6791				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B



Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2960
Location:	Louth Wy - West				
X Coordinate:	-121.31185				
Y Coordinate:	38.68056				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF		
Description:	Change in level greater than 1/2"				
As Built Desc:	1/2" lip in sidewalk surface				
Solution:	Grind or repair sidewalk to remove trip hazard				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2961
Location:	Louth Wy - East				
X Coordinate:	-121.31136				
Y Coordinate:	38.68117				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	33	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.3% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	2 Recommended	Cost Estimate:	\$4,125.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--



Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2962
Location:	Louth Wy and Leirim Ct - Corner B				
X Coordinate:	-121.31146				
Y Coordinate:	38.68082				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No compliant curb cut at corner (intersection)			
As Built Desc:	4.0% running slope at depressed area			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners B,C

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2963
Location:	Louth Wy and Leirim Ct - Corner C				
X Coordinate:	-121.31156				
Y Coordinate:	38.68064				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No compliant curb cut at corner (intersection)			
As Built Desc:	5.3% running slope at depressed area			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners B,C

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2964
Location:	Louth Wy and Steffano Ct - Corner B				
X Coordinate:	-121.31192				
Y Coordinate:	38.67985				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No compliant curb cut at corner (intersection)			
As Built Desc:	3.3% running slope at depressed area			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners B,C

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2965
Location:	Louth Wy and Steffano Ct - Corner C				
X Coordinate:	-121.31193				
Y Coordinate:	38.67972				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No compliant curb cut at corner (intersection)			
As Built Desc:	4.0% running slope at depressed area			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners B,C

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2966A
Location:	Bremen Dr - South				
X Coordinate:	-121.31076				
Y Coordinate:	38.67907				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	76	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (2.1% to 3.0%)				
As Built Desc:	3.0% cross slope				
Solution:	Low severity barrier - no remediation recommended				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2966B
Location:	Bremen Dr - South				
X Coordinate:	-121.31076				
Y Coordinate:	38.67907				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF		
Description:	Change in level greater than 1/2"				
As Built Desc:	1/2" lip in sidewalk surface				
Solution:	Grind or repair sidewalk to remove trip hazard				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2967
Location:	Bremen Dr and Van Maren Ln - Corner A				
X Coordinate:	-121.31052				
Y Coordinate:	38.67906				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No compliant curb cut at corner (intersection)				
As Built Desc:	6.4% running slope at depressed area				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,D

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2968
Location:	Bremen Dr and Van Maren Ln - Corner D				
X Coordinate:	-121.31053				
Y Coordinate:	38.67891				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No compliant curb cut at corner (intersection)				
As Built Desc:	5.0% running slope at depressed area				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,D


Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2969
Location:	Bremen Dr - South				
X Coordinate:	-121.31089				
Y Coordinate:	38.67897				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	37	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (2.1% to 3.0%)			
As Built Desc:	2.8% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,625.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2970
Location:	Bremen Dr - South				
X Coordinate:	-121.31112				
Y Coordinate:	38.67895				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	50	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.6% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$6,250.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2971
Location:	Bremen Dr - South				
X Coordinate:	-121.31133				
Y Coordinate:	38.67896				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	37	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.4% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$4,625.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2972
Location:	Longford Dr - East				
X Coordinate:	-121.31441				
Y Coordinate:	38.67852				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	35	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (2.1% to 3.0%)			
As Built Desc:	2.5% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,375.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--



Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2973
Location:	Longford Dr - East				
X Coordinate:	-121.31453				
Y Coordinate:	38.67832				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1/2" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--


Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2974
Location:	Bremen Dr - East				
X Coordinate:	-121.31636				
Y Coordinate:	38.67909				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	37	Quantity:	LF
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.1% cross slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2975
Location:	Bremen Dr - East				
X Coordinate:	-121.31638				
Y Coordinate:	38.67883				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	30	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.4% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$3,750.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2976A
Location:	Greenback Ln - North				
X Coordinate:	-121.31493				
Y Coordinate:	38.67827				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Seat Depth				
Code Ref:	ADAAG 4.37.1 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH		
Description:	Bench seat depth not 20" - 24" deep				
As Built Desc:	16" bench seat depth				
Solution:	Provide min. 1 accessible bench at bench stop				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$775.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--



Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2976B
Location:	Greenback Ln - North				
X Coordinate:	-121.31493				
Y Coordinate:	38.67827				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Seat Height				
Code Ref:	ADAAG 4.37.3* and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH
Description:	Bench seat height not between 17" - 19"		
As Built Desc:	12-1/2" bench seat height		
Solution:	Provide new compliant bench or remount at compliant height where possible		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2976C
Location:	Greenback Ln - North				
X Coordinate:	-121.31493				
Y Coordinate:	38.67827				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Back Support				
Code Ref:	ADAAG 4.37.4 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH
Description:	Bench has no back support of at least 18" high		
As Built Desc:	12-1/2" back support height		
Solution:	Provide min. 1 accessible bench at bench stop or shelter		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2977
Location:	Van Maren Ln - West				
X Coordinate:	-121.31065				
Y Coordinate:	38.68043				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	29	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	6.4% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$3,625.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2978
Location:	Donegal Dr - South				
X Coordinate:	-121.31298				
Y Coordinate:	38.68152				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	37	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.1% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	2 Recommended	Cost Estimate:	\$4,625.00	Status:	
Implementation Priority:	3	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2979
Location:	Donegal Dr and Auburn Blvd - Corner B				
X Coordinate:	-121.3146				
Y Coordinate:	38.68288				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	3	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners B,C

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2980
Location:	Donegal Dr and Auburn Blvd - Corner C				
X Coordinate:	-121.31472				
Y Coordinate:	38.68282				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	3	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners B,C

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2981
Location:	Donegal Dr and Wexford Cir - Corner A				
X Coordinate:	-121.31277				
Y Coordinate:	38.68159				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	3	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,B

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2982
Location:	Donegal Dr and Wexford Cir - Corner B				
X Coordinate:	-121.3127				
Y Coordinate:	38.68158				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	3	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,B

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2983
Location:	Donegal Dr and Wexford Cir - Corner A				
X Coordinate:	-121.31113				
Y Coordinate:	38.68159				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	3	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2984
Location:	Donegal Dr and Wexford Cir - Corner B				
X Coordinate:	-121.31104				
Y Coordinate:	38.68158				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	3	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B

Field Date:	12/1/2010	Report Date:	12/1/2010	Barrier #:	2985
Location:	Donegal Dr - North				
X Coordinate:	-121.31099				
Y Coordinate:	38.68158				
Barrier Area:	Sidewalks				
Barrier Type:	Running Slope (New Construction)				
Code Ref:	CBC 1133B.7.3 and ADA/ABA 403.3				



As Built Meas:	8	Quantity:	LF
Description:	Running slope exceeds 5.0% where roadway slope does not		
As Built Desc:	7.1% running slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2986A
Location:	Greenback Ln and Bremen Dr - Corner A A-A				
X Coordinate:	-121.31669				
Y Coordinate:	38.67825				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (4.1% to 4.9%)		
As Built Desc:	4.6% at 12" grooves		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	2 Recommended	Cost Estimate:	\$2,500.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	Four - way intersection corners A,B,C,D. Corners A A-B,C A-B compliant
--------	--



Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2986B
Location:	Greenback Ln and Bremen Dr - Corner A A-A				
X Coordinate:	-121.31669				
Y Coordinate:	38.67825				
Barrier Area:	Signalized Intersections				
Barrier Type:	APS Vibrotactile Control				
Code Ref:	PROWAG R306.2				



As Built Meas:	1	Quantity:	JOB		
Description:	No vibrotactile pedestrian buttons provided				
As Built Desc:	No vibrotactile buttons provided				
Solution:	Recommended: Provide vibrotactile ped buttons				
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Four - way intersection corners A,B,C,D. Corners A A-B,C A-B compliant

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2986C
Location:	Greenback Ln and Bremen Dr - Corner A A-B				
X Coordinate:	-121.31669				
Y Coordinate:	38.67825				
Barrier Area:	Signalized Intersections				
Barrier Type:	APS Vibrotactile Control				
Code Ref:	PROWAG R306.2				



As Built Meas:	1	Quantity:	JOB		
Description:	No vibrotactile pedestrian buttons provided				
As Built Desc:	No vibrotactile buttons provided				
Solution:	Recommended: Provide vibrotactile ped buttons				
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,700.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Four - way intersection corners A,B,C,D. Corners A A-B,C A-B compliant

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2987A
Location:	Greenback Ln and Bremen Dr - Corner B A-A				
X Coordinate:	-121.31641				
Y Coordinate:	38.67826				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH		
Description:	12" grooves at top of curb ramp are not level (4.1% to 4.9%)				
As Built Desc:	4.6% at 12" grooves				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	2 Recommended	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Four - way intersection corners A,B,C,D. Corners A A-B,C A-B compliant

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2987B
Location:	Greenback Ln and Bremen Dr - Corner B A-A				
X Coordinate:	-121.31641				
Y Coordinate:	38.67826				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (>5.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH		
Description:	12" grooves at top of curb ramp are not level (>5.0%)				
As Built Desc:	5.4% at 12" grooves				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Four - way intersection corners A,B,C,D. Corners A A-B,C A-B compliant



Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2987C
Location:	Greenback Ln and Bremen Dr - Corner B A-A				
X Coordinate:	-121.31641				
Y Coordinate:	38.67826				
Barrier Area:	Signalized Intersections				
Barrier Type:	APS Vibrotactile Control				
Code Ref:	PROWAG R306.2				



As Built Meas:	1	Quantity:	JOB		
Description:	No vibrotactile pedestrian buttons provided				
As Built Desc:	No vibrotactile buttons provided				
Solution:	Recommended: Provide vibrotactile ped buttons				
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,700.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Four - way intersection corners A,B,C,D. Corners A A-B,C A-B compliant

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2987D
Location:	Greenback Ln and Bremen Dr - Corner B A-B				
X Coordinate:	-121.31641				
Y Coordinate:	38.67826				
Barrier Area:	Signalized Intersections				
Barrier Type:	APS Vibrotactile Control				
Code Ref:	PROWAG R306.2				



As Built Meas:	1	Quantity:	JOB		
Description:	No vibrotactile pedestrian buttons provided				
As Built Desc:	No vibrotactile buttons provided				
Solution:	Recommended: Provide vibrotactile ped buttons				
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,700.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Four - way intersection corners A,B,C,D. Corners A A-B,C A-B compliant

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2988A
Location:	Greenback Ln and Bremen Dr - Corner C A-B				
X Coordinate:	-121.31637				
Y Coordinate:	38.67795				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH	
Description:	12" grooves at top of curb ramp are not level (4.1% to 4.9%)			
As Built Desc:	4.1% at 12" grooves			
Solution:	Demolish existing and construct new curb ramp			
Bar. Severity:	2 Recommended	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Four - way intersection corners A,B,C,D. Corners A A-B,C A-B compliant

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2988B
Location:	Greenback Ln and Bremen Dr - Corner C A-B				
X Coordinate:	-121.31637				
Y Coordinate:	38.67795				
Barrier Area:	Signalized Intersections				
Barrier Type:	APS Vibrotactile Control				
Code Ref:	PROWAG R306.2				



As Built Meas:	1	Quantity:	JOB	
Description:	No vibrotactile pedestrian buttons provided			
As Built Desc:	No vibrotactile buttons provided			
Solution:	Recommended: Provide vibrotactile ped buttons			
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,700.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Four - way intersection corners A,B,C,D. Corners A A-B,C A-B compliant

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2988C
Location:	Greenback Ln and Bremen Dr - Corner C A-A				
X Coordinate:	-121.31637				
Y Coordinate:	38.67795				
Barrier Area:	Signalized Intersections				
Barrier Type:	APS Vibrotactile Control				
Code Ref:	PROWAG R306.2				



As Built Meas:	1	Quantity:	JOB		
Description:	No vibrotactile pedestrian buttons provided				
As Built Desc:	No vibrotactile buttons provided				
Solution:	Recommended: Provide vibrotactile ped buttons				
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,700.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Four - way intersection corners A,B,C,D. Corners A A-B,C A-B compliant

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2988D
Location:	Greenback Ln and Bremen Dr - Corner C A-A				
X Coordinate:	-121.31637				
Y Coordinate:	38.67795				
Barrier Area:	Signalized Intersections				
Barrier Type:	Ped Button - Existing Landing (3.1% to 4.0%)				
Code Ref:	CBC 1118B.4				



As Built Meas:	1	Quantity:	JOB		
Description:	Landing at pedestrian button not level (3.1% to 4.0%)				
As Built Desc:	3.5% landing slope				
Solution:	Relocated pedestrian button to level area				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$1,200.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Four - way intersection corners A,B,C,D. Corners A A-B,C A-B compliant

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2989A
Location:	Greenback Ln and Bremen Dr - Corner D A-B				
X Coordinate:	-121.31664				
Y Coordinate:	38.67794				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (>5.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (>5.0%)		
As Built Desc:	7.6% at 12" grooves		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes: Four - way intersection corners A,B,C,D. Corners A A-B,C A-B compliant

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2989B
Location:	Greenback Ln and Bremen Dr - Corner D A-B				
X Coordinate:	-121.31664				
Y Coordinate:	38.67794				
Barrier Area:	Curb Ramps				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.2				



As Built Meas:	1	Quantity:	EACH
Description:	Ramp run cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.6% cross slope		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes: Four - way intersection corners A,B,C,D. Corners A A-B,C A-B compliant

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2989C
Location:	Greenback Ln and Bremen Dr - Corner D A-A				
X Coordinate:	-121.31664				
Y Coordinate:	38.67794				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (4.1% to 4.9%)		
As Built Desc:	4.2% at 12" grooves		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	2 Recommended	Cost Estimate:	\$2,500.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes: Four - way intersection corners A,B,C,D. Corners A A-B,C A-B compliant

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2989D
Location:	Greenback Ln and Bremen Dr - Corner D A-A				
X Coordinate:	-121.31664				
Y Coordinate:	38.67794				
Barrier Area:	Curb Ramps				
Barrier Type:	Cross Slope - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.2				



As Built Meas:	1	Quantity:	EACH
Description:	Ramp run cross slope exceeds 2.0% (2.1% to 3.0%)		
As Built Desc:	2.8% cross slope		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	4 Low Severity	Cost Estimate:	\$0.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes: Four - way intersection corners A,B,C,D. Corners A A-B,C A-B compliant

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2989E
Location:	Greenback Ln and Bremen Dr - Corner D A-B				
X Coordinate:	-121.31664				
Y Coordinate:	38.67794				
Barrier Area:	Signalized Intersections				
Barrier Type:	APS Vibrotactile Control				
Code Ref:	PROWAG R306.2				



As Built Meas:	1	Quantity:	JOB		
Description:	No vibrotactile pedestrian buttons provided				
As Built Desc:	No vibrotactile buttons provided				
Solution:	Recommended: Provide vibrotactile ped buttons				
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,700.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Four - way intersection corners A,B,C,D. Corners A A-B,C A-B compliant

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2989F
Location:	Greenback Ln and Bremen Dr - Corner D A-B				
X Coordinate:	-121.31664				
Y Coordinate:	38.67794				
Barrier Area:	Signalized Intersections				
Barrier Type:	Ped Button - Existing Landing (4.1% to 4.9%)				
Code Ref:	CBC 1118B.4				



As Built Meas:	1	Quantity:	JOB		
Description:	Landing at pedestrian button not level (4.1% to 4.9%)				
As Built Desc:	4.2% landing slope				
Solution:	Relocated pedestrian button to level area				
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,200.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Four - way intersection corners A,B,C,D. Corners A A-B,C A-B compliant



Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2989G
Location:	Greenback Ln and Bremen Dr - Corner D A-A				
X Coordinate:	-121.31664				
Y Coordinate:	38.67794				
Barrier Area:	Signalized Intersections				
Barrier Type:	APS Vibrotactile Control				
Code Ref:	PROWAG R306.2				



As Built Meas:	1	Quantity:	JOB		
Description:	No vibrotactile pedestrian buttons provided				
As Built Desc:	No vibrotactile buttons provided				
Solution:	Recommended: Provide vibrotactile ped buttons				
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,700.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Four - way intersection corners A,B,C,D. Corners A A-B,C A-B compliant

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2989H
Location:	Greenback Ln and Bremen Dr - Corner D A-A				
X Coordinate:	-121.31664				
Y Coordinate:	38.67794				
Barrier Area:	Signalized Intersections				
Barrier Type:	Ped Button - Existing Landing(5.0% or more)				
Code Ref:	CBC 1118B.4				



As Built Meas:	1	Quantity:	JOB		
Description:	Landing at pedestrian button not level (5.0% or more)				
As Built Desc:	6.2% landing slope				
Solution:	Relocated pedestrian button to level area				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,200.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Four - way intersection corners A,B,C,D. Corners A A-B,C A-B compliant



Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2990A
Location:	Greenback Ln - North				
X Coordinate:	-121.31688				
Y Coordinate:	38.67828				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Seat Depth				
Code Ref:	ADAAG 4.37.1 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH		
Description:	Bench seat depth not 20" - 24" deep				
As Built Desc:	12-1/2" bench seat depth				
Solution:	Provide min. 1 accessible bench at bench stop				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$775.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2990B
Location:	Greenback Ln - North				
X Coordinate:	-121.31688				
Y Coordinate:	38.67828				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Back Support				
Code Ref:	ADAAG 4.37.4 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH		
Description:	Bench has no back support of at least 18" high				
As Built Desc:	16" back support height				
Solution:	Provide min. 1 accessible bench at bench stop or shelter				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2991
Location:	Greenback Ln - North				
X Coordinate:	-121.31808				
Y Coordinate:	38.67826				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	38	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	9.3% running slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,750.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2992
Location:	Greenback Ln - North				
X Coordinate:	-121.31827				
Y Coordinate:	38.67827				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	43	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	8.5% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$5,375.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date: 12/2/2010 Report Date: 12/2/2010 Barrier #: 2993

Location: Greenback Ln - North

X Coordinate: -121.31868

Y Coordinate: 38.67825

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 60 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 8.5% running slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 4 Low Severity Cost Estimate: \$7,500.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 12/2/2010 Report Date: 12/2/2010 Barrier #: 2994

Location: Greenback Ln - North

X Coordinate: -121.31962

Y Coordinate: 38.6784

Barrier Area: Sidewalks

Barrier Type: Driveway - New Construction

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 52 Quantity: LF

Description: Driveway cross/running slope exceeds 2.0%

As Built Desc: 8.8% running slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 1 Necessary Cost Estimate: \$6,500.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2995
Location:	Greenback Ln - North				
X Coordinate:	-121.32015				
Y Coordinate:	38.67874				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	52	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	4.7% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$6,500.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2996
Location:	Greenback Ln - North				
X Coordinate:	-121.3202				
Y Coordinate:	38.67877				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	103	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.3% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$12,875.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2997
Location:	Auburn Blvd - East				
X Coordinate:	-121.32038				
Y Coordinate:	38.67909				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	80	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.5% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$10,000.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2998A
Location:	Auburn Blvd - East				
X Coordinate:	-121.32014				
Y Coordinate:	38.67923				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Seat Depth				
Code Ref:	ADAAG 4.37.1 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH
Description:	Bench seat depth not 20" - 24" deep		
As Built Desc:	12-1/2" bench seat depth		
Solution:	Provide min. 1 accessible bench at bench stop		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$775.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2998B
Location:	Auburn Blvd - East				
X Coordinate:	-121.32014				
Y Coordinate:	38.67923				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Back Support				
Code Ref:	ADAAG 4.37.4 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH		
Description:	Bench has no back support of at least 18" high				
As Built Desc:	16" back support height				
Solution:	Provide min. 1 accessible bench at bench stop or shelter				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	2999
Location:	Auburn Blvd - East				
X Coordinate:	-121.32004				
Y Coordinate:	38.67929				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	52	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.8% cross slope, 10.0% running slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	1 Necessary	Cost Estimate:	\$6,500.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--



Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3000
Location:	Auburn Blvd - East				
X Coordinate:	-121.31994				
Y Coordinate:	38.67936				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	54	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.2% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$6,750.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3001
Location:	Auburn Blvd - East				
X Coordinate:	-121.31977				
Y Coordinate:	38.67948				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	41	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.1% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$5,125.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--



Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3002
Location:	Auburn Blvd - East				
X Coordinate:	-121.31905				
Y Coordinate:	38.67996				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	37	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.9% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,625.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3003
Location:	Auburn Blvd - East				
X Coordinate:	-121.31895				
Y Coordinate:	38.68004				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	16	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.3% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$2,000.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3004
Location:	Auburn Blvd - East				
X Coordinate:	-121.31887				
Y Coordinate:	38.68008				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	45	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.3% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	2 Recommended	Cost Estimate:	\$5,625.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3005
Location:	Auburn Blvd - East				
X Coordinate:	-121.31875				
Y Coordinate:	38.68016				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	60	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.5% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$7,500.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3006
Location:	Auburn Blvd - East				
X Coordinate:	-121.31856				
Y Coordinate:	38.68026				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	45	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.8% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	2 Recommended	Cost Estimate:	\$5,625.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3007
Location:	Auburn Blvd - East				
X Coordinate:	-121.31843				
Y Coordinate:	38.68035				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	51	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.7% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$6,375.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3008
Location:	Auburn Blvd - East				
X Coordinate:	-121.31824				
Y Coordinate:	38.68049				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	41	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.9% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	2 Recommended	Cost Estimate:	\$5,125.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3009
Location:	Auburn Blvd - East				
X Coordinate:	-121.31812				
Y Coordinate:	38.68058				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	46	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.1% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$5,750.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3010
Location:	Auburn Blvd - East				
X Coordinate:	-121.31786				
Y Coordinate:	38.68076				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	344	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.9% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$43,000.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3011A
Location:	Auburn Blvd - East				
X Coordinate:	-121.31675				
Y Coordinate:	38.68146				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	347	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.5% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$43,375.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3011B
Location:	Auburn Blvd - East				
X Coordinate:	-121.3159				
Y Coordinate:	38.68199				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	4	Quantity:	LF		
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)				
As Built Desc:	Cracked concrete				
Solution:	Repair surface to make firm and stable				
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3012A
Location:	Auburn Blvd - East				
X Coordinate:	-121.31573				
Y Coordinate:	38.68217				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	107	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.7% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$13,375.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--



Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3012B
Location:	Auburn Blvd - East				
X Coordinate:	-121.31572				
Y Coordinate:	38.68217				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	16	Quantity:	LF		
Description:	Change in level greater than 1/2"				
As Built Desc:	1/2" lip due to tree heaves				
Solution:	Grind or repair sidewalk to remove trip hazard				
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,000.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3013A
Location:	Auburn Blvd - East				
X Coordinate:	-121.31516				
Y Coordinate:	38.68249				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	55	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	6.7% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$6,875.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--



Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3013B
Location:	Auburn Blvd - East				
X Coordinate:	-121.31516				
Y Coordinate:	38.68249				
Barrier Area:	Sidewalks				
Barrier Type:	Running Slope (Existing)				
Code Ref:	CBC 1133B.7.3 and ADA/ABA 403.3				



As Built Meas:	4	Quantity:	LF
Description:	Running slope exceeds 5.0%		
As Built Desc:	6.5% running slope		
Solution:	No remediation where sidewalk sloped as roadway		
Bar. Severity:	5 Technically Infeasible	Cost Estimate:	\$0.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3013C
Location:	Auburn Blvd - East				
X Coordinate:	-121.3151				
Y Coordinate:	38.6825				
Barrier Area:	Sidewalks				
Barrier Type:	Running Slope (Existing)				
Code Ref:	CBC 1133B.7.3 and ADA/ABA 403.3				



As Built Meas:	4	Quantity:	LF
Description:	Running slope exceeds 5.0%		
As Built Desc:	9.7% running slope		
Solution:	No remediation where sidewalk sloped as roadway		
Bar. Severity:	5 Technically Infeasible	Cost Estimate:	\$0.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3013D
Location:	Auburn Blvd - East				
X Coordinate:	-121.3151				
Y Coordinate:	38.6825				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	4	Quantity:	LF	
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)			
As Built Desc:	Cracked concrete			
Solution:	Repair surface to make firm and stable			
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3014
Location:	Auburn Blvd - East				
X Coordinate:	-121.31448				
Y Coordinate:	38.68287				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ( $\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	4	Quantity:	LF	
Description:	Pedestrian route is not min. 48" wide ( $\leq 31"$ or less)			
As Built Desc:	28" clear width due to pole			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3015
Location:	Auburn Blvd - East				
X Coordinate:	-121.31409				
Y Coordinate:	38.68315				
Barrier Area:	Sidewalks				
Barrier Type:	Running Slope (Existing)				
Code Ref:	CBC 1133B.7.3 and ADA/ABA 403.3				



As Built Meas:	5	Quantity:	LF		
Description:	Running slope exceeds 5.0%				
As Built Desc:	7.1% running slope				
Solution:	No remediation where sidewalk sloped as roadway				
Bar. Severity:	5 Technically Infeasible	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3016
Location:	Auburn Blvd - East				
X Coordinate:	-121.31358				
Y Coordinate:	38.68346				
Barrier Area:	Sidewalks				
Barrier Type:	Running Slope (Existing)				
Code Ref:	CBC 1133B.7.3 and ADA/ABA 403.3				



As Built Meas:	5	Quantity:	LF		
Description:	Running slope exceeds 5.0%				
As Built Desc:	7.7% running slope				
Solution:	No remediation where sidewalk sloped as roadway				
Bar. Severity:	5 Technically Infeasible	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3017
Location:	Auburn Blvd - East				
X Coordinate:	-121.3131				
Y Coordinate:	38.6837				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	128	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	6.3% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$16,000.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3018
Location:	Auburn Blvd - East				
X Coordinate:	-121.31273				
Y Coordinate:	38.68396				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	47	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	6.6% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$5,875.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3019
Location:	Auburn Blvd - East				
X Coordinate:	-121.31259				
Y Coordinate:	38.68407				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	504	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.5% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$63,000.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3020
Location:	Auburn Blvd - East				
X Coordinate:	-121.31122				
Y Coordinate:	38.68496				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	48	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	8.3% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$6,000.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3021
Location:	Auburn Blvd - East				
X Coordinate:	-121.31108				
Y Coordinate:	38.68506				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	70	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$8,750.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3022A
Location:	Auburn Blvd - East				
X Coordinate:	-121.31092				
Y Coordinate:	38.68523				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Seat Depth				
Code Ref:	ADAAG 4.37.1 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH
Description:	Bench seat depth not 20" - 24" deep		
As Built Desc:	16" bench seat depth		
Solution:	Provide min. 1 accessible bench at bench stop		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$775.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--



Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3022B
Location:	Auburn Blvd - East				
X Coordinate:	-121.31092				
Y Coordinate:	38.68523				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1121B.2.1 and ADAAG 10.2.1(1)				



As Built Meas:	8	Quantity:	LF		
Description:	Cross slope at bus pad or shelter exceeds 2.0% (5.0% or more)				
As Built Desc:	5.4% cross slope				
Solution:	Demolish existing and construct new bus pad or shelter pad				
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3023
Location:	Auburn Blvd - East				
X Coordinate:	-121.31086				
Y Coordinate:	38.68525				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	490	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.9% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$61,250.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--



Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3024
Location:	Van Maren Ln - West				
X Coordinate:	-121.30888				
Y Coordinate:	38.68637				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	770	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.1% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$96,250.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3025A
Location:	Van Maren Ln and Arcade Creek - Corner A				
X Coordinate:	-121.3092				
Y Coordinate:	38.68424				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (>5.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH	
Description:	12" grooves at top of curb ramp are not level (>5.0%)			
As Built Desc:	7.3% at 12" grooves			
Solution:	Demolish existing and construct new curb ramp			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners A,D
--------	------------------------------------

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3025B
Location:	Van Maren Ln and Arcade Creek - Corner A				
X Coordinate:	-121.3092				
Y Coordinate:	38.68424				
Barrier Area:	Curb Ramps				
Barrier Type:	Running Slope - Existing (9.5% or more)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.1				



As Built Meas:	1	Quantity:	EACH		
Description:	Ramp run cross slope exceeds 2.0% (9.5% or more)				
As Built Desc:	11.6% running slope				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,D

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3025C
Location:	Van Maren Ln and Arcade Creek - Corner A				
X Coordinate:	-121.3092				
Y Coordinate:	38.68424				
Barrier Area:	Curb Ramps				
Barrier Type:	Parallel Ramp Landing - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1127B.5.4 and ADA/ABA 406.4				



As Built Meas:	1	Quantity:	EACH		
Description:	Curb ramp landing or pan not level (2.1% to 3.0%)				
As Built Desc:	2.8% landing slope				
Solution:	Demolish existing and construct new transition				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,D

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3025D
Location:	Van Maren Ln and Arcade Creek - Corner A				
X Coordinate:	-121.3092				
Y Coordinate:	38.68424				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,D

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3026A
Location:	Van Maren Ln and Arcade Creek - Corner D				
X Coordinate:	-121.3092				
Y Coordinate:	38.68413				
Barrier Area:	Curb Ramps				
Barrier Type:	Running Slope - Existing (9.5% or more)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.1				



As Built Meas:	1	Quantity:	EACH	
Description:	Ramp run cross slope exceeds 2.0% (9.5% or more)			
As Built Desc:	10.9% running slope			
Solution:	Demolish existing and construct new curb ramp			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,D

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3026B
Location:	Van Maren Ln and Arcade Creek - Corner D				
X Coordinate:	-121.3092				
Y Coordinate:	38.68413				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,D

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3027
Location:	Van Maren Ln - West				
X Coordinate:	-121.30923				
Y Coordinate:	38.68401				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	190	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	4.0% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$23,750.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3028A
Location:	Van Maren Ln - West				
X Coordinate:	-121.3095				
Y Coordinate:	38.68333				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	48	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	7.8% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$6,000.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3028B
Location:	Van Maren Ln - West				
X Coordinate:	-121.30954				
Y Coordinate:	38.68318				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF		
Description:	Change in level greater than 1/2"				
As Built Desc:	1/2" lip in sidewalk surface				
Solution:	Grind or repair sidewalk to remove trip hazard				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3029
Location:	Van Maren Ln - West				
X Coordinate:	-121.30972				
Y Coordinate:	38.68284				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1/2" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3030A
Location:	Van Maren Ln - West				
X Coordinate:	-121.30975				
Y Coordinate:	38.68272				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	16	Quantity:	LF
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)		
As Built Desc:	Cracked concrete		
Solution:	Repair surface to make firm and stable		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,000.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--



Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3030B
Location:	Van Maren Ln - West				
X Coordinate:	-121.30974				
Y Coordinate:	38.68278				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	20	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.7% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3031
Location:	Greenback Lane - North				
X Coordinate:	-121.30981				
Y Coordinate:	38.67828				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	30	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.5% cross slope, 8.8% running slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	1 Necessary	Cost Estimate:	\$3,750.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3032A
Location:	Greenback Ln - North - Corner A				
X Coordinate:	-121.30904				
Y Coordinate:	38.67827				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (>5.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH		
Description:	12" grooves at top of curb ramp are not level (>5.0%)				
As Built Desc:	10.7% at 12" grooves				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3032B
Location:	Greenback Ln - North - Corner A				
X Coordinate:	-121.30904				
Y Coordinate:	38.67827				
Barrier Area:	Curb Ramps				
Barrier Type:	Running Slope - Existing (9.5% or more)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.1				



As Built Meas:	1	Quantity:	EACH		
Description:	Ramp run cross slope exceeds 2.0% (9.5% or more)				
As Built Desc:	13.8% running slope				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3032C
Location:	Greenback Ln - North - Corner A				
X Coordinate:	-121.30904				
Y Coordinate:	38.67827				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,B

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3032D
Location:	Greenback Ln - North - Corner A				
X Coordinate:	-121.30904				
Y Coordinate:	38.67827				
Barrier Area:	Curb Ramps				
Barrier Type:	Transition into Roadway - Existing (8.3% or more)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.2				



As Built Meas:	16	Quantity:	SF	
Description:	Transition from gutter into roadway slope exceeds 5.0% (8.3% or more)			
As Built Desc:	10.1% transition slope			
Solution:	Demolish existing and construct new transition			
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,B

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3033A
Location:	Greenback Ln - North - Corner B				
X Coordinate:	-121.30893				
Y Coordinate:	38.67826				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (>5.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH		
Description:	12" grooves at top of curb ramp are not level (>5.0%)				
As Built Desc:	12.5% at 12" grooves				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3033B
Location:	Greenback Ln - North - Corner B				
X Coordinate:	-121.30893				
Y Coordinate:	38.67826				
Barrier Area:	Curb Ramps				
Barrier Type:	Running Slope - Existing (9.5% or more)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.1				



As Built Meas:	1	Quantity:	EACH		
Description:	Ramp run cross slope exceeds 2.0% (9.5% or more)				
As Built Desc:	12.9% running slope				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3033C
Location:	Greenback Ln - North - Corner B				
X Coordinate:	-121.30893				
Y Coordinate:	38.67826				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3033D
Location:	Greenback Ln - North - Corner B				
X Coordinate:	-121.30893				
Y Coordinate:	38.67826				
Barrier Area:	Curb Ramps				
Barrier Type:	Transition into Roadway - Existing (8.3% or more)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.2				



As Built Meas:	16	Quantity:	SF		
Description:	Transition from gutter into roadway slope exceeds 5.0% (8.3% or more)				
As Built Desc:	6.7% transition slope				
Solution:	Demolish existing and construct new transition				
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3034
Location:	Greenback Ln - North				
X Coordinate:	-121.30838				
Y Coordinate:	38.67828				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	60	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.1% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$7,500.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3035A
Location:	Greenback Lane and Paris St - Corner A				
X Coordinate:	-121.30799				
Y Coordinate:	38.6784				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH		
Description:	12" grooves at top of curb ramp are not level (4.1% to 4.9%)				
As Built Desc:	4.2% at 12" grooves				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	2 Recommended	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	Two - way intersection corners A,B
--------	------------------------------------



Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3035B
Location:	Greenback Lane and Paris St - Corner A				
X Coordinate:	-121.30799				
Y Coordinate:	38.6784				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,B

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3036A
Location:	Greenback Ln and Paris St - Corner B				
X Coordinate:	-121.30788				
Y Coordinate:	38.67842				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH	
Description:	12" grooves at top of curb ramp are not level (4.1% to 4.9%)			
As Built Desc:	4.5% at 12" grooves			
Solution:	Demolish existing and construct new curb ramp			
Bar. Severity:	2 Recommended	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,B

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3036B
Location:	Greenback Ln and Paris St - Corner B				
X Coordinate:	-121.30788				
Y Coordinate:	38.67842				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	Two - way intersection corners A,B
--------	------------------------------------

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3037
Location:	Greenback Ln - North				
X Coordinate:	-121.30778				
Y Coordinate:	38.67838				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	840	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.3% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$105,000.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3038
Location:	Greenback Ln - North				
X Coordinate:	-121.30459				
Y Coordinate:	38.67829				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	30	Quantity:	LF
Description:	Driveway cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.3% cross slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	2 Recommended	Cost Estimate:	\$3,750.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3039
Location:	Greenback Ln - North				
X Coordinate:	-121.30429				
Y Coordinate:	38.67832				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	48	Quantity:	LF
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	7.7% cross slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	4 Low Severity	Cost Estimate:	\$6,000.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3040
Location:	Greenback Ln - North				
X Coordinate:	-121.30405				
Y Coordinate:	38.67834				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	30	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.8% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	2 Recommended	Cost Estimate:	\$3,750.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3041
Location:	Greenback Ln - North				
X Coordinate:	-121.30383				
Y Coordinate:	38.67832				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - New Construction				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	48	Quantity:	LF		
Description:	Driveway cross/running slope exceeds 2.0%				
As Built Desc:	3.4% cross slope, 9.2% running slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	1 Necessary	Cost Estimate:	\$6,000.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3042
Location:	Greenback Ln - North				
X Coordinate:	-121.30319				
Y Coordinate:	38.67833				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	47	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.6% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	2 Recommended	Cost Estimate:	\$5,875.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/2/2010	Report Date:	12/2/2010	Barrier #:	3043
Location:	Greenback Ln - North				
X Coordinate:	-121.30229				
Y Coordinate:	38.67837				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	43	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	8.5% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$5,375.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3043
Location:	Greenback Ln - North				
X Coordinate:	-121.3019				
Y Coordinate:	38.67835				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	42	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (2.1% to 3.0%)				
As Built Desc:	2.7% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	1 Necessary	Cost Estimate:	\$5,250.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3044
Location:	Greenback Ln - North				
X Coordinate:	-121.30106				
Y Coordinate:	38.67836				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	38	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (2.1% to 3.0%)				
As Built Desc:	2.7% cross slope, 8.6% running slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,750.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--



Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3045
Location:	Greenback Ln - North				
X Coordinate:	-121.30086				
Y Coordinate:	38.67835				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	4	Quantity:	LF		
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)				
As Built Desc:	Cracked concrete				
Solution:	Repair surface to make firm and stable				
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3046
Location:	Greenback Ln - North				
X Coordinate:	-121.30049				
Y Coordinate:	38.67836				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	42	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (2.1% to 3.0%)				
As Built Desc:	3.0% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	1 Necessary	Cost Estimate:	\$5,250.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3047
Location:	Greenback Ln - North				
X Coordinate:	-121.30029				
Y Coordinate:	38.67836				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	49	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.2% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	2 Recommended	Cost Estimate:	\$6,125.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3048
Location:	Greenback Ln - North				
X Coordinate:	-121.2997				
Y Coordinate:	38.67834				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	41	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	10.4% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$5,125.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3049
Location:	Greenback Ln - North				
X Coordinate:	-121.29927				
Y Coordinate:	38.67834				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	48	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (2.1% to 3.0%)				
As Built Desc:	3.0% cross slope, 10.0% running slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	1 Necessary	Cost Estimate:	\$6,000.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3050
Location:	Greenback Ln - North				
X Coordinate:	-121.29906				
Y Coordinate:	38.67836				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	123	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.1% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$15,375.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3051
Location:	Greenback Ln - North				
X Coordinate:	-121.29856				
Y Coordinate:	38.67837				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ( $\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	4	Quantity:	LF		
Description:	Pedestrian route is not min. 48" wide ( $\leq 31"$ or less)				
As Built Desc:	26" clear width due to pole				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3052
Location:	Greenback Ln - North				
X Coordinate:	-121.29807				
Y Coordinate:	38.67838				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	117	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.3% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$14,625.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3053
Location:	Greenback Ln - North				
X Coordinate:	-121.29762				
Y Coordinate:	38.67835				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	46	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.9% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$5,750.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3054A
Location:	Greenback Ln - North				
X Coordinate:	-121.29708				
Y Coordinate:	38.67841				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Seat Depth				
Code Ref:	ADAAG 4.37.1 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH		
Description:	Bench seat depth not 20" - 24" deep				
As Built Desc:	9-1/2" bench seat depth				
Solution:	Provide min. 1 accessible bench at bench stop				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$775.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3054B
Location:	Greenback Ln - North				
X Coordinate:	-121.29708				
Y Coordinate:	38.67841				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Back Support				
Code Ref:	ADAAG 4.37.4 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH		
Description:	Bench has no back support of at least 18" high				
As Built Desc:	No back support provided				
Solution:	Provide min. 1 accessible bench at bench stop or shelter				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3055
Location:	Greenback Ln - North				
X Coordinate:	-121.29665				
Y Coordinate:	38.67839				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	52	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.6% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$6,500.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--



Field Date: 12/3/2010 Report Date: 12/3/2010 Barrier #: 3056

Location: Greenback Ln - North

X Coordinate: -121.29594

Y Coordinate: 38.67845

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (8.3% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (8.3% or more)

As Built Desc: 8.5% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary Cost Estimate: \$750.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 12/3/2010 Report Date: 12/3/2010 Barrier #: 3057A

Location: Greenback Ln - North

X Coordinate: -121.29321

Y Coordinate: 38.67843

Barrier Area: Bus Stops and Shelters

Barrier Type: Bench Seat Depth

Code Ref: ADAAG 4.37.1 and ADA/ABA 903.4



As Built Meas: 1 Quantity: EACH

Description: Bench seat depth not 20" - 24" deep

As Built Desc: 12-1/2" bench seat depth

Solution: Provide min. 1 accessible bench at bench stop

Bar. Severity: 3 Hindrance Cost Estimate: \$775.00 Status:

Implementation Priority: 1 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3057B
Location:	Greenback Ln - North				
X Coordinate:	-121.29321				
Y Coordinate:	38.67843				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Seat Height				
Code Ref:	ADAAG 4.37.3* and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH	
Description:	Bench seat height not between 17" - 19"			
As Built Desc:	16" bench seat height			
Solution:	Provide new compliant bench or remount at compliant height where possible			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3057C
Location:	Greenback Ln - North				
X Coordinate:	-121.29321				
Y Coordinate:	38.67843				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1121B.2.1 and ADAAG 10.2.1(1)				



As Built Meas:	8	Quantity:	LF	
Description:	Cross slope at bus pad or shelter exceeds 2.0% (5.0% or more)			
As Built Desc:	12.6% cross slope			
Solution:	Demolish existing and construct new bus pad or shelter pad			
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3058
Location:	Greenback Ln - North				
X Coordinate:	-121.29308				
Y Coordinate:	38.67844				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	39	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	6.8% cross slope, 13.4% running slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,875.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3059
Location:	Greenback Ln - North				
X Coordinate:	-121.29209				
Y Coordinate:	38.67846				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	45	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.6% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$5,625.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3060
Location:	Greenback Ln - North				
X Coordinate:	-121.29192				
Y Coordinate:	38.67847				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	39	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	8.8% cross slope, 9.4% running slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,875.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3061
Location:	Greenback Ln - North				
X Coordinate:	-121.29171				
Y Coordinate:	38.67845				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	28	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	10.2% cross slope, 12.6% running slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	1 Necessary	Cost Estimate:	\$3,500.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3062
Location:	Greenback Ln - North				
X Coordinate:	-121.29162				
Y Coordinate:	38.67845				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	20	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.3% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3063
Location:	Greenback Ln - North				
X Coordinate:	-121.2914				
Y Coordinate:	38.67845				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	34	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.6% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,250.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3064
Location:	Greenback Ln - North				
X Coordinate:	-121.29131				
Y Coordinate:	38.67846				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	40	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (2.1% to 3.0%)				
As Built Desc:	2.8% cross slope, 8.9% running slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	1 Necessary	Cost Estimate:	\$5,000.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3065
Location:	Greenback Ln - North				
X Coordinate:	-121.29084				
Y Coordinate:	38.67845				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	36	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.7% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$4,500.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--



Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3066
Location:	Greenback Ln - North				
X Coordinate:	-121.29054				
Y Coordinate:	38.67842				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	40	Quantity:	LF
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	8.8% cross slope, 10.7% running slope at cracked concrete		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	1 Necessary	Cost Estimate:	\$5,000.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3067A
Location:	Greenback Ln and Sylvan Wy - Corner A				
X Coordinate:	-121.29038				
Y Coordinate:	38.67846				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (3.1% to 4.0%)		
As Built Desc:	3.4% at 12" grooves		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$2,500.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	Two - way intersection corners A,B
--------	------------------------------------

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3067B
Location:	Greenback Ln and Sylvan Wy - Corner A				
X Coordinate:	-121.29038				
Y Coordinate:	38.67846				
Barrier Area:	Curb Ramps				
Barrier Type:	Running Slope - Existing (9.5% or more)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.1				



As Built Meas:	1	Quantity:	EACH	
Description:	Ramp run cross slope exceeds 2.0% (9.5% or more)			
As Built Desc:	12.2% running slope			
Solution:	Demolish existing and construct new curb ramp			
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,B

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3067C
Location:	Greenback Ln and Sylvan Wy - Corner A				
X Coordinate:	-121.29038				
Y Coordinate:	38.67846				
Barrier Area:	Curb Ramps				
Barrier Type:	Parallel Ramp Landing - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1127B.5.4 and ADA/ABA 406.4				



As Built Meas:	1	Quantity:	EACH	
Description:	Curb ramp landing or pan not level(4.1% to 4.9%)			
As Built Desc:	4.4% landing slope			
Solution:	Demolish existing and construct new transition			
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,B

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3067D
Location:	Greenback Ln and Sylvan Wy - Corner A				
X Coordinate:	-121.29038				
Y Coordinate:	38.67846				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3067E
Location:	Greenback Ln and Sylvan Wy - Corner A				
X Coordinate:	-121.29038				
Y Coordinate:	38.67846				
Barrier Area:	Curb Ramps				
Barrier Type:	Gutter Slope - Existing (5.9% - 6.5%)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.2				



As Built Meas:	6	Quantity:	SF		
Description:	Gutter slope exceeds 5.0% (5.9% - 6.5%)				
As Built Desc:	5.9% gutter slope				
Solution:	Demolish existing and construct new gutter				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3067F
Location:	Greenback Ln and Sylvan Wy - Corner A				
X Coordinate:	-121.29038				
Y Coordinate:	38.67846				
Barrier Area:	Curb Ramps				
Barrier Type:	Lip - Gutter to Asphalt Transition				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 303.3				



As Built Meas:	1	Quantity:	EACH		
Description:	Transition at transition into asphalt not flush and free of any lip				
As Built Desc:	1" lip at asphalt transition into roadway				
Solution:	Remove lip to create flush transition				
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3068A
Location:	Greenback Ln and Sylvan Wy - Corner B				
X Coordinate:	-121.29016				
Y Coordinate:	38.67843				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH		
Description:	12" grooves at top of curb ramp are not level (3.1% to 4.0%)				
As Built Desc:	3.9% at 12" grooves				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3068B
Location:	Greenback Ln and Sylvan Wy - Corner B				
X Coordinate:	-121.29016				
Y Coordinate:	38.67843				
Barrier Area:	Curb Ramps				
Barrier Type:	Running Slope - Existing (9.0% to 9.4%)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.1				



As Built Meas:	1	Quantity:	EACH		
Description:	Ramp run cross slope exceeds 2.0% (9.0% to 9.4%)				
As Built Desc:	9.3% running slope				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3068C
Location:	Greenback Ln and Sylvan Wy - Corner B				
X Coordinate:	-121.29016				
Y Coordinate:	38.67843				
Barrier Area:	Curb Ramps				
Barrier Type:	Parallel Ramp Landing - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1127B.5.4 and ADA/ABA 406.4				



As Built Meas:	1	Quantity:	EACH		
Description:	Curb ramp landing or pan not level (2.1% to 3.0%)				
As Built Desc:	2.8% landing slope				
Solution:	Demolish existing and construct new transition				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3068D
Location:	Greenback Ln and Sylvan Wy - Corner B				
X Coordinate:	-121.29016				
Y Coordinate:	38.67843				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3068E
Location:	Greenback Ln and Sylvan Wy - Corner B				
X Coordinate:	-121.29016				
Y Coordinate:	38.67843				
Barrier Area:	Curb Ramps				
Barrier Type:	Lip - Bottom of Ramp at Flow Line				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 303.3				



As Built Meas:	1	Quantity:	EACH		
Description:	Transition at ramp bottom (flow line) is not flush and free of any lip				
As Built Desc:	1" lip at flow line				
Solution:	Remove lip to create flush transition				
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B



Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3068F
Location:	Greenback Ln and Sylvan Wy - Corner B				
X Coordinate:	-121.29016				
Y Coordinate:	38.67843				
Barrier Area:	Curb Ramps				
Barrier Type:	Gutter Slope - Existing (8.3% or more)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.2				



As Built Meas:	6	Quantity:	SF
Description:	Gutter slope exceeds 5.0% (8.3% or more)		
As Built Desc:	9.0% gutter slope		
Solution:	Demolish existing and construct new gutter		
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes: Two - way intersection corners A,B


Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3068G
Location:	Greenback Ln and Sylvan Wy - Corner B				
X Coordinate:	-121.29016				
Y Coordinate:	38.67843				
Barrier Area:	Curb Ramps				
Barrier Type:	Lip - Gutter to Asphalt Transition				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 303.3				



As Built Meas:	1	Quantity:	EACH
Description:	Transition at transition into asphalt not flush and free of any lip		
As Built Desc:	1/2" lip at asphalt transition into roadway		
Solution:	Remove lip to create flush transition		
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes: Two - way intersection corners A,B

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3069
Location:	Mercedes Ave - South				
X Coordinate:	-121.31034				
Y Coordinate:	38.6803				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	353	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.3% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$44,125.00	Status:
Implementation Priority:	3	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3070
Location:	Mercedes Ave and Chapel View Ln - Corner A				
X Coordinate:	-121.30893				
Y Coordinate:	38.68037				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	3	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners A,B
--------	------------------------------------

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3071
Location:	Mercedes Ave and Chapel View Ln - Corner B				
X Coordinate:	-121.3088				
Y Coordinate:	38.6804				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes: Two - way intersection corners A,B

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3072
Location:	Mercedes Ave and Chapel View Ln - Corner C				
X Coordinate:	-121.30879				
Y Coordinate:	38.68028				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes: Two - way intersection corners C,D

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3073A
Location:	Mercedes Ave and Chapel View Ln - Corner D				
X Coordinate:	-121.30893				
Y Coordinate:	38.68028				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH		
Description:	12" grooves at top of curb ramp are not level (3.1% to 4.0%)				
As Built Desc:	3.7% at 12" grooves				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	3	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners C,D

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3073B
Location:	Mercedes Ave and Chapel View Ln - Corner D				
X Coordinate:	-121.30893				
Y Coordinate:	38.68028				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	3	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners C,D

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3074
Location:	Mercedes Ave - South				
X Coordinate:	-121.3086				
Y Coordinate:	38.68031				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	200	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.7% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$25,000.00	Status:
Implementation Priority:	3	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3075
Location:	Mercedes Ave and Paris St - Corner C				
X Coordinate:	-121.30788				
Y Coordinate:	38.68032				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	3	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners C,D
--------	------------------------------------


Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3076
Location:	Mercedes Ave and Paris St - Corner D				
X Coordinate:	-121.30802				
Y Coordinate:	38.68032				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	3	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners C,D
--------	------------------------------------

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3077A
Location:	Paris St - West				
X Coordinate:	-121.30801				
Y Coordinate:	38.68011				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	670	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.1% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$83,750.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--



Field Date: 12/2/2010 Report Date: 12/3/2010 Barrier #: 3077B

Location: Paris St - West

X Coordinate: -121.30803

Y Coordinate: 38.67881

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 60 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete and loose gravel

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$7,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 12/2/2010 Report Date: 12/3/2010 Barrier #: 3078A

Location: Paris St and Greenback Ln Frontage - Corner A

X Coordinate: -121.30797

Y Coordinate: 38.67842

Barrier Area: Curb Ramps

Barrier Type: 12" Grooves - Existing (3.1% to 4.0%)

Code Ref: CBC 1127B.5.6



As Built Meas: 1 Quantity: EACH

Description: 12" grooves at top of curb ramp are not level (3.1% to 4.0%)

As Built Desc: 3.9% at 12" grooves

Solution: Demolish existing and construct new curb ramp

Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3078B
Location:	Paris St and Greenback Ln Frontage - Corner A				
X Coordinate:	-121.30797				
Y Coordinate:	38.67842				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,B

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3079A
Location:	Paris St and Greenback Ln Frontage - Corner B				
X Coordinate:	-121.30785				
Y Coordinate:	38.67842				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH	
Description:	12" grooves at top of curb ramp are not level (4.1% to 4.9%)			
As Built Desc:	4.1% at 12" grooves			
Solution:	Demolish existing and construct new curb ramp			
Bar. Severity:	2 Recommended	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,B


Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3079B
Location:	Paris St and Greenback Ln Frontage - Corner B				
X Coordinate:	-121.30785				
Y Coordinate:	38.67842				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners A,B
--------	------------------------------------

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3080A
Location:	Paris St - East				
X Coordinate:	-121.30785				
Y Coordinate:	38.67852				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	153	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.8% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$19,125.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3080B
Location:	Paris St - East				
X Coordinate:	-121.30785				
Y Coordinate:	38.67862				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF	
Description:	Change in level greater than 1/2"			
As Built Desc:	1" lip in sidewalk surface			
Solution:	Grind or repair sidewalk to remove trip hazard			
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3081
Location:	Paris St and Le Mans Ave - Corner B				
X Coordinate:	-121.30786				
Y Coordinate:	38.679				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners B,C
--------	------------------------------------


Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3082
Location:	Paris St and Le Mans Ave - Corner C				
X Coordinate:	-121.30786				
Y Coordinate:	38.67893				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners B,C
--------	------------------------------------

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3083
Location:	Paris St - East				
X Coordinate:	-121.30786				
Y Coordinate:	38.67937				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	192	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.6% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$24,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3084
Location:	Paris St and Shalimar Wy - Corner B				
X Coordinate:	-121.30786				
Y Coordinate:	38.67976				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners B,C

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3085
Location:	Paris St and Shalimar Wy - Corner C				
X Coordinate:	-121.30788				
Y Coordinate:	38.67963				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners B,C



Field Date: 12/2/2010 Report Date: 12/3/2010 Barrier #: 3086

Location: Paris St - East


X Coordinate: -121.3079

Y Coordinate: 38.68015

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 192 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 6.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$24,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 12/2/2010 Report Date: 12/3/2010 Barrier #: 3087

Location: Mercedes Ave - South


X Coordinate: -121.30777

Y Coordinate: 38.68033

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 1021 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$127,625.00 Status:

Implementation Priority: 3 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3088
Location:	Mercedes Ave and Binet Dr - Corner C				
X Coordinate:	-121.30475				
Y Coordinate:	38.68047				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	3	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners C,D


Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3089
Location:	Mercedes Ave and Binet Dr - Corner D				
X Coordinate:	-121.30483				
Y Coordinate:	38.68046				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	3	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners C,D

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3090
Location:	Binet Dr - West				
X Coordinate:	-121.30473				
Y Coordinate:	38.68021				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	379	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	6.1% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$47,375.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3091
Location:	Binet Dr and Le Mans Ave - Corner A				
X Coordinate:	-121.30442				
Y Coordinate:	38.67924				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners A,D
--------	------------------------------------

Field Date: 12/2/2010 Report Date: 12/3/2010 Barrier #: 3092

Location: Binet Dr and Le Mans Ave - Corner D

X Coordinate: -121.30436

Y Coordinate: 38.67917

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date: 12/2/2010 Report Date: 12/3/2010 Barrier #: 3093

Location: Le Mans Ave and Shalimar Wy - Corner A

X Coordinate: -121.30521

Y Coordinate: 38.67901

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,B


Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3094
Location:	Le Mans Ave and Shalimar Wy - Corner B				
X Coordinate:	-121.30512				
Y Coordinate:	38.67901				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners A,B
--------	------------------------------------


Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3095
Location:	Shalimar Dr - East				
X Coordinate:	-121.30525				
Y Coordinate:	38.67927				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	246	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	7.0% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$30,750.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3096
Location:	Shalimar Dr - North				
X Coordinate:	-121.30578				
Y Coordinate:	38.67971				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	674	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.9% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$84,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3097A
Location:	Shalimar Dr - South				
X Coordinate:	-121.30774				
Y Coordinate:	38.67973				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	611	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.8% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$76,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--




Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3097B
Location:	Shalimar Dr - South				
X Coordinate:	-121.30556				
Y Coordinate:	38.67965				
Barrier Area:	Sidewalks				
Barrier Type:	Running Slope (Existing)				
Code Ref:	CBC 1133B.7.3 and ADA/ABA 403.3				



As Built Meas:	12	Quantity:	LF
Description:	Running slope exceeds 5.0%		
As Built Desc:	13.4% running slope		
Solution:	No remediation where sidewalk sloped as roadway		
Bar. Severity:	5 Technically Infeasible	Cost Estimate:	\$0.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3098A
Location:	Shalimar Dr - West				
X Coordinate:	-121.30551				
Y Coordinate:	38.6796				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	229	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$28,625.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3098B
Location:	Shalimar Dr - West				
X Coordinate:	-121.30538				
Y Coordinate:	38.67932				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ( $\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	2	Quantity:	LF
Description:	Pedestrian route is not min. 48" wide ( $\leq 31"$ or less)		
As Built Desc:	31" clear width due to foliage		
Solution:	Trim foliage		
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3099
Location:	Le Mans Ave - North				
X Coordinate:	-121.30538				
Y Coordinate:	38.67902				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	697	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$87,125.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date: 12/2/2010 Report Date: 12/3/2010 Barrier #: 3100A

Location: Le Mans Ave - South


X Coordinate: -121.3058

Y Coordinate: 38.67895

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 961 Quantity: LF

Description: Cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 5.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 1 Necessary Cost Estimate: \$120,125.00

Status:

Implementation Priority: 4

Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 12/2/2010 Report Date: 12/3/2010 Barrier #: 3100B

Location: Le Mans Ave - South

X Coordinate: -121.30574

Y Coordinate: 38.67894

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00

Status:

Implementation Priority: 4


Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:


Field Date: 12/2/2010 Report Date: 12/3/2010 Barrier #: 3101  
 Location: Binet Dr - West  
 X Coordinate: -121.30424  
 Y Coordinate: 38.67912  
 Barrier Area: Sidewalks  
 Barrier Type: Driveway - Existing (5.0% or more)  
 Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 42 Quantity: LF  
 Description: Driveway cross slope exceeds 2.0% (5.0% or more)  
 As Built Desc: 9.9% cross slope, 9.8% running slope  
 Solution: Provide min. 48" wide level walkway through driveway  
 Bar. Severity: 1 Necessary Cost Estimate: \$5,250.00 Status:  
 Implementation Priority: 4 Facility Function:  
 Implementation Phase: Implementation Date:  
 Official Responsible:

Notes:

Field Date: 12/2/2010 Report Date: 12/3/2010 Barrier #: 3102  
 Location: Binet Dr - West  
 X Coordinate: -121.3041  
 Y Coordinate: 38.67905  
 Barrier Area: Sidewalks  
 Barrier Type: Cross Slope - Existing (3.1% to 4.0%)  
 Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 265 Quantity: LF  
 Description: Cross slope exceeds 2.0% (3.1% to 4.0%)  
 As Built Desc: 4.0% cross slope  
 Solution: Demolish existing and construct new route  
 Bar. Severity: 3 Hinderance Cost Estimate: \$33,125.00 Status:  
 Implementation Priority: 4 Facility Function:  
 Implementation Phase: Implementation Date:  
 Official Responsible:

Notes:

Field Date: 12/2/2010 Report Date: 12/3/2010 Barrier #: 3103

Location: Binet Dr - West


X Coordinate: -121.30368

Y Coordinate: 38.67885

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 42 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 10.5% cross slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 4 Low Severity Cost Estimate: \$5,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 12/2/2010 Report Date: 12/3/2010 Barrier #: 3104

Location: Binet Dr - West


X Coordinate: -121.30358

Y Coordinate: 38.67844

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 153 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.3% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$19,125.00 Status:


Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:


Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3105
Location:	Binet Dr - East				
X Coordinate:	-121.30344				
Y Coordinate:	38.67827				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	42	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	9.5% cross slope, 8.8% running slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	1 Necessary	Cost Estimate:	\$5,250.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3106
Location:	Binet Dr - East				
X Coordinate:	-121.30346				
Y Coordinate:	38.67874				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	117	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.8% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$14,625.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--



Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3107
Location:	Binet Dr and Burnham Dr - Corner B				
X Coordinate:	-121.30354				
Y Coordinate:	38.67892				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners B,C

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3108
Location:	Binet Dr and Burnham Dr - Corner C				
X Coordinate:	-121.30351				
Y Coordinate:	38.67885				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners B,C

Field Date: 12/2/2010 Report Date: 12/3/2010 Barrier #: 3109

Location: Binet Dr - East

X Coordinate: -121.30374

Y Coordinate: 38.67906

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (5.0% or more)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 27 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (5.0% or more)

As Built Desc: 7.0% cross slope

Solution: Provide min. 48" wide level walkway through driveway

Bar. Severity: 4 Low Severity Cost Estimate: \$3,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date: 12/2/2010 Report Date: 12/3/2010 Barrier #: 3110

Location: Binet Dr - East

X Coordinate: -121.30385

Y Coordinate: 38.67914

Barrier Area: Sidewalks

Barrier Type: Driveway - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3

As Built Meas: 27 Quantity: LF

Description: Driveway cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.7% cross slope

Solution: Provide min. 48" wide level walkway through driveway


Bar. Severity: 3 Hinderance Cost Estimate: \$3,375.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:



Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3111
Location:	Binet Dr -East				
X Coordinate:	-121.30424				
Y Coordinate:	38.67923				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	340	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.2% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$42,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3112
Location:	Binet Dr and Le Havre Wy - Corner B				
X Coordinate:	-121.30449				
Y Coordinate:	38.67993				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners B,C
--------	------------------------------------


Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3113
Location:	Binet Dr and Le Havre Wy - Corner C				
X Coordinate:	-121.30445				
Y Coordinate:	38.67982				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners B,C
--------	------------------------------------


Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3114
Location:	Binet Dr - East				
X Coordinate:	-121.30455				
Y Coordinate:	38.68007				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	177	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.9% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$22,125.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3115
Location:	Mercedes Ave - South				
X Coordinate:	-121.30464				
Y Coordinate:	38.6805				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	1077	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.0% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$134,625.00	Status:
Implementation Priority:	3	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3116
Location:	Mercedes Ave - South				
X Coordinate:	-121.30438				
Y Coordinate:	38.68054				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	8	Quantity:	LF	
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)			
As Built Desc:	Cracked concrete			
Solution:	Repair surface to make firm and stable			
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:
Implementation Priority:	3	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3117
Location:	Mercedes Ave and Le Havre Wy - Corner C				
X Coordinate:	-121.30077				
Y Coordinate:	38.68059				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	3	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners C,D

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3118
Location:	Mercedes Ave and Le Havre Wy - Corner D				
X Coordinate:	-121.30088				
Y Coordinate:	38.68059				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				




As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	3	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners C,D




Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3119
Location:	Le Havre Wy - West				
X Coordinate:	-121.30088				
Y Coordinate:	38.68016				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	53	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.8% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$6,625.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3120
Location:	Le Havre Wy - North				
X Coordinate:	-121.30123				
Y Coordinate:	38.68001				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	996	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.4% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$124,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3121A
Location:	Le Havre Wy - South				
X Coordinate:	-121.30428				
Y Coordinate:	38.67983				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	1027	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$128,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--


Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3121B
Location:	Le Havre Wy - South				
X Coordinate:	-121.30142				
Y Coordinate:	38.67988				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--


Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3122
Location:	Le Havre - East				
X Coordinate:	-121.30077				
Y Coordinate:	38.68039				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	216	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.1% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$27,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3123
Location:	Mercedes Ave - South				
X Coordinate:	-121.30068				
Y Coordinate:	38.68061				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	179	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.8% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$22,375.00	Status:
Implementation Priority:	3	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3124
Location:	Mercedes - South				
X Coordinate:	-121.30045				
Y Coordinate:	38.68059				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF		
Description:	Change in level greater than 1/2"				
As Built Desc:	1/2" lip in sidewalk surface				
Solution:	Grind or repair sidewalk to remove trip hazard				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3125
Location:	Mercedes Ave and Burnham Dr - Corner A				
X Coordinate:	-121.3				
Y Coordinate:	38.68069				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	3	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	Two - way intersection corners A,B
--------	------------------------------------


Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3126
Location:	Mercedes Ave and Burnham Dr - Corner B				
X Coordinate:	-121.29999				
Y Coordinate:	38.68059				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	3	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,B


Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3127
Location:	Burnham Dr - North				
X Coordinate:	-121.30162				
Y Coordinate:	38.67928				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	610	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.5% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$76,250.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:


Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3128
Location:	Burnham Dr - South				
X Coordinate:	-121.30339				
Y Coordinate:	38.67888				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	63	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.7% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$7,875.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3129
Location:	Burnham Dr - South				
X Coordinate:	-121.30319				
Y Coordinate:	38.67898				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	38	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	7.6% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,750.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--




Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3130
Location:	Burnham Dr - South				
X Coordinate:	-121.30307				
Y Coordinate:	38.67901				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	8	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	12.2% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--


Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3131
Location:	Burnham Dr - South				
X Coordinate:	-121.30299				
Y Coordinate:	38.67906				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	337	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.8% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$42,125.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--


Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3132
Location:	Burnham Dr - East				
X Coordinate:	-121.30115				
Y Coordinate:	38.6792				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	386	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.8% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$48,250.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3133
Location:	Mercedes Ave - North				
X Coordinate:	-121.30014				
Y Coordinate:	38.68068				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	706	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.5% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$88,250.00	Status:
Implementation Priority:	3	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3134
Location:	Mercedes Ave and Dearborn Dr - Corner A				
X Coordinate:	-121.3031				
Y Coordinate:	38.68072				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	3	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners A,B
--------	------------------------------------

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3135
Location:	Mercedes Ave and Dearborn Dr - Corner B				
X Coordinate:	-121.303				
Y Coordinate:	38.68071				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	3	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners A,B
--------	------------------------------------

Field Date: 12/2/2010 Report Date: 12/3/2010 Barrier #: 3136A

Location: Dearborn Dr - East


X Coordinate: -121.303

Y Coordinate: 38.68077

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 98 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.9% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$12,250.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 12/2/2010 Report Date: 12/3/2010 Barrier #: 3136B

Location: Dearborn Dr - East

X Coordinate: -121.303

Y Coordinate: 38.68077

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1/2" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:


Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3136C
Location:	Dearborn Dr - East				
X Coordinate:	-121.30301				
Y Coordinate:	38.68088				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	2" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--


Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3137
Location:	Mercedes Ave - North				
X Coordinate:	-121.30326				
Y Coordinate:	38.6807				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	1582	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$197,750.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--


Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3138
Location:	Mercedes Ave - North				
X Coordinate:	-121.30805				
Y Coordinate:	38.68043				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ( $\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	2	Quantity:	LF
Description:	Pedestrian route is not min. 48" wide ( $\leq 31"$ or less)		
As Built Desc:	24" clear width due to foliage		
Solution:	Trim foliage		
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/2/2010	Report Date:	12/3/2010	Barrier #:	3139
Location:	Mercedes Ave - North				
X Coordinate:	-121.31022				
Y Coordinate:	38.68039				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	354	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$44,250.00
Implementation Priority:	3	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--



Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3140
Location:	Van Maren Ln - East				
X Coordinate:	-121.31037				
Y Coordinate:	38.67831				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	464	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.0% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$58,000.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3141
Location:	Van Maren Ln - East				
X Coordinate:	-121.3103				
Y Coordinate:	38.67977				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	39	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	7.6% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,875.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3142A
Location:	Van Maren Ln - East				
X Coordinate:	-121.31033				
Y Coordinate:	38.67982				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	59	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.1% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$7,375.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3142B
Location:	Van Maren Ln - East				
X Coordinate:	-121.31036				
Y Coordinate:	38.67986				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF		
Description:	Change in level greater than 1/2"				
As Built Desc:	1" lip in sidewalk surface				
Solution:	Grind or repair sidewalk to remove trip hazard				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3143A
Location:	Van Maren Ln and Mercedes Ave - Corner B				
X Coordinate:	-121.31033				
Y Coordinate:	38.68043				
Barrier Area:	Curb Ramps				
Barrier Type:	Running Slope - Existing (9.5% or more)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.1				



As Built Meas:	1	Quantity:	EACH		
Description:	Ramp run cross slope exceeds 2.0% (9.5% or more)				
As Built Desc:	9.7% running slope				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners B,C

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3143B
Location:	Van Maren Ln and Mercedes Ave - Corner B				
X Coordinate:	-121.31033				
Y Coordinate:	38.68043				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners B,C

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3144A
Location:	Van Maren Ln and Mercedes Ave - Corner C				
X Coordinate:	-121.31032				
Y Coordinate:	38.68024				
Barrier Area:	Curb Ramps				
Barrier Type:	Running Slope - Existing (9.5% or more)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.1				



As Built Meas:	1	Quantity:	EACH	
Description:	Ramp run cross slope exceeds 2.0% (9.5% or more)			
As Built Desc:	9.9% running slope			
Solution:	Demolish existing and construct new curb ramp			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners B,C

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3144B
Location:	Van Maren Ln and Mercedes Ave - Corner C				
X Coordinate:	-121.31032				
Y Coordinate:	38.68024				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners B,C

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3145
Location:	Van Maren Ln - East				
X Coordinate:	-121.30973				
Y Coordinate:	38.68238				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF	
Description:	Change in level greater than 1/2"			
As Built Desc:	1" lip in sidewalk surface			
Solution:	Grind or repair sidewalk to remove trip hazard			
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3146A
Location:	Van Maren Ln and Chapel Ct - Corner B				
X Coordinate:	-121.30959				
Y Coordinate:	38.68273				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners B,C
--------	------------------------------------



Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3146B
Location:	Van Maren Ln and Chapel Ct - Corner B				
X Coordinate:	-121.30959				
Y Coordinate:	38.68273				
Barrier Area:	Curb Ramps				
Barrier Type:	Gutter Slope - Existing (6.6% to 8.2%)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.2				



As Built Meas:	6	Quantity:	SF	
Description:	Gutter slope exceeds 5.0% (6.6% to 8.2%)			
As Built Desc:	6.8% gutter slope			
Solution:	Demolish existing and construct new gutter			
Bar. Severity:	2 Recommended	Cost Estimate:	\$750.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners B,C

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3147A
Location:	Van Maren Ln and Chapel Ct - Corner C				
X Coordinate:	-121.30969				
Y Coordinate:	38.68254				
Barrier Area:	Curb Ramps				
Barrier Type:	Parallel Ramp Landing - Existing (>5.0% or more)				
Code Ref:	CBC 1127B.5.4 and ADA/ABA 406.4				



As Built Meas:	1	Quantity:	EACH	
Description:	Curb ramp landing or pan not level (>5.0% or more)			
As Built Desc:	6.8% landing slope			
Solution:	Demolish existing and construct new transition			
Bar. Severity:	1 Necessary	Cost Estimate:	\$250.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners B,C



Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3147B
Location:	Van Maren Ln and Chapel Ct - Corner C				
X Coordinate:	-121.30969				
Y Coordinate:	38.68254				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners B,C

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3147C
Location:	Van Maren Ln and Chapel Ct - Corner C				
X Coordinate:	-121.30969				
Y Coordinate:	38.68254				
Barrier Area:	Curb Ramps				
Barrier Type:	Gutter Slope - Existing (6.6% to 8.2%)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.2				



As Built Meas:	6	Quantity:	SF	
Description:	Gutter slope exceeds 5.0% (6.6% to 8.2%)			
As Built Desc:	6.9% gutter slope			
Solution:	Demolish existing and construct new gutter			
Bar. Severity:	2 Recommended	Cost Estimate:	\$750.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners B,C

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3148
Location:	Van Maren Ln - East				
X Coordinate:	-121.3095				
Y Coordinate:	38.68293				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3149
Location:	Van Maren Ln - East				
X Coordinate:	-121.30933				
Y Coordinate:	38.68323				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	35	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.4% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,375.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3150
Location:	Van Maren Ln - East				
X Coordinate:	-121.30915				
Y Coordinate:	38.68363				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	164	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.3% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$20,500.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:				
--------	--	--	--	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3151A
Location:	Van Maren Ln and Christ the King Retreat Center Entrance - Corner B				
X Coordinate:	-121.3089				
Y Coordinate:	38.68424				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH	
Description:	12" grooves at top of curb ramp are not level (3.1% to 4.0%)			
As Built Desc:	3.6% at 12" grooves			
Solution:	Demolish existing and construct new curb ramp			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners B,C			
--------	------------------------------------	--	--	--

Field Date: 12/3/2010 Report Date: 12/3/2010 Barrier #: 3151B  
 Location: Van Maren Ln and Christ the King Retreat Center Entrance - Corner B  
 X Coordinate: -121.3089  
 Y Coordinate: 38.68424  
 Barrier Area: Curb Ramps  
 Barrier Type: Running Slope - Existing (9.5% or more)  
 Code Ref: CBC 1127B.5.3 and ADA/ABA 406.1



As Built Meas: 1 Quantity: EACH  
 Description: Ramp run cross slope exceeds 2.0% (9.5% or more)  
 As Built Desc: 10.6% running slope  
 Solution: Demolish existing and construct new curb ramp  
 Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:   
 Implementation Priority: 1 Facility Function:   
 Implementation Phase: Implementation Date:   
 Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: 12/3/2010 Report Date: 12/3/2010 Barrier #: 3151C  
 Location: Van Maren Ln and Christ the King Retreat Center Entrance - Corner B  
 X Coordinate: -121.3089  
 Y Coordinate: 38.68424  
 Barrier Area: Curb Ramps  
 Barrier Type: Detectable Warnings - Truncated Domes  
 Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH  
 Description: No truncated domes provided at curb ramp  
 As Built Desc: No detectable warnings at curb ramp  
 Solution: Provide compliant truncated domes  
 Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:   
 Implementation Priority: 1 Facility Function:   
 Implementation Phase: Implementation Date:   
 Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: 12/3/2010 Report Date: 12/3/2010 Barrier #: 3152A  
 Location: Van Maren Ln and Christ the King Retreat Center Entrance - Corner C  
 X Coordinate: -121.30896  
 Y Coordinate: 38.68409  
 Barrier Area: Curb Ramps  
 Barrier Type: Cross Slope - Existing (3.1% to 4.0%)  
 Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 1 Quantity: EACH  
 Description: Ramp run cross slope exceeds 2.0% (3.1% to 4.0%)  
 As Built Desc: 3.5% cross slope  
 Solution: Demolish existing and construct new curb ramp  
 Bar. Severity: 3 Hindrance Cost Estimate: \$2,500.00 Status:  
 Implementation Priority: 1 Facility Function:  
 Implementation Phase: Implementation Date:  
 Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: 12/3/2010 Report Date: 12/3/2010 Barrier #: 3152B  
 Location: Van Maren Ln and Christ the King Retreat Center Entrance - Corner C  
 X Coordinate: -121.30896  
 Y Coordinate: 38.68409  
 Barrier Area: Curb Ramps  
 Barrier Type: Running Slope - Existing (9.5% or more)  
 Code Ref: CBC 1127B.5.3 and ADA/ABA 406.1



As Built Meas: 1 Quantity: EACH  
 Description: Ramp run cross slope exceeds 2.0% (9.5% or more)  
 As Built Desc: 12.6% running slope  
 Solution: Demolish existing and construct new curb ramp  
 Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:  
 Implementation Priority: 1 Facility Function:  
 Implementation Phase: Implementation Date:  
 Official Responsible:

Notes: Two - way intersection corners B,C



Field Date: 12/3/2010 Report Date: 12/3/2010 Barrier #: 3152C  
 Location: Van Maren Ln and Christ the King Retreat Center Entrance - Corner C  
 X Coordinate: -121.30896  
 Y Coordinate: 38.68409  
 Barrier Area: Curb Ramps  
 Barrier Type: Detectable Warnings - Truncated Domes  
 Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH  
 Description: No truncated domes provided at curb ramp  
 As Built Desc: No detectable warnings at curb ramp  
 Solution: Provide compliant truncated domes  
 Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:   
 Implementation Priority: 1 Facility Function:   
 Implementation Phase: Implementation Date:   
 Official Responsible:

Notes: Two - way intersection corners B,C

Field Date: 12/3/2010 Report Date: 12/3/2010 Barrier #: 3153  
 Location: Van Maren Ln - East  
 X Coordinate: -121.30892  
 Y Coordinate: 38.68425  
 Barrier Area: Sidewalks  
 Barrier Type: Cross Slope - Existing (5.0% or more)  
 Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 563 Quantity: LF  
 Description: Cross slope exceeds 2.0% (5.0% or more)  
 As Built Desc: 5.4% cross slope  
 Solution: Demolish existing and construct new route  
 Bar. Severity: 1 Necessary Cost Estimate: \$70,375.00 Status:   
 Implementation Priority: 1 Facility Function:   
 Implementation Phase: Implementation Date:   
 Official Responsible:

Notes:



Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3154
Location:	Van Maren Ln - East				
X Coordinate:	-121.30875				
Y Coordinate:	38.68595				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	76	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.4% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$9,500.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3155
Location:	Van Maren Ln - East				
X Coordinate:	-121.30859				
Y Coordinate:	38.68643				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	41	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	7.8% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$5,125.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3156A
Location:	Auburn Blvd - South				
X Coordinate:	-121.30818				
Y Coordinate:	38.6872				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Back Support				
Code Ref:	ADAAG 4.37.4 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH		
Description:	Bench has no back support of at least 18" high				
As Built Desc:	16" back support height				
Solution:	Provide min. 1 accessible bench at bench stop or shelter				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$1,400.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3156B
Location:	Auburn Blvd - South				
X Coordinate:	-121.30818				
Y Coordinate:	38.6872				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Seat Depth				
Code Ref:	ADAAG 4.37.1 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH		
Description:	Bench seat depth not 20" - 24" deep				
As Built Desc:	12-1/2" bench seat depth				
Solution:	Provide min. 1 accessible bench at bench stop				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3157A
Location:	Auburn Blvd - South				
X Coordinate:	-121.30724				
Y Coordinate:	38.68789				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	351	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	6.0% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$43,875.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3157B
Location:	Auburn Blvd - South				
X Coordinate:	-121.30686				
Y Coordinate:	38.68817				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF		
Description:	Change in level greater than 1/2"				
As Built Desc:	1" lip in sidewalk surface				
Solution:	Grind or repair sidewalk to remove trip hazard				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3158A
Location:	Auburn Blvd - South				
X Coordinate:	-121.30629				
Y Coordinate:	38.6886				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Seat Depth				
Code Ref:	ADAAG 4.37.1 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH
Description:	Bench seat depth not 20" - 24" deep		
As Built Desc:	12-1/2" bench seat depth		
Solution:	Provide min. 1 accessible bench at bench stop		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$775.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3158B
Location:	Auburn Blvd - South				
X Coordinate:	-121.30629				
Y Coordinate:	38.6886				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Back Support				
Code Ref:	ADAAG 4.37.4 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH
Description:	Back support does not extend from 2" above seat to min. 18" above seat		
As Built Desc:	16" back support height		
Solution:	Provide min. 1 accessible bench at bench stop or shelter		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3158C
Location:	Auburn Blvd - South				
X Coordinate:	-121.30629				
Y Coordinate:	38.6886				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1121B.2.1 and ADAAG 10.2.1(1)				



As Built Meas:	10	Quantity:	LF		
Description:	Cross slope at bus pad or shelter exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.8% cross slope				
Solution:	Demolish existing and construct new bus pad or shelter pad				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$1,250.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3159
Location:	Auburn Blvd - South				
X Coordinate:	-121.30625				
Y Coordinate:	38.68861				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	211	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.0% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$26,375.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3160A
Location:	Auburn Blvd and Crossroads Pkwy - Corner D				
X Coordinate:	-121.30562				
Y Coordinate:	38.68899				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH	
Description:	12" grooves at top of curb ramp are not level (3.1% to 4.0%)			
As Built Desc:	3.8% at 12" grooves			
Solution:	Demolish existing and construct new curb ramp			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners C,D. Corner C compliant

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3160B
Location:	Auburn Blvd and Crossroads Pkwy - Corner D				
X Coordinate:	-121.30562				
Y Coordinate:	38.68899				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners C,D. Corner C compliant



Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3161
Location:	Crosswoods Pkwy - West				
X Coordinate:	-121.30554				
Y Coordinate:	38.68889				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	28	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	7.8% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$3,500.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3162
Location:	Crosswoods Pkwy - West				
X Coordinate:	-121.30531				
Y Coordinate:	38.68864				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	50	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.9% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$6,250.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3163
Location:	Crosswoods Pkwy and Crosswoods Cir - Corner A				
X Coordinate:	-121.30515				
Y Coordinate:	38.68833				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3164
Location:	Crosswoods Pkwy and Crosswoods Cir - Corner B				
X Coordinate:	-121.30486				
Y Coordinate:	38.68849				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3165
Location:	Crosswoods Cir - North				
X Coordinate:	-121.30516				
Y Coordinate:	38.68829				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	91	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.9% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$11,375.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3166
Location:	Crosswoods Cir - North				
X Coordinate:	-121.30543				
Y Coordinate:	38.68811				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	25	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	7.7% cross slope, 11.0% running slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	1 Necessary	Cost Estimate:	\$3,125.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3167
Location:	Crosswoods Cir - North				
X Coordinate:	-121.30552				
Y Coordinate:	38.68797				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	28	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	8.6% cross slope, 9.9% running slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	1 Necessary	Cost Estimate:	\$3,500.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3168
Location:	Crosswoods Cir - North				
X Coordinate:	-121.30557				
Y Coordinate:	38.68791				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	25	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.6% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$3,125.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3169
Location:	Crosswoods Cir - West				
X Coordinate:	-121.30552				
Y Coordinate:	38.687				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	47	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.6% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$5,875.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3170
Location:	Crosswoods Cir - North				
X Coordinate:	-121.30517				
Y Coordinate:	38.68665				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	350	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.5% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$43,750.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3171
Location:	Crosswoods Cir and Castillo Ct - Corner A				
X Coordinate:	-121.30471				
Y Coordinate:	38.68538				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,D

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3172
Location:	Crosswoods Cir and Castillo Ct - Corner D				
X Coordinate:	-121.30469				
Y Coordinate:	38.6853				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,D



Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3173
Location:	Crosswoods Cir and Crosswoods Ct - Corner A				
X Coordinate:	-121.30481				
Y Coordinate:	38.68481				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,D

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3174
Location:	Crosswoods Cir and Crosswoods Ct - Corner D				
X Coordinate:	-121.30482				
Y Coordinate:	38.68475				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,D

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3175
Location:	Crosswoods Cir and Crosswoods Ct - Corner A				
X Coordinate:	-121.30482				
Y Coordinate:	38.68463				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners A,D
--------	------------------------------------

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3176
Location:	Crosswoods Cir and Crosswoods Ct - Corner D				
X Coordinate:	-121.30478				
Y Coordinate:	38.68454				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners A,D
--------	------------------------------------

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3177
Location:	Crosswoods Cir - West				
X Coordinate:	-121.30477				
Y Coordinate:	38.68448				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	21	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.8% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$2,625.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3178
Location:	Crosswoods Cir and San Dimas Ct - Corner A				
X Coordinate:	-121.30472				
Y Coordinate:	38.68444				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	Two - way intersection corners A,D
--------	------------------------------------

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3179
Location:	Crosswoods Cir and San Dimas Ct - Corner D				
X Coordinate:	-121.30465				
Y Coordinate:	38.68436				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH		
Description:	No curb cut at corner (intersection)				
As Built Desc:	No curb ramp at corner				
Solution:	Demolish existing and construct curb cut				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	Two - way intersection corners A,D
--------	------------------------------------

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3180
Location:	Crosswoods Cir - West				
X Coordinate:	-121.30461				
Y Coordinate:	38.68431				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	91	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.7% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$11,375.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date: 12/3/2010 Report Date: 12/3/2010 Barrier #: 3181

Location: Crosswoods Cir and Madrea Ct - Corner C

X Coordinate: -121.30386

Y Coordinate: 38.68409

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D

Field Date: 12/3/2010 Report Date: 12/3/2010 Barrier #: 3182

Location: Crosswoods Cir and Madrea Ct - Corner D


X Coordinate: -121.30405

Y Coordinate: 38.68408

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3183
Location:	Crosswoods Cir - West				
X Coordinate:	-121.30379				
Y Coordinate:	38.68411				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	300	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.4% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$37,500.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3184
Location:	Crosswoods Cir and Monteverde Ln - Corner C				
X Coordinate:	-121.30269				
Y Coordinate:	38.68381				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners C,D
--------	------------------------------------



Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3185
Location:	Crosswoods Cir and Monteverde Ln - Corner D				
X Coordinate:	-121.30279				
Y Coordinate:	38.68383				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No curb cut at corner (intersection)		
As Built Desc:	No curb ramp at corner		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes: Two - way intersection corners C,D

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3186
Location:	Crosswoods Cir - West				
X Coordinate:	-121.30276				
Y Coordinate:	38.68382				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	24	Quantity:	LF
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)		
As Built Desc:	Crosswalk concrete in very poor condition		
Solution:	Repair surface to make firm and stable		
Bar. Severity:	1 Necessary	Cost Estimate:	\$3,000.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3187
Location:	Crosswoods Cir - West				
X Coordinate:	-121.3026				
Y Coordinate:	38.68377				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	370	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.5% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$46,250.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3188
Location:	Crosswoods Cir - East				
X Coordinate:	-121.30208				
Y Coordinate:	38.6827				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	370	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.5% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$46,250.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date: 12/3/2010 Report Date: 12/3/2010 Barrier #: 3189

Location: Crosswoods Cir and Monteverde Ln - Corner A

X Coordinate: -121.30172

Y Coordinate: 38.68188

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 11.4% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date: 12/3/2010 Report Date: 12/3/2010 Barrier #: 3190

Location: Crosswoods Cir and Monteverde Ln - Corner D

X Coordinate: -121.30169

Y Coordinate: 38.68177

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp - Depressed Existing Curb

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No compliant curb cut at corner (intersection)

As Built Desc: 11.1% running slope at depressed area

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners A,D

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3191
Location:	Crosswoods Cir - East				
X Coordinate:	-121.30159				
Y Coordinate:	38.68195				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	211	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.9% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$26,375.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3192
Location:	Crosswoods Cir and Crosswoods Cir - Corner B				
X Coordinate:	-121.30189				
Y Coordinate:	38.68268				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No compliant curb cut at corner (intersection)			
As Built Desc:	7.7% running slope at depressed area			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners B,C
--------	------------------------------------

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3193
Location:	Crosswoods Cir and Crosswoods Cir - Corner C				
X Coordinate:	-121.30188				
Y Coordinate:	38.68263				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	12.0% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	Two - way intersection corners B,C
--------	------------------------------------

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3194
Location:	Crosswoods Cir - East				
X Coordinate:	-121.30186				
Y Coordinate:	38.68285				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	220	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.6% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$27,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3195
Location:	Crosswoods Cir and Crosswoods Ct - Corner B				
X Coordinate:	-121.30199				
Y Coordinate:	38.68333				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No compliant curb cut at corner (intersection)			
As Built Desc:	6.2% running slope at depressed area			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners B,C

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3196
Location:	Crosswoods Cir and Crosswoods Ct - Corner C				
X Coordinate:	-121.30193				
Y Coordinate:	38.68325				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No compliant curb cut at corner (intersection)			
As Built Desc:	7.7% running slope at depressed area			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners B,C



Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3197
Location:	Crosswoods Cir - East				
X Coordinate:	-121.30199				
Y Coordinate:	38.6835				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	132	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	6.9% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$16,500.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3198
Location:	Crosswoods Cir - East				
X Coordinate:	-121.30264				
Y Coordinate:	38.68401				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	156	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.8% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$19,500.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3199
Location:	Crosswoods Cir and Amado Ct - Corner A				
X Coordinate:	-121.30328				
Y Coordinate:	38.6842				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,B

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3200
Location:	Crosswoods Cir and Amado Ct - Corner B				
X Coordinate:	-121.30316				
Y Coordinate:	38.68417				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,B

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3201
Location:	Crosswoods Cir - East				
X Coordinate:	-121.30319				
Y Coordinate:	38.68417				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	10	Quantity:	LF	
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)			
As Built Desc:	Cracked concrete			
Solution:	Repair surface to make firm and stable			
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,250.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:				
--------	--	--	--	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3202
Location:	Crosswoods Cir - East				
X Coordinate:	-121.30332				
Y Coordinate:	38.68419				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	426	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.6% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$53,250.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:				
--------	--	--	--	--

Field Date: 12/3/2010 Report Date: 12/3/2010 Barrier #: 3203

Location: Crosswoods Cir - East

X Coordinate: -121.30467

Y Coordinate: 38.68482

Barrier Area: Sidewalks

Barrier Type: Abrupt Change in Level - > 1/2"

Code Ref: CBC 1133B.7.1 and ADA/ABA 303.3



As Built Meas: 4 Quantity: LF

Description: Change in level greater than 1/2"

As Built Desc: 1" lip in sidewalk surface

Solution: Grind or repair sidewalk to remove trip hazard

Bar. Severity: 1 Necessary Cost Estimate: \$1,000.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 12/3/2010 Report Date: 12/3/2010 Barrier #: 3204

Location: Crosswoods Cir and San Angelo Ct - Corner B

X Coordinate: -121.30467

Y Coordinate: 38.68501

Barrier Area: Curb Ramps

Barrier Type: No Curb Ramp

Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH

Description: No curb cut at corner (intersection)

As Built Desc: No curb ramp at corner

Solution: Demolish existing and construct curb cut

Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners B,C

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3205
Location:	Crosswoods Cir and San Angelo Ct - Corner C				
X Coordinate:	-121.30464				
Y Coordinate:	38.68493				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners B,C
--------	------------------------------------

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3206
Location:	Crosswoods Cir - East				
X Coordinate:	-121.30451				
Y Coordinate:	38.68586				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	293	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	6.0% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$36,625.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3207
Location:	Crosswoods Cir and Monticello Ct - Corner B				
X Coordinate:	-121.30451				
Y Coordinate:	38.68592				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners B,C

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3208
Location:	Crosswoods Cir and Monticello Ct - Corner C				
X Coordinate:	-121.30451				
Y Coordinate:	38.68586				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No curb cut at corner (intersection)			
As Built Desc:	No curb ramp at corner			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners B,C



Field Date: 12/3/2010 Report Date: 12/3/2010 Barrier #: 3209

Location: Crosswoods Cir - East

X Coordinate: -121.3045

Y Coordinate: 38.68584

Barrier Area: Sidewalks

Barrier Type: Surface Condition - Damaged

Code Ref: CBC 1133B.7.1 and ADA/ABA 302.1



As Built Meas: 4 Quantity: LF

Description: Surface is not firm and stable (cracked, broken or loose soil, etc.)

As Built Desc: Cracked concrete

Solution: Repair surface to make firm and stable

Bar. Severity: 1 Necessary Cost Estimate: \$500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date: 12/3/2010 Report Date: 12/3/2010 Barrier #: 3210A

Location: Crosswoods Cir - East

X Coordinate: -121.30452

Y Coordinate: 38.68598

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 364 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.4% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$45,500.00 Status:

Implementation Priority: 2 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3210B
Location:	Crosswoods Cir - East				
X Coordinate:	-121.30485				
Y Coordinate:	38.68646				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3211
Location:	Crosswoods Cir - East				
X Coordinate:	-121.30549				
Y Coordinate:	38.68757				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	20	Quantity:	LF
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)		
As Built Desc:	Cracked concrete		
Solution:	Repair surface to make firm and stable		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--


Field Date:	12/3/2010	Report Date:	12/3/2010	Barrier #:	3212
Location:	Crosswoods Cir - East				
X Coordinate:	-121.30538				
Y Coordinate:	38.68787				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	115	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.6% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$14,375.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:				
--------	--	--	--	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3213A
Location:	Crosswoods Cir - South				
X Coordinate:	-121.30506				
Y Coordinate:	38.68817				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	152	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.4% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$19,000.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:				
--------	--	--	--	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3213B
Location:	Crosswoods Cir - South				
X Coordinate:	-121.3046				
Y Coordinate:	38.68846				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF
Description:	Change in level greater than 1/2"		
As Built Desc:	1/2" lip in sidewalk surface		
Solution:	Grind or repair sidewalk to remove trip hazard		
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3214
Location:	Crosswoods Cir - South				
X Coordinate:	-121.30414				
Y Coordinate:	38.68858				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	486	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.3% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$60,750.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--


Field Date: 12/6/2010 Report Date: 12/6/2010 Barrier #: 3215  
Location: Crosswoods Cir - South  
X Coordinate: -121.30275  
Y Coordinate: 38.6886  
Barrier Area: Sidewalks  
Barrier Type: Driveway - Existing (5.0% or more)  
Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 31 Quantity: LF  
Description: Driveway cross slope exceeds 2.0% (5.0% or more)  
As Built Desc: 8.2% cross slope  
Solution: Provide min. 48" wide level walkway through driveway  
Bar. Severity: 4 Low Severity Cost Estimate: \$3,875.00 Status:  
Implementation Priority: 2 Facility Function:  
Implementation Phase: Implementation Date:  
Official Responsible:

Notes:


Field Date: 12/6/2010 Report Date: 12/6/2010 Barrier #: 3216  
Location: Crosswoods Cir - South  
X Coordinate: -121.30268  
Y Coordinate: 38.68855  
Barrier Area: Sidewalks  
Barrier Type: Cross Slope - Existing (4.1% to 4.9%)  
Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 440 Quantity: LF  
Description: Cross slope exceeds 2.0% (4.1% to 4.9%)  
As Built Desc: 4.1% cross slope  
Solution: Demolish existing and construct new route  
Bar. Severity: 2 Recommended Cost Estimate: \$55,000.00 Status:  
Implementation Priority: 2 Facility Function:  
Implementation Phase: Implementation Date:  
Official Responsible:

Notes:


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3217
Location:	Crosswoods Cir - West				
X Coordinate:	-121.30131				
Y Coordinate:	38.68797				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	38	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	8.1% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,750.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3218
Location:	Crosswoods Cir - West				
X Coordinate:	-121.30126				
Y Coordinate:	38.68787				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				




As Built Meas:	178	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.1% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$22,250.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--




Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3219
Location:	Crosswoods Cir - East				
X Coordinate:	-121.30086				
Y Coordinate:	38.68676				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	35	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.3% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,375.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3220
Location:	Crosswoods Cir - East				
X Coordinate:	-121.30088				
Y Coordinate:	38.68734				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	38	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.7% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$4,750.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3221
Location:	Crosswoods Cir - East				
X Coordinate:	-121.30095				
Y Coordinate:	38.68771				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	114	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.1% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$14,250.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3222
Location:	Crosswoods Cir - East				
X Coordinate:	-121.30101				
Y Coordinate:	38.68781				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	39	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	7.0% cross slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,875.00	Status:	
Implementation Priority:	2	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3223
Location:	Crosswoods Cir and San Tomas Dr - Corner A				
X Coordinate:	-121.30208				
Y Coordinate:	38.68864				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	8.6% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes: Two - way intersection corners A,B

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3224
Location:	Crosswoods Cir and San Tomas Dr - Corner B				
X Coordinate:	-121.30199				
Y Coordinate:	38.68858				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	10.2% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	2	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes: Two - way intersection corners A,B


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3225
Location:	San Tomas Dr - East				
X Coordinate:	-121.30199				
Y Coordinate:	38.68866				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	264	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	4.0% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$33,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3226
Location:	San Tomas Dr - East				
X Coordinate:	-121.30149				
Y Coordinate:	38.68928				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	38	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.1% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,750.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3227
Location:	San Tomas Dr - East				
X Coordinate:	-121.3014				
Y Coordinate:	38.68937				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	172	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.9% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$21,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3228
Location:	San Tomas Dr - East				
X Coordinate:	-121.30112				
Y Coordinate:	38.68979				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	39	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	7.1% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,875.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3229
Location:	San Tomas Dr - East				
X Coordinate:	-121.30114				
Y Coordinate:	38.68985				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	338	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.7% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$42,250.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3230
Location:	San Tomas Dr - West				
X Coordinate:	-121.30145				
Y Coordinate:	38.69037				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				




As Built Meas:	201	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.1% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$25,125.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--



Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3231
Location:	San Tomas Dr - West				
X Coordinate:	-121.3013				
Y Coordinate:	38.69007				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	40	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	6.7% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$5,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3232A
Location:	San Tomas Dr - West				
X Coordinate:	-121.30198				
Y Coordinate:	38.6889				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	457	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.2% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$57,125.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3232B
Location:	San Tomas Dr - West				
X Coordinate:	-121.302				
Y Coordinate:	38.68888				
Barrier Area:	Sidewalks				
Barrier Type:	Running Slope (Existing)				
Code Ref:	CBC 1133B.7.3 and ADA/ABA 403.3				



As Built Meas:	20	Quantity:	LF	
Description:	Running slope exceeds 5.0%			
As Built Desc:	7.6% running slope			
Solution:	No remediation where sidewalk sloped as roadway			
Bar. Severity:	5 Technically Infeasible	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3233
Location:	San Tomas Dr - West				
X Coordinate:	-121.30209				
Y Coordinate:	38.68882				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	42	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	7.0% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$5,250.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3234
Location:	Crosswoods Cir - North				
X Coordinate:	-121.30238				
Y Coordinate:	38.68862				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	463	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.8% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$57,875.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3235
Location:	Crosswoods Cir - North				
X Coordinate:	-121.30403				
Y Coordinate:	38.68877				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	40	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	8.2% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$5,000.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3236
Location:	Crosswoods Cir - North				
X Coordinate:	-121.30415				
Y Coordinate:	38.68873				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	203	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.9% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$25,375.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3237
Location:	Crosswoods Pkwy - North				
X Coordinate:	-121.30493				
Y Coordinate:	38.68857				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	227	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.6% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$28,375.00	Status:
Implementation Priority:	2	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3238
Location:	Auburn Blvd - East				
X Coordinate:	-121.3048				
Y Coordinate:	38.68951				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	702	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.5% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$87,750.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3239A
Location:	Auburn Blvd - East				
X Coordinate:	-121.30312				
Y Coordinate:	38.69018				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Seat Depth				
Code Ref:	ADAAG 4.37.1 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH		
Description:	Bench seat depth not 20" - 24" deep				
As Built Desc:	12-1/2" bench seat depth				
Solution:	Provide min. 1 accessible bench at bench stop				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$775.00	Status:	
Implementation Priority:	1	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3239B
Location:	Auburn Blvd - East				
X Coordinate:	-121.30312				
Y Coordinate:	38.69018				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Back Support				
Code Ref:	ADAAG 4.37.4 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH	
Description:	Bench has no back support of at least 18" high			
As Built Desc:	16-1/2" back support height			
Solution:	Provide min. 1 accessible bench at bench stop or shelter			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3240
Location:	Auburn Blvd - East				
X Coordinate:	-121.30276				
Y Coordinate:	38.69032				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				




As Built Meas:	434	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.8% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$54,250.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--



Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3241
Location:	Auburn Blvd - East				
X Coordinate:	-121.30125				
Y Coordinate:	38.6908				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	48	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.4% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$6,000.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3242
Location:	Auburn Blvd - East				
X Coordinate:	-121.29898				
Y Coordinate:	38.69151				
Barrier Area:	Sidewalks				
Barrier Type:	Running Slope (Existing)				
Code Ref:	CBC 1133B.7.3 and ADA/ABA 403.3				



As Built Meas:	16	Quantity:	LF	
Description:	Running slope exceeds 5.0%			
As Built Desc:	7.0% running slope			
Solution:	No remediation where sidewalk sloped as roadway			
Bar. Severity:	5 Technically Infeasible	Cost Estimate:	\$0.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3243A
Location:	Auburn Blvd - East				
X Coordinate:	-121.29792				
Y Coordinate:	38.69191				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Cross Slope - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1121B.2.1 and ADAAG 10.2.1(1)				



As Built Meas:	8	Quantity:	LF	
Description:	Cross slope at bus pad or shelter exceeds 2.0% (2.1% to 3.0%)			
As Built Desc:	2.4% cross slope			
Solution:	Demolish existing and construct new bus pad or shelter pad			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$1,000.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3243B
Location:	Auburn Blvd - East				
X Coordinate:	-121.29792				
Y Coordinate:	38.69191				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Seat Height				
Code Ref:	ADAAG 4.37.3* and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH	
Description:	Bench seat height not between 17" - 19"			
As Built Desc:	12-1/2" bench seat height			
Solution:	Provide new compliant bench or remount at compliant height where possible			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$775.00	Status:
Implementation Priority:	1	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3243C
Location:	Auburn Blvd - East				
X Coordinate:	-121.29792				
Y Coordinate:	38.69191				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Back Support				
Code Ref:	ADAAG 4.37.4 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH
Description:	Bench has no back support of at least 18" high		
As Built Desc:	No back support provided		
Solution:	Provide min. 1 accessible bench at bench stop or shelter		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3244
Location:	Auburn Blvd - East				
X Coordinate:	-121.29497				
Y Coordinate:	38.69291				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	282	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$35,250.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3245
Location:	Chivalry Wy - West				
X Coordinate:	-121.29392				
Y Coordinate:	38.69307				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ( $\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	2	Quantity:	LF		
Description:	Pedestrian route is not min. 48" wide ( $\leq 31"$ or less)				
As Built Desc:	24" clear width due to foliage				
Solution:	Trim foliage				
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3246
Location:	Chivalry Wy - West				
X Coordinate:	-121.29389				
Y Coordinate:	38.69302				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	397	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.8% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$49,625.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3247
Location:	Chivalry Wy and Chivalry Wy - Corner A				
X Coordinate:	-121.29406				
Y Coordinate:	38.69212				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No compliant curb cut at corner (intersection)			
As Built Desc:	11.8% running slope at depressed area			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners A,B
--------	------------------------------------


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3248
Location:	Chivalry Wy and Chivalry Wy - Corner B				
X Coordinate:	-121.29395				
Y Coordinate:	38.69202				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No compliant curb cut at corner (intersection)			
As Built Desc:	11.7% running slope at depressed area			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners A,B
--------	------------------------------------

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3249
Location:	Chivalry Wy - North				
X Coordinate:	-121.29422				
Y Coordinate:	38.69202				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	175	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	3 Hinderance	Cost Estimate:	\$21,875.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3250
Location:	Chivalry Wy - South				
X Coordinate:	-121.29452				
Y Coordinate:	38.69189				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				




As Built Meas:	172	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.8% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	3 Hinderance	Cost Estimate:	\$21,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--



Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3251
Location:	Gallant Cir - South				
X Coordinate:	-121.29395				
Y Coordinate:	38.69185				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	672	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.7% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$84,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3252
Location:	Gallant Cir - East				
X Coordinate:	-121.29155				
Y Coordinate:	38.69183				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	251	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	6.6% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$31,375.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3253
Location:	Gallant Cir and Sutro Ct - Corner A				
X Coordinate:	-121.29264				
Y Coordinate:	38.69273				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	14.1% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes: Two - way intersection corners A,B


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3254
Location:	Gallant Cir and Sutro Ct - Corner B				
X Coordinate:	-121.29283				
Y Coordinate:	38.69272				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH
Description:	No compliant curb cut at corner (intersection)		
As Built Desc:	13.9% running slope at depressed area		
Solution:	Demolish existing and construct curb cut		
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes: Two - way intersection corners A,B

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3255
Location:	Sutro Ct - East				
X Coordinate:	-121.29269				
Y Coordinate:	38.69279				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	213	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.8% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$26,625.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3256
Location:	Sutro Ct - West				
X Coordinate:	-121.29298				
Y Coordinate:	38.69323				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	216	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.7% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$27,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3257
Location:	Gallant Cir - North				
X Coordinate:	-121.29292				
Y Coordinate:	38.69271				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	225	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	6.3% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$28,125.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3258
Location:	Gallant Cir and Chivalry Wy - Corner B				
X Coordinate:	-121.29373				
Y Coordinate:	38.69274				
Barrier Area:	Curb Ramps				
Barrier Type:	No Curb Ramp - Depressed Existing Curb				
Code Ref:	CBC 1127B.5.1 and ADA/ABA 402.2				



As Built Meas:	1	Quantity:	EACH	
Description:	No compliant curb cut at corner (intersection)			
As Built Desc:	16.3% running slope at depressed area			
Solution:	Demolish existing and construct curb cut			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners B,C
--------	------------------------------------

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3259A
Location:	Gallant Cir and Chivalry Wy - Corner C				
X Coordinate:	-121.29382				
Y Coordinate:	38.6926				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH	
Description:	12" grooves at top of curb ramp are not level (3.1% to 4.0%)			
As Built Desc:	3.8% at 12" grooves			
Solution:	Demolish existing and construct new curb ramp			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners B,C

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3259B
Location:	Gallant Cir and Chivalry Wy - Corner C				
X Coordinate:	-121.29382				
Y Coordinate:	38.6926				
Barrier Area:	Curb Ramps				
Barrier Type:	Parallel Ramp Landing - New Construction				
Code Ref:	CBC 1127B.5.4 and ADA/ABA 406.4				



As Built Meas:	1	Quantity:	EACH	
Description:	Curb ramp top landing not min. 48" deep			
As Built Desc:	4.6% landing slope			
Solution:	Demolish existing and construct new transition			
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners B,C

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3259C
Location:	Gallant Cir and Chivalry Wy - Corner C				
X Coordinate:	-121.29382				
Y Coordinate:	38.6926				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH
Description:	No truncated domes provided at curb ramp		
As Built Desc:	No detectable warnings at curb ramp		
Solution:	Provide compliant truncated domes		
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes: Two - way intersection corners B,C

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3259D
Location:	Gallant Cir and Chivalry Wy - Corner C				
X Coordinate:	-121.29382				
Y Coordinate:	38.6926				
Barrier Area:	Curb Ramps				
Barrier Type:	Gutter Slope - Existing (8.3% or more)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.2				




As Built Meas:	6	Quantity:	SF
Description:	Gutter slope exceeds 5.0% (8.3% or more)		
As Built Desc:	9.7% gutter slope		
Solution:	Demolish existing and construct new gutter		
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes: Two - way intersection corners B,C



Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3260
Location:	Gallant Cir - South				
X Coordinate:	-121.29362				
Y Coordinate:	38.6926				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	553	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.6% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$69,125.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3261
Location:	Gallant Cir - West				
X Coordinate:	-121.29166				
Y Coordinate:	38.69244				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	186	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.9% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$23,250.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3262
Location:	Gallant Cir - West				
X Coordinate:	-121.29167				
Y Coordinate:	38.69201				
Barrier Area:	Sidewalks				
Barrier Type:	Elbow in Sidewalk - Cross Slope (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	6	Quantity:	LF		
Description:	Cross slope at elbow exceeds 2.0% (5.0% or more)				
As Built Desc:	14.2% cross slope				
Solution:	Demolish existing and construct new sidewalk without curb ramp				
Bar. Severity:	1 Necessary	Cost Estimate:	\$750.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3263
Location:	Gallant Cir - North				
X Coordinate:	-121.2917				
Y Coordinate:	38.69195				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	628	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	5.2% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$78,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3264
Location:	Chivalry Wy - East				
X Coordinate:	-121.29389				
Y Coordinate:	38.6921				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	195	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.8% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$24,375.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3265
Location:	Chivalry Wy - East				
X Coordinate:	-121.29392				
Y Coordinate:	38.69225				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	160	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.5% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$20,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3266
Location:	Auburn Blvd - South				
X Coordinate:	-121.29125				
Y Coordinate:	38.69415				
Barrier Area:	Sidewalks				
Barrier Type:	Running Slope (Existing)				
Code Ref:	CBC 1133B.7.3 and ADA/ABA 403.3				



As Built Meas:	8	Quantity:	LF
Description:	Running slope exceeds 5.0%		
As Built Desc:	7.0% running slope		
Solution:	No remediation where sidewalk sloped as roadway		
Bar. Severity:	5 Technically Infeasible	Cost Estimate:	\$0.00
Implementation Priority:	1	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3267
Location:	Sylvan Rd - West				
X Coordinate:	-121.29047				
Y Coordinate:	38.69303				
Barrier Area:	Sidewalks				
Barrier Type:	Running Slope (Existing)				
Code Ref:	CBC 1133B.7.3 and ADA/ABA 403.3				



As Built Meas:	16	Quantity:	LF
Description:	Running slope exceeds 5.0%		
As Built Desc:	8.9% running slope		
Solution:	No remediation where sidewalk sloped as roadway		
Bar. Severity:	5 Technically Infeasible	Cost Estimate:	\$0.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3268
Location:	Sylvan Rd - West				
X Coordinate:	-121.29042				
Y Coordinate:	38.69215				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	62	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (2.1% to 3.0%)			
As Built Desc:	2.9% cross slope			
Solution:	Low severity barrier - no remediation recommended			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3269
Location:	Sylvan Rd - West				
X Coordinate:	-121.29042				
Y Coordinate:	38.69191				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	50	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.2% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$6,250.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3270
Location:	Sylvan Rd - West				
X Coordinate:	-121.2904				
Y Coordinate:	38.69138				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	28	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (2.1% to 3.0%)			
As Built Desc:	2.6% cross slope, 14.8% running slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	1 Necessary	Cost Estimate:	\$3,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3271
Location:	Sylvan Rd - West				
X Coordinate:	-121.29042				
Y Coordinate:	38.69101				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				




As Built Meas:	106	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.8% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$13,250.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--




Field Date: 12/6/2010 Report Date: 12/6/2010 Barrier #: 3272  
Location: Sylvan Rd - West  
X Coordinate: -121.29045  
Y Coordinate: 38.69068  
Barrier Area: Sidewalks  
Barrier Type: Driveway - Existing (5.0% or more)  
Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 58 Quantity: LF  
Description: Driveway cross slope exceeds 2.0% (5.0% or more)  
As Built Desc: 5.8% cross slope  
Solution: Provide min. 48" wide level walkway through driveway  
Bar. Severity: 4 Low Severity Cost Estimate: \$7,250.00 Status:  
Implementation Priority: 4 Facility Function:  
Implementation Phase: Implementation Date:  
Official Responsible:

Notes:


Field Date: 12/6/2010 Report Date: 12/6/2010 Barrier #: 3273  
Location: Sylvan Rd - West  
X Coordinate: -121.29046  
Y Coordinate: 38.69047  
Barrier Area: Sidewalks  
Barrier Type: Cross Slope - Existing (5.0% or more)  
Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 391 Quantity: LF  
Description: Cross slope exceeds 2.0% (5.0% or more)  
As Built Desc: 5.3% cross slope  
Solution: Demolish existing and construct new route  
Bar. Severity: 1 Necessary Cost Estimate: \$48,875.00 Status:  
Implementation Priority: 4 Facility Function:  
Implementation Phase: Implementation Date:  
Official Responsible:

Notes:


Field Date: 12/6/2010 Report Date: 12/6/2010 Barrier #: 3274  
 Location: Sylvan Rd - West  
 X Coordinate: -121.29048  
 Y Coordinate: 38.68913  
 Barrier Area: Sidewalks  
 Barrier Type: Driveway - Existing (3.1% to 4.0%)  
 Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 64 Quantity: LF  
 Description: Driveway cross slope exceeds 2.0% (3.1% to 4.0%)  
 As Built Desc: 4.0% cross slope  
 Solution: Provide min. 48" wide level walkway through driveway  
 Bar. Severity: 2 Recommended Cost Estimate: \$8,000.00 Status:  
 Implementation Priority: 4 Facility Function:  
 Implementation Phase: Implementation Date:  
 Official Responsible:

Notes:

Field Date: 12/6/2010 Report Date: 12/6/2010 Barrier #: 3275  
 Location: Sylvan Rd - West  
 X Coordinate: -121.29049  
 Y Coordinate: 38.68784  
 Barrier Area: Sidewalks  
 Barrier Type: Cross Slope - Existing (4.1% to 4.9%)  
 Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 244 Quantity: LF  
 Description: Cross slope exceeds 2.0% (4.1% to 4.9%)  
 As Built Desc: 4.1% cross slope  
 Solution: Demolish existing and construct new route  
 Bar. Severity: 2 Recommended Cost Estimate: \$30,500.00 Status:  
 Implementation Priority: 4 Facility Function:  
 Implementation Phase: Implementation Date:  
 Official Responsible:

Notes:


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3276
Location:	Sylvan Rd and Oaks Apartment Entrance - Corner A				
X Coordinate:	-121.29054				
Y Coordinate:	38.68717				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,D


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3277
Location:	Sylvan Rd and Oaks Apartment Entrance - Corner D				
X Coordinate:	-121.29057				
Y Coordinate:	38.68703				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,D

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3278
Location:	Sylvan Rd - West				
X Coordinate:	-121.29048				
Y Coordinate:	38.6866				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	378	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.8% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$47,250.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3279A
Location:	Sylvan Rd and Woodside Dr - Corner A				
X Coordinate:	-121.29049				
Y Coordinate:	38.68566				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (>5.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH		
Description:	12" grooves at top of curb ramp are not level (>5.0%)				
As Built Desc:	9.1% at 12" grooves				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	Two - way intersection corners A,D
--------	------------------------------------

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3279B
Location:	Sylvan Rd and Woodside Dr - Corner A				
X Coordinate:	-121.29049				
Y Coordinate:	38.68566				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,D

Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3280A
Location:	Sylvan Rd and Woodside Dr - Corner D				
X Coordinate:	-121.29052				
Y Coordinate:	38.68545				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (>5.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH		
Description:	12" grooves at top of curb ramp are not level (>5.0%)				
As Built Desc:	8.1% at 12" grooves				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,D


Field Date:	12/6/2010	Report Date:	12/6/2010	Barrier #:	3280B
Location:	Sylvan Rd and Woodside Dr - Corner D				
X Coordinate:	-121.29052				
Y Coordinate:	38.68545				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	Two - way intersection corners A,D
--------	------------------------------------

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3281
Location:	Woodside Dr - North				
X Coordinate:	-121.29096				
Y Coordinate:	38.68567				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				




As Built Meas:	38	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (2.1% to 3.0%)				
As Built Desc:	3.0% cross slope, 11.4% running slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,750.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--



Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3282
Location:	Woodside Dr - North				
X Coordinate:	-121.29109				
Y Coordinate:	38.68566				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	110	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.8% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$13,750.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3283
Location:	Woodside Dr - North				
X Coordinate:	-121.29142				
Y Coordinate:	38.68563				
Barrier Area:	Sidewalks				
Barrier Type:	No Sidewalk - Transition to Shoulder				
Code Ref:	CBC 1121B.2 and ADA/ABA 206.2.1				



As Built Meas:	1	Quantity:	JOB	
Description:	Sidewalk ends and no ramp to pedestrian shoulder is provided			
As Built Desc:	No ramp to shoulder to enable pedestrian travel onto existing shoulder			
Solution:	Provide transition ramp to paved shoulder where no opposite sidewalk exists			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3284
Location:	Woodside Dr - North				
X Coordinate:	-121.29149				
Y Coordinate:	38.6856				
Barrier Area:	Sidewalks				
Barrier Type:	Shoulder Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	220	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.3% cross slope			
Solution:	Demolish existing and construct new pedestrian route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$27,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3285
Location:	Woodside Dr - North				
X Coordinate:	-121.2923				
Y Coordinate:	38.68558				
Barrier Area:	Sidewalks				
Barrier Type:	No Sidewalk - Transition to Shoulder				
Code Ref:	CBC 1121B.2 and ADA/ABA 206.2.1				



As Built Meas:	1	Quantity:	JOB	
Description:	Sidewalk ends and no ramp to pedestrian shoulder is provided			
As Built Desc:	No ramp to shoulder to enable pedestrian travel onto existing shoulder			
Solution:	Provide transition ramp to paved shoulder where no opposite sidewalk exists			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3286
Location:	Woodside Dr - North				
X Coordinate:	-121.2945				
Y Coordinate:	38.68555				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ( $\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	4	Quantity:	LF	
Description:	Pedestrian route is not min. 48" wide ( $\leq 31"$ or less)			
As Built Desc:	24" clear width due to foliage			
Solution:	Trim foliage			
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3287
Location:	Thalia Wy - South				
X Coordinate:	-121.29547				
Y Coordinate:	38.68657				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	105	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (2.1% to 3.0%)			
As Built Desc:	3.0% cross slope			
Solution:	Low severity barrier - no remediation recommended			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3288
Location:	Thalia Wy - South				
X Coordinate:	-121.29492				
Y Coordinate:	38.68655				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	144	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.2% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$18,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3289
Location:	Hespera Wy - West				
X Coordinate:	-121.29513				
Y Coordinate:	38.68719				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	190	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.6% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$23,750.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3290
Location:	Hera Ct - South				
X Coordinate:	-121.29394				
Y Coordinate:	38.68443				
Barrier Area:	Sidewalks				
Barrier Type:	No Sidewalk - Cane Detectable Barricade				
Code Ref:	CBC 1133B.8.6 and MUTCD Section 6D.02				



As Built Meas:	40	Quantity:	LF		
Description:	No cane detectable warning on existing barricade				
As Built Desc:	Existing barricade lacks warning for the visually impaired				
Solution:	Provide cane detectable warning on barricade (max. 6" above ground)				
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3291A
Location:	Woodside Dr - South				
X Coordinate:	-121.29426				
Y Coordinate:	38.68546				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	163	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.5% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$20,375.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3291B
Location:	Woodside Dr - South				
X Coordinate:	-121.2939				
Y Coordinate:	38.68546				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ( $\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	4	Quantity:	LF		
Description:	Pedestrian route is not min. 48" wide ( $\leq 31"$ or less)				
As Built Desc:	28" clear width due to pole				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3292
Location:	Woodside Dr - South				
X Coordinate:	-121.29338				
Y Coordinate:	38.68546				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ( $\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	4	Quantity:	LF		
Description:	Pedestrian route is not min. 48" wide ( $\leq 31"$ or less)				
As Built Desc:	28" clear width due to pole				
Solution:	Demolish existing and construct new route				
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00	Status:	
Implementation Priority:	44	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--



Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3293
Location:	Woodside Dr - South				
X Coordinate:	-121.29277				
Y Coordinate:	38.68549				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ( $\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	4	Quantity:	LF	
Description:	Pedestrian route is not min. 48" wide ( $\leq 31"$ or less)			
As Built Desc:	30" clear width due to pole			
Solution:	Demolish existing and construct new route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3294
Location:	Woodside Dr - South				
X Coordinate:	-121.29246				
Y Coordinate:	38.68551				
Barrier Area:	Sidewalks				
Barrier Type:	No Sidewalk - Transition to Shoulder				
Code Ref:	CBC 1121B.2 and ADA/ABA 206.2.1				



As Built Meas:	1	Quantity:	JOB	
Description:	Sidewalk ends and no ramp to pedestrian shoulder is provided			
As Built Desc:	No ramp to shoulder to enable pedestrian travel onto existing shoulder			
Solution:	Provide transition ramp to paved shoulder where no opposite sidewalk exists			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3295
Location:	Woodside Dr - South				
X Coordinate:	-121.29173				
Y Coordinate:	38.68548				
Barrier Area:	Sidewalks				
Barrier Type:	Shoulder Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	126	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.6% cross slope			
Solution:	Demolish existing and construct new pedestrian route			
Bar. Severity:	1 Necessary	Cost Estimate:	\$15,750.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3296
Location:	Woodside Dr - South				
X Coordinate:	-121.29096				
Y Coordinate:	38.68541				
Barrier Area:	Sidewalks				
Barrier Type:	Shoulder Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	216	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.1% cross slope			
Solution:	Demolish existing and construct new pedestrian route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$27,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3297
Location:	Woodside Dr - South				
X Coordinate:	-121.29049				
Y Coordinate:	38.68532				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	38	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.2% cross slope, 10.4% running slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,750.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3298
Location:	Sylvan Rd - West				
X Coordinate:	-121.29044				
Y Coordinate:	38.68479				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	156	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.8% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$19,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--


Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3299A
Location:	Sylvan Rd - West				
X Coordinate:	-121.29045				
Y Coordinate:	38.68466				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Seat Depth				
Code Ref:	ADAAG 4.37.1 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH	
Description:	Bench seat depth not 20" - 24" deep			
As Built Desc:	12-1/2" bench seat depth			
Solution:	Provide min. 1 accessible bench at bench stop			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$775.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3299B
Location:	Sylvan Rd - West				
X Coordinate:	-121.29045				
Y Coordinate:	38.68466				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Back Support				
Code Ref:	ADAAG 4.37.4 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH	
Description:	Bench has no back support of at least 18" high			
As Built Desc:	16-1/2" back support height			
Solution:	Provide min. 1 accessible bench at bench stop or shelter			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3300
Location:	Sylvan Rd - West				
X Coordinate:	-121.29044				
Y Coordinate:	38.68427				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	121	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.8% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$15,125.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3301
Location:	Sylvan Rd - West				
X Coordinate:	-121.29046				
Y Coordinate:	38.68419				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	134	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	5.0% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$16,750.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3302
Location:	Stock Ranch Rd - North				
X Coordinate:	-121.29081				
Y Coordinate:	38.68202				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	52	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.8% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	2 Recommended	Cost Estimate:	\$6,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3303A
Location:	Stock Ranch Rd and Emeritus Entrance - Corner A				
X Coordinate:	-121.29322				
Y Coordinate:	38.68197				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH	
Description:	12" grooves at top of curb ramp are not level (3.1% to 4.0%)			
As Built Desc:	3.8% at 12" grooves			
Solution:	Demolish existing and construct new curb ramp			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners A,B
--------	------------------------------------



Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3303B
Location:	Stock Ranch Rd and Emeritus Entrance - Corner A				
X Coordinate:	-121.29322				
Y Coordinate:	38.68197				
Barrier Area:	Curb Ramps				
Barrier Type:	Running Slope - Existing (8.6% to 8.9%)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.1				



As Built Meas:	1	Quantity:	EACH		
Description:	Ramp run cross slope exceeds 2.0% (8.6% to 8.9%)				
As Built Desc:	8.9% running slope				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3303C
Location:	Stock Ranch Rd and Emeritus Entrance - Corner A				
X Coordinate:	-121.29322				
Y Coordinate:	38.68197				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners A,B

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3303D
Location:	Stock Ranch Rd and Emeritus Entrance - Corner A				
X Coordinate:	-121.29322				
Y Coordinate:	38.68197				
Barrier Area:	Curb Ramps				
Barrier Type:	Lip - Bottom of Ramp at Flow Line				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 303.3				



As Built Meas:	1	Quantity:	EACH	
Description:	Transition at ramp bottom (flow line) is not flush and free of any lip			
As Built Desc:	1" lip at flow line			
Solution:	Remove lip to create flush transition			
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,B

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3304A
Location:	Stock Ranch Rd and Emeritus Entrance - Corner B				
X Coordinate:	-121.29303				
Y Coordinate:	38.68193				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH	
Description:	12" grooves at top of curb ramp are not level (4.1% to 4.9%)			
As Built Desc:	4.5% at 12" grooves			
Solution:	Demolish existing and construct new curb ramp			
Bar. Severity:	2 Recommended	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,B

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3304B
Location:	Stock Ranch Rd and Emeritus Entrance - Corner B				
X Coordinate:	-121.29303				
Y Coordinate:	38.68193				
Barrier Area:	Curb Ramps				
Barrier Type:	Running Slope - Existing (9.5% or more)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.1				



As Built Meas:	1	Quantity:	EACH
Description:	Ramp run cross slope exceeds 2.0% (9.5% or more)		
As Built Desc:	12.0% running slope		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes: Two - way intersection corners A,B

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3304C
Location:	Stock Ranch Rd and Emeritus Entrance - Corner B				
X Coordinate:	-121.29303				
Y Coordinate:	38.68193				
Barrier Area:	Curb Ramps				
Barrier Type:	Parallel Ramp Landing - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1127B.5.4 and ADA/ABA 406.4				



As Built Meas:	1	Quantity:	EACH
Description:	Curb ramp landing or pan not level(4.1% to 4.9%)		
As Built Desc:	4.8% landing slope		
Solution:	Demolish existing and construct new transition		
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes: Two - way intersection corners A,B

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3304D
Location:	Stock Ranch Rd and Emeritus Entrance - Corner B				
X Coordinate:	-121.29303				
Y Coordinate:	38.68193				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,B

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3304E
Location:	Stock Ranch Rd and Emeritus Entrance - Corner B				
X Coordinate:	-121.29303				
Y Coordinate:	38.68193				
Barrier Area:	Curb Ramps				
Barrier Type:	Lip - Bottom of Ramp at Flow Line				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 303.3				



As Built Meas:	1	Quantity:	EACH	
Description:	Transition at ramp bottom (flow line) is not flush and free of any lip			
As Built Desc:	1/2" lip at flow line			
Solution:	Remove lip to create flush transition			
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,B


Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3305
Location:	Stock Ranch Rd - North				
X Coordinate:	-121.29499				
Y Coordinate:	38.68279				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	312	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (2.1% to 3.0%)				
As Built Desc:	2.4% cross slope				
Solution:	Low severity barrier - no remediation recommended				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3306
Location:	Stock Ranch Rd and Aspen Gardens Wy - Corner A				
X Coordinate:	-121.29779				
Y Coordinate:	38.68637				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	Three - way intersection corners A,C,D
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3307A
Location:	Stock Ranch Rd and Aspen Gardens Wy - Corner C				
X Coordinate:	-121.29752				
Y Coordinate:	38.68632				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - New Construction				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH	
Description:	No 12" grooves at top of curb ramp			
As Built Desc:	No 12" grooves provided at top of ramp			
Solution:	Demolish existing and construct new curb ramp			
Bar. Severity:	1 Necessary	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Three - way intersection corners A,C,D

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3307B
Location:	Stock Ranch Rd and Aspen Gardens Wy - Corner C				
X Coordinate:	-121.29752				
Y Coordinate:	38.68632				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Three - way intersection corners A,C,D



Field Date: 12/7/2010 Report Date: 12/7/2010 Barrier #: 3308

Location: Stock Ranch Rd and Aspen Gardens Wy - Corner D

X Coordinate: -121.29771

Y Coordinate: 38.68623

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection corners A,C,D

Field Date: 12/7/2010 Report Date: 12/7/2010 Barrier #: 3309

Location: Aspen Gardens Wy - North

X Coordinate: -121.29787

Y Coordinate: 38.68633

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (3.1% to 4.0%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 94 Quantity: LF

Description: Cross slope exceeds 2.0% (3.1% to 4.0%)

As Built Desc: 3.8% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 3 Hinderance Cost Estimate: \$11,750.00 Status:


Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:


Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3310
Location:	Aspen Gardens Wy and Ryan Taylor Wy - Corner B				
X Coordinate:	-121.29824				
Y Coordinate:	38.68623				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH
Description:	No truncated domes provided at curb ramp		
As Built Desc:	No detectable warnings at curb ramp		
Solution:	Provide compliant truncated domes		
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes: Three - way intersection corners B,C,D

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3311A
Location:	Aspen Gardens Wy and Ryan Taylor Wy - Corner C				
X Coordinate:	-121.29808				
Y Coordinate:	38.68614				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH
Description:	12" grooves at top of curb ramp are not level (3.1% to 4.0%)		
As Built Desc:	3.2% at 12" grooves		
Solution:	Demolish existing and construct new curb ramp		
Bar. Severity:	3 Hindrance	Cost Estimate:	\$2,500.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes: Three - way intersection corners B,C,D


Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3311B
Location:	Aspen Gardens Wy and Ryan Taylor Wy - Corner C				
X Coordinate:	-121.29808				
Y Coordinate:	38.68614				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Three - way intersection corners B,C,D


Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3312A
Location:	Aspen Gardens Wy and Ryan Taylor Wy - Corner D				
X Coordinate:	-121.29822				
Y Coordinate:	38.68612				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Three - way intersection corners B,C,D

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3312B
Location:	Aspen Gardens Wy and Ryan Taylor Wy - Corner D				
X Coordinate:	-121.29822				
Y Coordinate:	38.68612				
Barrier Area:	Curb Ramps				
Barrier Type:	Lip - Gutter to Asphalt Transition				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 303.3				



As Built Meas:	1	Quantity:	EACH		
Description:	Transition at transition into asphalt not flush and free of any lip				
As Built Desc:	1/2" lip at asphalt transition into roadway				
Solution:	Remove lip to create flush transition				
Bar. Severity:	1 Necessary	Cost Estimate:	\$250.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Three - way intersection corners B,C,D

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3313A
Location:	Aspen Gardens Wy - North				
X Coordinate:	-121.29826				
Y Coordinate:	38.68623				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	62	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.8% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$7,750.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3313B
Location:	Aspen Gardens Wy - North				
X Coordinate:	-121.29839				
Y Coordinate:	38.68619				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ( $\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	2	Quantity:	LF	
Description:	Pedestrian route is not min. 48" wide ( $\leq 31"$ or less)			
As Built Desc:	30" clear width due to foliage			
Solution:	Trim foliage			
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3314
Location:	Aspen Gardens Wy and Aspen Glen Ct - Corner A				
X Coordinate:	-121.29871				
Y Coordinate:	38.6861				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Three - way intersection corners A,B,C
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3315
Location:	Aspen Gardens Wy and Aspen Glen Ct - Corner B				
X Coordinate:	-121.29859				
Y Coordinate:	38.68614				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Three - way intersection corners A,B,C

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3316
Location:	Aspen Gardens Wy and Aspen Glen Ct - Corner C				
X Coordinate:	-121.29849				
Y Coordinate:	38.68603				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Three - way intersection corners A,B,C



Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3317
Location:	Aspen Glen Ct - North				
X Coordinate:	-121.29868				
Y Coordinate:	38.68626				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	136	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.6% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$17,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3318
Location:	Aspen Gardens Wy - East				
X Coordinate:	-121.29909				
Y Coordinate:	38.68564				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	364	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.8% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$45,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--


Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3319
Location:	Aspen Gardens Wy and Aspen View Ct - Corner A				
X Coordinate:	-121.29913				
Y Coordinate:	38.68462				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Three - way intersection corners A,B,C


Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3320
Location:	Aspen Gardens Wy and Aspen View Ct - Corner B				
X Coordinate:	-121.29905				
Y Coordinate:	38.6847				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Three - way intersection corners A,B,C

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3321
Location:	Aspen Gardens Wy and Aspen View Ct - Corner C				
X Coordinate:	-121.299				
Y Coordinate:	38.68456				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Three - way intersection corners A,B,C

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3322
Location:	Aspen Gardens Wy - East				
X Coordinate:	-121.2991				
Y Coordinate:	38.68448				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	600	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.2% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$75,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:


Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3323
Location:	Aspen Ranch Ct and Cedar Ranch Ct - Corner B				
X Coordinate:	-121.29894				
Y Coordinate:	38.68303				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Three - way intersection corners B,C,D

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3324A
Location:	Aspen Ranch Ct and Cedar Ranch Ct - Corner C				
X Coordinate:	-121.29892				
Y Coordinate:	38.68292				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH		
Description:	12" grooves at top of curb ramp are not level (3.1% to 4.0%)				
As Built Desc:	3.7% at 12" grooves				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Three - way intersection corners B,C,D

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3324B
Location:	Aspen Ranch Ct and Cedar Ranch Ct - Corner C				
X Coordinate:	-121.29892				
Y Coordinate:	38.68292				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Three - way intersection corners B,C,D

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3325
Location:	Aspen Ranch Ct and Cedar Ranch Ct - Corner D				
X Coordinate:	-121.29906				
Y Coordinate:	38.68286				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3326
Location:	Aspen Ranch Ct - West				
X Coordinate:	-121.29904				
Y Coordinate:	38.68264				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	177	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.2% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$22,125.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3327
Location:	Aspen Ranch Ct - South				
X Coordinate:	-121.29891				
Y Coordinate:	38.68215				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				




As Built Meas:	235	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.7% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$29,375.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--



Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3328
Location:	Aspen Ranch Ct - North				
X Coordinate:	-121.29815				
Y Coordinate:	38.6823				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	232	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.1% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$29,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3329
Location:	Aspen Ranch Ct - East				
X Coordinate:	-121.29887				
Y Coordinate:	38.68245				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	173	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.2% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$21,625.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3330
Location:	Aspen Ranch Ct - East				
X Coordinate:	-121.29895				
Y Coordinate:	38.68314				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	537	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.7% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$67,125.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3331
Location:	Aspen View Ct - South				
X Coordinate:	-121.2989				
Y Coordinate:	38.68454				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	186	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.5% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$23,250.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3332
Location:	Aspen View Ct - North				
X Coordinate:	-121.29837				
Y Coordinate:	38.68476				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	166	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.2% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$20,750.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3333
Location:	Aspen Gardens Wy - East				
X Coordinate:	-121.29901				
Y Coordinate:	38.68475				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	337	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.2% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$42,125.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/7/2010	Report Date:	12/7/2010	Barrier #:	3334
Location:	Stock Ranch Rd - South				
X Coordinate:	-121.29759				
Y Coordinate:	38.68603				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	456	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.1% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$57,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3335A
Location:	Stock Ranch Rd and Cedar Ranch Dr - Corner C				
X Coordinate:	-121.29692				
Y Coordinate:	38.68468				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH	
Description:	12" grooves at top of curb ramp are not level (2.1% to 3.0%)			
As Built Desc:	2.5% at 12" grooves			
Solution:	Demolish existing and construct new curb ramp			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners C,D
--------	------------------------------------

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3335B
Location:	Stock Ranch Rd and Cedar Ranch Dr - Corner C				
X Coordinate:	-121.29692				
Y Coordinate:	38.68468				
Barrier Area:	Curb Ramps				
Barrier Type:	Parallel Ramp Landing - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1127B.5.4 and ADA/ABA 406.4				



As Built Meas:	1	Quantity:	EACH		
Description:	Curb ramp landing or pan not level (3.1% to 4.0%)				
As Built Desc:	3.5% landing slope				
Solution:	Demolish existing and construct new transition				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners C,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3335C
Location:	Stock Ranch Rd and Cedar Ranch Dr - Corner C				
X Coordinate:	-121.29692				
Y Coordinate:	38.68468				
Barrier Area:	Curb Ramps				
Barrier Type:	Running Slope - Existing (8.6% to 8.9%)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.1				



As Built Meas:	1	Quantity:	EACH		
Description:	Ramp run cross slope exceeds 2.0% (8.6% to 8.9%)				
As Built Desc:	8.9% running slope				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners C,D

Field Date: 12/10/2010 Report Date: 12/10/2010 Barrier #: 3335D

Location: Stock Ranch Rd and Cedar Ranch Dr - Corner C

X Coordinate: -121.29692

Y Coordinate: 38.68468

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D

Field Date: 12/10/2010 Report Date: 12/10/2010 Barrier #: 3335E

Location: Stock Ranch Rd and Cedar Ranch Dr - Corner C

X Coordinate: -121.29692

Y Coordinate: 38.68468

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (8.3% or more)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (8.3% or more)

As Built Desc: 8.6% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 1 Necessary Cost Estimate: \$0.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Two - way intersection corners C,D



Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3336A
Location:	Stock Ranch Rd and Cedar Ranch Dr - Corner D				
X Coordinate:	-121.297				
Y Coordinate:	38.68481				
Barrier Area:	Curb Ramps				
Barrier Type:	Parallel Ramp Landing - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1127B.5.4 and ADA/ABA 406.4				



As Built Meas:	1	Quantity:	EACH		
Description:	Curb ramp landing or pan not level (2.1% to 3.0%)				
As Built Desc:	3.0% landing slope				
Solution:	Demolish existing and construct new transition				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners C,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3336B
Location:	Stock Ranch Rd and Cedar Ranch Dr - Corner D				
X Coordinate:	-121.297				
Y Coordinate:	38.68481				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH		
Description:	12" grooves at top of curb ramp are not level (3.1% to 4.0%)				
As Built Desc:	3.1% at 12" grooves				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners C,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3336C
Location:	Stock Ranch Rd and Cedar Ranch Dr - Corner D				
X Coordinate:	-121.297				
Y Coordinate:	38.68481				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners C,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3336D
Location:	Stock Ranch Rd and Cedar Ranch Dr - Corner D				
X Coordinate:	-121.297				
Y Coordinate:	38.68481				
Barrier Area:	Curb Ramps				
Barrier Type:	Gutter Slope - Existing (6.6% to 8.2%)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.2				



As Built Meas:	6	Quantity:	SF	
Description:	Gutter slope exceeds 5.0% (6.6% to 8.2%)			
As Built Desc:	6.9% gutter slope			
Solution:	Demolish existing and construct new gutter			
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners C,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3337
Location:	Cedar Ranch Dr - West				
X Coordinate:	-121.29715				
Y Coordinate:	38.6847				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	64	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.5% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$8,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3338A
Location:	Cedar Ranch Cr and Ryan Taylor Wy - Corner A				
X Coordinate:	-121.2973				
Y Coordinate:	38.68462				
Barrier Area:	Curb Ramps				
Barrier Type:	Running Slope - Existing (8.6% to 8.9%)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.1				



As Built Meas:	1	Quantity:	EACH		
Description:	Ramp run cross slope exceeds 2.0% (8.6% to 8.9%)				
As Built Desc:	8.9% running slope				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	3 Hindrance	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	Two - way intersection corners A,D				
--------	------------------------------------	--	--	--	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3338B
Location:	Cedar Ranch Cr and Ryan Taylor Wy - Corner A				
X Coordinate:	-121.2973				
Y Coordinate:	38.68462				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3338C
Location:	Cedar Ranch Cr and Ryan Taylor Wy - Corner A				
X Coordinate:	-121.2973				
Y Coordinate:	38.68462				
Barrier Area:	Curb Ramps				
Barrier Type:	Gutter Slope - Existing (5.9% - 6.5%)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.2				



As Built Meas:	6	Quantity:	SF	
Description:	Gutter slope exceeds 5.0% (5.9% - 6.5%)			
As Built Desc:	6.4% gutter slope			
Solution:	Demolish existing and construct new gutter			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3339A
Location:	Cedar Ranch Cr and Ryan Taylor Wy - Corner D				
X Coordinate:	-121.29738				
Y Coordinate:	38.68454				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH	
Description:	12" grooves at top of curb ramp are not level (4.1% to 4.9%)			
As Built Desc:	4.1% at 12" grooves			
Solution:	Demolish existing and construct new curb ramp			
Bar. Severity:	2 Recommended	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3339B
Location:	Cedar Ranch Cr and Ryan Taylor Wy - Corner D				
X Coordinate:	-121.29738				
Y Coordinate:	38.68454				
Barrier Area:	Curb Ramps				
Barrier Type:	Parallel Ramp Landing - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1127B.5.4 and ADA/ABA 406.4				



As Built Meas:	1	Quantity:	EACH	
Description:	Curb ramp landing or pan not level (2.1% to 3.0%)			
As Built Desc:	2.7% landing slope			
Solution:	Demolish existing and construct new transition			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3339C
Location:	Cedar Ranch Cr and Ryan Taylor Wy - Corner D				
X Coordinate:	-121.29738				
Y Coordinate:	38.68454				
Barrier Area:	Curb Ramps				
Barrier Type:	Running Slope - Existing (9.5% or more)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.1				



As Built Meas:	1	Quantity:	EACH	
Description:	Ramp run cross slope exceeds 2.0% (9.5% or more)			
As Built Desc:	9.5% running slope			
Solution:	Demolish existing and construct new curb ramp			
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3339D
Location:	Cedar Ranch Cr and Ryan Taylor Wy - Corner D				
X Coordinate:	-121.29738				
Y Coordinate:	38.68454				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners A,D



Field Date: 12/10/2010 Report Date: 12/10/2010 Barrier #: 3340

Location: Ryan Taylor Wy and Cedar Park Ct - Corner A

X Coordinate: -121.29782

Y Coordinate: 38.68552

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection corners A,C,D

Field Date: 12/10/2010 Report Date: 12/10/2010 Barrier #: 3341A

Location: Ryan Taylor Wy and Cedar Park Ct - Corner C

X Coordinate: -121.29791

Y Coordinate: 38.6854

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection corners A,C,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3341B
Location:	Ryan Taylor Wy and Cedar Park Ct - Corner C				
X Coordinate:	-121.29791				
Y Coordinate:	38.6854				
Barrier Area:	Curb Ramps				
Barrier Type:	Gutter Slope - Existing (6.6% to 8.2%)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.2				



As Built Meas:	6	Quantity:	SF	
Description:	Gutter slope exceeds 5.0% (6.6% to 8.2%)			
As Built Desc:	6.6% gutter slope			
Solution:	Demolish existing and construct new gutter			
Bar. Severity:	2 Recommended	Cost Estimate:	\$750.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Three - way intersection corners A,C,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3342A
Location:	Ryan Taylor Wy and Cedar Park Ct - Corner D				
X Coordinate:	-121.29797				
Y Coordinate:	38.68549				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Three - way intersection corners A,C,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3342B
Location:	Ryan Taylor Wy and Cedar Park Ct - Corner D				
X Coordinate:	-121.29797				
Y Coordinate:	38.68549				
Barrier Area:	Curb Ramps				
Barrier Type:	Lip - Gutter to Asphalt Transition				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 303.3				



As Built Meas:	1	Quantity:	EACH		
Description:	Transition at transition into asphalt not flush and free of any lip				
As Built Desc:	1/2" lip at asphalt transition into roadway				
Solution:	Remove lip to create flush transition				
Bar. Severity:	1 Necessary	Cost Estimate:	\$250.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Three - way intersection corners A,C,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3342C
Location:	Ryan Taylor Wy and Cedar Park Ct - Corner D				
X Coordinate:	-121.29797				
Y Coordinate:	38.68549				
Barrier Area:	Curb Ramps				
Barrier Type:	Gutter Slope - Existing (5.1% - 5.8%)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.2				



As Built Meas:	6	Quantity:	SF		
Description:	Gutter slope exceeds 5.0% (5.1% - 5.8%)				
As Built Desc:	5.8% gutter slope				
Solution:	Demolish existing and construct new gutter				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$750.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Three - way intersection corners A,C,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3343
Location:	Ryan Taylor Wy - North				
X Coordinate:	-121.29806				
Y Coordinate:	38.686				
Barrier Area:	Sidewalks				
Barrier Type:	Clear Width - Existing ( $\leq 31"$ or less)				
Code Ref:	CBC 1133B.7.1				



As Built Meas:	2	Quantity:	LF	
Description:	Pedestrian route is not min. 48" wide ( $\leq 31"$ or less)			
As Built Desc:	30" clear width due to foliage			
Solution:	Trim foliage			
Bar. Severity:	1 Necessary	Cost Estimate:	\$125.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3344
Location:	Cedar Park Ct - South				
X Coordinate:	-121.29828				
Y Coordinate:	38.68535				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	121	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.7% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$15,125.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3345
Location:	Cedar Ranch Dr - West				
X Coordinate:	-121.29738				
Y Coordinate:	38.68449				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	121	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.7% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$15,125.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3346
Location:	Cedar Ranch Dr - West				
X Coordinate:	-121.2979				
Y Coordinate:	38.68385				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	48	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.5% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$6,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date: 12/10/2010 Report Date: 12/10/2010 Barrier #: 3347A

Location: Cedar Ranch Dr and Cedar Garden Ct - Corner A

X Coordinate: -121.29804

Y Coordinate: 38.68376

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection corners A,B,D

Field Date: 12/10/2010 Report Date: 12/10/2010 Barrier #: 3347B

Location: Cedar Ranch Dr and Cedar Garden Ct - Corner A

X Coordinate: -121.29804

Y Coordinate: 38.68376

Barrier Area: Curb Ramps

Barrier Type: Gutter Slope - Existing (5.9% - 6.5%)

Code Ref: CBC 1127B.5.3 and ADA/ABA 406.2



As Built Meas: 6 Quantity: SF

Description: Gutter slope exceeds 5.0% (5.9% - 6.5%)

As Built Desc: 6.2% gutter slope

Solution: Demolish existing and construct new gutter

Bar. Severity: 3 Hindrance Cost Estimate: \$750.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection corners A,B,D



Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3348A
Location:	Cedar Ranch Dr and Cedar Garden Ct - Corner B				
X Coordinate:	-121.29793				
Y Coordinate:	38.68372				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Three - way intersection corners A,B,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3348B
Location:	Cedar Ranch Dr and Cedar Garden Ct - Corner B				
X Coordinate:	-121.29793				
Y Coordinate:	38.68372				
Barrier Area:	Curb Ramps				
Barrier Type:	Gutter Slope - Existing (6.6% to 8.2%)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.2				



As Built Meas:	6	Quantity:	SF	
Description:	Gutter slope exceeds 5.0% (6.6% to 8.2%)			
As Built Desc:	8.5% gutter slope			
Solution:	Demolish existing and construct new gutter			
Bar. Severity:	2 Recommended	Cost Estimate:	\$750.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Three - way intersection corners A,B,D

Field Date: 12/10/2010 Report Date: 12/10/2010 Barrier #: 3349

Location: Cedar Ranch Dr and Cedar Garden Ct - Corner D

X Coordinate: -121.29809

Y Coordinate: 38.68362

Barrier Area: Curb Ramps

Barrier Type: Detectable Warnings - Truncated Domes

Code Ref: CBC 1127B.5.7 and ADA/ABA 705.1.3



As Built Meas: 1 Quantity: EACH

Description: No truncated domes provided at curb ramp

As Built Desc: No detectable warnings at curb ramp

Solution: Provide compliant truncated domes

Bar. Severity: 2 Recommended Cost Estimate: \$1,400.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes: Three - way intersection corners A,B,D

Field Date: 12/10/2010 Report Date: 12/10/2010 Barrier #: 3350

Location: Cedar Garden Ct - North

X Coordinate: -121.2981

Y Coordinate: 38.68379

Barrier Area: Sidewalks

Barrier Type: Cross Slope - Existing (4.1% to 4.9%)

Code Ref: CBC 1133B.7.1.3 and ADA/ABA 403.3



As Built Meas: 145 Quantity: LF

Description: Cross slope exceeds 2.0% (4.1% to 4.9%)

As Built Desc: 4.1% cross slope

Solution: Demolish existing and construct new route

Bar. Severity: 2 Recommended Cost Estimate: \$18,125.00 Status:

Implementation Priority: 4 Facility Function:

Implementation Phase: Implementation Date:

Official Responsible:

Notes:

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3351
Location:	Cedar Garden Ct - South				
X Coordinate:	-121.29838				
Y Coordinate:	38.68376				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	78	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.9% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$9,750.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:				
--------	--	--	--	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3352
Location:	Cedar Ranch Dr - West				
X Coordinate:	-121.29809				
Y Coordinate:	38.68358				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	212	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.4% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$26,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:				
--------	--	--	--	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3353
Location:	Cedar Ranch Dr - South				
X Coordinate:	-121.29847				
Y Coordinate:	38.68291				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	82	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.1% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$10,250.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:				
--------	--	--	--	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3354
Location:	Cedar Ranch Dr - East				
X Coordinate:	-121.29824				
Y Coordinate:	38.68304				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	262	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.5% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$32,750.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:				
--------	--	--	--	--


Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3355
Location:	Cedar Ranch Dr - East				
X Coordinate:	-121.29719				
Y Coordinate:	38.68459				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	67	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.1% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$8,375.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3356
Location:	Fountain Square Dr - East				
X Coordinate:	-121.29815				
Y Coordinate:	38.6785				
Barrier Area:	Sidewalks				
Barrier Type:	Running Slope (Existing)				
Code Ref:	CBC 1133B.7.3 and ADA/ABA 403.3				



As Built Meas:	20	Quantity:	LF	
Description:	Running slope exceeds 5.0%			
As Built Desc:	6.9% running slope			
Solution:	No remediation where sidewalk sloped as roadway			
Bar. Severity:	5 Technically Infeasible	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3357
Location:	Stock Ranch Rd - South				
X Coordinate:	-121.29502				
Y Coordinate:	38.68257				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	80	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.1% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$10,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3358A
Location:	Stock Ranch Rd and Vintage Oaks Entrance - Corner C				
X Coordinate:	-121.29386				
Y Coordinate:	38.68183				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH	
Description:	12" grooves at top of curb ramp are not level (3.1% to 4.0%)			
As Built Desc:	3.5% at 12" grooves			
Solution:	Demolish existing and construct new curb ramp			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	Two - way intersection corners C,D
--------	------------------------------------



Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3358B
Location:	Stock Ranch Rd and Vintage Oaks Entrance - Corner C				
X Coordinate:	-121.29386				
Y Coordinate:	38.68183				
Barrier Area:	Curb Ramps				
Barrier Type:	Perpendicular Ramp Landing - New Construction				
Code Ref:	CBC 1127B.5.4 and ADA/ABA 406.4				



As Built Meas:	1	Quantity:	EACH		
Description:	Curb ramp top landing not min. 48" deep				
As Built Desc:	No top landing provided				
Solution:	Demolish existing and construct new transition				
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners C,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3358C
Location:	Stock Ranch Rd and Vintage Oaks Entrance - Corner C				
X Coordinate:	-121.29386				
Y Coordinate:	38.68183				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners C,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3359A
Location:	Stock Ranch Rd and Vintage Oaks Entrance - Corner D				
X Coordinate:	-121.29408				
Y Coordinate:	38.68189				
Barrier Area:	Curb Ramps				
Barrier Type:	12" Grooves - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1127B.5.6				



As Built Meas:	1	Quantity:	EACH		
Description:	12" grooves at top of curb ramp are not level (4.1% to 4.9%)				
As Built Desc:	4.7% at 12" grooves				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	2 Recommended	Cost Estimate:	\$2,500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners C,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3359B
Location:	Stock Ranch Rd and Vintage Oaks Entrance - Corner D				
X Coordinate:	-121.29408				
Y Coordinate:	38.68189				
Barrier Area:	Curb Ramps				
Barrier Type:	Flares - Existing (11.1% or more)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.3				



As Built Meas:	1	Quantity:	EACH		
Description:	Ramp flare slope exceeds 10.0% (11.1% or more)				
As Built Desc:	13.6% flare slope				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners C,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3359C
Location:	Stock Ranch Rd and Vintage Oaks Entrance - Corner D				
X Coordinate:	-121.29408				
Y Coordinate:	38.68189				
Barrier Area:	Curb Ramps				
Barrier Type:	Running Slope - Existing (9.5% or more)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.1				



As Built Meas:	1	Quantity:	EACH		
Description:	Ramp run cross slope exceeds 2.0% (9.5% or more)				
As Built Desc:	9.6% running slope				
Solution:	Demolish existing and construct new curb ramp				
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners C,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3359D
Location:	Stock Ranch Rd and Vintage Oaks Entrance - Corner D				
X Coordinate:	-121.29408				
Y Coordinate:	38.68189				
Barrier Area:	Curb Ramps				
Barrier Type:	Perpendicular Ramp Landing - New Construction				
Code Ref:	CBC 1127B.5.4 and ADA/ABA 406.4				



As Built Meas:	1	Quantity:	EACH		
Description:	Curb ramp top landing not min. 48" deep				
As Built Desc:	No top landing provided				
Solution:	Demolish existing and construct new transition				
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners C,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3359E
Location:	Stock Ranch Rd and Vintage Oaks Entrance - Corner D				
X Coordinate:	-121.29408				
Y Coordinate:	38.68189				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH	
Description:	No truncated domes provided at curb ramp			
As Built Desc:	No detectable warnings at curb ramp			
Solution:	Provide compliant truncated domes			
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners C,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3360A
Location:	Stock Ranch Rd and Vintage Oaks Entrance - Corner C				
X Coordinate:	-121.29301				
Y Coordinate:	38.68182				
Barrier Area:	Curb Ramps				
Barrier Type:	Running Slope - Existing (9.0% to 9.4%)				
Code Ref:	CBC 1127B.5.3 and ADA/ABA 406.1				



As Built Meas:	1	Quantity:	EACH	
Description:	Ramp run cross slope exceeds 2.0% (9.0% to 9.4%)			
As Built Desc:	9.1% running slope			
Solution:	Demolish existing and construct new curb ramp			
Bar. Severity:	2 Recommended	Cost Estimate:	\$2,500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes: Two - way intersection corners C,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3360B
Location:	Stock Ranch Rd and Vintage Oaks Entrance - Corner C				
X Coordinate:	-121.29301				
Y Coordinate:	38.68182				
Barrier Area:	Curb Ramps				
Barrier Type:	Perpendicular Ramp Landing - New Construction				
Code Ref:	CBC 1127B.5.4 and ADA/ABA 406.4				



As Built Meas:	1	Quantity:	EACH		
Description:	Curb ramp top landing not min. 48" deep				
As Built Desc:	No top landing provided				
Solution:	Demolish existing and construct new transition				
Bar. Severity:	1 Necessary	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners C,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3360C
Location:	Stock Ranch Rd and Vintage Oaks Entrance - Corner C				
X Coordinate:	-121.29301				
Y Coordinate:	38.68182				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$0.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners C,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3361A
Location:	Stock Ranch Rd and Vintage Oaks Entrance - Corner D				
X Coordinate:	-121.29318				
Y Coordinate:	38.6818				
Barrier Area:	Curb Ramps				
Barrier Type:	Perpendicular Ramp Landing - New Construction				
Code Ref:	CBC 1127B.5.4 and ADA/ABA 406.4				



As Built Meas:	1	Quantity:	EACH		
Description:	Curb ramp top landing not min. 48" deep				
As Built Desc:	No top landing provided				
Solution:	Demolish existing and construct new transition				
Bar. Severity:	1 Necessary	Cost Estimate:	\$250.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners C,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3361B
Location:	Stock Ranch Rd and Vintage Oaks Entrance - Corner D				
X Coordinate:	-121.29318				
Y Coordinate:	38.6818				
Barrier Area:	Curb Ramps				
Barrier Type:	Detectable Warnings - Truncated Domes				
Code Ref:	CBC 1127B.5.7 and ADA/ABA 705.1.3				



As Built Meas:	1	Quantity:	EACH		
Description:	No truncated domes provided at curb ramp				
As Built Desc:	No detectable warnings at curb ramp				
Solution:	Provide compliant truncated domes				
Bar. Severity:	2 Recommended	Cost Estimate:	\$1,400.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes: Two - way intersection corners C,D



Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3362
Location:	Stock Ranch Rd - South				
X Coordinate:	-121.29161				
Y Coordinate:	38.68182				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	35	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.7% cross slope, 9.1% running slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,375.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3363
Location:	Stock Ranch Rd - South				
X Coordinate:	-121.29116				
Y Coordinate:	38.6818				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	174	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.9% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	3 Hinderance	Cost Estimate:	\$21,750.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3364
Location:	Sylvan Rd - West				
X Coordinate:	-121.29042				
Y Coordinate:	38.68167				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	6	Quantity:	LF	
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)			
As Built Desc:	Cracked concrete			
Solution:	Repair surface to make firm and stable			
Bar. Severity:	1 Necessary	Cost Estimate:	\$750.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3365A
Location:	Sylvan Rd - West				
X Coordinate:	-121.29043				
Y Coordinate:	38.68149				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Back Support				
Code Ref:	ADAAG 4.37.4 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH	
Description:	Bench has no back support of at least 18" high			
As Built Desc:	15-1/2" back support height			
Solution:	Provide min. 1 accessible bench at bench stop or shelter			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$775.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3365B
Location:	Sylvan Rd - West				
X Coordinate:	-121.29043				
Y Coordinate:	38.68149				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Seat Depth				
Code Ref:	ADAAG 4.37.1 and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH	
Description:	Bench seat depth not 20" - 24" deep			
As Built Desc:	12-1/2" bench seat depth			
Solution:	Provide min. 1 accessible bench at bench stop			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3365C
Location:	Sylvan Rd - West				
X Coordinate:	-121.29043				
Y Coordinate:	38.68149				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Bench Seat Height				
Code Ref:	ADAAG 4.37.3* and ADA/ABA 903.4				



As Built Meas:	1	Quantity:	EACH	
Description:	Bench seat height not between 17" - 19"			
As Built Desc:	16-1/2" bench seat height			
Solution:	Provide new compliant bench or remount at compliant height where possible			
Bar. Severity:	3 Hindrance	Cost Estimate:	\$0.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:	
--------	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3365D
Location:	Sylvan Rd - West				
X Coordinate:	-121.29043				
Y Coordinate:	38.68149				
Barrier Area:	Bus Stops and Shelters				
Barrier Type:	Cross Slope - Existing (2.1% to 3.0%)				
Code Ref:	CBC 1121B.2.1 and ADAAG 10.2.1(1)				



As Built Meas:	4	Quantity:	LF		
Description:	Cross slope at bus pad or shelter exceeds 2.0% (2.1% to 3.0%)				
As Built Desc:	3.0% cross slope				
Solution:	Demolish existing and construct new bus pad or shelter pad				
Bar. Severity:	4 Low Severity	Cost Estimate:	\$500.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3366
Location:	Sylvan Rd - West				
X Coordinate:	-121.29044				
Y Coordinate:	38.68138				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	326	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)				
As Built Desc:	3.5% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	3 Hinderance	Cost Estimate:	\$40,750.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:					
--------	--	--	--	--	--

Field Date: 12/10/2010 Report Date: 12/10/2010 Barrier #: 3367  
 Location: San Juan Ave and San Juan Plaza Shopping Center Entrance - Corner  
 X Coordinate: -121.29105  
 Y Coordinate: 38.68025  
 Barrier Area: Curb Ramps  
 Barrier Type: No Curb Ramp - Depressed Existing Curb  
 Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH  
 Description: No compliant curb cut at corner (intersection)  
 As Built Desc: 8.4% running slope at depressed area  
 Solution: Demolish existing and construct curb cut  
 Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:  
 Implementation Priority: 4 Facility Function:  
 Implementation Phase: Implementation Date:  
 Official Responsible:

Notes: Two - way intersection corners A,D

Field Date: 12/10/2010 Report Date: 12/10/2010 Barrier #: 3368  
 Location: San Juan Ave and San Juan Plaza Shopping Center Entrance - Corner  
 X Coordinate: -121.29118  
 Y Coordinate: 38.68018  
 Barrier Area: Curb Ramps  
 Barrier Type: No Curb Ramp - Depressed Existing Curb  
 Code Ref: CBC 1127B.5.1 and ADA/ABA 402.2



As Built Meas: 1 Quantity: EACH  
 Description: No compliant curb cut at corner (intersection)  
 As Built Desc: 14.7% running slope at depressed area  
 Solution: Demolish existing and construct curb cut  
 Bar. Severity: 1 Necessary Cost Estimate: \$2,500.00 Status:  
 Implementation Priority: 4 Facility Function:  
 Implementation Phase: Implementation Date:  
 Official Responsible:

Notes: Two - way intersection corners A,D

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3369
Location:	San Juan Ave - West				
X Coordinate:	-121.29229				
Y Coordinate:	38.67934				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	40	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	4.0% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	3 Hinderance	Cost Estimate:	\$5,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3370
Location:	San Juan Ave - West				
X Coordinate:	-121.2926				
Y Coordinate:	38.67887				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	40	Quantity:	LF
Description:	Driveway cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	4.0% cross slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	2 Recommended	Cost Estimate:	\$5,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--



Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3371
Location:	San Juan Ave - West				
X Coordinate:	-121.29262				
Y Coordinate:	38.67882				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	40	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.2% cross slope, 10.6% running slope				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	1 Necessary	Cost Estimate:	\$5,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3372A
Location:	Sylvan Rd - East				
X Coordinate:	-121.2923				
Y Coordinate:	38.6786				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	50	Quantity:	LF		
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)				
As Built Desc:	4.5% cross slope				
Solution:	Demolish existing and construct new route				
Bar. Severity:	2 Recommended	Cost Estimate:	\$6,250.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3372B
Location:	Sylvan Rd - East				
X Coordinate:	-121.2923				
Y Coordinate:	38.6786				
Barrier Area:	Sidewalks				
Barrier Type:	Surface Condition - Damaged				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 302.1				



As Built Meas:	4	Quantity:	LF	
Description:	Surface is not firm and stable (cracked, broken or loose soil, etc.)			
As Built Desc:	Cracked concrete			
Solution:	Repair surface to make firm and stable			
Bar. Severity:	1 Necessary	Cost Estimate:	\$500.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:				
--------	--	--	--	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3373
Location:	Sylvan Rd - East				
X Coordinate:	-121.29229				
Y Coordinate:	38.6787				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	35	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	10.2% cross slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,375.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:				
--------	--	--	--	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3374
Location:	San Juan Ave - East				
X Coordinate:	-121.2922				
Y Coordinate:	38.67884				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	35	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (3.1% to 4.0%)			
As Built Desc:	3.8% cross slope, 16.4% running slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	1 Necessary	Cost Estimate:	\$4,375.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:				
--------	--	--	--	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3375
Location:	San Juan Ave - East				
X Coordinate:	-121.29209				
Y Coordinate:	38.6793				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	55	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.8% cross slope, 15.8% running slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	1 Necessary	Cost Estimate:	\$6,875.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:				
--------	--	--	--	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3376
Location:	San Juan Ave - East				
X Coordinate:	-121.29152				
Y Coordinate:	38.67974				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	55	Quantity:	LF		
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)				
As Built Desc:	9.0% cross slope, 12.6% running slope at cracked concrete				
Solution:	Provide min. 48" wide level walkway through driveway				
Bar. Severity:	1 Necessary	Cost Estimate:	\$6,875.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3377
Location:	Sylvan Rd - West				
X Coordinate:	-121.29137				
Y Coordinate:	38.67984				
Barrier Area:	Sidewalks				
Barrier Type:	Abrupt Change in Level - > 1/2"				
Code Ref:	CBC 1133B.7.1 and ADA/ABA 303.3				



As Built Meas:	4	Quantity:	LF		
Description:	Change in level greater than 1/2"				
As Built Desc:	1" lip in sidewalk surface				
Solution:	Grind or repair sidewalk to remove trip hazard				
Bar. Severity:	1 Necessary	Cost Estimate:	\$1,000.00	Status:	
Implementation Priority:	4	Facility Function:			
Implementation Phase:		Implementation Date:			
Official Responsible:					

Notes:	
--------	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3378
Location:	Sylvan Rd - West				
X Coordinate:	-121.29033				
Y Coordinate:	38.68034				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	50	Quantity:	LF
Description:	Cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	5.7% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	1 Necessary	Cost Estimate:	\$6,250.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3379
Location:	Sylvan Rd - West				
X Coordinate:	-121.29033				
Y Coordinate:	38.68012				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	35	Quantity:	LF
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	6.7% cross slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	4 Low Severity	Cost Estimate:	\$4,375.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3380
Location:	Sylvan Rd - West				
X Coordinate:	-121.29031				
Y Coordinate:	38.67998				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	325	Quantity:	LF	
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)			
As Built Desc:	4.8% cross slope			
Solution:	Demolish existing and construct new route			
Bar. Severity:	2 Recommended	Cost Estimate:	\$40,625.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:				
--------	--	--	--	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3381
Location:	Sylvan Rd - West				
X Coordinate:	-121.29033				
Y Coordinate:	38.67895				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	40	Quantity:	LF	
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)			
As Built Desc:	8.0% cross slope, 12.8% running slope			
Solution:	Provide min. 48" wide level walkway through driveway			
Bar. Severity:	1 Necessary	Cost Estimate:	\$5,000.00	Status:
Implementation Priority:	4	Facility Function:		
Implementation Phase:		Implementation Date:		
Official Responsible:				

Notes:				
--------	--	--	--	--



Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3382
Location:	Sylvan Rd - West				
X Coordinate:	-121.29032				
Y Coordinate:	38.6789				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	32	Quantity:	LF
Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)		
As Built Desc:	3.2% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	3 Hinderance	Cost Estimate:	\$4,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3383
Location:	Sylvan Rd - West				
X Coordinate:	-121.29037				
Y Coordinate:	38.67876				
Barrier Area:	Sidewalks				
Barrier Type:	Driveway - Existing (5.0% or more)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	40	Quantity:	LF
Description:	Driveway cross slope exceeds 2.0% (5.0% or more)		
As Built Desc:	8.2% cross slope, 10.5% running slope		
Solution:	Provide min. 48" wide level walkway through driveway		
Bar. Severity:	1 Necessary	Cost Estimate:	\$5,000.00
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			

Notes:	
--------	--

Field Date:	12/10/2010	Report Date:	12/10/2010	Barrier #:	3384
Location:	Sylvan Rd - West				
X Coordinate:	-121.29035				
Y Coordinate:	38.67868				
Barrier Area:	Sidewalks				
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)				
Code Ref:	CBC 1133B.7.1.3 and ADA/ABA 403.3				



As Built Meas:	60	Quantity:	LF
Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)		
As Built Desc:	4.1% cross slope		
Solution:	Demolish existing and construct new route		
Bar. Severity:	2 Recommended	Cost Estimate:	\$7,500.00
		Status:	
Implementation Priority:	4	Facility Function:	
Implementation Phase:		Implementation Date:	
Official Responsible:			
Notes:			

---

---

<b>Cost Estimate Total Summary :</b>	\$6,402,025.00
--------------------------------------	----------------

---

---

<b>Cost Estimate - Priority 1:</b>	\$1,421,875.00
------------------------------------	----------------

<b>Cost Estimate - Priority 2:</b>	\$854,875.00
------------------------------------	--------------

<b>Cost Estimate - Priority 3:</b>	\$738,550.00
------------------------------------	--------------

<b>Cost Estimate - Priority 4:</b>	\$3,386,225.00
------------------------------------	----------------

---

---